



North Carolina Department of Environment and Natural Resources
Division of Energy, Mineral and Land Resources
Land Quality Section

Tracy E. Davis, PE, CPM
Director

Pat McCrory, Governor
John E. Skvarla, III, Secretary

NOTICE OF INSPECTION

Date: March 11, 2014

Duke Energy Corporation
Attention: Sean DeNeale
526 South Church Street, ECI-013
Charlotte, North Carolina 28202

RE: Buck Steam Station Main Dam
ROWAN-047 – High Hazard Potential
Rowan County

Dear Mr. DeNeale:

The "Dam Safety Law of 1967," as amended, provides for the certification and inspection of dams in the interest of public health, safety, and welfare, in order to reduce the risk of failure of such dams; to prevent injuries to persons, damage to property; and to insure the maintenance of stream flows.

Our record indicates that you are the owner and/or responsible for the referenced dam, which is located off Dukeville Road and was inspected on February 26, 2014 by personnel of the Land Quality Section. This inspection revealed the conditions outlined below. Please note that references to "right" and "left" in descriptions of the dam structure are referenced while looking in the downstream direction.

1. The last section of the concrete chute spillway outlet channel has separated from the channel and settled. It is recommended that you monitor this situation and notify this office if the condition worsens.
2. Please continue to perform internal inspections of the discharge pipe at least annually. As previously stated in correspondence issued by Mr. Steve McEvoy, PE, and State Dam Safety Engineer on March 25, 2011, we request the annual inspection video be reviewed by a registered professional engineer experienced in pipe condition assessment and that this engineer render a professional opinion as to the integrity of the pipe pursuant to such review. Please continue to provide this Division with a copy of the inspection report, and include copies of pictures and/or videos taken during the inspection.

Mooreville Regional Office
610 East Center Avenue, Suite 301, Mooreville, North Carolina 28115
Telephone: 704-663-1699 / FAX: 704-663-6040 • Internet: <http://portal.ncdenr.org/web/ir/land-quality>
An Equal Opportunity / Affirmative Action Employer – 50% Recycled / 10% Post Consumer Paper

3. Wetness with clear flow was observed at the dam center toe. You should inspect this area periodically and notify this office if there is an increase in the amount of wetness, discoloration of water, or if embankment sliding occurs.
4. An area of saturated soils was observed approximately three-fourths height distance from the top of dam adjacent to the right abutment, potentially due to heavy, recent rain. Please monitor this area and notify this office if there is a sudden change in the area.
5. Trees and bushes are growing on the dam in the dam extension area. This type of growth can cause problems and even failure of the dam by creating holes when trees are uprooted due to wind or ice; by leaving possible seepage holes when trees die and their roots decay; or by causing erosion of the dam around this growth should the dam overtop during heavy rains. This woody growth can also hinder inspection and provide habitat for burrowing animals. Therefore, we recommend that this type of growth be removed and a good grass cover be established on the dam.

Though it is not our policy to allow any trees to grow on a dam, it is recommended that all trees greater than six inches in diameter be left on the dam. Trees larger than six inches that are in poor shape or pose a threat to the structural integrity of the dam and need removal require the supervision of a registered professional engineer competent in the area of dam safety. Also, prior approval must be obtained from the Division of Energy, Mineral and Land Resources for the removal of trees greater than six inches in diameter. All trees less than six inches should be removed.

6. Areas of surface damage possibly due to mower activity and areas of stressed vegetation due to recent rains were observed on the downstream slope of the dam. It is recommended that the areas be monitored and vegetation reestablished as needed to prevent surface erosion.

Additionally, the following general maintenance procedures are recommended:

1. Periodically check the operation of all drain valve facilities. This will ensure satisfactory operation of the drains should an emergency situation arise.
2. Periodically monitor the subject dam and appurtenant works with respect to elements affecting its safety. This is in light of the legal duties, obligations, and liabilities arising from the ownership and/or operation of a dam.

During this inspection we also investigated the potential for property damage and loss of life in the event that your dam fails. This investigation determined that failure of your dam could result in significant environmental damage to the Yadkin River and possible interruption of utility service. Therefore, we are listing your dam in the "High Hazard Potential" Note that all hazard classifications are subject to change due to downstream conditions.

Please be advised that the Division of Energy, Mineral and Land Resources must approve any excavation, modification, or major repair work to this dam before the work commences. Also, note that this dam may not be

breached, meaning the dam may not be drained by cutting a notch in the dam, without prior engineered breach plans being submitted to and approved by the Division of Energy, Mineral and Land Resources.


The "Dam Operation Maintenance and Inspection Manual" published by this Division provides inspection guidelines and recommended routine dam maintenance activities for the owner as well as emergency procedures in the event of possible dam failure. This document may be viewed online at <http://portal.ncdenr.org/web/lr/dams>.

Although every reasonable effort is made to determine the safety of each dam, our resources generally limit us to a surficial inspection of the dam and its appurtenant structures. This letter carries no implication regarding the internal stability of the dam. Dams, and especially their spillways and conduits, deteriorate with age. You are therefore advised to keep a close watch on the dam and notify us if you detect any changes, especially cracks, ground movements, or changes in seepage rate or color.

Please notify this office in writing if you wish to assert that you have no ownership or otherwise are not responsible for maintenance or repairs to the subject dam. If you have an emergency situation during non-office hours, you should notify 911 and the State Emergency Operations Center at 1 (800) 858-0368. They will notify the appropriate personnel in this Office of the situation.

Your cooperation and consideration in maintaining a safe dam is appreciated. Should you have any questions concerning our inspection, please contact me at (704) 663-1699.

Sincerely,



Zahid S. Khan, CPM, CPESC, CPSWQ
Regional Engineer
Land Quality Section

THE/cys

cc: Steven M. McEvoy, PE, State Dam Safety Engineer

DAM SAFETY INSPECTION REPORT

BW-GHAZALE

NAME <i>BURL STREAM STATION MAIN DAM</i>	COUNTY <i>ROWAN</i>	NO. <i>047</i>	INSPECTED BY <i>EPLIN, KORMANIK</i>	DATE <i>2/26/2014</i>
---	------------------------	-------------------	--	--------------------------

OWNER <i>DUKE ENERGY</i>	ADDRESS <i>See file</i>	PHONE
-----------------------------	----------------------------	-------

TYPE DAM <input type="checkbox"/> Concrete gravity <input type="checkbox"/> Concrete arch <input type="checkbox"/> Other <input type="checkbox"/> Embankment <input type="checkbox"/> Concrete buttress <input type="checkbox"/> Stone masonry	TYPE INSPECTION <input type="checkbox"/> Initial <input type="checkbox"/> Followup <input type="checkbox"/> Other <input checked="" type="checkbox"/> Periodic	SITE CONDITIONS <input type="checkbox"/> Dry <input type="checkbox"/> Snowcover <input type="checkbox"/> Other <input checked="" type="checkbox"/> Wet
--	--	--

HAZARD DESCRIPTION <i>See file</i>	HAZARD CLASS <input type="checkbox"/> Low (A) <input type="checkbox"/> Intermediate (B) <input checked="" type="checkbox"/> High (C)
---------------------------------------	---

REMARKS <i>Alex Papp, Sean Denial, Opre Wooten, Scott Nordgren, Tom Barber, Mike Miller, Max Gardner, Henry Lathams, Recent heavy rains</i>	ACTION <input type="checkbox"/> None <input checked="" type="checkbox"/> Maintenance <input type="checkbox"/> Monitoring <input type="checkbox"/> Minor repair <input type="checkbox"/> Engineering	RECOMMENDATIONS <input checked="" type="checkbox"/> Inspection letter <input type="checkbox"/> Deficiency letter <input type="checkbox"/> PE notice <input type="checkbox"/> Engineering study <input type="checkbox"/> Inspection by PE <input type="checkbox"/> Inspection by DSE <input type="checkbox"/> Dam safety order <input type="checkbox"/> Enforcement <input checked="" type="checkbox"/> Periodic reinspection <input type="checkbox"/> Other reinspection
--	--	--

AREA	PROBLEMS	COMMENTS
UPSTREAM SLOPE / FACE	<input type="checkbox"/> 1. None <input type="checkbox"/> 11. Displaced rip rap <input type="checkbox"/> 2. Trees <input type="checkbox"/> 12. Cracks <input type="checkbox"/> 3. High bushes <input type="checkbox"/> 13. Undermining <input type="checkbox"/> 4. Burrows <input type="checkbox"/> 14. Holes <input type="checkbox"/> 5. Wave erosion <input type="checkbox"/> 15. Spalling <input type="checkbox"/> 6. Livestock damage <input type="checkbox"/> 16. Displaced joints <input type="checkbox"/> 7. Slides <input type="checkbox"/> 17. Deteriorated joints <input type="checkbox"/> 8. Depressions <input type="checkbox"/> 18. Exposed reinforcement <input type="checkbox"/> 9. Bulges <input type="checkbox"/> 19. Other <input type="checkbox"/> 10. Sparse rip rap	COVER: <input checked="" type="checkbox"/> Vegetation <input type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Asphalt <input type="checkbox"/> Other <i>SOME WOODY GROWTH ON DAM EXTENSION AREA</i>
TOP OF DAM	<input checked="" type="checkbox"/> 1. None <input type="checkbox"/> 11. Cracks <input type="checkbox"/> 2. Trees <input type="checkbox"/> 12. Spalling <input type="checkbox"/> 3. High bushes <input type="checkbox"/> 13. Deteriorated joints <input type="checkbox"/> 4. Burrows <input type="checkbox"/> 14. Displaced joints <input type="checkbox"/> 5. Pits <input type="checkbox"/> 15. Exposed reinforcement <input type="checkbox"/> 6. Livestock damage <input type="checkbox"/> 16. Other <input type="checkbox"/> 7. Depressions <input type="checkbox"/> 8. Uneven <input type="checkbox"/> 9. Misalignment <input type="checkbox"/> 10. Has overtopped	COVER: <input checked="" type="checkbox"/> Vegetation <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Concrete <input type="checkbox"/> Asphalt <input type="checkbox"/> Other
DOWNSTREAM SLOPE / FACE	<input type="checkbox"/> 1. None <input type="checkbox"/> 11. Seepage <input type="checkbox"/> 2. Trees <input type="checkbox"/> 12. Boils <input type="checkbox"/> 3. High bushes <input type="checkbox"/> 13. Cracks <input type="checkbox"/> 4. Burrows <input type="checkbox"/> 14. Holes <input type="checkbox"/> 5. Erosion <input type="checkbox"/> 15. Spalling <input type="checkbox"/> 6. Livestock damage <input type="checkbox"/> 16. Displaced joints <input type="checkbox"/> 7. Slides <input type="checkbox"/> 17. Deteriorated joints <input type="checkbox"/> 8. Depressions <input type="checkbox"/> 18. Exposed reinforcement <input type="checkbox"/> 9. Bulges <input type="checkbox"/> 19. Other <input type="checkbox"/> 10. Wetness	COVER: <input checked="" type="checkbox"/> Vegetation <input type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Other <i>Soft area ~ 3/4 down slope below apron, visually estimated Slope levels out, no flow/wetness observed.</i>
TOE CONTACT	<input type="checkbox"/> 1. None <input type="checkbox"/> 11. Seepage <input type="checkbox"/> 2. Trees <input type="checkbox"/> 12. Boils <input type="checkbox"/> 3. High bushes <input type="checkbox"/> 13. Cracks <input type="checkbox"/> 4. Burrows <input type="checkbox"/> 14. Holes <input type="checkbox"/> 5. Erosion <input type="checkbox"/> 15. Spalling <input type="checkbox"/> 6. Livestock damage <input type="checkbox"/> 16. Displaced joints <input type="checkbox"/> 7. Slides <input type="checkbox"/> 17. Deteriorated joints <input type="checkbox"/> 8. Depressions <input type="checkbox"/> 18. Exposed reinforcement <input type="checkbox"/> 9. Bulges <input type="checkbox"/> 19. Undermining <input type="checkbox"/> 10. Wetness <input type="checkbox"/> 20. Other	COVER: <input checked="" type="checkbox"/> Vegetation <input checked="" type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Other <i>WETNESS AT TOE, HISTORICAL CONDITION SOME SURFACE EROSION IN AREA ~15 FT AND ~ 20 FT UPSLOPE OF CHEMICAL STORAGE BUILDING REPAIR/ESTABLISH VEGETATION RECOMMENDED TOTAL FLOW AT TOE IS CLEAR, VISUALLY ESTIMATED AT < 1 GPM INCLUDING SURFACE FLOW FROM ENTIRE DAM</i>

AREA	PROBLEMS	COMMENTS
ABUTMENT CONTACTS	<input checked="" type="checkbox"/> 1. None <input type="checkbox"/> 2. Trees <input type="checkbox"/> 3. High bushes <input type="checkbox"/> 4. Burrows <input type="checkbox"/> 5. Erosion <input type="checkbox"/> 6. Livestock damage <input type="checkbox"/> 7. Slides <input type="checkbox"/> 8. Depressions <input type="checkbox"/> 9. Bulges <input type="checkbox"/> 10. Weibness <input type="checkbox"/> 11. Seepage <input type="checkbox"/> 12. Boils <input type="checkbox"/> 13. Cracks <input type="checkbox"/> 14. Holes <input type="checkbox"/> 15. Spalling <input type="checkbox"/> 16. Displaced joints <input type="checkbox"/> 17. Deteriorated joints <input type="checkbox"/> 18. Exposed reinforcement <input type="checkbox"/> 19. Undermining <input type="checkbox"/> 20. Other	COVER: <input type="checkbox"/> Vegetation <input checked="" type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Other
PRINCIPAL SPILLWAY	<input type="checkbox"/> 1. None <input type="checkbox"/> 2. No trashguard <input type="checkbox"/> 3. Obstructed <input type="checkbox"/> 4. Plugged <input type="checkbox"/> 5. Rusted <input type="checkbox"/> 6. Damaged <input type="checkbox"/> 7. Gates leaking <input type="checkbox"/> 8. Joints leaking <input type="checkbox"/> 9. Cracks <input type="checkbox"/> 10. Joint deterioration <input checked="" type="checkbox"/> 11. Joint displacement <input type="checkbox"/> 12. Undermined <input type="checkbox"/> 13. Voids <input type="checkbox"/> 14. Erosion <input type="checkbox"/> 15. Holes <input type="checkbox"/> 16. Conduit collapsed <input type="checkbox"/> 17. Spalling <input type="checkbox"/> 18. Outlet undercutting <input type="checkbox"/> 19. Misalignment <input checked="" type="checkbox"/> 20. Other	TYPE/SIZE: 10'x10' CONCRETE RISER w/ 36" CMP BARREL 20) LAST INTERNAL INSPECTION OF 36" CMP BARREL WAS 10/11/2013 - see file 11) LAST SECTION OF CONCRETE CHUTE SEPARATED - HISTORICAL CONDITION, UNDERMINING OF CONCRETE CHUTE 2ND SECTION, AT LEAST 1.5-2FT ON LEFT SIDE, VISUALLY ESTIMATED AT RIVER'S EDGE
EMERGENCY SPILLWAY	<input checked="" type="checkbox"/> 1. None <input type="checkbox"/> 2. No ES <input type="checkbox"/> 3. Same as PS <input type="checkbox"/> 4. Obstructed <input type="checkbox"/> 5. Erosion <input type="checkbox"/> 6. Displaced rip rap <input type="checkbox"/> 7. Sparse rip rap <input type="checkbox"/> 8. Joints leaking <input type="checkbox"/> 9. Cracks <input type="checkbox"/> 10. Joint deterioration <input type="checkbox"/> 11. Joint displacement <input type="checkbox"/> 12. Undermining <input type="checkbox"/> 13. Voids <input type="checkbox"/> 14. Holes <input type="checkbox"/> 15. Exposed reinforcement <input type="checkbox"/> 16. Spalling <input type="checkbox"/> 17. Outlet erosion <input type="checkbox"/> 18. Misalignment <input type="checkbox"/> 19. Inadequate capacity <input type="checkbox"/> 20. Other	TYPE/SIZE: Earthen channel
DRAINS / OTHER OUTLETS	<input checked="" type="checkbox"/> 1. None <input type="checkbox"/> 2. No bottom drain <input type="checkbox"/> 3. Bottom drain inoperable <input type="checkbox"/> 4. Subsurface drain dry <input type="checkbox"/> 5. Subsurface drain muddy flow <input type="checkbox"/> 6. Subsurface drain obstructed <input type="checkbox"/> 7. No animal guard <input type="checkbox"/> 8. Other	TYPE: N/A

SKETCHES/COMMENTS

MONTHLY PIEZOMETER READINGS REVIEWED FOR THE PAST YEAR. OPIE HAS NOTED CORRELATION OF LEVELS WITH RAINS, FOR THOSE W/ CHANGING ELEVATIONS.