JUH, PALV, TED & JOHN BRUMTON, PED BRUTTON WAKESONE - CANDSUDE CA BUSINE (OKSISE MITO 1/8/92 150-250PM) - Caused by blast along western pide between mine excavation and asther Creek senting in with material sledy into the Creek. Maturil has filled 2900 gourn week (15' wide it the crech and Cer- 70' wide down bank) - creek not really backed up-flowing through with; slight workercutting of bank (opposite ride) as creek flowing around and of fill

- When los agreed that 100' buffer in this area has been violated

be also between by stope failure. - We agreed to immediately Commence removing material from creek and fame and advised us of their proposed plant action. We is also currently evaluately blast records + design to determine cause of the like. - Cos sourced We that we would meet with CHE and drewen the junger course of action - IH, THE and TD met with CHG and discussed our fudings - Cett due ted TH to deapt up a deficiency letter noting the violation of the buffer your and authory the conection actions needed Chart report of black and conclusions made, planfor removal of slede material provincel + that fact pull time frame for confliction and stabilizate). Oble agreed that letter must state no the further blesty in the western area as there appear to be no refe way to continue blasty in the area blout fature

315 pm

- It comment and will have letter (deep) sent to us for several and comment before sending to as.

GAX: #919 571 4718 1/13/22 X6XP. Mm gleare fax the attached permit to John Holley Ast Che whiting mut for write a letter! This for me.

and Then return this Marker 1 Pay 12 SE)

Wake Stone Corporation

Quarry Phone Numbers: 919/266-9266—Knightdale 919/677-0050—Triangle 919/775-7349—Moncure 919/985-4411—Nash County Locations:
U.S. 64 East, Raleigh, N.C.
I-40 at Harrison Ave., Cary, N.C.
U.S. 1 at Deep River, Moncure, N.C.
SR 1527 at I-95, Gold Rock, N.C.

Business Office Address: P.O. Box 190 Knightdale, N.C. 27545 919/266-1100

January 13, 1992

RECEIVED
JAN 1 3 1992

Mr. Tracy E. Davis, E. I. T., Mining Specialist N. C. Dept. EHNR - Land Quality Section P. O. Box 27687 Raleigh, North Carolina 27611-7687

LAND QUALITY SECTION

SUBJECT: Plan For Remedial Action for Triangle Quarry

Rock Slide of January 7, 1992

Dear Tracy:

Enclosed is our proposed Plan For Remedial Action to clean up the rock slide which occurred at our Triangle Quarry on January 7, 1992. In the Plan we have provided a narrative statement and site plan to indicate how we intend to access the site and remove the slide material from the channel of Crabtree Creek and the slope leading to the creek as we discussed during your site visit on January 8, 1992.

During the clean-up process we will report to you or John Holley on the progress of the operation at whatever interval you request. We will also report to you the completion of the clean-up operation. As we conclude our technical review of the blast data we will submit a report of our findings as to the cause of the slide as well as what we intend to do to insure we do not have a reoccurrence of the problem.

We initiated the preparation of the access road with hand clearing of the roadway immediately after your visit on January 8th. By the end of the day on Saturday January 11th the roadway accessing the slide site was nearing completion including construction of the downslope silt fence and placement of the stone fill for the road surface.

Letter to Mr. Tracy E. Davis January 13, 1992 Page 2

If you have any questions or comments on the Plan For Remedial Action please call me at 266-1100.

Sincerely,

Wake Stone Corporation

David F. Yee

DFL/ Enclosure

cc: Mr. John Holley

Raleigh Regional Office



PLAN FOR REMEDIAL ACTION - TRIANGLE QUARRY ROCKASS TO SECTION

1. Entering from the north through the permanent buffer establish a temporary road to the toe of the slide area.

This can be done with a minimal amount of disturbance to the buffer on the northwest side of the pit. The road will be kept to as narrow a width as possible to accomplish the clean-up task. The road will be established in the following sequence of construction steps:

- a) Existing vegetation will be removed by cutting at ground level with a chain saw. Maximum effort will be made to minimize the number of large trees removed.
- b) A temporary silt fence will be constructed between the roadway and the top of the bank of Crabtree Creek. This will take place concurrently with the hand clearing of the roadway to insure adequate sedimentation and erosion control structures are in place prior to disturbance of the ground surface by heavy equipment (see design specifications on attached sheet).
- C) Upon completion of hand clearing of the roadway and construction of the silt fence, the roadway will be established to the toe of the slide area using stone fill on top of the existing grade. The intent is to provide a roadway suitable to handle the heavy equipment used in the clean-up work, yet be removable once the clean-up task is completed (see Reclamation Plan for impacted slope and roadway).

2. Remove all slide material from the slope and channel of Crabtree Creek.

The first step of the removal process will be to dig out the shot material remaining on the incline ramp (color coded orange on the accompanying site plan). This will lessen the loading on the slide material on the slope to the creek while minimizing the possibility of additional material sliding into the creek channel. Once the shot material remaining on the incline ramp is removed, the slide material on the slope and in the creek channel will be removed using a crane and track-mounted excavator to remove the material and load it into rented articulated off-road haul trucks.



TRIANGLE QUARRY ROCK SLIDE RECLAMATION/REVEGETATION PLAN FOR SLOPE AND ACCESS ROPE ITY SECTION

Once the slide material is removed from the slope and creek channel, the impacted areas will be reclaimed and restored to as near pre-slide conditions as is feasible. Attempts will be made to replace lost vegetation with like species in addition to providing a grass and small grain cover crop. The reclamation/re-vegetation will proceed in the following sequence of steps:

a) Upon completion of removal of the slide material the creek bank and slope will be graded and shaped to as near pre-slide lines and grades as is feasible.

b) Upon final egress from the slide removal site the stone access road will be removed and the roadway graded to as near pre-slide lines and grades as is feasible.

c) Upon completion of site grading, revegetation will be initiated according to the following revegetation plan.

d) Once a grass and small grain cover crop is established, an attempt will be made to secure and plant shrub and tree species lost during the slide event and clean-up activities. Emphasis will be placed on securing and planting laurel, holly, oak, beech, and pine seedlings in an effort to establish native vegetation on the affected areas.

Revegetation Plan

Initial revegetation of the affected areas will be with a mixture of fescue and rye grain. Soil amendments will be applied at the time of seeding. Upon completion of the seeding operation, the area will mulched with small grain straw.


Application Rates


Ky 31 tall fescue at 100 lbs. per acre Rye grain (as nurse crop) at 50 lbs. per acre Pelletized lime at 2000 lbs. per acre 10-10-10 fertilizer at 1000 lbs. per acre. Small grain straw mulch at approximately 150 bales per acre.

Removal of Silt Fencing

Once the affected areas are stablilzed by vegetation, the silt fence installed between the access roadway and the bank of Crabtree Creek will be removed.

RECEIVED





SEDIMENT FENCE
TYPICAL CONSTRUCTION DETAIL



RECEIVED

JAN 1 5 1992

State of North Carolina Department of Environment, Health, and Natural Charles Raleigh Regional Office

James G. Martin, Governor William W. Cobey, Jr., Secretary Edmond John Maguire Regional Manager

DIVISION OF LAND RESOURCES

January 13, 1992

NOTICE OF MINE PERMIT DEFICIENCIES

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Wake Stone Corp. P.O. Box 190 Knightdale, NC 27545 ATTN: Mr. John R. Bratton

RE: Triangle (Cary) Quarry (92-10)
Wake County

Dear Mr. Bratton:

This is to document our observations during the inspection on January 8, 1992 following your report of the rock slide into Crabtree Creek at the west end of the pit.

As you know, it was determined that deficiencies exist with respect to one or more of the conditions contained in your mining permit. The applicable conditions and our observations are as follows:

(3.B. and E.) The undisturbed buffer along Crabtree Creek in the area affected by the rock slide has not been sufficient to prevent deposition of material in the watercourse. The material extended approximately 90% across the width of the main channel.

* **

In order to bring the subject site into compliance, the following corrective actions must be taken:

A plan must be provided for our approval and implemented sufficent to make safe access to the slide area and address removal of the material deposited in the creek and floodway. The plan must incorporate the stone access along the base of the slope and reclamation of the affected areas by vegetation and tree planting as we discussed at the site. Sediment control during installation and removal must also be addressed. Pending our approval of the plan in writing, implementation must begin as soon as possible and must be completed in a timely manner.

If the deficiencies are not corrected in a timely manner, appropriate enforcement action will be initiated by the issuance of an official Notice of Violation. The deadline for submittal of the required plan is February 1, 1992.

In addition to the previously described corrective actions, further blasting along the western buffer along Crabtree Creek must be suspended until a full report is provided. In that the buffer has proven to be inadequate to contain material lost during such a blasting accident, future blasting along this buffer will not be allowed unless evidence can be provided to demonstrate that modifications to the current blasting program can be implemented sufficient to prevent such accidents.

Thank you for your prompt reporting of the blasting accident and your willingness to correct the deficiencies in a timely manner. Based on the excellent work observed in your northern expansion area and your past efforts at this site I am confident that the rock slide will be corrected as soon as possible.

Please do not hesitate to contact Mr. Tracy Davis or me regarding any questions you might have about this matter.

Sincerely,

John L. Holley, Jr., P.E., CPESC

Regional Engineer
Land Quality Section

cc: Tracy Davis
Tim Donnelly

North Carolina Department of Environment, Health, and Natural Resources, Division of Land Resources, Land Quality Section		
TOPICETARY		
MINE INSPECTION REPORT JAN 1 5 1992		
(PERMITTED MINE)		
1. MINE NAME 2. MINING REPORT SECTION 2. MININ		
3. OPERATOR WAKE STENE CAP. 4. COUNTY GONT COUNTY STENE CAP. 4. COUNTY OF THE COUNTY O		
6 Person (s) contacted at site JOHNNY + TED BRATTON, PAVID LEE		
O Date last inspected: 3 / 27/ 40 10 Any mining since last inspection?		
11. Is the mine in compliance with the Operating Conditions of the Permit?		
If no, explain: B. E. S: THE UNDISTURBED BUFFER Aron'S CRABTREE		
CHEKK @ THE WEST END OF THE SITE HAS BINOT		
PROVIDED ADEQUATE PROTECTION IN THAT THE RECENT		
IN CLABIRETE CREEK.		
12. Is the mine in compliance with the Reclamation Conditions of the Permit? X Yes No		
If no, explain:		
13. Did any of the above deficiencies result in offsite damage? Yes No If yes, describe the type		
MATERIALS LOST INTO CRARTICE CREEK BELOW SLICE		
AREA. ROCK FEXTENDS APPROX. 90% ACROSS CREEK, ROW		
14. Corrective measures needed and / or taken: AND INDEMNATED FOR ASSESS TO THE SHOPE ASSESS.		
AND REMOVER OF MATERIAL DEPOSITED IN THE CREEK AND		
FLUODURY, THE PLAN MUST PROPERS PECLAMONION OF		
THE SCOTE TIME TIESES - DUE TO THE TOTAL T		
15. Other recommendations and comments: THAM YOU FOR YOUR PROPERTY OF THE ARCHOENT TO US & YOUR WALLINGWEST		
TO COPERATE. EXPIRATION DATE: 4-1-2001		
16. Is the Annual Reclamation Report + / - map accurate ? Yes No (Explain) Not Reviewed		
10. Is the Allibar resolution respect to the passage of the passag		
17. Follow-up inspection needed? Yes No Proposed date 1/15/92 ±		
1 2		
18. No. of additional pages of Inspection Report		
INSPECTED BY: RHN HOLEY MELLNEY LES TRAY DAYLS DATE: 1 8 192		
Phone No: (919) 57/4700		
White copy to file Yellow copy to operator Pink copy to Mining Specialist		

John Holley RNO-CES	SPEED LETTER DATE 12412
MFSSACE	t deput on both Slade), habe G.
the above references segent.	
La Charles to Consider as now	
FOLD TOK NO. 9	CC: Jim Sunm Hother 10
SIGNED Wilson-Jones - Carboniese - MADE IN U.S.A. 44-903 Triplicate - © Wilson-Jones, 1983	SIGNED.

SENDER: DETACH AND RETAIN YELLOW COPY, SEND WHITE AND PINK COPIES

Wake Stone Corporation

Quarry Phone Numbers: 919/266-9266—Knightdale 919/677-0050—Triangle 919/775-7349—Moncure 919/985-4411—Nash County

Locations:
U.S. 64 East, Raleigh, N.C.
I-40 at Harrison Ave., Cary, N.C.
U.S. 1 at Deep River, Moncure, N.C.
SR 1527 at I-95. Gold Rock, N.C.

Business Office Address: P.O. Box 190 Knightdale, N.C. 27545 919/266-1100

January 20, 1992

RECEIVED

JAN 2 2 1992

Mr. Tracy E. Davis, E. I. T., Mining Specialist N. C. Dept. EHNR - Land Quality Sect. P. O. Box 27687 Raleigh, North Carolina 27611-7687

LAND QUALITY SECTIO

SUBJECT: Wake Stone Corporation Triangle Quarry

Summary of January 7, 1992 Blast and Factors Causing Rock

Slide to Crabtree Creek.

Dear Mr. Davis:

This is a summary of our blast at Triangle Quarry on January 7, 1992 and an explanation for why the rock slide occurred. Also enclosed is a letter to me from Mr. Rufus E. Flinchum who is a technical representative of Explosive Technologies International. Mr. Flinchum's letter reports the findings of his study of the blast data as he was requested by me to do on January 8, 1992.

This blast pattern was typical of several previous shots that had been successfully executed along the same western ridge of our pit. It consisted of fifty holes arranged on an eight feet spacing by eight feet of burden pattern (8'x 8' hole spacing). Refer to the enclosed blast design drawing. The shot had seven rows of holes delayed with non-electric caps wired in a pattern to force the rock to move in a southeast direction.

When the pit foreman designed the shot he saw the necessity to add additional rows of holes to the north end. This is a common occurrence when designing any blast as we not only want to control the shot rock, but we also need to consider what the remaining wall or face will look like for the next shot that will be drilled. In this case, the ridge was narrow so the additional holes were drilled in order to guarantee drill accessibility for the next shot. The extra burden generated by the additional three rows of holes slowed the movement of the stone in the desired direction causing it to impede complete movement to the southeast. When this happened, the force of the blast was directed to the area of least burden, resulting in the blasted material sliding down the slope into Crabtree Creek.

Letter to Mr. Tracy E. Davis January 18, 1992 Page 2 10

A second variable which contributed to the slide was the hardness of the rock in the shot. Normally, the rock on the east and south sides of this ridge is hard, with the rock on the west being deeply weathered. This weathered rock is soft and will react to the impact from the blast much differently than hard rock. It tends to absorb the energy from the blast and does not move as readily as hard rock. With hard rock there is an opposite situation in that it tends to fracture more readily and is therefore more likely to move in the direction desired. This makes it possible to direct the movement of the shot rock by using time delay caps and wiring patterns tailored to the particular shot.

On the previous shots along the western ridge, we were successful in forcing the hard rock to move in a southeast direction, leaving a high ridge of soft rock along the western side that we would excavate with a hydraulic shovel. As you could see from your inspection on January 8th, there was no weathered rock in the muck pile. Instead, the material was all hard. This hard rock reacted to the force of the blast differently than had the previous shots. This factor, combined with the size of the blast as discussed earlier, lead to the material fracturing more than anticipated and moving to the west down the slope and into Crabtree Creek.

In order to safeguard against future recurrence of this situation I would like to propose the following steps to be taken on each subsequent blast:

- 1) Utilize the expertise of an explosives technician to design and load the next shot on this western ridge.
- 2) Lay out remaining shots on the ridge with a maximum of three rows of holes. The ridge continues to widen to the north so drill accessibility improves and will not be a problem as before,
- 3) Change the angle of the south wall (face) so that it is no longer perpendicular to Crabtree Creek but more open to the quarry pit. This will give us more control in directing the shot to move to the southeast into the roadway and pit opening (see Proposed Blast Design Layout drawing for future shots), and

Letter to Mr. Tracy E. Davis January 16, 1992 Page 3 1

> 4) Continue advancing the western roadway to the north by removing the material in two levels. At present the roadway is twelve feet from reaching the intended final grade with a 27' high face existing at present. Upon attaining final grade a 39' high face will remain. It is our intention to advance the cut horizontally carrying a 19' high face until sufficient distance is gained that a second lift can be advanced to the target elevation. In this fashion we will be carrying a constant 19' high face, and then with a second cut, advance on the intended minus 8% grade, sinking to the intended final elevation. By removing the remaining material in two lifts we will have effectively reduced, by as much as half, the amount of material involved in any single blasting event.

In addition to Mr. Flinchum's letter, I am enclosing a copy of our blasting report and a diagram of the blast layout for the January 7, 1992 blast. The blasting report provides technical data on the explosives and detonation agents used in the blast. If I can provide additional information on the blast or answer any question which may arise in your review of this report, please call me at (919) 266-1100.

Sincerely, Theodore D. Bratton

Wake Stone Corporation

Thurdon 1) Broke

TDB/dfl


Enclosures

WAKE STONE CORPORATION

P.O. BOX 190 KNIGHTDALE, N. C. 27545

######################################	Triangle	BLASTIN	G REPORT		
			Date of Blast	./7/1992	
Time of Day: A.M.; 4:22P.M. Weather at Time Blast Fired: Clear XXX ; Low Clouds ; High Clouds Raining ; Wind Out of NW ; Approx. Speed 0-5 Location of Blast in Pit Including Bench Number and location on bench West Side Road					
If Seismograph Used advise where machine was set up and who operated it.					
HILLIAND CONTROL OF THE PROPERTY OF THE PROPER	ТҮРЕ	OF BLAST	CONTROL OF THE PARTY OF THE PAR	and the second s	
	Wall	Leveling	Sinking	Toe	
Vertical	erice contains a silver or contain		45	decided supplied to the supplied of the suppli	
No. Holes Sloped		account the control of	5	,	
Size Holes		100	411		
			34 ' - 38 '		
Depth Holes			4 1	110.10	
Depth Sub-Drilling	***************************************	Contractors of the section	4	**************************************	
Stemming			6-30	***************************************	
Spacing			8x8	***************************************	
Number Rows		· · · · · · · · · · · · · · · · · · ·	7	h444444444 ****************************	
ELECTRIC FIRING: Instantaneo	us Blast ;	Delay Blast	; No. Delay Perio	ods in Blast	
	Series in Blast				
Number holes primed with Regu	lar EB Caps		Total Pounds Explosive	Used	
Number holes primed with No.			Total Pounds Explosive		
Number holes primed with No.	2 (MS50) Caps		Total Pounds Explosive Total Pounds Explosive	Used	
Number holes primed with No. Number holes primed with No.	o (MS100) Caps 4 (MS100) Caps		Total Pounds Explosive	Used	
Number holes primed with No.	5 (MS125) Caps		Total Pounds Explosive	Used	
Number holes primed with No.	6 (MS150) Caps		Total Pounds Explosive	Used	
Number holes primed with No.	7 (MS175) Caps	Actual Mining	Total Pounds Explosive	Used	
Number holes primed with No.	8 (MS200) Caps		Total Pounds Explosive	Used	
Number holes primed with No.	9 (MS250) Caps		Total Pounds Explosive	Used	
Number holes primed with No. 1 Number holes primed with No. 1	u (MS350) Caps 1 (MS350) Capa		Total Pounds Explosive	: Used	
Number holes primed with No. 1. Number holes primed with No. 1.	2 (MS400) Caps		Total Pounds Explosive	Used	
Number holes primed with No. 1	3 (MS450) Caps		Total Pounds Explosive	Used	
Number holes primed with No. 1	4 (MS500) Caps		Total Pounds Explosive	Used	

Total Pounds Explosive Used




34 DELAY TIME IN MILLISECONDS.

WAKE STONE CORP. TRIANGLE QUARRY WESTERN PIT ROAD RAMP

SHOT DESIGN FOR JANUARY 7, 1992 SHOT





WAKE STONE CORP. TRIANGLE QUARRY WESTERN PIT ROAD RAMP

PROPOSED BLAST DESIGN LAYOUT FOR FUTURE SHOTS



P.O. Box 69 Van Wyck, SC 29744 (803) 286-6185

RECEIVED
JAN 2 2 1992

LAND QUALITY SECTIO

January 10, 1992

Mr. Ted Bratton, V.P. Operations Wake Stone Corp. P.O. Box 190 Knightdale, N.C. 27545

Dear Ted,

As per your request, I visited your Triangle Quarry to look at the blast data from the shot on 01/07/92. This was a seven row shot which automatically creates a problem, but after discussions with you and the blasting crew it is very understandable why they felt the need to have the shot with this configuration.

The bench that was blasted was only 48 feet at the widest point and the drill crew felt the need to bring the shot back to an area that would be wide enough to ensure good access for the drills on the next blast. This shot did achieve the goal of having good access, but allowed part of the blasted rock to roll into Crabtree Creek, which runs parallel with bench being blasted.

After observing the material that has been blasted and excavated, prior to this blast, it is easy to see the material was quite different in previous shots. Prior shots had material with very little hard rock in them. The bench was composed of weathered rock, dirt, and punky material. This soft material and punky rock accepts the explosive energy quite different than a mass of hard rock.

Very little or no movement will occur when weathered rock is blasted. This would explain why very little movement has been seen on previous blast. This shot, however, was not the normal soft punky material that had been encountered on all previous blasts. Instead it was a seam of very good hard grey granite. If this material had been soft, as expected, by the powderman, movement would have allowed the blasted material to be retained on the

roadway, even with the seven rows of holes. The remainder of the material appears to be the hard grey granite excavated in the blast on 01/07/92.

I believe we will be able to blast and excavate the remaining material in this roadway and maintain the material on the desired bench by reducing the number of rows in the blast. I suggest keeping the blast to a maximum of three rows. This will allow ample time and area for the blasted material to move in the desired direction. I would also turn the open face on a slight angle away from the creek. This would allow more room for the blasted material to go toward the open pit while reducing the chances for the material to slide or roll into Crabtree Creek. If these procedures are followed properly, I believe we can attain the required access you need and maintain the integrity of the important buffer zone.

If I can be of any further assistance, please let me know.

Sincerely,

Rufus Flinchum

Technical Representative Explosive Technologies Int.

RF/mm

Enclosures

) N N N N	17 18) 34	12 34 34	२० ६) ३५	7 @7 70
	्र इ.प	(S) 34	(D) 34	34	F. Bry C. J.
20 35	(g) 35	K (B)	& & 35	35	
2000 35	\@\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	ر <u>ه</u> 35	35	35	99 199 199 199
8 ७ ४	36	30 30	ک چو عد	& & 34	36 36
20 60 37	% 37	(1) (3) (3)	(II) 37	(g)) 37	37
70 (F) AB	6	े श्रि	\$ \$\$\$\$\$\$	(S) 33	\$ 100 mg

MENTENESTRE STREET, ST

Stem

depth

delay

Shot data:
50 holes 4 nuch diameter
8×8 PAHERN
Side OF Shot Toward CREEK
had 25 FEET burden

NORTH

PROPOSEL FOR FUTURE NEW ROMP Blast: TO NEXT beach CRABTRE CREEK SLOPE Towards CREEK PREVIOUS BlaST TURN FACE ON ANGLE Away From CREEK TO WUNIYEM HIW TTAREE LINES.



RECEIVED
JAN 2 2 1992

State of North Carolina Department of Environment, Health, and Natural Resources Raleigh Regional Office

James G. Martin, Governor William W. Cobey, Jr., Secretary Edmond John Maguire Regional Manager

DIVISION OF LAND RESOURCES

January 21, 1992

Wake Stone Corp. P.O. Box 190 Knightdale, NC 27545 ATTN: Mr. John R. Bratton

RE: Triangle (Cary) Quarry (92-10) Wake County

Dear Mr. Bratton:

This is to acknowledge our receipt of the remedial plan submitted by Mr. David Lee on January 13, 1992 and to document my observations during the inspection on January 15, 1992.

Based on my review and field observations, it has been determined that the remedial plan satisfies the applicable requirements of our January 13, 1992 Notice with the following stipulations:

- (1) The silt fence installation below the emergency access road in the natural drainageway must be monitored and replaced with a suitable stone check dam if necessary to prevent soil loss to Crabtree Creek.
- (2) All mulch must be tacked. Crimping will be acceptable for flat areas. Use of netting over the mulch will be acceptable for the slope as discussed with Ted Bratton at the site. This treatment must extend down through the current water elevation along the toe of the slope. Rip-rap will not be required in this area due to the existing rock visible along the creekbank.

Implementation of this plan as approved in this letter must continue in a timely manner until completion. Please notify this office when the slope has been seeded and mulched so that we may evaluate your progress.

Please be advised that further blasting along the western buffer along Crabtree Creek must continue to be suspended until a full report is provided to our central office and is reviewed.

Thank you for your continued cooperation. Please do not hesitate to contact Mr. Tracy Davis or me regarding any questions you might have about this matter.

Sincerely,

John L. Holley, Jr., P.E., CPESC

Regional Engineer Land Quality Section

cc: Tracy Davis
Tim Donnelly

North Carolina Department of Environment, Health, and Natural Resources. Division of Land Resources, Land Quality Section
Division of Land Resources, Land Quality Section MINE INSPECTION REPORT (PERMITTED MINE) 1. MINE NAME (CARY) TRIANCLE QUARRY 2. MINING PERMIT # AND QUALITY SECTION 3. OPERATOR 3. OPERATOR 4. COUNTY WARE 5. ADDRESS (O. 50X 190 KNIGHTDAVE, NC 27545
(PERMITTED MINE)
1. MINE NAME (CARY) TRIANGLE QUARRY 2. MINING PERMIT # AND QUALITY
3. OPERATOR WAKE STONE CORP. 4. COUNTY WAKE
6. Person (s) contacted at site
9. Date last inspected: 1/0/97 10. Any mining since last inspection? X Yes No
11. Is the mine in compliance with the Operating Conditions of the Permit? Yes No If no, explain:
3. B.E.: THE UNDISTURBED BUFFER ALUNG CHAPTREE
CAPERLO THE WEST END OF THE SITE HAS NOT BEEN COMPLETELY RECEDENCE, WORK IS PROFESSING WELLSHOWENED
AND AN MATTERIAL HAS NOW BEEN REMOVED FROM
THE CHANNEL.
12. Is the mine in compliance with the Reclamation Conditions of the Permit ? Yes No
If no, explain:
13. Did any of the above deficiencies result in offsite damage? Yes No If yes, describe the type
and severity of the damage: VEM SUGHT SOIL LOSS TO CRAFTEE CREEK AT A
RESULT OF CLEAN-UP WORK, SUCH LOSS IS UNAVOIDABLE
AND NOT PROBLEMATIC.
14. Corrective measures needed and / or taken: RENEDIAL RAN RECEIVED 1-13-92
AND IS BEING CARRIED OUT IN A TIMELY MANNER CHANNEL
BANK AND SLOPE PROVE HAVE BEEN SATISFACTORILY DRESSED AND WILL SOON BE PREPARED FOR SEEDING. H-CESS ROAD
FOR MEPARS LOOKS GOODS SILT FENCE BETOW DIMENTORWAY
15. Other recommendations and comments: MULCH W/ NETTING OF STONE POR
MATTING NEEDED ON SLOPE PATTER SEEDING.
16. Is the Annual Reclamation Report + / - map accurate ? Yes No (Explain) Not Reviewed
17. Follow-up inspection needed? Yes No Proposed date 1,24,92 ±
1 21 0-
18. No. of additional pages of Inspection Report 19. Copy of Report sent to operator / (date)
INSPECTED BY: JOHN HOUSY DATE: 15192
Phone No: (919 571-4700
White copy to file Yellow copy to operator Pink copy to Mining Specialist
889

N.C. Department of Environment, Health, and Natural Resources Division of Land Resources, Land Quality Section

Telephone Log Date: 1 122192 Call: Placed
Received Returned 🔣 County: WAXE THANGLE QUALRY 2. Conversation with: DAVID Telephone: () 266-1100 3. Affiliation: 4. Content of conversation: JAN 7 4 1772 LAND QUALITY SECTION DAVIS Filed by:

	SPEED LETTER
TO DATE	FROM DATE 17/5/92
John Holley	(Mun)
John Helley Pro-Las	SPEED LETTER DATE LOS
SUBJECT Who the Cop - Downy (40)	92-10) Wake Courts
FOLD NO. 9 or 10	
MESSAGE I have reviewed the January	from Vale Some Cop and drawn
13, 1992 letter and Blan in demedial	with you and Charles Gardon to
action and declaration / Nevertelian	eppropuetile address fatur
Ilan for the work slide area	blasting in this location of the
autmitted by My David bee of	graner.
Wale Store Cop. It appears to me	- Receptor me Dat a copy
that raid plan are acceptable	of the blasting study & will forward you a way, then we
as written. However before we	forward you a copy then we
respond in writing to Wake Stone	you review and discum. Please
long. I would like to receive	let me prow of you should have
and review the blast report study	any problems with the Remedial action
Wilson-Jorres - Carboniese - MADE IN U.S.A. 44-903 Triplicate - O Wilson-Jones, 1989	Ilan. Sichtouler for your assistance
WHISORIJOHES • Carbonless • MADE IN U.S.A. 44-903 Triplicate • O WilsonJones, 1989	0 0

SENDER: DETACH AND RETAIN YELLOW COPY, SEND WHITE AND PINK COPIES

MEMO

JUN 0 4 1992

DATE: 2-12-92

FILE-TRIANGLE QUARRY (9270) SUBJECT: BRIEF PRIVICENT
OF FINISHED SLAPET

I VISITED THE SITE AND DESERVED THE WASTER CREEK CASTILLIAM IN THE AREA ARONG CHARTER CREEK THAT WAS ATTERED BY THE BLASING ACCIDENT. THE SURE IS IN GOOD CONDITION AND SCHERAL STATES SHOTS HAVE BEEN SUCCESSFULLY PLUE IN ACCORPANIE WITH THE APPRIATED MODIFICATIONS. WE WILL CONTINUE TO PREMIOR MODIFICATIONS. WE WILL CONTINUE TO PREMIOR FRANCE STEEL SAFER DAMES AREA

From:



North Carolina Department of Environment, Health, and Natural Resources



State of North Carolina Department of Environment, Health, and Natural Resources Division of Land Resources

James G. Martin, Governor William W. Cobey, Jr., Secretary

Charles H. Gardner Director

February 5, 1992

Mr. John Bratton Wake Stone Corporation P. O. Box 190 Knightdale, North Carolina 27545

RE: Triangle Quarry Mining Permit No. 92-10

Wake County

Dear Mr. Bratton:

This office has completed its review of your company's January 20, 1992 report regarding the blast and corresponding rock slide that occurred on January 7, 1992 along the western pit boundary adjacent to Crabtree Creek. This office concurs with the findings of the report and the safeguards that are proposed therein to prevent future incidents from occurring at this site. Therefore, your mining permit has been modified to incorporate the report, in its entirety, and require compliance with the corrective actions proposed. I would like to draw your particular attention to Operating Conditions Nos. 3 and 10 of the enclosed permit.

Please review the modified permit and advise this office should you have any questions concerning this matter. I would like to extend the Department's appreciation to you and your company for the timely and professional manner in which you investigated and rectified this situation at your mine site.

Sincerely,

Tracy (E./ Davis, E.I.T. Mining Specialist

Land Quality Section

TED/se

Enclosures

cc: Mr. John Holley, P.E.