# Little Beaver Creek (DMS #221) Stream and Wetland Restoration Site

2015 Annual Monitoring Report (MY5)

**Wake County** 

Division of Mitigation Services Project No. 221
Design Firm: Earthtech
Construction Completed: February 2007
Construction Repairs Completed: May 2013



### Prepared for:



## NCDENR/ Division of Mitigation Services (DMS)

1652 Mail Service Center

Raleigh, NC 27699-1652

### Prepared by:



The Catena Group

1000 Corporate Drive, Suite 101

Hillsborough, NC 27278

and



Rummel, Klepper & Kahl Consulting Engineers 900 Ridgefield Dr Raleigh, NC 27609

### **TABLE OF CONTENTS**

1.0	EXECUTIVE SUMMARY	-
1.1	Goals and Objectives	-
1.2	Vegetative Assessment	
1.3	Stream Assessment	)
1.4	Wetland Assessments	;
1.5	Annual Monitoring Summary	;
2.0	METHODOLOGY4	Ļ
3.0	REFERENCES	Ļ
	APPENDICES	
Appen	ndix A5	į
Appen	ndix B	)
Appen	ndix C	}
Appen	ndix D	)
Appen	ndix E	į
Appen	ndix F	7

#### 1.0 EXECUTIVE SUMMARY

The Little Beaver Creek stream and wetland restoration project consists of 3,712 linear feet of stream restoration, 1,513 linear feet of stream preservation, and 2.4 acres of wetland restoration. Little Beaver Creek is located in Wake County southwest of Apex, North Carolina at the end of Olive Farm Road (SR 1178). Construction began in July 2005; due to Hurricane Katrina in August 2005 and contractual issues there was a delay in the completion of the construction until 2006, which prevented planting until the dormant 2006/2007. Tropical storm Alberto caused damage in June 2006, which required repair. Collectively, this caused planting to be delayed until February 2007 the official end of construction.

Between January 14 and May 6, 2013, spot repairs were made to approximately 400 linear feet of channel, riffles were installed, existing structures were adjusted through boulder removal, unwanted/invasive plants were treated, pine and sweet gum saplings were thinned within the outer 40 feet of the 50 foot stream buffer, and supplemental planting was conducted. For specific details about the repairs, please see the 2013 Supplemental Monitoring Report (Appendix F).

#### 1.1 Goals and Objectives

The goals and objectives for the Little Beaver Creek (DMS #221) stream and wetland restoration are:

#### Goals

- Improve water quality and reduce erosion
- Improve aquatic habitat
- Re-establish connectivity of the stream with its floodplain
- Restore characteristic natural plant communities/wildlife habitat and hydrologic regime to disturbed wetlands

### **Objectives**

- Implementation of stream stabilization techniques
- Improve aquatic habitat through the implementation of natural structures such as rootwads, rock vanes, woody debris, and the planting of a riparian buffer
- Provide aesthetic value, wildlife habitat, and bank stability through the creation or enhancement of a riparian zone with plantings
- Provide a stable stream channel that neither aggrades or degrades while maintaining its dimension, pattern, and profile, with the capacity to transport water and sediments

### 1.2 Vegetative Assessment

The vegetation on site is intact with evidence of woody species recruitment throughout the conservation easement. As a result of the stream repairs in 2013, the conservation easement received supplemental plantings in March 2013. Re-grading only occurred in plots 8 and 10. A cut stump herbicidal treatment method was employed on the Loblolly Pine and Sweetgum saplings throughout the conservation easement starting 10 feet from the channel edge, altering plots 5, 7, 11, and 14 in MY4. All plots received supplemental plantings in MY4. VP 2 remained relatively intact and undisturbed with the exception of the supplemental plantings. Please see the 2013 Supplemental Monitoring Report for more details.

Eight vegetation monitoring plots (VP 2, 5, 7, 8, 9, 10, 11, and 14) were surveyed for Monitoring Year 5 (MY5). Of these eight plots, 87.5% of the plots (VP 5, 7, 8, 9, 10, 11, and 14) are meeting the vegetation

success criteria; VP 2 is the only plot not meeting the success criteria, however with the additional volunteers the stem density far exceeded the planted stem success criterion. The average stems per acre for all eight monitoring plots, including natural and planted stems, is 12,581 (2,185-30,140) stems per acre; the average planted stems per acre for all eight monitoring plots, excluding live stakes, is 551 (121-1,244) stems per acre. Success criterion for planted woody species is 288 stems/acre after MY4. A mortality rate of ten percent will be allowed after MY5 (260 stems/acre). Currently the vegetation criteria are being met throughout the site with 577 planted stems/acre. Although sweetgum and pine were thinned in 2013, the seed bank within the valley for these species is apparently very large and many stems are growing on the site. However, this site is more diverse than earlier in its history and exhibits between 9 and 19 species per plot with 34 species noted site wide.

Similar to MY-04, multiflora rose (*Rosa multiflora*) is the only notable vegetation problem areas for MY5; several stems were observed throughout the conservation easement and are identified in the Current Conditions Plan View. Other Invasive exotics within the conservation easement include Tall Fescue (*Schedonurus arundinaceus*), Gill over the Ground (*Glechoma hederacea*), Japanese Honeysuckle (*Lonicera japonica*), and Japanese Stiltgrass (*Microstegium vimineum*). Although these species have been given different ranks of severity, the functionality of the project is not expected to be impaired significantly. It is likely that all of these species were present in and adjacent to the conservation easement previous to construction. For additional information relating to vegetation, see Appendix C.

#### 1.3 Stream Assessment

The project is divided into three separate reaches (Reach 1, Reach 2, and Reach 3) for the purposes of the design. Reach 1 and 2 consist of Priority 1 and 2 stream restoration. Tributaries were restored using Priority 1 restoration. Due to bedrock constraints, the restoration of Reach 3 below the road crossing was abandoned. This portion of Reach 3 (i.e. Reach 3b) is preserved within the permanent conservation easement.

The majority of Little Beaver Creek, Reach 1 (station 10+00-19+90), Reach 2 (19+90 to 23+50), and Reach 3 (23+50 to 38+00) are in stable condition with some isolated bank scour areas, three structure with some piping, and beaver activity. The portion of Little Beaver Creek below station 38+00 to the culvert at the end of the restored reach is stable and well vegetated. Two tributaries located on the project site tie into the north bank of Little Beaver Creek. Tributary 1 is exhibiting some very minor bank scour but remains in stable condition. Tributary 2 is very stable with vegetation that has established throughout the channel bed and banks.

Repairs to Little Beaver Creek were conducted between January 14 and May 6 2014. These repairs consisted of the following:

A description of stream bank and channel repairs is listed as follows by station.

- 1. Constructed riffle installed Station 23+86 to 24+12
- 2. Bank repair right 24+30 hole filled and matted
- 3. Bank repair right 24+52 to 24+78 graded and some rock added to toe after soil lost in a large rain event after construction.
- 4. Bank graded and brush toe added to right bank station 26+42 to27+08. One boulder taken off structures at 27+55 and two boulders from structure at 27+75 used in the repair.
- 5. Bank re-graded 27+60 to 27+75 and two boulders removed from upstream structure.
- 6. Graded bank 27+95 to 28+18 right and removal of former beaver dam remnant debris.
- 7. Brush toe from 28+45 to 28+75 to repair large channel blow out bank left.

Little Beaver Creek Stream and Wetland Restoration NCDMS Project number: 221

- 8. Class B stone added below structure at 28+80
- 9. Bank Rt. graded from 29+25 to 29+41 and 5 boulders added to the toe for reinforcement from structure at 29+45 where the boulders were removed.
- 10. Graded bank left from 29+58 to 29+72 and matted.
- 11. Constructed riffle added 29+92 to 30+26 and right bank graded and matted.
- 12. Graded bank left and matted 30+86 to 31+06
- 13. Graded bank right and rock toe added 31+33 to 31+53. Four boulders used removed from structure at 31+60.
- 14. Graded bank right with rock toe added 31+92 to 32+12. Three boulders used from structure at 32+00.
- 15. Proposed riffle at station 32+80 to 33+05 not constructed. The stream in this area had filled in with stone and had formed a riffle the banks in the area were stable. No work in this area was needed.
- 16. One boulder was removed from the structure at 33+60
- 17. Constructed riffle added 37+85 to 38+18. Broad and deep blow out area. Banks reconstructed and one large boulder and two small added from structure at 37+30 due to the riffle due the extreme depth of the void.
- 18. Graded bank at 39+02 smaller riprap used for the rock at toe due to the presence of saprolite in the area.

In accordance with the Supplemental Monitoring Report, the 2014 MY4 and 2015 MY5 surveys were conducted utilizing the newly established survey control points.

#### 1.4 Wetland Assessments

Eight RDS groundwater gauges (2, 3, 4, 5, 6, 7, 8, & 9) are located within the conservation easement. Hydrologic restoration is considered successful if groundwater levels are within 12 inches of the surface at 12.5% of the growing season or for a hydroperiod comparable to the reference wetland. If the period of saturation is between 5-12.5% of the growing season, the presence of hydrophytic vegetation and hydric soils will be taken into consideration. By recommendation from EEP, these gauges were installed on June 25, 2008, to replace an older set of gauges. In January of 2010, four gauges (2, 3, 4, and 5) were relocated upstream to more appropriate locations. After completion of the MY3 report in spring 2010, monitoring was delayed due to various repair considerations. MY4 did not begin until the fall of 2013, near the end of the growing season. Five of the eight groundwater gauges (Gauge 3, 4, 5, 7, and 8) failed between the MY3 and MY4 monitoring (2009 to 2013) and were repaired during MY4 but resulted in some data gaps during this period. Wetland hydrology success criteria is met when the water table elevation is within 12 inches of the soil surface for at least 12.5 percent of the growing season. In MY5, only four gauges are meeting hydrological requirements: 3, 6, 7, and 8 (Table 13). A bankfull event was observed and recorded on January 12, 2014 (Table 12).

### 1.5 Annual Monitoring Summary

Summary information/data related to the occurrences of items such as beaver or encroachment, and statistics related to performance of various project and monitoring elements, can be found in the tables and figures in the report appendices. Narrative background and supporting information formerly found in these reports can be found in the mitigation plan and restoration plan documents available on EEPs website. All raw data supporting the tables and figures in the appendices is available from EEP upon request.

### 2.0 METHODOLOGY

Methodologies follow the current EEP monitoring report template (Version 1.5 - 06/08/12). Level II of the CVS –EEP Protocol for Recording Vegetation (Lee et al. 2008) was used for vegetation data collection. Photos were taken with a digital camera. A Trimble Geo XT handheld unit with sub-meter accuracy was used to collect monitoring feature locations and vegetation problem areas. Precipitation data were obtained from the State Climate Office of North Carolina (http://www.nc-climate.ncsu.edu/services/request.php) (State Climate Office of North Carolina 2012). Flora of the Carolinas, Virginia, Georgia, and Surrounding Areas was the taxonomic standard used throughout vegetation data collection (Weakley 2012). Vegetation monitoring data was collected on August 21, 2014.

Stream monitoring was completed by utilizing total station survey along with Rosgen Level II techniques to determine stream stability and performance. The annual cross-sectional survey included points surveyed at breaks in slope, including bankfull, inner berm, edge of water, ground shot and thalweg, if the features were present. Longitudinal profile survey was conducted for the entire length of the restored channel for all stream reaches. Measurements included thalweg, water surface, and bankfull. Existing onsite benchmarks were used for survey control. The previous monitoring surveys did not utilize survey control and were manually adjusted. The 2015 MY5 monitoring survey was conducted utilizing survey control, but due to the manual adjustment of the previous data, the 2014 MY4 and 2015 MY5 data did not spatially match the previous monitoring efforts. The 2015 total station survey was supplemented with additional traditional level survey for cross sections T1, T2, 8, and portions of the longitudinal profile to maintain data integrity. Although the 2015 MY5 raw survey is coordinately correct, the data was adjusted to match the previous monitoring data. The adjustment was completed to maintain spatial congruency and does not affect the integrity or accuracy of the survey data. Photo monitoring was conducted by walking each stream reach and taking photos at each pre-determined photo point location using a digital camera. Stream monitoring was conducted on March 9 and 10, 2014.

#### 3.0 REFERENCES

Lee, Michael T., R. K. Peet, S. D. Roberts, and T. R. Wentworth. 2008. CVS-EEP Protocol for Recording Vegetation, Version 4.2 (http://cvs.bio.unc.edu/methods.htm)


Rosgen, D. 1996. Applied River Morphology. Wildland Hydrology, Pagosa Springs, CO.

State Climate Office of North Carolina. 2015. Apex Station Precipitation Data (Jan 1, 2010 – May 5, 2015; Daily Totals). (http://www.nc-climate.ncsu.edu/services/request.php

Weakley, A.S. 2012. Flora of the Carolinas, Virginia, Georgia, and Surrounding Areas. Working draft of November 2012. University of North Carolina Herbarium, North Carolina, Botanical Garden, University of North Carolina. 1015pp.

## Appendix A

**Project Vicinity Map and Background Tables** 





Stream and Wetland Restoration Site Site Location Map

Wake County, North Carolina

EEP Project No. 221

USGS 7.5-Minute Topographic Quadrangle Map (Newhill, NC)

Division of Mitigation Services

Date:

May 2015

Table 1 Project Components Mitigation Credits

		_	]	Little I	Beaver (	Creek /P	roject	No. 221				
					Mitig	ation Cr	edits					
			Rip	arian		Riparian				rogen	Phosph	orus
	Str			tland	_	etland	Bu	ıffer	Nutrie	nt Offset	Nutrient	Offse
Type	R	RE	R	RE	R	RE						
Totals	3712	191	2.4	-	-	-		-		-	-	
	_		1		<u>Projec</u>	t Compo						
Project			Exis	_				ation–or		Restoration		
Component -or		ioning/		tage/	Approa	. ,		toration	] ]	Footage or	Miti	
- <b>Reach ID</b> Little Beaver	Loc	cation	Acr	eage	PII,	etc)	Equ	iivalent		Acreage	K	atio
Creek/Reach 1	SEE	CCPV	2.4 a	acres	N/	'A	2.4	4 acres		2.4 acres	1	1:1
Little Beaver Creek/Reach 1 & 2	SEE	CCPV	TE	BD	N/	A	ŕ	ГВО		TBD	T	BD
Little Beaver Creek/Reach 1 & 2	SEE	CCPV	TE	3D	N/	Ά	,	ГВО		TBD	T	BD
Little Beaver Creek/Reach 1 & 2	19+ 9	+00 to 91/19+ 1 to 3+00	230	00 lf	P1 &	: PII	2300 lf			2300 lf		1:1
Little Beaver Creek/Reach 3a	33-	+00 to )+32	732	2 lf	P	П	7	'32 lf		732 lf		1:1
Little Beaver Creek/Reach 3b		+00 to 3+13	151	131f	Preser	vation	Pres	ervation	F	Preservation		0:1
Tributary 1	13	+00 to 8+81	38	1 lf	P	II	3	881 lf		381 lf	1	1:1
Tributary 2	12	+00 to 2+06	200	6 lf	P	II	2	206 lf		206 lf		1:1
Tributary 3		+00 to )+93	93	lf	P			93		93 lf	1	1:1
					Compor	ient Sun	ımation					
Restoration Level	Stı	ream (lir feet)	near	Rip	arian We			Wet	iparian land res)	Buffer (square feet)	e Up	land cres)
				Rive	rine	Non-Ri	verine					
Restoration		3712		2.	4							
Enhancement												
Enhancement I	_											
Enhancement II	L											
Creation		1012						-				
Preservation HQPreservation	,	1913										
11Q1 1 csci vauloi	<u> </u>		<u> </u>		RM	P Eleme	nte	<u> </u>				
Element	L	ocation		Purpos	e/Functio		<u> </u>		Not	es		
BMP Elements: BR = Bioretention	on Cell:	SF = San	d Filter:	SW = S	tormwater	· Wetland:	WDP =	Wet Deter	ntion Pon	d: DDP = D	ry Detention	Pon

FS = Filter Strip; S = Grassed Swale; LS = Level Spreader; NI = Natural Infiltration Area; FB = Forested Buffer

Table 2. Project Activity and Reporting History

Little Beaver Creek Stream	and Wetland Restoration	Site-Project No. 221
Activity or Reporting	Data Collection Complete	Actual Completion Date
Restoration Plan	2003	March 2003
Final Design-90%	2005	2005
Primary Grading Complete	2005	November 2005
Temporary S&E mix applied to entire project area	2005	2005
Permanent seed mix applied to entire project area	2005	2005
Tropical Storm Alberto		June 2006
Storm Repairs		Fall 2006
Containerized, B&B, and livestake planting		February 2007
Mitigation Plan/As-built (Year 0		Morphology – Fall 2006;
Monitoring-baseline)	March 2006	Vegetation - February 2007
Year 1 Monitoring	Fall 2007	November 2007
Year 2 Monitoring	Fall 2008	December 2008
Year 3 Monitoring	May 2010	May 2010
Site Repairs	NA	May 2013
Supplemental Replanting	NA	May 2013
Year 4 Monitoring (Vegetation)	October 2013	October 2013
Year 4 Monitoring (Geomorphology Surveys)	April 2014	April 2014
Year 5 Monitoring (Vegetation)	October 2014	October 2014
Year 5 Monitoring (Geomorphology Surveys)	April 2015	April 2015

**Table 3. Project Contact Table** 

Little Beave	er Creek Stream and Wetland Restoration Site-Project No. 221
Designer POC	Earth Tech 701 Corporate Center Drive Suite 475 Raleigh, NC 27607 Bill Jenkins PE (919) 854-6200
Construction Contractor	Envirocon, Inc. 651 Corporate Circle Suite 114 Golden, CO 80401 Verne Musser (303) 215-0187
Planting Contractor POC	Seal Brothers 131 West Cleve St. Mt. Airy, NC 27030 Brain Seal (336) 786- 2263
Seeding Contractor POC	Seal Brothers 131 West Cleve St. Mt. Airy, NC 27030 Brain Seal (336) 786- 2263
Seed Mix Sources	Evergreen Seeding 4792 Rawls Church Rd. Fuquay-Varina, NC 27526
Nursury Stock Suppliers	Mellow March Farm 1312 Woody Store Rd. Siler City, NC 27344 (919) 742- 1200
Monitoring Performers	The Catena Group 410-B Millstone Drive Hillsborough, NC 27278
Stream Monitoring	Rummel, Klepper & Kahl Consulting Engineers 900 Ridgefield Dr Raleigh, NC 27609
Vegetation Monitoring	The Catena Group, 1000 Corporate Drive, Suite 101, Hillsborough, NC 27278
Wetland Monitoring	The Catena Group, 1000 Corporate Drive, Suite 101, Hillsborough, NC 27278


**Table 4. Project Baseline Information Attributes** 

Little Beaver Creek Stream an		Restoration S	Site-Project I	No. 221	
	ject Inform				
County	Wake	;			
Project Area (acres)	52 ac				
Project Coordinates	35.69	5, -78.922			
Project Waters	shed Summa	ary Informat	ion		
Physiographic Province	Piedn	nont			
River Basin					
USGS Hydrologic Unit 8-Digit 03030002	USGS	S Hydrologic	Unit 14-Digit	0303000	2060160
NCDWQ Sub-basin for Project	03060	)5		1	
Project Drainage Area (acres)	Little	Beaver Cree	k: 1.1 sq mi		
Project Drainage Area % of Impervious Area	< 5%				
CGIA Land Use Classification	311, 3	323, 414, 422,	441		
Reach St	ummary Inf	formation			
Parameters		Reach 1	Reach 2	Reach 3a	Reach 3b
Length of reach (linear feet)		991	1309	732	1490
,		Low	Low	Low	Low
		Slope	Slope	Slope	Slope
V 11 C1 10 11		Alluvial	Alluvial	Alluvial	Alluvial
Valley Classification		Valley	Valley	Valley	Valley
Drainage area (acres)		391	527	658	695
NCDWQ Stream Identification Score		NA WS-IV	NA WS-IV	NA WS-IV	NA WG IV
NCDWQ Water Quality Classification		NSW	WS-IV NSW	WS-IV NSW	WS-IV NSW
Morphological Description (Stream Type)		C4	C4	C4	C4
Evolutionary Trend		NA	NA	NA	NA
Evolutionary Trend		Wehadkee	Wehadkee	Wehadkee	Wehadkee
Underlying Mapped Soils		silt loam	silt loam	silt loam	silt loam
, , , , , , , , , , , , , , , , , , ,		Poorly	Poorly	Poorly	Poorly
Drainage Class		drained	drained	drained	drained
Soil Hydric Status		A	A	A	A
Slope		0.6%	0.5%	0.5%	0.5%
FEMA Classification		None	Zone AE	Zone AE	Zone AE
		Alluvial	Alluvial	Alluvial	Alluvial
Native Vegetation Community		Forests	Forests	Forests	Forests
Percent Composition of Exotic Vegetation		<10%	<10%	<10%	<10%

	Wetland S	ummary Iı	nformation			
Parameters			Wetlands 1	Wetland 2	Wetland 3	
Size of Wetland (acres)			2.4			
Wetland Type (non-riparian, riparia	an riverine, or no	n-				
riverine)			Riparian			
Mapped Soil Series			Wehadkee silt loam			
Drainage Class			Poorly drained			
Soil Hydric Status			Yes			
			Precipitation, flooding, water			
Source of Hydrology			table			
Hydrologic Impairment		Low Water table				
Native Vegetation Community			Headwater Wetland Type			
Percent Composition of Exotic Veg	getation		0	0	0	
	Regulat	ory Consid	erations			
Regulation	Applicable?	Resolved	1? S	upporting Docum	nents	
Waters of the US - Section 404	Yes	NA	S	ee Permit Applica	ation	
Waters of the US - Section 401	Yes	NA		ee Permit Applica		
Endangered Species Act	No	NA		NA		
Historic Preservation Act	No	NA		NA		
CZMA/CAMA	No	NA		NA		
FEMA Floodplain Compliance	Yes	NA	See Mitigation Plan			
Essential Fisheries Habitat	No	NA		NA		

Appendix B.

**Visual Assessment Data** 





Division of Mitigation Services

## Little Beaver Creek Stream and Wetland Restoration

MY-05 Current Conditions Plan View

Wake County, North Carolina





Figure Key






Division of Mitigation Services


## Little Beaver Creek Stream and Wetland Restoration

MY-05 Current Conditions Plan View

Wake County, North Carolina











Division of Mitigation Services

## Little Beaver Creek Stream and Wetland Restoration

MY-05 Current Conditions Plan View

Wake County, North Carolina









Division of Mitigation Services

## Little Beaver Creek Stream and Wetland Restoration

MY-05 Current Conditions Plan View

Wake County, North Carolina








Division of Mitigation Services

## Little Beaver Creek Stream and Wetland Restoration

MY-05 Current Conditions Plan View

Wake County, North Carolina








Division of Mitigation Services


## Little Beaver Creek Stream and Wetland Restoration

MY-05 Current Conditions Plan View

Wake County, North Carolina

0	30	60 Feet	
EEP Projec	t No.:	Date:	-
221		May 2015	






Division of Mitigation Services

## Little Beaver Creek Stream and Wetland Restoration

MY-05 Current Conditions Plan View

Wake County, North Carolina






Table 5. Visual Stream Morphological Stability Assessment Reach  ${\bf ID-1, 2, 3A}$ 

Assessed Length – 3032 LF

Major Channel Category	Channel Sub-Category	Metric	Number Stable, Performing as Intended	Total Number in As-built	Number of Unstable Segments	Amount of Unstable Footage	% Performing as Intended	Number with Stabilizing Woody Vegetation	Footage with Stabilizing Woody Vegetation	Adjusted % for Stabilizing Woody Vegetation
1. Bed	1. Vertical Stability	1. Sediment Deposition			0	0	100%			
	(Riffle and Run Units)	2. Degradation			0	0	100%			
	2. Riffle Condition	1. Texture/Substrate	58	64			91%			
	3. Meander Pool	1. Depth	52	64			81%			
	Condition	2. Length	55	64	_		86%			
	4. Thalweg Condition	Thalweg at upstream of meander bend	51	64			80%			
		2. Thalweg centering at downstream of meander	52	64			81%			
2. Bank	1. Scoured/Eroding	Bank lacking vegetative cover from poor growth and/or scour and erosion			5	55	98%			98%
	2. Undercut	Banks undercut/overhanging			0	0	100%			100%
	3. Mass Wasting	Bank slumping, caving, or collapse			1	17	99%			99%
				Totals	5	72	97%			97%
3. Engineered	1. Overall Integrity	Structures physically intact with no dislodged boulders or logs	22	25			88%			
Structures	2. Grade Control	Grade Control exhibiting maintenance of grade across the sill	34	34			100%			
	2a. Piping	Structures Lacking any substantial flow underneath sills or arms	22	25			88%			
	3. Bank Protection	Bank erosion within the structures extent of influence does not exceed 15%	N/A	N/A			N/A			
	4. Habitat	Pool forming structures maintaining – Max Pool Depth: Mean Bankfull Depth Ratio ≥ 1.6 Rootwads/logs providing some cover at base flow.	N/A	N/A			N/A			

Little Beaver Creek Stream and Wetland Restoration NCDMS Project number: 221

The Catena Group 20

Year 5 Monitoring Report Year 5 of 5 June 2015

Table 5. Visual Stream Morphological Stability Assessment Reach ID – Tributary 1 Assessed Length – 381 LF

Major Channel Category	Channel Sub-Category	Metric	Number Stable, Performing as Intended	Total Number in As-built	Number of Unstable Segments	Amount of Unstable Footage	% Performing as Intended	Number with Stabilizing Woody Vegetation	Footage with Stabilizing Woody Vegetation	Adjusted % for Stabilizing Woody Vegetation
1. Bed	1. Vertical Stability	1. Sediment Deposition			0	0	100%			
	(Riffle and Run Units)	2. Degradation			0	0	100%			
	2. Riffle Condition	1. Texture/Substrate	9	11			81%			
	3. Meander Pool	1. Depth	9	11			81%			
	Condition	2. Length	10	11			90%			
	4. Thalweg Condition	1. Thalweg at upstream of meander bend	11	11			100%			
		2. Thalweg centering at downstream of meander	11	11			100%			
2. Bank	1. Scoured/Eroding	Bank lacking vegetative cover from poor growth and/or scour and erosion			0	0	100%			100%
	2. Undercut	Banks undercut/overhanging			0	0	100%			100%
	3. Mass Wasting	Bank slumping, caving, or collapse			0	0	100%			100%
				Totals	0	0	100%			100%
3. Engineered Structures	1. Overall Integrity	Structures physically intact with no dislodged boulders or logs	2	2			100%			
	2. Grade Control	Grade Control exhibiting maintenance of grade across the sill	2	2			100%			
	2a. Piping	Structures Lacking any substantial flow underneath sills or arms	N/A	N/A			N/A			
	3. Bank Protection	Bank erosion within the structures extent of influence does not exceed 15%	N/A	N/A			N/A			
	4. Habitat	Pool forming structures maintaining – Max Pool Depth: Mean Bankfull Depth Ratio ≥ 1.6 Rootwads/logs providing some cover at base flow.	N/A	N/A			N/A			

Little Beaver Creek Stream and Wetland Restoration

NCDMS Project number: 221

Year 5 Monitoring Report Year 5 of 5 June 2015

**Table 6. Vegetation Condition Assessment** 

Planted Acreage – 5 acres

Vegetation Category	Definitions	Mapping Threshold	CCPV Depiction	Number of Polygons	Combined Acreage	% of Planted Acreage
1. Bare Areas	Very Limited Cover of both woody and herbaceous material	0.01ac	NA	NA	NA	NA
2. Low Stem Density Areas	Woody stem densities clearly below target levels based on MY3, 4, or 5 stem count criteria	0.01ac	NA	NA	NA	NA
3. Areas of Poor Growth Rates or Vigor	Areas with woody stems of a size class that are obviously small given the monitoring year	0.01ac	NA	NA	NA	NA

Easement Acreage – 52 acres

Vegetation Category	Definitions	Mapping Threshold	CCPV Depiction	Number of Polygons	Combined Acreage	% of Planted Acreage
4. Invasive Areas of Concern	Areas or points (if too small to render as polygons on map scale)	1000 sq ft	See CCPV Legend	NA	NA	NA
2. Easement Encroachment Areas	Areas or points (if too small to render as polygons on map scale)	NA	See CCPV Legend	NA	NA	NA

### **Table 6. Vegetation Condition Assessment Table**

Planted Acreage – 5 acres

Vegetation Category	Definitions	Mapping Threshold	CCPV Depiction	Number of Polygons	Combined Acreage	% of Planted Acreage
1. Multiflora Rose	Very Limited Cover of both woody and herbaceous material	0.01 ac	Pink Circle with dot	39 points	NA	NA
			TOTAL			

## Stream Station Photos (all photos recorded on April 16, 2014)



1 – Reach 1, 2, 3 - Cross Section 1 – Looking upstream



4 - Reach 1, 2, 3 - Cross Section 4 – Looking upstream



3 - Reach 1, 2, 3 - Cross Section 3 – Looking upstream



2 - Reach 1, 2, 3.- Cross Section 2 – Looking upstream



5 - Reach 1, 2, 3 - Cross Section 5 – Looking downstream



6 - Reach 1, 2, 3 - Cross Section 6 – Looking upstream

Little Beaver Creek Stream and Wetland Restoration NCDMS Project number: 221 The Catena Group



7 - Reach 1, 2, 3 - Cross Section 7 – Looking downstream



8 – Reach 1, 2, 3 - Cross Section 8 – Looking upstream



9 – Tributary 1 – Cross Section 1 - Looking upstream



10 - Tributary 1 - Cross Section 2 - Looking upstream

## **Vegetation Monitoring Plot Photos**

### MY-04 (2013) Monitoring Plots



Vegetation Plot 2



Vegetation Plot 5



Vegetation Plot 7

### MY05 (2014) Monitoring Plots



Vegetation Plot 2



Vegetation Plot 5



Vegetation Plot 7

## MY-04 (2013) Monitoring Plots

## MY-05 (2014) Monitoring Plots



Vegetation Plot 8



Vegetation Plot 8





Vegetation Plot 9



Vegetation Plot10



Vegetation Plot 10

## MY-04 (2013) Monitoring Plots

Vegetation Plot 11



Vegetation Plot 14

## MY-05 (2014) Monitoring Plots



Vegetation Plot 11



Vegetation Plot 14

Appendix C.

**Vegetation Plot Data** 

Table 7. Vegetation Plot Success by Project Asset Type

Plot #	Riparian Buffer Stems <sup>1</sup>	Stream/ Wetland Stems <sup>2</sup>	Live Stakes	Invasives	Volunteers <sup>3</sup>	Total⁴	Unknown Growth Form
0002	n/a	3	0	0	156	159	0
0005	n/a	30	0	0	715	745	0
0007	n/a	20	0	0	332	353	1
0008	n/a	9	0	0	105	114	0
0009	n/a	12	0	0	542	554	0
0010	n/a	13	0	0	88	101	0
0011	n/a	11	0	0	396	407	0
0014	n/a	11	0	0	42	54	0

	Wetland/Strea	m Vegetation Totals		R	iparian Buffer	Vegetation Tota	nls
			(per acr	re)	1	T	
Plot #	Stream/ Wetland Stems <sup>2</sup>	Volunteers <sup>3</sup>	Total⁴	Success Criteria Met?		Riparian Buffer Stems <sup>1</sup>	Success Criteria Met?
0002	121	28935	6435	No		n/a	~
0005	1214	13436	30149	Yes		n/a	~
0007	809	4249	14285	Yes		n/a	~
0008	364	21934	4613	Yes		n/a	~
0009	486	3561	22420	Yes		n/a	~
0010	526	16026	4087	Yes		n/a	~
0011	445	1740	16471	Yes		n/a	~
0014	445	12024	2185	Yes		n/a	~
Project Avg	551	28935	12581	Yes		n/a	~

Stem Class Characteristics

<sup>1</sup>Buffer Stems Native planted hardwood trees. Does NOT include shrubs. No pines. No vines.

<sup>2</sup>Stream/ Wetland Stems Native planted woody stems. Includes shrubs, does NOT include live stakes. No vines

<sup>3</sup>Volunteers Native woody stems. Not planted. No vines.

<sup>4</sup>Total Planted + volunteer native woody stems. Includes live stakes. Excl. exotics. Excl. vines.

29

### **Color for Density**

Exceeds requirements by 10%

Exceeds requirements, but by less than 10%

Fails to meet requirements, by less than 10%

Fails to meet requirements by more than 10%

 Table 8. CVS Stem Count Total and Planted with/without Livestakes by Plot and Species

DMS Project Code 221. Project Name: Little Beaver Creek

											Curr	ent P	lot Da	ata (M	1Y6 2	2014)															Annu	ıal Me	eans	,			,		,
				21-01-		E <b>221-</b> 0			221-01	1-	<b>E</b> 2	221-0	1-	E2	221-0	1-		221-0			221-0			1-01-													i		
				0002		0005	; 		0007			0008			0009			0010			0011		00	)14	N	1Y6 (2	014)	M	Y5 (20	013)	M	Y4 (20	)13)	MY	Y3 (200)	9)	MY	Y2 (20	08)
Scientific Name	Common Name	Species Type	PnoLS	P-all T	PnoLS	P-all	T	PnoLS	P-all	T	PnoLS	P-all	Т	PnoLS	P-all	T	PnoLS	P-all	T	PnoLS	P-all	T	PnoLS	P-all	PnoLS	P-all	L	PnoLS	P-all	Т	PnoLS	P-all	T	PnoLS	P-all	L	PnoLS	P-all	T
Acer rubrum	Red maple	Tree		19			25			2			1			5						42		$\epsilon$			100			2		<u> </u>	<u> </u>						15
Acer rubrum var. rubrum	Red maple	Tree																	5								5						33			72			235
Alnus serrulata	Hazel alder	Shrub			1	1	1													1	1	1			2	2	2	3	3	3	5	5	5				1		
Amelanchier arborea	Common serviceberry	Tree												1	1	1									1	1	1	1	1	1		1					i		
Aronia arbutifolia	Red chokeberry	Shrub			3	3	3																		3	3	3	3	3	3	3	3	3	3	3	3	3	3	3
Aronia prunifolia								1	1	1															1	1	1	1	1	1		1					1		
Baccharis halimifolia	Eastern baccharis	Shrub		1															1			1					3			3		1	5			7	1		2
Betula nigra	River birch	Tree	1	1 1				1	1	1	1	1	1				2	2	2				3	3 3	8	8	8	9	9	9	10	10	11			6			6
Carpinus caroliniana	American hornbeam	Tree														1											1												94
Carpinus caroliniana var. caroliniana	Coastal american hornbeam	Tree																					1	1 1	1	1	1	1	1	1	1	1	3	1	1	3	1	1	1
Carya	Hickory	Tree															1	1	1						1	1	1	1	1	1	1	1	1			1	1		
Cornus florida	Flowering dogwood	Tree																														1		3	3	3	2	2	2
Corylus americana	American hazelnut	Shrub		1	1	1	1	1	1	1				1	1	1							1	1 1	4	4	5	4	4	4	1	1	1						
Diospyros virginiana	Common persimmon	Tree								1	2	2	2	2	2	9	1	1	1				1	1 1	6	6	14	5	5	5	6	6	7						4
Fraxinus pennsylvanica	Green ash	Tree			20	20	21	2	2	4				1	1	1	2	2	3	5	5	8	2	2 2	32	32	39	32	32	36	33	33	33	35	35	38	33	33	35
Hamamelis virginiana	American witchhazel	Tree																										1	1	1		1					5	5	5
Hamamelis virginiana var. virginiana	American witchhazel	Tree						4	4	4				3	3	3	3	3	3	1	1	1			11	11	11	11	11	11	11	11	11	10	10	10	6	6	6
Hypericum	St. Johnswort	Shrub																														ļ	<u> </u>			1			9
Ilex decidua var. decidua	Possum-haw	shrub									1	1	1												1	1	1	3	3	3	6	6	6						
Ilex opaca	American holly	Tree														1											1					<u> </u>	<u> </u>						
Juniperus virginiana var.	Eastern redcedar	Trace																														1 1					i		
virginiana	Eastern redcedar	Tree					67			27						46						31					194			144			1			176			347
Liquidambar styraciflua	Sweetgum	Tree		63			0			27 0			99			46 0			56			0		17			5			9		<b>─</b> ─ <sup>!</sup>	753	4		4			6
Liriodendron tulipifera	Tuliptree	Tree					1			1						9						1					12			1		—— <sup> </sup>	L'	$\perp$		1			2
Liriodendron tulipifera var. tulipifera	Tulip-tree, Yellow Poplar, Whitewood	Tree																										1	1	1	5	5	5			6	i		11
Morella cerifera	Wax myrtle	shrub						8	8	12															8	8	12	8	8	9	8	8	8	11	11	11	10	10	11
Nyssa sylvatica	Blackgum	Tree														35											35					1				1			2
Pinus taeda	Loblolly pine	Tree		70			13			38						14			15			3		19			172			219		<del></del>	199			350	i T		160
Planera	Planertree	Tree																																		3	i		
Platanus occidentalis	American sycamore	Tree					1			1			3			1											6			2							1		1
Platanus occidentalis var. occidentalis	Sycamore, Plane-tree	Tree	1	1 1				2	2	2	2	2	2		1	1									6	6	6	6	6	6	6	6	6	1	1	11			9
Prunus serotina	Black cherry	Tree																												1		- <del></del>							2
Prunus serotina var. serotina	Black cherry	Tree																																		2			
	ĺ																															<del></del>							

Little Beaver Creek Stream and Wetland Restoration

NCDMS Project number: 221

The Catena Group

30

Year 5 Monitoring Report Year 5 of 5

June 2015

Quercus	Oak	Tree	I					3			1					I	- 1	-			Ī		3				1	1	2			1	1	33
Quercus alba	White oak	Tree															1	1	1		1	1	1	1	1	1	1	1	1	1	1	1 1	1	1
Quercus lyrata	Overcup oak	Tree	1 1	1 3	3	3				1	1	1	1								5	5	6	5	5	6	5	5	5	8	8 8	8 6	6	6
Quercus nigra	Water oak	Tree											3			9			3				15			7			10		44	4		28
Quercus phellos	Willow oak	Tree					1 1	8	1	1 2			2	1	1	1	1	1	2	2 2 2	6	6	17	6	6	7	7	7	9	1	1 2	2 2	2	4
Rhus	Sumac	shrub						1															1											
Rhus copallinum var. copallinum	Flameleaf sumac	shrub																													3	3		3
Rosa multiflora	Multiflora rose	Exotic																																1
Salix nigra	Black willow	Tree																											2					
Sambucus canadensis	Common elderberry	Shrub																																1
Ulmus	Elm	Tree																													22	2		10
Ulmus alata	Winged elm	Tree																								1								
Ulmus rubra	Slippery elm	Tree		2 1	. 1	5		1					4	1	1	2	1	1	33	1	3	3	48	3	3	3	3	3	16		۷	4		2
Unknown		Shrub or Tree																									3	3	3					
Vaccinium	Blueberry	Shrub						1															1											
Viburnum	Viburnum	shrub					1 1	1													1	1	1	1	1	1	1	1	1					
Viburnum nudum	Possumhaw	Shrub		1	1	1			2	2 2	2	2	2	2	2	2	1	1	1	1 1 1	9	9	9	9	9	9	9	9	9	1	1	1 1	1	1
		Stem count		5 9 30	30	74 5	21 21	35 3	9	9 11 9 4		12	55 4	13	13	10 1	11	11	40 7	11 11 54	11 0	11 0	248 7	11 5	11 5	180 7	12 6	12 6	114 9	75 7	5 237	7 8 70	70	418 1
		size (ares)	1		1		1			1		1			1			1		1		8			8			8			8		8	
		size (ACRES)	0.02		0.02	2	0.02		0.	02		0.02	2		0.02			0.02		0.02		0.20	•		0.20	•		0.20	•	0	.20		0.20	
		Species count	3 3	9 7	7	12	9 9	19	6	6 10	8	8	19	8	8	13	7	7	13	7 7 11	20	20	34	22	22	31	21	21	28	11 1	1 27	7 11	11	33
			121 121 6435	12.1	1214	30149	850	14285	364	304 4613	486	486	22420	526	526	4087	445	445	16471	445 445 2185	556	556	12581	582	582	9141	637	637	5812	379	12029	354	354	21152
		Stems per ACRE																																

### **Color for Density**

Exceeds requirements by 10%

Exceeds requirements, but by less than 10%

Fails to meet requirements, by less than 10%

Fails to meet requirements by more than 10%

Appendix D.

**Stream Survey Data** 

## Project Name Little Beaver Creek, MY5 Watershold Cross Section 1 Drainings Area NA Bate Mar-15 Cree Boars, Ward

### **Cross Sections with Annual Overlays**

BF Width

W/D Ratio EIR Bank Height Ratio Steam Type

Flood Pront Elv. Flood Pront Width Max Depth Mean Depth Photo of Cross-Section 1 - Riffle -Looking Upstream

Picture Tuken March 31, 2015


18.8

294.5

7.4

N/M	Boggs, 1	Ward_	-		_	-		_	-		_			-	
	Built Survey		20	2008			2009			2010			2014		2015
As-E	Built Survey	•	20	08 MYI	2000	20	69 MY2	202.000	20	10 MY3	995.55	20	H4 MY4	20	015 MY5
Station	Div	Notes	Station		Nates	Station		Notes	States		Nates	Station	Elv Notes	Station	Eb Notes
			0.00	256.22		9.00	296.27	LPIN	0.00		XIIP		296.33	9.00	296.00
			5.00	295.63		11.04	295,47		7.24	295.73		18.55	294.85	29.60	294.50
			10.00	295.75		20.11	294.83		17.43	294.82		50.00	294.66	53.40	294.60
			14.00	295.13		31.79	294.84		35.70	294.85		57.20	292.99	36.14	291.97
			17,00	294.91		41.33	294.71		49.41	294.70		59.30	292.10	72.64	291.64
			20.00	294.83	2 1	47.43	294.65		51.44	293,66		73.00	291.99	76.67	290.49
			22.50	294.51	- 1	92.75	294.10		58.05	292.03		76.50	299.86	33.94	289.58
			24.00	294.71	- 1	56.75	292.71		66.60	291.83	20,000	77,30	2999.20	28.55	289.21
			29.00	294.74	- 1	60.95	292.00	757	72.45	291,86	BKP	81.18	298.99	81.42	288.90
			35.00	294.73		79.56	291.82	BKF	77,64	290.21	10.100	62.61	299.69	33.19	290.48
			40.00	294.56	8 1	73.54	291.09		77.81	288.96		86.80	291.25	86.43	292.04
			49.50	294.69	96	76.60	299.15	Tot L	80.17	288.59	TW	87.00	291.80	100.89	291.90
			54.00	293.96	8 1	77.63	288.93		82.30	288.87		99.50	291.50	111.32	292.79
			57,00	292.42		79.11	288.77	TW	83.23	290.10		115.20	292.80	167.50	292.80
			58.50	292.04		80.98	288.95		86.73	291.72	BKZ	567.50	292.80		
			65,00	291.90		81.84	289.10		99.57	291.37	7.0				
			70.00	291.93	Simo.	82.52	290.33		109.31	292.67				1	
			13.30	291.90	BKF	83.73	299.51	Actorios	122.29	292.90					
			76-30	290.55	3000	84.94	299.89		148.91	292.70					
			77.20	289.96	83 H	86.67	291.65	BKF	167.52	292,72	X LRP				
			78.00	289.62	8 1	91.51	201.41								
			78.20	289.18	lov	101.45	291.36								
			79.20	288.67	22	107.37	292.20								
			80.00	288.81		111.16	292.53								
			81.00	288.59	Ob	117.06	292.83				- 1				
			\$3.90	288.44	TW	131.38	292.79								
			83.00	288.64	1/2010	142.99	292.91				- 1				
			83.10	289.97		195.43	292.93								
			67.70	701 70	DEE	167.76	292.80	B PRINT						1	





Project Name Little Beaver Crock, MYS
Washed
Cross Name 2
Passings tree NA
Name Mar-15

Photo of Cross-Section 2 - Pool -Looking Upstream

Picture Taken March 31, 2015

Summary Data

124 2.6 0.8

36.1

4.4

BF Area BF Width Flood Prone Elv.


W/D Ratio

Flood Prone Width Max Depth Mean Depth

Bunk Height Ratio Stream Type

					_			$\overline{}$						$\overline{}$	
As-Built As-Built		X	20	2008 08 MYI		20	2009 09 MY2			2010 10 MY3			2014 14 MY4	21	2015 015 MY5
Station	Eb	Nes	Station	Div	Notes .	Station		Nates	Station	Div	Notes	Station	Elv Notes	Station	Dr Notes
0.00	291.21	RPIN2	1.09	291.18	X2	-5.43	291.41	1.5	-3.68	291.68	X21.P	0.00	291.00	9.00	291.00
1.30	291.08	9	14.60	290.47	X2	-1.41	290.92		1.01	291.03	Jane Branch	11.06	290.44	44.72	289.90
18.20	290.91	20	35.30	290.06	X2	5.39	290,43		8.94	290.89	9	18.74	290.12	53.99	287,97
32.22	290.42	8	50.17	289.04	X3	16.54	290.39		24.89	290.21	77	47.02	289.48	68.71	287.64
44,98	290.36	(i)	56.52	288.32	X2	27.09	290.19		31.38	290.02	8	48.80	288.63	36.33	286.25
49.49	289.57	8	62.63	287.79	X2BKF	36.76	289.91		45.67	289.85	8	67.31	287.63	71.27	286.05
52.54	288.73	22	70.62	286.60	X2EOW	45.94	289.80		53.11	288.56	Ű I	69.05	286.79	24.70	285.89
59.60	288.06	8	72.48	285.58	X21W	50.49	288.80		55.88	287.61	II.	72.91	286.58	75.12	285.50
67.81	287.05	8	73.53	285.93	X2	55.R3	287.51		58.50	288.10	HKF	74.20	286.16	25.70	283.89
72.53	286.76	3	25.79	286.04	XZTW	57.40	287.92		63.27	287.65	15000	74.95	286.29	27.25	287.35
73.26	286.73	LEW	76.62	286.56	X2EOW	60.40	287.88	BKF3.	69.04	287.72	100	75.95	286.72	12.46	288.31
74.96	286.62		81.88	288.47	X2BKF	64.38	287.24		70.61	286.49	8	77.04	287.51	93.29	288.89
75.34	286.40	8	92.90	288.74	N2	68.73	287.63		72.48	286.13	1	86.27	288.63	199.60	290.20
76.39	286.34	8	96.70	299.67	X2	76.72	286.25	TOES	74.06	285.96	TW	91.70	289.03	120.48	289.70
77.04	286.45	8	103.32	289.90	X2	73.21	285.64	TW	75.99	286.36	1	98.55	290.00	136.00	290.40
77.25	255.73	0	108.64	290.05	X2	75.22	285.87		78.15	287.69	ii	122.60	289.80		
27.23	256.89	66	118.77	289.67	3.2	26.71	286.29	10E R	81.65	288.54	BKF	136.00	290.40		
29,28	287.88	En son	128.76	289.99	X2	77.83	287.42	50,590	85.67	288.94	No.				
82.83	288.67	BKJ	136.62	290.36	X2RPIN	80.81	288.23		89.09	289.17	ñ				
91.59	288.88	gnies				43.53	288.87	TIKPER	92.10	288.92	-10				
94,00	289.39	0				\$6.56	289,14		97.87	290.01	60				
96.74	290.22	33				93.19	288.99		104.92	290.11	32				
109.15	290.33	0				97.55	289.98		123.94	289.73	16				
124.33	289.80	8				165.23	290.09		136.86	290.32	X289				
135.39	290.48	8				118.77	289.64								
136.86	290.68	6				136.62	296.36	827							





Project Name Little Beaver Crock, MY5 Watershod Cross Section 3 Drainage Area NA Date Mar-15

Photo of Cross-Section 3 - Riffle -Looking Upstream

Picture Taken March 31, 2015

Summary Data lankfull Elv.

BF Width

Max Depth

Mean Depth

Bank Height Ratio Stream Type

W/D Ratio

Flood Prone Elv. Flood Prone Width 16.3

286


50.9

26.6

0.6

		****			_												_
As-Built			20	2008 08 MYI		20	2009 09 MY2			2010 10 MY3			2014 14 MY4		1000	2015 115 MY5	
Station	Els.	Names	Station	Dr.	Notes	Station	Dr	Nates	Station	Dr	Notes	Nation .	th	Neter-	Station.	100 N	whet
0.00	288.44	LPINS	0.04	288,44	X31.	0.00	288.44	82	0.60	288.44	X3LF	0.00	288.26		0.00	288.51	
0.55	288.40	500000	26.60	287.91	X53	17.50	287.93	55.9	29.16	288.27	povens	14.69	281,97		48.00	287.49	
14,19	288.30	6	50.26	287.39	X53	34.63	287.56	- 1	36.88	287.46	8	22.01	287,91		55.64	284.45	
74.61	287.58	8	57.46	284.15	X53	44.52	287.66	- 1	47.43	287.47	8	28.30	287.87		66.28	284.03	
49,17	287.38	8	66.40	284.43	X53	48.45	287.29	- 1	37.25	284,32	8	35.37	387.28		67.92	283.30	
53.76	285.66	8	70.36	282.82	XS3BKF	57.10	284.54		64.79	284.25	BKF	40.67	287.08		69.42	283.05	
57.99	284.14	0.0	71.88	282.65	33E0W	64.33	284.34	BKF	68.97	283.53	50	44.32	287.79		72.55	282.61	
600.86	283.96	Ø.,	72.75	282.01	XSTW	68.70	283.71	727	71.45	262.81		49.14	287.10		73.73	282.72	
65.21	284.02	HEF	24.54	282.24	X83	72.44	282.68	TOUL	72.74	262.12	X	52.83	285.61		76.53	283.87	
68.45	283.14		56.51	282.43	SHOW	23.24	282.23	2000	23.69	281.91	TW	56.02	284.38		80.49	284.08	
71.36	282.41	66	77.86	283.23	XS3BKF	74.01	281.95	TW	74.68	282.09		60.70	284.01		92.36	284.55	
71.83	282,37	LEW	81.70	284.22	XS3	75.66	282:10		75.79	283.12	똤	63,47	284.23		112,48	287,38	
72.49	282.28	3	92.96	284.43	883	76.30	282.70	TOER	78.39	283.56	3	67.49	293,68		134.55	288.00	
73.79	282.14	8	108.81	287.28	383	78.40	283.40		82.24	284.45	DEF	68.68	283.20				
75.36	282.17	Š	135.88	288.01	351	\$1.19	28431	2007	93.50	284.57	镁	69.79	282.82		1		
76.15	282.37	HEW				\$5.97	284.31		197.80	287.00		70.83	282.19		1		
77,44	282.78	Statement				94.40	284.48	- 1	122.63	287,74	10	71.63	281,88		1		
81,73	284.25	8				105.56	286.81	- 1	148.82	287.30	Bayes	73.61	282.01		1		
88.14	284.16	8				115.27	287.30		166.50	287.19	XMP	75.20	282.32		1		
94.49	284.47	8				133.36	286.90					76.79	283,20		1		
100.34	285.77	0				153.15	286.25	- 1				77.53	293,49		1		
108,79	287.29	0				105.06	287.19	307				79.12	283.95		1		
125.76	287.82	8										82.27	284.23		1		
146.55	287.31	0.						- 1				87.47	284.20		1		
165.22	287.08	8										93.61	294,50				
166,39	287.18	RPINS						- 1				.100.47	286.16				
		CC:00/176						- 1				112:10	297.32				
								- 1				136.17	287.46				





Project Name Little Beaver Creek, MY5 Watershed Cross Section 4

Drainage AreaNA Date Mar-15 Photo of Cross-Section 4 - Pool -Looking Upstream

Picture Taken March 31, 2015

Summary Data Bankfull Elv. 2 BF Area

BF Width


Flood Prone Elv. Flood Prone Width Max Depth Mean Depth W/D Ratio

Bank Height Ratio Stream Type 30.6

286.7

As-Built As-Built		8	20	2008 08 MYI		20	2009 09 MY2			2010 10 MY3			2014 14 MY4	20	2015 015 MYS
Station	13s	Non.	Station	Dr	Notes	Steller	Elv.	Nates	Station	Div	Notes	Station	Elv. Neter	Stelles	Ele No
0.00	285.74	RPIN4	438	285.33	X54	0.00	285.72	1.8	0.00	285.66	X41.P	0.00	283.60	0.00	285.55
1.65	285.52	0.000	11.69	285.75	X54	9.32	285.50	50.0	3.41	285.37	(Content	25.85	286.20	10.00	2905.86
13,94	285.79	8	26.39	256.01	X54	22.94	286.36		16.39	285.92	6	12.10	285.00	:23.86	290.18
26.12	286.28	8	36,19	284.10	X54	29.27	285.78		21.68	285.91	12	78.50	294.10	30.21	285.14
31.29	285.20	(i)	48.17	283.55	XS4BKF	34.09	284,46		26.06	286.23	10	47.50	284.03	40.64	284.05
36.68	283.91	8	50.00	281.89	(\$4E0%)	37,89	284.01		31.50	285.18	90	49.61	283.00	47.29	283.99
47.48	283.66	2	52.31	280.83	XS4TW	43.16	284.17	100.000	35.72	284.12	W	50.53	281.38	48.92	283.02
49.14	282.86	S.,,,,,,,	54.91	281.55	XS4TW	47.07	284.18	BIKE	45.34	284,39	HKF	52.32	280.62	49.02	282.05
50.99	281.92	LEW	57.97	281.63	34E09/	48.47	283.44	(1-3)	48.44	285.53	(P. (S) 2)	55.49	281.68	49.90	281.23
51.77	288.93		63.56	283.40	X54BKF	50.26	281.96	TOUL	49.47	282.95	8	57.65	281.76	54.43	280.85
52.91	280.83	8	75.15	283.84	X84	51.28	281,21	00/0000	59.28	281.68	8	58.20	292.04	55.64	281.84
53,97	281.00	8 1	81.12	285.47	X54	52.30	283,11	TW	51.72	281.49	No.	58.71	282.84	62.76	282.90
55.36	281.43	6	101.11	285.17	334	54.21	281.27		53.49	281.17	TH	61.54	382.76	67.24	283.68
56.77	281.63					56.92	281.62		55.54	281.21		65.12	293.60	73.71	284.00
58.02	281.94	BEW				58.34	282.02	TOTAL	56.33	281.77	į.	73,78	283.71	79.93	293.52
59.70	282.46	8				58.79	282.49		59.73	282.65	0	78.45	284.95	101.29	285.43
63.41	283.39	BKF				39.87	282.75		61.44	282.92	<b>3</b>	84.13	285.46	135.10	284.76
71.34	283.79	00000				61.26	282.90	6000	64.72	283.54	ē	105.50	289.25	000000	
76.63	284.41	8 1				63.34	283.40	BASE	69.12	283.78	9	135.10	284.75		
81.67	285.49	8				67.06	283.72		73.00	281.78	TIKP				
95.84	285.41	3				73.71	283.92		29.41	285.06	3				
115.21	284.77	6				25.81	284.25		82.05	285.61	))				
133.15	284.69	2				71.58	284.96		92.78	285.57	3				
134.77	284.77	LPINE				\$1.63	285.48		109.32	285.13	20				
						\$6.29	285.66		124.61	284,79	Vincer.				
						163.94	285.33		135.09	284.72	X4.82°				
						123.27	284.92				2000			1	





Project Name Little Beaver Creek, MY5 Watershed Cross Section 5

Cross Section 5
Drainage AreaNA
Date Mar-15

Photo of Cross-Section 5 - Riffle -Looking Downstream

Picture Taken March 31, 2015

Summary Data

BF Area

BF Width Flood Prone Elv.

Flood Prone Width Max Depth Mean Depth W/D Ratio


Stream Type

281.5

34.8

As-Built As-Built		3	26	2008 08 MYI		20	2009 09 MY2			2010 10 MY3			2014 14 MY4	E	20	2015 015 MY5
Station	f3s	Nees	Station	Dr	Notes	Station	Dr.	Nation	Station	Div	Notes	Station .	th	Neter	Station	Els Not
0.99	281.56	LPINS	9.76	282.76	355	9.00	281,44	1.5	0.00	281.43	X51.P	0.00	281.40		9.00	281.50
0.33	281.48	galosay	18.55	282.16	X53	4.10	281.45	200	1.60	281.59	Jane Cal	6.00	292.00		7,80	282.87
3.33	281.45		43.37	281.94	X53	10.87	282.83		4.41	281.69	00	10.00	282.90		21.60	282.02
9,33	282.86	8	53.09	281.67	X85	19.52	281.9E		8.21	282.98	8	21.50	281.95		35.43	281.86
19.12	281.88	8	70.01	279.87	XS50KF	35.77	283,67		16.13	282.61	33	37.75	281.80		47.05	282.41
37.50	281.49	8	70.93	279.21	355	44.29	282.19		18.27	282.16	8	44.40	282.29		60.95	281.37
45.76	282.62	8	72.22	277.64	355	52.89	281.67		36.12	281.71	11	55.60	281.50		69.16	281.30
54.98	281.45	Same.	74.65	278.22	X53	61.74	281.50	BKF	43.91	282.31	12	68.02	281.26		72.21	278.05
66.19	281.20	BEF	77.75	279.00	35000	64.15	280.99	(0.000)	52.85	281.70	10	19.08	280,38		75.86	277.13
69.21	280.41	No.	82.77	281.47	KSSBKF	67.25	280,77		63.32	281.61	3/	79.42	279.08		75.68	278.37
71,77	279.29	LEW	100.07	281.42	XS5	69.23	279.96		67.09	281.32	DKF	13.38	211.76		76.98	279.27
72.47	279.11	BEW	115.41	283.56	X85	79.18	279.67		69.27	280.68	6	77.50	277.59		11.31	280.48
73.33	278.74		135.85	283.79	355	78.75	278.03	TOE L	79.63	278.23		77.27	278.63		12.97	281.15
74.78	279.16	8				73.75	277.88		73.38	277.78	Š	77.95	279.83		95.43	281.09
76.72	279.17	BEW				75.46	277.66	TW	74.75	277.90	1.80	80.12	280.40		102.97	282.15
77.61	279:29	Popular				77.48	278.22	2000	77.56	278.07	90	83,05	281.24		120.66	283.72
81.94	280.33					37,61	278.35		28.61	279.83	16	95.20	281.50		137.50	284.00
83.60	281.35	200				78.32	239.56	03,000	80.90	280.38	Harma.	118.50	283.60		CHOILES.	
94.31	281.27	0				79.80	279.82		84.20	281.50	DKF	137.90	283.90			
103,70	282.52	8				81.46	280.55		96.10	281.68	1					
114.69	283.52	8				\$3.50	281.43	TOCH	98:13	281.69	9%					
128.07	283.75	O .				91.87	281.47		107.88	282.92						
137.36	283.82	10.15.254				101.20	281.88		.117.43	285.65	100					
137.67	283.81	LPINA	2.			110.84	283.19		129.61	283.86						
						122.73	283.63		137.91	283.93	X5 RP					
						139.67	283.79				- 919 III					
						136.98	283.94	2.5.4								
						137.81	283.92	RP							1	

ne tuken munen 31, 2013.		



Project Name Little Beaver Crock, MYS Watershod Cross Section 6 Drainage Arca NA Bate Man 15

Photo of Cross-Section 6 - Riffle -Looking Upstream

Pict			


Summary Data

Bankfull Elv. BF Area BF Width Flood Prone Elv. Flood Prone Width Max Depth Wen Depth W/D Ratio

Stream Type

As-Built As-Built	5 TO 10 TO 1		26	2008 08 MYI		20	2009 09 MY2			2010 10 MY3			2014 14 MY4		26	2015 05 MY	5
Station .	£3x	Name .	Station	Die	Notes	Station	Elv	Netes	Station	Dr	Notes	Station	Dr. No	***	Stellon	Div	Notes
0.00	281.84	RPINE	13.28	282.02	X6	0.00	281.73	1.9	9.00	281.76	X61.P	0.00	281.75		1.28	281.67	
18.75	281.79	o o	33.81	281.88	X6	12.51	282.05	200	1.62	282.00	Secretary	20.00	282.00	- 1	25.76	281,69	
26.19	281.54	8 1	55.54	280.60	X6	36.06	281.59		21.24	282.97	n	56.60	281.20	- 1	32.06	280.84	
43.89	281.23	8	65.11	278.96	XSHKP	48.28	281.20		39.11	281:69	0. III	72.30	278.50	- 1	39.77	278.62	
56.64	280,74	6	77.75	278.46	X6	58.49	280.72		53.78	281.11	7. 11	81.00	278.28	- 1	81.82	278.36	
62.25	279.67	5	83.53	276.31	X6	64.05	279.71	- 1	59.38	280.66	8 11	82.96	277.70	- 1	83.78	277.10	
68.18	278.59	8	85.26	276.12	X6TW	67.61	278.80		71.27	278.53	CU	85.89	277.29	- 1	67.68	276.63	
77.93	278.17	8	88.15	276.20	X6	80.05	278,25	BKF	29.17	278.28	BKF	87.14	276.59	- 1	88.92	276.63	
81.90	277.32	8	89.95	276.65	XAECOR!	83.66	277,22	3(=55)	81.69	277.79	(A)00000	90.85	276.47	- 1	91.39	276.83	
84.15	276.50	8	94.86	278.31	X6	85.37	277.17	- 1	84.59	277.27	9 III	93.16	276.72	- 1	96.19	277.36	
85.21	276.31	LEW	110.84	278.84	X6	\$6.43	276.57	TOIL	85.73	277.33	9 1	93,98	277.38	- 1	105.89	278.43	
86.12	376.27	2	129.71	289.32	X6	89.13	276.46	TW	86.41	276,67	a	96.85	278.05	- 1	118.82	279.10	
88.17	276.14	8	125.50	289.42	X6	91.70	276.57	TOT: 8	87.95	276.60	TW	101.55	278.28	- 1	193.61	281.32	
89.02	276.23	8	138.13	279.87	36	94.01	277.07		90.45	276.66	V 11	113.37	278.55	- 1	177.05	281.90	
90.55	276.27	8	152.54	281.29	X6	101.28	278.63	BEF	91.87	276.89	Ø 11	142.30	280.18	- 1	190.00	281.90	
91.48	276.32	9	189.33	281.72	XeRPIN	115.97	278.81		92.40	276,99	() II	162.40	281.50	- 1			
92.36	276.47	Same of			1.00.00	134.98	279.45		99.67	277.14	Your !	190.00	281.80	- 1			
97.87	277.89	1007				153.02	281.31		100.42	278.56	HEF			- 1			
106.30	278.30	80 mass				172.91	281.79		107.66	278.53	grades.			- 1			
121.49	278.48	8 1				186.18	281.93		111.57	278.65	16 H			- 1			
138.98	278.96	8 I				189.98	281.85	9.0	117.49	278.95	10 III			- 1			
156.76	281.09	3							128.91	279.48	66			- 1			
172.73	281.57	33							141.96	280.00	7. III			- 1			
188.65	281.69	8							154.92	281.32	9			- 1			
189.32	281.74	8							173.80	281.85	90 III			- 1			
202.09	281.83	9							188.24	281.93	lkedel			- 1			
									190.03	281.83	X6.RP			- 1			





Project Name Little Beaver Crock, MY5 Watershot

Boggs, Ward

Watershed Cross Section 7 Drainage AreaNA Date Mar-15

185.11

190.41

289.46

286.53

Photo of Cross-Section 7 - Pool -Looking Upstream

Picture Taken March 31, 2015

Summary Data

40.6

21.9

282.8 190.8

1.9 11.8 8.7


														- 1		Summary D
As-Buil	Survey	9		2008			2009			2010			2014		2015	Bankfall Elv.
As-Buil	Survey	9	20	08 MYI		29	09 MY2		29	10 MY3		20	14 MY4		OLS MYS	DF Area
Station	Ele	Name .	Station.	10v	Notes .	Notice	Div	Name	Station	Dr	Notes	Station	Elv Note	Station	Elt. Nates	BF Widh
0.00	279.04	LPIN7	0.00	278.84	XTLPIN	0.00	279.00	LP	0.00	278.90	X7 LP	0.00	278.90	0.00	279.00	Flood Prone Elv.
0.51	379.01	50000	33.87	279.49	X7	16.98	279,04	5.0	0.78	278,97	F-200	38.50	279.60	78.18	379.87	Flood Prone Width
21.57	279.15	2	80.04	279.43	X7	2127	279.46		9.10	279.00	16	50.70	280.00	87.91	277/95	Max Depth
51.28	279.69	8	\$2.98	278.17	XT	51.48	219.62		39.67	279.56	9 III	62.30	279.56	96.35	277.85	Mean Depth
72.99	279.32	10	93.22	278.00	XT	64.37	279.69		47.46	279.88	E 11	79,15	279.60	103.71	276.41	W/D Ratio
79.63	279.60	ŭ.	95.72	277.74	S7BKF	79.27	279.73		59.29	279.41	31 11	87,40	278.50	104.70	274.84	ER
82.59	279.74	8	9635	276.99	X2	84.35	278.44		78.35	279.82	8 III	96.30	278.10	306.15	273.55	Bank Height Ratio
87.64	278.19		99.37	276.86	3.7	93.18	278.09		83.08	278.54	9)	101.25	276.60	109.69	272.94	Stream Type
94.24	277.96	BKF	100.51	276.50	X7	98.41	277.36	BIKE	90.68	278.31	9 III	104.50	276.20	110.29	273.22	-
96,14	276.99	11/2/20	194.62	275.73	XT	100.05	276.62	199223	94.59	278.12	8 11	108,80	274.10	111.05	273.97	
102.16	278.05	8	105.51	275.84	X7EOW	104.88	275.89		96.51	277,84	THEF	113.75	278.10	111.43	274,88	
103.93	275.91	LEW	107.14	274.46	Xf	106.12	275.59		97.53	277.64		126.10	278.35	112.64	276.24	
105.97	279.50	6	109.08	273.71	XTFW	106.98	273.56	TORE.	100.27	276.93	(i)	133.00	279.50	113.13	277.86	
107.48	275.00	0	110.65	274.18	XT	105.65	272.99	TW	102.39	276.73	10 III	137.55	281.00	127.04	279.58	
109.21	274.77	8	112.52	276.79	3.7	109.62	274.05		163.97	276.51	W 11	190.60	290.50	133.82	280.71	
110.70	274.73		113.12	278.09	3.7	111.01	214.57		104.82	275.68	10 III			154.18	280.71	
111.47	275.85	REW	124.51	278.21	107	111.90	275.05		105.08	273.57	3			185.25	280.40	
113.14	278.16	2011000	128.63	278.60	N7	119.43	278.21	70,070	106,95	272.78	16			190.80	280.50	
115.19	278.22	6	133.27	289.31	X7	128.11	278.74		109.27	272.10	116			25545011		
119.54	278.15	8	176.97	280.34	3.7	131.95	290.45		110.89	272.72	3.00					
126,62	278.37	0	190.04	289.54	N78PIN	139.75	260.91		114.35	278.93	DKF					
131,05	279.63	8				152.76	289.79		128.12	278,69						
136.84	280.83	Ö				175.17	289.20		133.87	280,50	))					
151.13	250.81	10				189.83	289.53	RP	150.92	280,96	8					
170.43	786.49	66						- 1	125.66	290.58	6 11			1		

189.07 280.57

190.59

280.52 N7 83





Project Name Little Beaver Creek, MY5

Boggs, Ward

277.65

135.88

141.94

Watershed Cross Section 8 Drainage Area NA Mar-15

Photo of Cross-Section T8 - Riffle -Looking Upstream

Picture Taken March 31, 2015

Summary Data

24.2

18.4

70.4 2.5

14 3.8


								- 1						- 1			Summary D	ø
As-Built	Survey	9		2008			2009			2010			2014			2015	Bankfull Elv.	
As-Built	Survey	ž	26	08 MYI		20	09 MY2		201	10 MY3		26	14 MY4		24	15 MY5	BF Asea	
Station .	£br	Nation	Station.	Div	Notes	Station	Dr.	Nates	Station	Dr.	Notes	Station	Dr. N	otes.	Station	Els Notes	BF Width	Ī
0.99	278.13	RPIN8	0.00	228.13	XRLPIN	0.00	278.15	1.9	-0.02	278.13	X81.P	0.00	278.10	71.5	0.00	278.10	Flood Prone Elv	Ī
0.56	278.13	(A)	25.32	277.53	X8	2,47	278.11	200	18.03	277.85	0.000	41.54	277,10		22.84	277.80	Flood Prone Width	
9.08	217.87	8 1	40.75	276.88	3.8	9.65	277.93		39.42	277.36	6 H	47.30	276.00		44.52	277.10	Max Depth	
25.95	277,43	8	49.89	274.50	XX	22.03	277,64		44.68	276.72	8 II	52.85	274.25		52.34	274.31	Mean Depth	
40.23	277.27	9	57.68	273.88	XIBKF	31.79	277.58		50.67	274.44	9 H	57.25	274.20		60.18	274.19	W/D Ratio	Ī
47.20	275.74	8	61.18	273.68	XX	38.64	277.39		57.06	274.31	1007	63,90	273.10		62.44	273.44	ER	Ī
50.99	27430	8	64.71	271.89	X8	4438	276.75		59.93	273.99	6 H	65.90	272.10		62.94	273.00	Bank Height Ratio	
55.07	274.21	0	66.92	271.48	N.K	59.52	274.61		63.01	273.17	9 11	70.60	272.00		66.05	272.28	Stream Type	Ī
58.92	274.01	8	69.50	271.21	SETW	52.39	274.23	10000	64.65	272.44	9 11	77,40	273.85		66.40	271.92		Ī
62.83	272.85	8	70.92	272.19	XSEOW	58.74	274.18	BIKE	65.79	271.65	9 11	86.50	274.25		71.14	271.56		
65.58	271.76	SOLEW	76.16	273.83	XMEXIW	61.64	273.66	10000	68.12	271.38	TW	93.15	274.00		73.05	272.74		
65.82	271.65	3	82.66	274.11	33	63.35	272.96		69.99	271.31	3000	106.35	273.65		77.29	274.07		
67.49	271.60	3	89.15	274.14	X3	65.41	272.25		79.78	271.50		121.20	277.10		90.05	274.22		
68.66	271.63	9	96.62	275.29	X8	66.23	275.37	TOEL	71.64	272.40		142.20	277.80		34.01	254.22		
70.14	271.64	8	104.34	274.31	X8	68.42	271.39	TW	72.81	272.89	9. II				92.94	274.44		
70.51	271.78	HEW	104.36	274.34	X8	71.24	271.44	3068	75.80	273.66	i				94.00	274.95		
72,04	272.40	3 000	106.02	272.99	X8	72.72	272.41	357910	79.62	274.09	HKF				98.57	274.87		
76.21	273.87	1007	111.01	274.27	X8	71.29	272.74	4550.5	99.32	274.33	Samo				107.12	274.03		
81.67	274.96	5.000	117.84	277.00	X8	78.73	274.06	8837	94.59	274.94	8 H				117.40	276.96		
93.83	274.48	8 1				10.12	274.09	111000	106.57	273.39	10 H				142.00	279.00		
101.17	273.73	9				88.92	254.30		110163	274.28	2 H							
104.99	273.73	8				92.04	274,85		121.02	277.53	65 H							
110.07	275.17					99.82	215.12		134.12	277.53	9							
118.23	277.13	9				98,59	274,86		142.08	277.65	XERP			- 1				

164.80 273.44

101.85 234.15

110.58 274.27





Project Name Little Beaver Crock, MY5

Watershed Cross Section T1 Drainage AreaNA Mar-15

> 88.47 288.63

96.01

109.21

117.96

125.91

127.30

299.18

290,09

296.50

290.34

290.49 RPINT)

Photo of Cross-Section T1 - Pool -Looking Upstream

Picture Taken March 31, 2015

As-Buil As-Buil					2008 08 MY		20	2009 09 MY2			2010 10 MY3		20	2014 14 MY4	2	2015 H5 MV5
Station	Eb.	Nere	я.	Station	Div	Notes	Station	Elv	Nates	Station	Div	Notes	Station	Elv Notes	Stelles	Dr Note
0.00	290,60	LPIN	п	0.00	290.6	9.TILBN	0.00	290.69	1.9	8.07	290.68	XXIII	0.00	291.08	9.00	291.09
0.79	290.6	1	4	13.85	291.1	2 XTI	31.94	291.21	7.55	19.84	291.21	STATE OF THE PARTY OF	33.59	291.27	39.72	291.44
12.85	291.0	2	-1	38.65	291.1	1 X11	24.13	291.29		39.00	291.36	88	40.47	290.75	:53.00	287.50
55.25	291.4	6	-1	47.67	289.7	s XII	34.65	299.43		36.56	287,25	6	52.97	287.61	66.71	286.87
47.76	289.25		-1	54.18	287.6	3 XII	40.39	291.22		64.95	286.96	BKF	65.42	286.98	30.33	285.94
57.14	287.13	1	л	54.28	287.4	2 XTI	46.09	290.03		67.90	286.56	66	67.38	286.33	73.27	286.10
65.34	256.37	in in	ar.	63.34	287.6	2 KTHIKE	93.82	257.74		68.70	280.79	60	69.11	285.69	24.70	285.29
69.17	285.90	1.11	w	67.41	286.5	6 XTI	37.40	287.14	100000	69.22	285,71	(%-n)	70.41	285.39	75.12	286.98
69.46	289.89		ч.	67.50	285.1	O THOSE	64.23	287.03	BKF	71.06	285.58	TW	73,99	286.60	75.70	287.19
20.22	285.8	(i)	-1	67.35	285.0	2 THEOW	68.85	286.45	12500	72.26	285.83	(Service)	75.30	286.86	27.25	287.00
71.39	285.7	60	-1	68.58	284.5	S XTITW	69.36	285.58	TOEL	74.47	286.78	60	77.64	286.83	82.46	287.11
71.94	285.90	BE	w	70.25	285.4	1 XTTTW	71.00	285.48	TW	76.82	287.23	BKF	81.58	287.15	97.29	290.08
72.44	286.0		П	71.04	285.7	7 XIII W	72.15	285.78	TOE R	83.45	287.17	6	93.86	289.62	337.34	290.56
73.71	286.67	15	-1	72.56	285.5	2 THOW	74.08	286.71		93.65	289.81	100	119.53	291.05	127.30	290.00
75.78	287.1	0.0	-1	73.20	286.6	8 CTHIKE	75.93	287.11	BKF	114.60	290.29	0	127.50	290.00		
78.99	287.0	7	-1	77.75	287.2	6 СТИКР	79.65	287,07		127.56	290.51	XT 1 RP				
82.11	287.0	4	-1	83.72	287.2	4 XT1	84.39	287.20				1000			1	

88.37 288.34


299:12 117,09

290.33

94.97 290.12

101.47 107.80

121.67 290.83 124.62 290.50 127.63 290.51



BF Area BF Width

Flood Prone Elv.


Max Depth Mean Depth

W/D Ratio

Stream Type

Flood Prone Width





90.12 288.99 XTI

290.45 XT1

290.21 XTI

Project Name Little Beaver Creek, MY5 Watershed

Boggs, Ward

Cross Section T2 Drainage AreaNA Mar-15

74,49 285.82

77,78

84,67

95.95

106.05

121.39

129.48

130.58

141.65

286.26

286,17

285.21

287.03

288.80

288.91

289.62

299-16 LPINT2

Photo of Cross-Section T2 - Pool -Looking Upstream

Picture Taken March 31, 2015

As-Built As-Built			26	2008 08 MYI		20	2009 09 MY2			2010 10 MY3		20	2014 14 MY4	2	2015 015 MY	5
Station	Els	Netes	Station	Div	Notes	Station	Dr	Nates	Station	Div	Notes	Station	Els Notes	Station		Netes
2.00	290.16	RPINT2	29.05	299.15	X12	0.00	290.32	1.8	0.03	290.33	NT21F	29,07	290.14	9.00	290.33	(1000
15.71	290.17	() the	45.95	289.67	3772	4.97	290.18	131	16.72	290.21	No.	48.36	290.05	48.00	290.00	
33.69	290:11	0.	56.85	286.79	X17	22.13	290.16		32.94	290.91	03	57.00	286.75	58.64	288,37	
66.73	290.07	6	66.58	286.05	CT2BKF	34.82	290.22	- 1	47.52	290.05		63.85	286.57	66.28	286.40	
52.71	288.29	10	68.11	285.39	T2EOW	47.28	290.07		56.93	286.83		66.71	285.86	67.92	283.30	68
56.88	286.64	100	69.29	284.74	XT2	51.86	288.82	- 1	66.65	286.43		67.28	285.33	69.42	284.39	1
60.27	286.34		71:11	284.85	X12	55:59	287.23		64.04	280.31	Bior	67.63	284.78	30.53	284.38	8
65.09	286.2	10	71.62	285.31	TZEOW	37.68	286.69	- 1	66.27	286.15	1500	68.81	284.56	73.73	285.55	1
66.75	285.80	Comme	72.66	285.52	X12	60.91	286.43		68.81	284.4	TW	69.56	284.81	78.53	256.38	62
67.64	285.21	LEW	77.88	286.34	X12	65.64	286.26		68.87	284.4	Contract of	71.06	285.31	94.49	286.31	
68,30	284.88		93.88	286.14	X12	67.16	285.80	0.000	69.58	284.51	01	T1.46	285.54	121.76	289.05	(3)
68.90	284.80	6	102.17	286.79	XT2	68.21	285.09	TOEL	72.06	285.66		75,36	286.21	130.50	289.00	68
70.02	284.65	8	113.04	287.83	X12	68.63	284.61		77.49	286,30	BKF	97.18	286.64			
70.78	284.63	6	122.50	288.96	3.77	69.20	284.48	170	97.56	286.53	17	119.16	288.70			
71.62	284.79	8				20.34	284.74		103.98	287.08	10	122.50	288.90			
72.39	285.00	B.,				70.84	285.11	TOUR	122.34	289.13	16					
72.40	285.25	REW				23.06	285.77	70.833	139.76	288.99	XT 2 RP					

78.73

91.66 286.33

98.00 286.49

113.42 288.00

122.83 288.99

130.78 288.98

286.34



Bankfull Elv. BF-Width


Flood Prone Elv. Flood Prone Width


Max Depth

W/D Ratio Bank Height Ratio Storant Type

Mean Depth











The Catena Group

Year 5 Monitoring Report Year 5 of 5 June 2015











## **Pebble Counts with Annual Overlays**

			Project Nam	e: Little	Beaver Creek	
			Cross Sec	tion 1 - N	Iain Reach	
			Monitor	ing Year	5 - 2015	
Desc.	Mat	erial	Size (MM)	Count	% of Total	Cumulative %
		silt/clay	0.062	1	1.00%	1.00%
[	rev	ry fine sand	0.125	4	4.00%	5.00%
		fine sand	0.25	14	14.00%	19.00%
SAND	me	edium sand	0.5	15	15.00%	34.00%
[		oarse sand	1	21	21.00%	55.00%
	very o	coarse sand	2	29	29.00%	84.00%
	very	fine gravel	4	13	13.00%	97.00%
[		fine gravel	5.7	2	2.00%	99.00%
		fine gravel	8	0	0.00%	99.00%
[	med	dium gravel	11.3	0	0.00%	99.00%
GRAVEL	med	dium gravel	16	1	1.00%	100.00%
[	co	arse gravel	22.3		0.00%	100.00%
[	co	arse gravel	32		0.00%	100.00%
[	very co	arse gravel	45		0.00%	100.00%
	very co	arse gravel	64		0.00%	100.00%
	SI	mall cobble	90		0.00%	100.00%
COBBLE	med	ium cobble	128		0.00%	100.00%
	la	arge cobble	180		0.00%	100.00%
	very la	arge cobble	256			
	sm	nall boulder	362			
BOULDER	sm	nall boulder	512			
[	mediu	um boulder	1024			
	lar	rge boulder	2048			
TOTAL %	of whole c	ount:		100	100%	100%


Sumam	ry Data
D50	0.85
D84	2
D95	3.6






			-		Beaver Creek	
			Cross Sect	tion 3 - N	fain Reach	
			Monitor	ing Year	5 - 2015	
Desc.	Mat	erial	Size (MM)	Count	% of Total	Cumulative %
		silt/clay	0.062	8	8.00%	8.00%
[	ver	ry fine sand	0.125	13	13.00%	21.00%
		fine sand	0.25	19	19.00%	40.00%
SAND [	me	edium sand	0.5	31	31.00%	71.00%
[	(	coarse sand	1	20	20.00%	91.00%
	very o	coarse sand	2	7	7.00%	98.00%
	very	fine gravel	4	1	1.00%	99.00%
[		fine gravel	5.7		0.00%	99.00%
[	fine gravel medium gravel		8	1	1.00%	100.00%
[			11.3		0.00%	100.00%
GRAVEL	med	dium gravel	16		0.00%	100.00%
[	co	medium gravel coarse gravel			0.00%	100.00%
[	co	arse gravel	32		0.00%	100.00%
[	very co	arse gravel	45			
	very co	arse gravel	64			
	SI	mall cobble	90			
COBBLE	med	lium cobble	128			
	la	arge cobble	180			
	very la	arge cobble	256			
	sm	nall boulder	362			
BOULDER	sm	fine gravel medium gravel coarse gravel coarse gravel very coarse gravel very coarse gravel small cobble medium cobble large cobble very large cobble small boulder small boulder medium boulder large boulder				
[	mediu	um boulder	1024			
	lar	rge boulder	2048			
TOTAL %	of whole c	ount:		100	100%	100%


Sumam	ry Data
D50	0.31
D84	0.78
D95	1.5






			Project Nam	e: Little	Beaver Creek	
			Cross Sect	tion 5 - N	Iain Reach	
			Monitor	ing Year	5 - 2015	
Desc.	Mat	erial	Size (MM)	Count	% of Total	Cumulative %
		srial Size silt/clay ry fine sand fine sand coarse sand fine gravel fine gravel fine gravel dium gravel dium gravel dium gravel coarse gravel	0.062	2	2.00%	2.00%
	very fine sand fine sand medium sand coarse sand very coarse sand very fine gravel fine gravel fine gravel medium gravel medium gravel coarse gravel		0.125	2	2.00%	4.00%
		fine sand	0.25	1	1.00%	5.00%
SAND	me	edium sand	0.5	5	5.00%	10.00%
	(	oarse sand	1	19	19.00%	29.00%
	very o	coarse sand	2	27	27.00%	56.00%
	very	fine gravel	4	30	30.00%	86.00%
fine gravel			5.7	11	11.00%	97.00%
fine gravel		8		0.00%	97.00%	
fine gravel medium gravel GRAVEL medium gravel coarse gravel coarse gravel	11.3		0.00%	97.00%		
	dium gravel	16	1	1.00%	98.00%	
	22.3	1	1.00%	99.00%		
Г	co	arse gravel	32		0.00%	99.00%
Г	very co	arse gravel	45		0.00%	99.00%
Г	very fine sar  fine sar  medium sar  coarse sar  very coarse sar  very fine grav  fine grav  medium grav  medium grav  coarse grav  coarse grav  very coarse grav  small cobb  medium cobb  large cobb  very large cobb  small bould  small bould  large bould		64	1	1.00%	100.00%
	SI	mall cobble	90		0.00%	100.00%
COBBLE	med	ium cobble	128		0.00%	100.00%
	la	arge cobble	180			
Г	very la	arge cobble	256			
	sm	nall boulder	362			
BOULDER	sm	nall boulder	512			
Γ	silt/clay very fine sand fine sand coarse sand very coarse sand very fine gravel fine gravel fine gravel medium gravel coarse gravel coarse gravel very coarse gravel	1024				
Г	fine sand  AND  medium sand  coarse sand  very coarse sand  very fine gravel  fine gravel  fine gravel  medium gravel  coarse gravel  coarse gravel  very coarse gravel					
TOTAL % o	of whole c	ount:		100	100%	100%


Sumam	ry Data
D50	1.7
D84	3.8
D95	5.6






			Project Name	e: Little	Beaver Creek	
			Cross Sect	tion 6 - N	fain Reach	
			Monitor	ing Year	5 - 2015	
Desc.	Mat	erial	Size (MM)	Count	% of Total	Cumulative %
	Material Siz silt/clay very fine sand fine sand medium sand coarse sand very coarse sand very fine gravel fine gravel fine gravel medium gravel medium gravel coarse gravel coarse gravel very coarse gravel small cobble large cobble very large cobble small boulder	0.062	1	1.00%	1.00%	
	vei	ry fine sand	0.125	3	3.00%	4.009
		fine sand	0.25	2	2.00%	6.009
SAND	medium sar coarse sar very coarse sar very fine grav fine grav fine grav medium grav		0.5	10	10.00%	16.009
	(	oarse sand	1	8	8.00%	24.009
	very o	oarse sand	2	12	12.00%	36.009
	very	fine gravel	4	17	17.00%	53.009
	fine gravel fine gravel			20	20.00%	73.009
	fine gravel medium gravel		8	18	18.00%	91.009
medium gravel	11.3	6	6.00%	97.009		
medium gravel GRAVEL medium gravel		16	1	1.00%	98.009	
	co	arse gravel	22.3		0.00%	98.009
	co	arse gravel	32	1	1.00%	99.009
	very co	arse gravel	45	1	1.00%	100.009
	very co	arse gravel	64		0.00%	100.009
	SI	mall cobble	90			
COBBLE	med	ium cobble	128			
	la	arge cobble	180			
	very la	arge cobble	256			
	sm	nall boulder	362			
BOULDER	sm	nall boulder	512			
	medi	um boulder	1024			
	silt/clay very fine sand fine sand coarse sand very coarse sand very fine gravel fine gravel fine gravel medium gravel coarse gravel coarse gravel very coarse gravel small cobble large cobble very large cobble small boulder		2048			
TOTAL %	of whole c	ount:		100	100%	100%


Sumam	ry Data
D50	3.5
D84	7.2
D95	9.9





			Project Nam	e: Little	Beaver Creek	
			Cross Sect	tion 8 - N	Iain Reach	
			Monitor	ing Year	r 5 - 2015	
Desc.	Mat	erial	Size (MM)	Count	% of Total	Cumulative %
		silt/clay	0.062	4	4.00%	4.00%
	ver	ry fine sand	0.125	1	1.00%	5.00%
		fine sand	0.25	7	7.00%	12.00%
SAND	me	edium sand	0.5	16	16.00%	28.00%
	(	oarse sand	1	19	19.00%	47.00%
	very o	coarse sand	2	22	22.00%	69.00%
	very	fine gravel	4	14	14.00%	83.00%
		fine gravel	5.7	5	5.00%	88.00%
SAND medium sand coarse sand very coarse sand very fine gravel fine gravel fine gravel fine gravel medium gravel coarse gravel coarse gravel very coarse gravel very coarse gravel small cobble large cobble very large cobble small boulder small boulder small boulder		fine gravel	8	2	2.00%	90.00%
	med	dium gravel	11.3	3	3.00%	93.00%
	med	dium gravel	16	1	1.00%	94.00%
	co	arse gravel	22.3	3	3.00%	97.00%
	arse gravel	32		0.00%	97.00%	
	45		0.00%	97.00%		
	very co	arse gravel	64	2	2.00%	99.00%
	SI	mall cobble	90		0.00%	99.00%
COBBLE	med	ium cobble	128		0.00%	99.00%
	la	arge cobble	180		0.00%	99.00%
	very la	arge cobble	256		0.00%	99.00%
	sm	nall boulder	362		0.00%	99.00%
BOULDER	sm	nall boulder	512		0.00%	99.00%
	medi	um boulder	1024		0.00%	99.00%
	laı	rge boulder	2048	1	1.00%	100.00%
BEDROCK					0.00%	100.00%
TOTAL % of	whole co	unt:		100	100%	100%

	Cummulati	ve Percent	
120.00%			
100.00%			
80.00%			<del></del>
40.00% 40.00%			<del></del>
ð 40.00%			
20.00%			
0.00% 0.062 0.125 0.25 0.5	1 2 4 5.7 8 11.3	16 22.3 32 45 64 90 100	128 180 256 362 512 1024 2048
		Particle Size (mm)	
	MY5-2015 MY4-	2014 MY3-2010 MY2-2	1009
	Individual Class	Percent	



Sumami	ry Data
D50	1.1
D84	4.3
D95	18

## Table 9. Stream Bank Erosion Pin Data

Not Applicable

Table 10a and b. Baseline Stream Summary Data

					Little E	Beaver			Baselii m Rest						Reach	1									
Parameter	Gauge <sup>2</sup>	Reg	ional C				Pre-Existing Condition					Reference Reach(es) Data						Design		Monitoring Baseline					
Dimension and Substrate		LL	UL	Eq.	Min	Mean	Med	Max	SD <sup>5</sup>	n	Min	Mean	Med	Max	SD <sup>5</sup>	n	Min	Med	Max	Min	Mean	Med	Max	SD <sup>5</sup>	n
Bankfull Width (ft	)						11.2				14		14.4	16.7				14.5		13.8		21.8	29.7		
Floodprone Width (ft	)																								
Bankfull Mean Depth (ft	)						0.7				0.8		0.9	0.9				1.04		1.2		1.5	1.8		
<sup>1</sup> Bankfull Max Depth (ft							1.2				1.4		1.8	2				2.3		2.3		2.9	3.4		
Bankfull Cross Sectional Area (ft <sup>2</sup>							8				12.2		15.5	13.7				15		25.1		29.7	34.2		
Width/Depth Ratio							15.6				16		17.6	18				14		7.6		16.7	25.8		
Entrenchment Ratio	9						2				3		6.1	13.6				>8		4.3		7.8	11.2		
<sup>1</sup> Bank Height Ratio	9																								
Profile																									
Riffie Length (fi	)										4			18						17		32	68		
Riffle Slope (fl/ft	)				0.009			0.067			0.00083			0.1125			0.007		0.02	0.001		0.008	0.02		
Pool Length (fi	)										- 6			41.5						0.0013		0.0027	0.0035		
Pool Max depth (fi	)																								
Pool Spacing (ft	)				- 4			78			14			95.8			36.5		58	31			43		
Pattern																									
Channel Beltwidth (fl	)				12	П		16			- 5	Г		40			36		65	37.9		37.9	58.2	Г	
Radius of Curvature (fl	)				- 6			12			11			90			29		44	10.9		18.59	26.2		
Rc:Bankfull width (ft/ft	)																								
Meander Wavelength (ft											14			67			46		83	68.7		98.5	80.1		
Meander Width Ratio					1.1			1.4									2.5		4.5						
Transport parameters																									
Reach Shear Stress (competency) lb/f																									
Max part size (mm) mobilized at bankful	E00000																								
Stream Power (transport capacity) W/m	2																								
Additional Reach Parameters							7.00																		
Rosgen Classification							I	i4					C4	/C5				C4/C5							
Bankfull Velocity (fps																									
Bankfull Discharge (cfs																									
Valley length (ft																									
Channel Thalweg length (fl																									
Sinuosity (fi	)							ı					1.2	-1.5				1.3							
Water Surface Slope (Channel) (fl/ft	)						0.0	11					0.011					0.0066							
BF slope (fl/ft																									
<sup>3</sup> Bankfull Floodplain Area (acres	)																								
% of Reach with Eroding Bank																									
Channel Stability or Habitat Metric																									
Biological or Othe	r																								NO.

The Catena Group

Year 5 Monitoring Report Year 5 of 5 June 2015

											am Da					_									
	I 21	Little Beaver Creek Stream Restoration Pr  e <sup>2</sup> Regional Curve Pre-Existing Condition								n Proje					2										
Parameter	Gauge <sup>2</sup>	Reg	ional C	urve	1	Pre-	Existin	g Cond	lition		Reference Reach(es) Data						Design		Monitoring Baseline						
Dimension and Substrate		LL	UL	Eq.	Min	Mean	Med	Max	SD <sup>5</sup>	n	Min	Mean	Med	Max	SD <sup>5</sup>	n	Min	Med	Max	Min	Mean	Med	Max	SD <sup>5</sup>	n
Bankfull Width (ft)	)				10.5			15.1			14		14.4	16.7				16.1		15.4		17.8	21.1		
Floodprone Width (ft)																									
Bankfuli Mean Depth (fi					0.9			1.4			0.8		0.9	0.9				1.15		17.9		20.4	22.8		
¹Bankfull Max Depth (ft					1.9			2.5			1.4		1.8	2				2.5		1.88		2.29	2.54		
Bankfull Cross Sectional Area (ft <sup>2</sup> )					14.3			14.8			12.2		15.5	13.7				18.5		17.9		20.4	22.8		
Width/Depth Ratio											16		17.6	18				14		11.69		16.4	17.24		
Entrenchment Ratio	9						1.4				3		6.1	13.6				>11		2.27		5.8	8.07		
<sup>1</sup> Bank Height Ratio	9																								
Profile																									
Riffle Length (fi	)										4			18						17		32	68		
Riffle Slope (fl/fl)	)				0.009			0.045			0.00083			0.1125			0.005		0.015	0.001		0.008	0.02		
Pool Length (ff	)										6			41.5						0.0013		0.0027	0.0035		
Pool Max depth (fi	)																								
Pool Spacing (ff)					30			86			14			95.8			36.5		80.5	31			43		
Pattern																									
Channel Beltwidth (ff)	)				10	П		37			- 5			40			40		72	32.2		61	45		
Radius of Curvature (ff	)				6			35			11			90			32		48	18.3		24.4	31.8		
Rc:Bankfull width (ft/ft	)																								
Meander Wavelength (ft)	)				40			95			14			67			51		91	76.9			113.3		
Meander Width Ratio					1			1.9									2.5		4.5						
Transport parameters																									
Reach Shear Stress (competency) lb/f																									
Max part size (mm) mobilized at bankful																									
Stream Power (transport capacity) W/m	2																								
Additional Reach Parameters										(Z. 116)															
Rosgen Classification	1						F4	/34					C4	/C5				C4/C5							
Bankfull Velocity (fps)					-																				
Bankfull Discharge (cfs)					-						10000														
Valley length (ft)	)																								
Channel Thalweg length (ft																									
Sinuosity (ff)	)						1	1					1.2	-1.5				1.3							
Water Surface Slope (Channel) (fl/fl)	)							1055						0025				0.0066							
BF slope (ff/ft)																									
3Bankfull Floodplain Area (acres	)																								
% of Reach with Eroding Banks																									
Channel Stability or Habitat Metric																									
Biological or Other																									

Year 5 Monitoring Report Year 5 of 5 June 2015

											am Da					_									
	. 2	_			Little E	Beaver				toration	n Proje					3									
Parameter	Gauge <sup>2</sup>	Reg	ional C	urve	<u> </u>	Pre-	Existin	g Cond	lition			Refere	ence Re	each(es	) Data			Design			Mo	nitorin	g Basel	line	
Dimension and Substrate		LL	UL	Eq.	Min	Mean	Med	Max	SD <sup>5</sup>	n	Min	Mean	Med	Max	SD <sup>5</sup>	n	Min	Med	Max	Min	Mean	Med	Max	SD <sup>5</sup>	n
Bankfull Width (ft)					9.5			15.5			14		14.4	16.7				17.1		16.9		18.1	18.8		
Floodprone Width (ft)																									
Bankfull Mean Depth (ft)					1.4			2			0.8		0.9	0.9				1.22		1.1		1.4	1.8		
<sup>1</sup> Bankfuli Max Depth (ft					2.1			2.6			1.4		1.8	2				2.7		1.75		2.41	3.23		
Bankfull Cross Sectional Area (ft²)					19.2			21.9			12.2		15.5	13.7				21		20.1		25.5	33.6		
Width/Depth Ratio											16		17.6	18				14		10.48		13.41	17.24		
Entrenchment Ratio							1.6				3		6.1	13.6				3		4.06		10.17	4.42		
<sup>1</sup> Bank Height Ratio																									
Profile																									
Riffle Length (ft)											4			18						17		32	68		
Riffle Slope (ff./ff)					0.01			0.07			0.00083			0.1125						0.001		0.008	0.02		
Pool Length (ft)	)										6			41.5						0.0013		0.0027	0.0035		
Pool Max depth (fi)																									
Pool Spacing (ff)					18			122			14			95.8						31			43		
Pattern																									
Channel Beltwidth (ff)					9	П		79			- 5			40						19.4		32.4	43.2		
Radius of Curvature (ff)			10000		4	$\overline{}$		33			11			90						15.29		19.58	23.3		
Rc:Bankfull width (fl/fl)			12000																						
Meander Wavelength (ft)					19			135			14			67						78.8			123.3		
Meander Width Ratio					1			6.2																	
Transport parameters																									
Reach Shear Stress (competency) lb/f																									
Max part size (mm) mobilized at bankful																									
Stream Power (transport capacity) W/m <sup>2</sup>																									
Additional Reach Parameters																									
Rosgen Classification								34										C4/C5							
Bankfull Velocity (fps)					$\Box$																				
Bankfull Discharge (cfs)					$\overline{}$																				
Valley length (ft)																									
Channel Thalweg length (ft																									
Sinuosity (ft)							1	.1					1.2	-1.5											
Water Surface Slope (Channel) (fl/ft)							0.0	067					0.011	0025											
BF slope (ff./ft)																									
3Bankfull Floodplain Area (acres)																									
% of Reach with Eroding Banks																									
Channel Stability or Habitat Metric																									
Biological or Other																									

Year 5 Monitoring Report Year 5 of 5 June 2015

## Table 11a and b. Monitoring - Cross-Section Morphology Table

				Tat	ole 11	la. M		_								-				arame			ss Se	ction	s)										
															_																				
Based on fixed baseline bankfull elevation	Base	MY1	MY2	MY3	MY4	MYS	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+
Record elevation (datum) used		291.72	291.72	291.72	291.72	291.72			288.10	288.10	288.10	288.10	288.10																						
Bankfull Width (ft)		13.80	15.40	13.89	25.10	15.90			17.35	19.12	21.34	12.20	27.90																						
Floodprone Width (#)		154.00	154.00	154.00	116.00	117.40			87.00	87.00	87.00	88.20	12400																						
Bankfull Mean Depth (ft)		1.80	1.45	1.81	1.00	1.20			0.99	0.96	0.85	0.80	0.80																						
Bankfull Max Depth (ft)		3.40	2.88	3.13	2.70	2.80			2.21	2.24	2.14	1.90	2.60																						
Bankfull Cross Sectional Area (ff)		25.10	22.40	25.09	24.90	18.80			17.23	18.39	18.04	20.10	21.60																						
Bankfull Width/Depth Ratio		7.60	10.59	7.69	25.20	13.40			17.53	19.89	25.24	24.70	36.10																						
Bankfull Entrenchment Ratio		11.20	10.00	11.09	4.60	7.40			5.04	4.55	4.03	4.40	4.40																						
Bankfull Bank Height Ratio		1.00	1.00	1.00	1.00	1.00			1.00	1.00	1.00	1.00	1.00																						
Cross Sectional Area between and pins (ft)																																			
d50 (mm)		0.81	0.36	0.6		0.85			0.57	N/A	N/A	N/A	N/A																						
			Cro	ss Sec	tion 6					Cre	ss Sec	tion 7					Cro	ss Sec	tion 8					Cre	ss Sec	tion 9					Cres	s Secti	on 10		
Based on fixed baseline bankfull elevation	Ване	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY4
Record elevation (datum) uses	$\overline{}$	$\overline{}$	$\overline{}$		$\overline{}$	$\overline{}$	$\overline{}$	${}^{-}$	$\overline{}$	${}^{-}$	т	т	$\overline{}$	$\blacksquare$		$\blacksquare$	$\overline{}$	$\overline{}$	$\overline{}$	$\overline{}$	${}^{-}$	$\overline{}$			$\overline{}$	$\overline{}$	$\overline{}$								
Bankfull Width (ft)																																			
Floodprone Width (#)																																			
Bankfull Mean Depth (ff)																																			
Bankfull Max Depth (ft)																																			
Bankfull Cross Sectional Area (ff)																																			
Bankfull Width/Depth Ratio																																			
Bankfull Entrenchment Ratio																																			
Bankfull Bank Height Ratio																																			
Cross Sectional Area between end pins (ft)																																			
d50 (mm)																																			

<sup>1.</sup> MY-01 monitoring did not separate these parameters based on the separate reaches.

	Г											- 1				ole 111 ek Str												IIE.											
	⊢			17			_						ille b	eaver	Cree			Rest	лаш	JII PI	ojec	1 - E			1 - K	eacri	1 (99	LF)					_	_	_		_		_
arameter	_		Ба	seline			_			- N	Y-1			-			/Y-2		_	+			M	/- 3			-		Pi	Y- 4			-			MY-	.5		_
imension and Substrate - Riffle only	Min	Mear	n Med	Max	SE	o⁴ s	O <sup>4</sup>	Min	Mean	Med	Max	SD	n n	n	Mea	n Med	i Ma	x S0	)*	n N	Ain N	Mean	Med	Max	SD4	n	Min	Mear	Med	Ma	x SC	1	n M	n M	ean 1	Med	Max	SD4	
Bankfull Width (ft)					Т	11	5.9	13.8		15.58	17.35	5		27.9		17.2	6 19.1	12	Т	13	3.89		17.62	21.34			12.2		13.63	25.	1	Т	15	.9		21.9	27.9		Г
Floodprone Width (ft)						11	7.4	87		120.5	154			124		120.	5 15	4	$\top$	$\Box$	87		120.5	154			88.2		102.1	110	6	Т	11	A	1	120.7	124		Г
Bankfull Me an Depth (ft)				Т	Т	- 1	.2	0.99		1.395	1.8		$\top$	0.8	$\Box$	1.20	9 1.45	55	Т	0.	845		1.326	1.806			0.8		0.9	- 1	Т	Т	0.	В	$\Box$	1	1.2		Г
<sup>5</sup> Bankfull Max Depth (ft)					$\mathbf{L}$	- 2	1.8	2.21		2.805	3.4		$\Box$	2.6	$\Box$	2.56	2.8	8	$\top$	2	:14		2.635	3.13			1.9		2.3	2.7	7	Т	2	6	$\Box$	2.7	2.8		Г
Bankfull Cross Sectional Area (ft²)						- 11	8.8	17.23		21.17	25.1	П		21.6		20.4	22.	4	$\perp$	- 1	8.04		21.57	25.09			20.1		22.55	24.5	99	Т	18	.8	$\Box$	20.2	21.6		Г
Width/Depth Ratio					Т	13	3.4	7.6		12.57	17.53			36.1			19.1		Т	7	.69		16.47	25.24			24.7		24.95	25.	2	Т	13	.4	2		36.1		
Entrenchment Ratio					$\mathbf{L}$	7	7.4	5.04		8.12	11.2		$\perp$	4.4		7.27	5 10	)	$\top$	4	077		7.584	11.09	_		4.4		4.5	4.6	6	Т	4.	4	$\Box$	5.9	7.4		Г
<sup>1</sup> Bank Height Ratio						$\perp$	1	1		1	I.	П		1		- 1	- 1	$\perp$	$\perp$	$\Box$	1		1	1			1		- 6	1.1		Т		$\perp$	$\Box$	1	1		Е
Profile														Т	Т	Т	Т	Т	Т	Т	Т				П			П	Т	Т	Т	Т	Т	Т	Т	$\blacksquare$			Г
Riffle Length (ft)						0.	85	3.77		18.61	109.3	t	$\top$		Т	149	41		Т	Т	12		35	67	$\Box$		10.15		47.55	84.9	15		13.	40	- 4	45.20	77.00		Г
Fiffe Slope (ft/ft)	-	${}^{-}$	${}^{-}$	${}^{-}$	т	┰		0.006		0.04	1.7	$\top$	$\top$	0.01	$\top$	0.07	0.4	1	┰	0	.01		0.03	0.05	${}^{-}$	-	10.0	${}^{-}$	0.195	0.3	1	┰	0.0	0		0.20	0.39		Т
Pool Length (ft)	$\overline{}$			$\top$	Т	$\top$	┱	9.86		40.88	93.60		$\top$	9	$\top$	30	86		$\top$	┰	18		46	79	${}^{-}$		${}^{-}$		83	83	$\top$	$\top$	12	10	- 4	48.15	84.20		Т
Pool Max depth (ft)	$\overline{}$	-	-	-	${}^{-}$	┰	┱		$\overline{}$	г	${}^{-}$	${}^{-}$	$\top$	${}^{-}$	${}^{-}$	$\top$	$\top$	$\top$	┰	┰	$\neg$	$\neg$		г	${}^{-}$	${}^{-}$	т	-	-	${}^{-}$	$\top$	$\top$	┰	┰	$\neg$	$\neg$	$\neg$	г	т
Pool Spacing (ft)	$\overline{}$	${}^{-}$	${}^{-}$	${}^{-}$	т	$\top$	$\neg$	3.77		18.1	97.6	т	$\top$	17	$\top$	47.3	100	7	┰	$\top$	21		79	126	${}^{-}$		18.6	${}^{-}$	60.45	102	3	┰	21.	30	- 5	56.50	91.70		т
Pattern														_	Т	$\top$	т	$\top$	┰	┰	$\neg$			П	${}^{-}$	-	т	-	-	т	$\top$	т	┰	$\top$	$\top$	$\neg$			П
Channel Beltwidth (ft)	П	Т	Т	Т	т	Т	т					Т	Т				Т	$\blacksquare$	т	_	$\neg$									Т	$\top$	т	$\blacksquare$	$\top$	$\blacksquare$				Г
Radius of Curvature (ft)	$\overline{}$	${}^{-}$	${}^{-}$	${}^{-}$	т	┰	_				т	т	$\top$	Т	Т	$\top$	т	┰	┰	┰	$\neg$			П	${}^{-}$	т	т	т	${}^{-}$	т	┰	т	┰	Т	$\top$	$\neg$			г
Rc:Bankfull width (ft/ft)	-	${}^{-}$	${}^{-}$	${}^{-}$	$\top$	┰	_				${}^{-}$	т	$\top$	${}^{-}$	${}^{-}$	$\top$	т	$\top$	┰	┰	$\neg$			П	-	-	т	${}^{-}$	${}^{-}$	т	$\top$	┰	┰	$\top$	$\top$	$\neg$			Г
Meander Wavelength (ft)				$\top$	Т	$\top$	_					Т	$\top$				Т	$\top$	Т	_	$\neg$									Т	$\top$	Т	$\blacksquare$	$\top$	$\blacksquare$				Г
Meander Width Ratio	$\overline{}$	${}^{-}$	$\overline{}$	${}^{-}$	т	┰	_				Т	Т	$\overline{}$	Т	Т	$\overline{}$	т	┰	т	┰	$\neg$				${}^{-}$	Т	П	т	т	т	┰	т	┰	Т	$\top$	$\neg$			г
Additional Reach Parameters																				Т													Т						
Rosgen Classification							Т			C-	4/C5						C4			Т			C	14						C4			$\top$			C4	4		
Channel Thalweg length (ft)	$\overline{}$						┱			5	91			т			1033			┰			10	133			г						┰			103	3		
Sinuosity (ft)							$\neg$			1	.19			$\top$			1.24			$\top$			1	24						1.24			$\top$			1.2	4		
Water Surface Slope (Channel) (ft/ft)							$\neg$			0.	0069					- 0	.0065			$\top$			0.0	071									$\top$			0.00	66		
Meander Width Ratio											т		0	.0107			┰			0.	D1			г						┰			0.01	11					
%%/Ru%/P%/G%/S%						Т						$\Box$			T	T	T	Т	Т		Т									П	Т			Т	$\top$	$\Box$			
"50% / Sa% / G% / C% / B% / Be%							Т											Т	Т	Т	$\neg$											Т	Т	T	$\Box$	$\Box$			
*d16/d35/d50/d84/d95/							Т								Т			Т			$\neg$													$\top$	$\top$	$\neg$			Г
2% of Reach with Eroding Banks							$\Box$													T																_			
Channel Stability or Habitat Metric							Т													Т													T						
Biological or Other							Т													Т																			
Shaded cells indicate that these will typically not bi 1 = The distributions for these parameters can incl 2 = Proportion of reach exhibiting banks that are er 3 = Riffle, Run, Pool, Glide, Step; Silt/Clay, Sand, 4. = Of value/neaded only if the nexceeds 3	lude info roding l	ormation based o	n the vi	isual sur	vey fro	om visu	ral ass	séssmi	ent tabl			lie.																											

Little Beaver Creek Stream and Wetland Restoration NCDMS Project number: 221 The Catena Group

Year 5 Monitoring Report Year 5 of 5 June 2015

				Tat	ole 11	a. M	onitor	ing D	ata -	Dime	nsion	al Mo	npho	logy	Sumr	nary	Dime	ensio	nal P	arame	eters -	– Cro	ss Se	ction	s)										
							Little	Bear	ver C	reek !	Strear	n Res	torat	ion P	rojec	- EE	P No.	. 221	- Rea	ch 2 (	1309	LF)													
	П		Cro	ss Sec	tion 3					Cre	ss Sec	ion 4					Cro	ss Sec	tion 5			П							$\Box$						
Based on fixed haseline bankfull elevation	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+
Record elevation (datum) uses		284.29	284.29	284.29	284.29	284.29			203.76	263.76	283.78	203.70	203.70			201.50	201.50	201.50	201.50	201.50															
Bankfull Width (ft)		16.43	16.65	16.58	32.00	26.60			19.42	21.58	21.58	26.00	22.10			28.18				36.30															
Floodprone Width (#;		53.00	54.49	55.21	55.70	50.90			97.00	97.00	97.00	135.10	286.70			126.00	126.00	126.00	137.90	137.90															
Bankfull Mean Depth (ft	1	1.16	1.11	0.97	0.70	0.60			1.23	1.24	1.30	1.10	1.40			1.56	1.27	1.89	1.00	1.00															
Bankfull Max Depth (ft		2.32	2.36	2.34	2.40	2.60			2.71	_	2.75	3.20	2.90			3.93	_	3.72	_	4.40															
Bankfull Cross Sectional Area (ff)		19.10	18.54	16.06	21.40	16.30			23.93	26.86	28.15	27.60	30.60			43.98	38.96	36.86	39.00	3430															
Banidull Width/Depth Ratio		14.16	14.95	17.13	47.90	43.40			4.98	4.49	4.49	24.50	15.90			13.06	24.14	10.26	42.30	37.90															
Bankfull Entrenchment Ratio	4	3.25	3.27	3.33	1.70	1.90					22.99	5.20	6.10			4.47	4.11	6.48	3.40	3.80															
Bankfull Bank Height Ratio		1.00	1.00	1.00	1.00	1.00			1.00	0.85	0.95	1.00	1.00			1.00	0.99	0.92	1.00	1.00															
Cross Sectional Area between and pins (f)																																			
d50 (mm)		1.31	0.68	0.13		0.31			0.43	N/A	N/A	N/A	N/A			7.08	3	3.9		1.7															
as ed on fixed bas eline bankfull elevation	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY4
Record elevation (datum) uses								${}^{-}$												${}^{-}$	$\overline{}$								${}^{-}$						${}^{-}$
Bankfull Width (ft)																																			
Floodprone Width (#;																																			
Bankfull Mean Depth (ft																																			
Bankfull Max Depth (R	1																																		
Bankfull Cross Sectional Area (ff)																																			
Bankfull Width/Depth Ratio																																			
Bankfull Entrenchment Rati																																			
Bankfull Bank Height Rati																																			
Cross Sectional Area between end pins (f)																																			
d50 (mm)																				T									Т						

MY-01 monitoring did not separate these parameters based on the separate reaches.
 This reach has two distinct slopes with the transition at approximate station 27+00.

rameter Baseline											Litti									tream ct - El						9 LF)											
Parameter			Ba	seline					М	Y-1					M	Y-2					M'	Y- 3					М	Y- 4						MY	- 5		
Dimension and Substrate - Riffle only	Min	Mean	Med	Max	SD*	SD4	Min	Mean	Med	Max	SD <sup>4</sup>	n	2	Mean	Med	Max	SO <sup>4</sup>	п	Min	Mean	Med	Max	SD <sup>4</sup>	n	Min	Mean	Med	Ma	sx S	o⁴T	п	Min	Mean	Med	Max	SD <sup>4</sup>	n
Bankfull Width (ft)	32	26	40.6	${}^{-}$	${}^{-}$	15.9	16.43	T	22.31	28.18	-		27.9	-	23.66	30.67	-	${}^{-}$	26	-	33.3	40.6		${}^{-}$	26	-	33.3	40.	6	┰	$\neg$	22.10	$\neg$	29.2	36.30	$\Box$	$\vdash$
Floodprone Width (ft)	55.7	135.1	137.9	1	${}^{-}$	117.4	53	-	89.5	126	-		124	$\overline{}$	90.24	126	$\overline{}$	${}^{-}$	55.7	$\overline{}$	96.8	137.9	$\overline{}$	$\overline{}$	55.7	-	96.8	137	9	┱	$\neg$	50.90	$\neg$	168.8	286.70	$\blacksquare$	$\overline{}$
Bankfull Mean Depth (ft)	0.7	1.1	1	${}^{-}$	${}^{-}$	1.2	1.16	${}^{-}$	1.36	1.56	${}^{-}$	$\overline{}$	0.3	$\overline{}$	1.192	1.27	$\overline{}$	${}^{-}$	0.7	$\overline{}$	0.9	1.1	${}^{-}$	${}^{-}$	0.7	$\overline{}$	0.9	1.1	1	$\neg$	$\neg$	0.60	$\neg$	-1	1.40	$\neg$	г
Bankfull Max Depth (ft)	2.4	3.2	3.9	${}^{-}$	${}^{-}$	2.8	2.32	${}^{-}$	3.125	3.93	-		2.6	$\overline{}$	3.068	3.775	$\overline{}$	г	2.4		3.15	3.9		$\overline{}$	2.4	${}^{-}$	3.15	3.9	9	$\neg$	$\neg$	2.60	$\neg$	3.5	4.40	$\Box$	г
Bankfull Cross Sectional Area (ft <sup>2</sup> )	21.4	27.6	39			18.8	19.1	${}^{-}$	31.54	43.98			21.6		28.75	38.96			21.4		30.2	39			21.4		30.2	39	,	$\neg$	$\neg$	16.30	$\neg$	25.55	34.80	$\Box$	г
Width/Depth Ratio	47.9	24.5	42.3	${}^{-}$	Т	13.4	4.98	${}^{-}$	11.52	18.06	${}^{-}$	$\overline{}$	36.1	$\overline{}$	14.32	24.14	${}^{-}$	г	24.5	${}^{-}$	36.2	47.9	$\Box$	${}^{-}$	24.5	$\overline{}$	36.2	47.	9	┱	$\neg$	15.90	$\neg$	29.65	43.40	$\Box$	г
Entrenchment Ratio	1.7	5.2	3.4			7.4	3.25		11.93	20.61			4.4		13.05	22.84			1.7		3.45	5.2			1.7		3.45	5.2	2	$\neg$	$\neg$	1.90	$\neg$	4	6.10		Г
<sup>1</sup> Bank Height Ratio	1	1	1			1	-1		1	1			-1		0.925	1			-1		1	ı.			-1		- 1	- 1	Т	$\neg$		1		1	1		Г
rofile																												Т	Т	Т							П
Riffle Length (ft)				Т	Т	0.85	3.77	Т	18.61	109.31		П			15.6	50		П	12		45	215	Т	г	P.366		62.343	3 115:	32	$\neg$	$\neg$	8.52	$\neg$		94.30	$\Box$	г
Fiffe Slope (fbft)			П	${}^{-}$	Т	${}^{-}$	0.006	${}^{-}$	0.04	1.7			10.0		0.04	0.16	г	Г	0		0.02	0.07			10.0	${}^{-}$	0.055	0.1		$\neg$	$\neg$	0.01	$\neg$		0.82	$\Box$	Г
Pool Length (ft)						$\blacksquare$	9.86		40.88	93.65			17		41	97			19		37	57			21.22		43.89	66.5	96	$\neg$	$\neg$	15.78	$\neg$		86.30	$\Box$	г
Pool Max depth (ft)																												Т	Т	$\neg$	$\neg$	$\neg$	$\neg$		$\Box$		Г
Pool Spacing (ft)							3.77		18.05	97.59			24		77.7	173			35		18	238			27.91		95.23	162.	35	$\neg$		21.56			158.40		Г
attern																												Т	Т	Т		$\neg$					Г
Channel Beltwidth (ft)			П	т	Т	т	П	Т		П	П																	т	_	$\neg$	$\neg$						г
Radius of Curvature (ft)		$\overline{}$	$\overline{}$	${}^{-}$	$\overline{}$	${}^{-}$	П	-	-								$\overline{}$		П							$\overline{}$	$\overline{}$	т	┰	$\neg$	$\neg$	$\neg$	$\neg$				г
Rc:Bankfull width (ft/ft)				$\top$	Т	$\top$	П	${}^{-}$																				Т	Т	$\neg$	$\neg$		$\neg$				П
Meander Wavelength (ft)																												П	т	Т							
Meander Width Ratio																																					
dditional Reach Parameters																																					
Rosgen Classification	_						_		_	4/C:5			_		_	24			_		_	34			_			C4			_			C-	_		_
Channel Thalweg length (%)	-						┿			109			-			91			-			198			⊢			04			$\dashv$			131		_	_
	-						⊢			58			-			69						69			⊢						$\dashv$			1.6			_
Sinuosity (ft) Water Surface Slope (Channel) (ft/ft)							┿			0048			-		0.00124				—			0.0080**			⊢						$\dashv$		-	0.003370		_	_
BF slope (fvft)							┿			m39			$\vdash$		0.00194				-			0.0086**			$\vdash$						$\dashv$			0.001370			_
%%/Ru%/P%/G%/S%	$\vdash$	_	_	$\overline{}$	_		_	$\overline{}$	т.	T	$\overline{}$		-	_		10091			_		0.00131	0.00100			$\vdash$	_	$\overline{}$	_	$\overline{}$	-		$\overline{}$		0.001310			
*SC% / Sa% / G% / C% / B% / Be%							_						$\vdash$	-	-	-	-		_		$\vdash$	$\vdash$	-		$\vdash$	+	_	╈	+	-+	$\dashv$	$\overline{}$	$\dashv$	$\overline{}$	-	-	Е
*d161d351d501d841d951		-	-	_	-	_	_	-	-	-	-		$\vdash$	-	-	-	-		_	-	$\vdash$	-	-		$\vdash$	+	<del>-</del>	╈	╈	-	_	$\dashv$	$\dashv$	$\overline{}$	-	$\overline{}$	Н
<sup>2</sup> % of Reach with Eroding Banks		_	_	_	_	_	<del>-</del>		_			_	$\vdash$	_	_	_	_		<del>-</del>	_	_	_	_		$\vdash$	_	_		_	_	$\dashv$	_	_		_	_	_
Channel Stability or Habitat Metric	$\vdash$						┿						$\vdash$						_						⊢						$\dashv$					_	_
Biological or Other	$\vdash$						┿						$\vdash$						-						-						$\dashv$				_	_	_

"MIY-ST monitoring did not separate these parameters based on the separate reaches.

"This reach has two-distinct slopes with the transition at approximate station 27+00.

Shaded cells indicate that these will typically not be filled in.

1 = The distributions for these parameters can include information from both the cross-section surveys and the longitudinal profile.

Little Beaver Creek Stream and Wetland Restoration NCDMS Project number: 221 The Catena Group

Year 5 Monitoring Report Year 5 of 5 June 2015

<sup>2 =</sup> Proportion of reach exhibiting banks that are eroding based on the visual survey from visual assessment table
3 = Riffle, Run, Pool, Glide, Step; SiftClay, Sand, Gravel, Cobble, Boulder, Bedrock; dip = max pave, disp = max subpave
4 = Of value/needed only if the n exceeds 3

Table 11a. Monitoring Data - Dimensional Morphology Summary (Dimensional Parameters – Cross Sections)  Little Beaver Creek Stream Restoration Project - EEP No. 221 - Reach 3A (732 LF)																																			
							Little	Beav	er Cr	eek S	Strean	n Res	torati	ion P	roject	t - EE	P No.	221 -	Read	ch 3A	(732	LF)													
			Cro	ss Sec	tion 6					Cre	ss Sect	ion 7					Cros	s Sect	ion 8																
Based on fixed baseline bankfull elevation	Ване	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+
Record elevation (datum) used		277.94	277.94	277,94	277,94	277,94			277.93	277.93	277.93	277.93	277.93			234.09	234.09	274.09	274.09	274.09															
Bankfull Width (ft)		21.65	19.46	19.92	14.20	16.40			19.87	17.68	18.43	16.70	21.90			19.46	19.32	20.59	32.20	18.40															
Floodprone Width (#)		95.00	78.47	77.67	61.40	54.40			156.00	156.00	156.00	190.60	190.80			75.00	73.23	76.21	71.20	70.40															
Bankfull Mean Depth (ft)		1.13	1.07	0.96	0.90	0.80			1.91	1.96	2.62	1.70	1.90			1.21	1.43	1.29	0.80	1.30															
Bankfull Max Depth (ft)		2.34	1.79	1.68	1.50	1.30			4.29	4.72	5.83	3.80	5.00			2.68	2.67	2.78	2.10	2.50															
Bankfull Cross Sectional Area (ff)		25.54	20.82	19.02	12.40	12.30			38.05	34.68	48.27	28.90	40.60			23.62	27.63	26.50	25.60	2420															
Bankfull Width/Depth Ratio		18.35	18.19	20.86	16.40	21.70			10.40	9.01	7.04	9.60	11.80			16.08	13.51	15.99	40.40	1400															
Bankfull Entrenchment Ratio		4.40	4.03	3.90	4.30	3.30			7.86	3.32	2.46	11.40	8.70			3.84	3.79	3.70	2.20	3.80															
Bankfull Bank Height Ratio		1.00	1.00	1.00	1.00	1.00			1.00	0.93	0.98	1.00	1.00			1.00	1.00	0.97	1.00	1.00															
Cross Sectional Area between end pins (ff)																																			
d50 (mm)		3.4	7.75	11.9		3.5			0.2	N/A	N/A	N/A	N/A			0.21	0.38	12.3		1.1															
Bankfull Entrenchment Ratis 4.40 4.03 3.90 4.20 3.30 7.96 8.32 8.46 11.40 8.70 3.84 3.79 3.70 2.20 3.80 Bankfull Bank Height Ratis 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.0																																			
as ed on fixed bas eline bankfull elevation	Ване	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY-
Record elevation (datum) used																													$\blacksquare$						$\blacksquare$
Bankfull Width (Y)																																			$\blacksquare$
Floodprone Width (ft)																																			
Bankfull Mean Depth (ff)																																			
Bankfull Max Depth (ft)																																			
Bankfull Cross Sectional Area (ff)																																			
Bankfull Width/Depth Ratio																																			
Bankfull Entrenchment Ratio																																			
Bankfull Bank Height Ratio																																			
Cross Sectional Area between end pins (ft)																																			
d50 (mm)																													-						

MY-01 monitoring did not separate these parameters based on the separate reaches.
 This reach has two distinct slopes with the transition at approximate station 36+00.

											Litt	E) le Be	chibit	Table Creek	e 11b.	. Moi	nitori	ng D	ata - S	Strean ect - E	n Rea	ch Da	ata Su	ımma ach 1	ry 1 (991	LLE)										
arameter Baseline  imension and Substrate - Riffle only Min Mean Med Max SC <sup>4</sup> SC							П		M	Y-1	Litt	ic De		0100		Y-2	COLO	anoi	T			/- 3	i - Ke	ucii	(33		M	Y- 4			Т		M.	Y-5		_
Dimension and Substrate - Riffle only	Min	Mean	Med	Max	SD*	SD4	Min	Mean	Med	Max	SD <sup>4</sup>	n	n	Mean	Med	Max	SD <sup>4</sup>	п	Min	Mean	Med	Max	SD <sup>4</sup>	n	Min	Mean	Med	Mao	SO	₫ n	Mir	Mea	n Med	Max	SD <sup>4</sup>	n
Bankfull Width (ft)	142	16.7	32.2	-	_	15.9	19.46	-	20.56	21.65	-		27.9	-	18.57	19.46	_	_	18.43	-	19.51	20.59		-	14.2		23.2	32.2	-	+	16.4	0	19.16	21.9	-	-
Floodprone Width (ft)	61.4	190.6	71.2	-	_	117.4	75	-	115.5	156			124	-	114.6	156	_	-	76.21	-	116.1	156		-	61.4	-	126	190.	6	+	54.4	0	122.6	190.8	-	$\vdash$
Bankfull Me an Depth (ft)	0.9	1.7	0.8	${}^{-}$	-	1.2	1.18	-	1.545	1.91	$\overline{}$		0.8		1.516	1.962	-	-	0.955	-	1.787	2.619		${}^{-}$	0.8	-	1.25	1.7	${}^{-}$	$\top$	0.8	$\top$	1.35	1.9	-	г
<sup>5</sup> Bankfull Max Depth (ft)	1.5	3.8	2.1	${}^{\dagger}$	-	2.8	2.34	-	3.315	4.29			2.6		3.253	4.715	-	-	1.68	${}^{-}$	3.757	5.835		${}^{-}$	1.5	-	2.65	3.8	$\top$	$\top$	1.3	$\top$	3.15	-5	${}^{-}$	г
Bankfull Cross Sectional Area (ff)	12.4	28.9	25.6	${}^{-}$	-	18.8	23.62		30.84	38.05			21.6		27.75	34.68	-	-	19.02	-	33.65	48.27		$\overline{}$	12.4	-	20.65	28.9	1	$\top$	12.	3	26.45	40.6	$\overline{}$	г
Width/Depth Ratio	16.4	9.6	40.4	${}^{-}$	т	13.4	10.4	$\overline{}$	14.38	18.35			36.1		13.6	18.19	-	$\overline{}$	7.036	${}^{-}$	13.95	20.86		${}^{-}$	9.6	$\overline{}$	25	40.4	$\top$	$\top$	11.	8	12.9	14	${}^{-}$	г
Entrenchment Ratio	4.3	11.4	2.2	$\top$	т	7.4	3.84	${}^{-}$	5.85	7.86			4.4		6.307	8.824	${}^{-}$	${}^{-}$	3.702	T	6.083	3.465		$\Box$	2.2	$\overline{}$	6.8	11.4	$\top$	$\top$	3.3	$\top$	- 6	8.7	${}^{-}$	г
<sup>1</sup> Bank Height Ratio	1	1	1			1	1		1	I.			-1		0.963	1			0.975		0.987	ı.			1		1	1	$\top$	$\top$	- 1	$\top$	1	1		г
Profile																	П	П	Т	П								П	Т	Т	Т	Т	Т			
Riffle Length (ft)				Т	П	0.85	3.77		18.61	109.38					13.6	69			7	$\overline{}$	19	36		$\overline{}$	8.1		30.755	93.40	Т	$\top$	7.1	,	${}^{-}$	68.30	$\overline{}$	г
Riffle Slope (ft/ft)			П	${}^{-}$	Т	${}^{-}$	0.006		0.04	1.7			0.007		0.03	0.13	${}^{-}$	${}^{-}$	0	${}^{-}$	0.04	0.14			0.001	${}^{-}$	0.0555	0.11	Т	$\top$	0.03	:	${}^{-}$	0.03		г
Pool Length (ft)	$\overline{}$	-	$\overline{}$	$\overline{}$	-	${}^{-}$	9.86		40.88	93.65			10		27.4	54	-	-	23	${}^{-}$	30	111		${}^{-}$	13.26	$\overline{}$	36.5	99.74	1	$\top$	21.5	0	${}^{-}$	101.70		г
Pool Max depth (ft)						$\top$													Т						Г				Т	$\top$	$\top$	$\top$	$\top$			Г
Pool Spacing (ft)							3.77		18.05	97.59			1.5		37.7	73			20		76	115			18.622		32,411	36.2	Т	Т	19.9	0		22.80		
Pattern																			Т	П								П	Т	Т	Т	Т	Т			
Channel Beltwidth (ft)	$\overline{}$	т		$\overline{}$	т	т											-	т	т	-								т	т	_	_	-	-			
Radius of Curvature (ft)	$\overline{}$	$\overline{}$	$\overline{}$	${}^{-}$	$\overline{}$	${}^{-}$											-	-	т	${}^{-}$						$\overline{}$		Т	т	$\top$	$\top$	$\overline{}$	${}^{-}$			г
Rc:Bankfull width (ft/ft)				$\top$	Т	$\top$											Т	П	Т	Т								Т	Т	$\top$	┰	$\top$	${}^{-}$			
Meander Wavelength (ft)						Т																							Т							
Meander Width Ratio																																				
Additional Reach Parameters																																				
Rosgen Classification	_						$\overline{}$		Ca	VC:5			_		_	24			_			34			_		_	C4			_			34		_
Channel Thalweg length (ft)	-						_			32			-			90			_			90			-			100			+			90		_
Channel Thalweg length (ft) Sinuosity (ft)							_			17			-			26			+		_	26			-			26			+			26		
Water Surface Slope (Channel) (ft/ft)							_		0.0				-		0.002/0				_			0.0118**			-						+			0.0t16**		
BF slope (fvft)							_		0.0						0.0027.6				_		0.0024/				-						+			0.0125**		
%%/Ru%/P%/G%/S%		Т	Т	Т	Т											П	Т			Т			T		$\vdash$	Т	$\overline{}$	Т	Т			T	T		$\Box$	
"SC% / Sa% / G% / C% / B% / Be%																$\overline{}$	1	$\overline{}$		$\overline{}$		т			т			1	$\top$	$\overline{}$	_	$\top$	$\overline{}$	$\overline{}$	$\overline{}$	г
°d16/d35/d50/d84/d95/				${}^{-}$	т	${}^{-}$											-			${}^{-}$		${}^{-}$			г	-		-	$\top$			$\top$	${}^{-}$		${}^{-}$	
2% of Reach with Eroding Banks							$\overline{}$									_	_		$\mathbf{T}$						г	•	_		_		$\top$			_		
Channel Stability or Habitat Metric																															$\top$					_
Biological or Other	-						${}^{-}$												${}^{-}$						${}^{-}$						$\top$					_

"MY-01 monitoring did not separate these parameters based on the separate reaches.

"This reach has two distinct slopes with the transition at approximate station 27+00.

Shaded cells indicate that these will typically not be filled in.

The distributions for these parameters can include information from both the cross-section surveys and the longitudinal profile.
 Proportion of reach eshibiting banks that are eroding based on the visual survey from visual assessment table
 Rifle, Run, Pool, Gilde, Step, SibClay, Sand, Gravel, Cobble, Boulder, Bedrock, dip = max pave, disp = max subpave
 4. = Of valueheeded only if the n exceeds 3

Little Beaver Creek Stream and Wetland Restoration NCDMS Project number: 221 The Catena Group

Year 5 Monitoring Report Year 5 of 5 June 2015

Table 11a. Monitoring Data - Dimensional Morphology Summary (Dimensional Parameters – Cross Sections)  Little Beaver Creek Stream Restoration Project - EEP No. 221 - Tributary 1 (381 LF)																																			
Little Beaver Creek Stream Restoration Project - EEP No. 221 - Tributary 1 (381 LF)  Cross Section Trib 1 Cross Section Trib 2																																			
Based on fixed lasseline bankfull elevation Base MY1 MY2 MY3 MY4 MY5 MY4 Base MY1 MY2 MY3 MY4 MY5 Base MY1 MY2 MY3 MY4 MY5 MY4 Base MY1 MY2 MY3 MY4 MY5																																			
Based on fixed haseline bankfull elevation	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+
Record elevation (datum) used		287.11	287.11	287.11	287.11	287.11			206.30	206.30	206.30	206.30	286.30																						
Record elevation (datum) uses: 271 271 271 271 271 271 271 271 271 281 281 281 281 281 281 281 281 281 28																																			
Bankfull Width (ft) 12.43 14.00 15.07 18.00 19.20 9.46 13.81 12.61 15.00 11.60 Floodprone Width (ft) 42.00 38.84 38.26 41.60 44.90 53.00 60.30 60.20 53.00 60.20																																			
Bankfull Width (f) 12.48 14.09 15.07 18.00 19.20 9.46 13.81 12.61 15.30 11.60 9.00 9.00 9.00 9.00 9.00 9.00 9.00 9																																			
Floodprone Width (** 42,00 38.84 38.26 41.60 44.90 53.00 60.33 41.20 59.30 60.																																			
Floodprone Width (#) 42.00 38.84 38.26 44.69 44.90 53.80 60.33 64.20 58.30 60.20 58.30 58.																																			
Bankful Mean Depth (ft 0.8 0.6 0.6 0.6 0.6 0.6 0.6 0.6 0.7 0.6 0.9 0.6 0.9 0.6 0.9 0.6 0.9 0.6 0.9 0.6 0.9 0.6 0.9 0.6 0.9 0.6 0.7 0.6 0.9 0.6 0.9 0.6 0.7 0.6 0.9 0.6 0.9 0.6 0.9 0.6 0.9 0.9 0.9 0.9 0.9 0.9 0.9 0.9 0.9 0.9																																			
Bankfull Entrenchment Ratio		3.38	2.77	2.54	2.30	2.30			5.61	4.37	4.85	3.80	5.20																						
Bankfull Bank Height Ratio		1.00	0.97	0.91	1.00	1.00			1.00	0.98	0.99	1.00	1.00																						
Cross Sectional Area between and pins (ff)																																			
d50 (mm)		D. 59	N/A	N/A	N/A	N/A			0.18	N/A	N/A	N/A	N/A																						
Bas od on fixed bas eline bankfull elevation	Вазе	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+
Record elevation (datum) used																																			
Bankfull Width (N)																																			
Floodprone Width (ft)																																			
Bankfull Mean Depth (ft)																																			
Bankfull Max Depth (ft)																																			
Bankfull Cross Sectional Area (ff)																																			
Bankfull Width/Depth Ratio																																			
Bankfull Entrenchment Ratio																																			
Bankfull Bank Height Ratio																																			
Cross Sectional Area between end pins (ft)																																			
d50 (mm)																							Ц												

Parameter Baseline											1 10	E: tle Be									n Rea					LLE)										
Parameter	$\overline{}$		М	Y-1	LI	ne De	avei	Green		Y-2	CSLUI	auoi	T	CCL - E		V-3	1 - Ke	acii	(99	LF)	M	Y- 4			$\overline{}$		M	-5		_						
	=	_					=	_				_		_		_			=	_				_	=	_			_		=	_				
Dimension and Substrate - Riffle only	Min	Mean	Med	Max	SD4	SD4		Mean			SD*	n	_	Mean		_	SD4	п	_	Mean	_	_	SD4	n	_	Mear	_	-	-	'n	Min	Mean	Med	Max	SD*	n
Bankfull Width (ft)	_	_	_	_	_	15.9	9.46	lacksquare	10.97	12.48	$\perp$	$\vdash$	27.9	lacksquare		14	_	_	12.61	_	13.84			-	15.3	_	15.85	16.4	_	_	11.60	_	15.4	19.20		
Floodprone Width (ft)	-	$\vdash$	_	$\vdash$	$\vdash$	117.4	42	$\vdash$	47.5	53	$\vdash$	$\vdash$	124	$\vdash$	_	60.33	_	$\vdash$	38.26	$\vdash$	_	61.2	$\vdash$	$\vdash$	45.9	_	52.1	58.3	_	_	44.9	_	52.55	80.2		
Bankfull Me an Depth (ft)	_	_	ــــ	_	_	1.2	0.63	$\vdash$	0.74	0.85	_	$\vdash$	0.8	$\vdash$	_	0.658	$\vdash$	_	0.611	┺	0.702		$\vdash$	$\vdash$	0.6	┺	0.75	0.9	┺	┺	0.60	ــــ	0.75	0.90		_
<sup>5</sup> Bankfull Max Depth (ft)	_	ـــ	ـــ	ـــ	ـــ	2.8	1.31	_	1.675	2.04	┺	┺	2.6	╙	_	1.82	₩	╙	1.515	┺	1.703	1.89	┺	╙	1.7	┺	2.1	2.5	┺	┺	1.9	┺	2	2.1	_	<u> </u>
Bankfull Cross Sectional Area (ft <sup>2</sup> )	_	_	_	_	_	18.8	5.96	$\vdash$	8.31	10.66	_	$\vdash$	21.6	$\vdash$		9.086	_	_	9.214	┺	9.6	9.985	$\vdash$	$\vdash$	8.5	_	11.8	-	┺	_	-11	_	11	11		_
Width/Depth Ratio	_	_	ــــ	_	_	13.4	14.68	lacksquare	14.85		┖	┺	36.1	_		22.22	$\vdash$	_	15.93	┺	_	24.65	_	$\vdash$	17.7	$\perp$	22.65	27.6	┺	┺	12.4	ــــ	23	33.60		_
Entrenchment Ratio	_	$\vdash$				7.4	3.38		4.495	5.61	$\vdash$	$\vdash$	4.4	$\vdash$	_	4.37		_	2.539		3.696	_	$\vdash$		2.8	_	3.3	3.8	_		2.3		3.75	5.2		
<sup>1</sup> Bank Height Ratio						1	1		1	L			1		0.976	0.978			0.911		0.95	0.989			1		1	1			1		1	1		
Profile																																				
Riffle Length (ft)						0.85																														
Riffle Slope (ft/ft)																																				
Pool Length (ft)																																				
Pool Max depth (ft)																																				
Pool Spacing (ft)																																				
Pattern																	П		П	П	П		П		П	Т	П	П	Т	Т	П	П				
Channel Beltwidth (ft)																																				
Radius of Curvature (ft)											П	Т	П				П		П	П	П				П	Т		П	Т	Т	Т					
Rc:Bankfull width (ft/ft)																									П											
Meander Wavelength (ft)																																				
Meander Width Ratio																																				
Additional Reach Parameters																																				
Rosgen Classification	_						_						_						-						_						-					_
Channel Thalweg length (1)	-						━						━						-						━						-					_
Sinussity (R)	-						<del>-</del>						Н						┿						+						┿					-
Water Surface Slope (Channel) (ft/ft)	$\vdash$						-						-						+						┰						+					-
BF slope (ft/ft)	-						-						_						_						┪						+					_
*RM/Ru%/P%/G%/S%	$\vdash$	$\overline{}$	_	_	$\overline{}$		-			$\overline{}$	$\overline{}$		_	$\overline{}$	$\overline{}$	$\overline{}$	т —			т —	$\overline{}$	$\overline{}$	$\overline{}$		_	т —	$\overline{}$	т	т			_				
*SC% / Sa% / G% / C% / B% / Be%													_	-	-	_	+		_	_	+	-	-		Η-	+	<del>                                     </del>	_	+		1	_	-	$\vdash$	$\vdash$	
3d161d351d501d841d951	-	-	_	-	-	-	-				-	-	_	-	-	_	+		_	_	-	-	-		_	+	_	┿	+	_	_	_	-	$\vdash$		
2% of Reach with Eroding Banks	-	_	_		_		-				_	_	<del>-</del>	_	_	_	_	_	_	_	_	_	_		Η-	_	_	_	_	_	1	_	_	_		
Channel Stability or Habitat Metrid	$\vdash$						-						_						+						Η-						1					_
Biological or Other	-						-						_						_						┪						+					_
Shaded cells indicate that these will typically not be	e filled i	n					_						_						_						_						_					$\overline{}$

The Catena Group

Little Beaver Creek Stream and Wetland Restoration NCDMS Project number: 221

64

Year 5 Monitoring Report Year 5 of 5 June 2015

Shaded cells indicate that frese will typically not be filled in.

1 = The distributions for these parameters can include information from both the cross-section surveys and the longitudinal profile.

2 = Proportion of reach exhibiting banks that are eroding based on the visual survey from visual assessment table.

3 = Riffle, Run, Pool, Citide, Stept, SiRC lay, Sand, Gravel, Cobble, Boulder, Bedrock; dip = max pove, disp = max subpave.

4. = Of value/heeded only if the niexceeds 3.

Appendix E.


**Hydrologic Data** 


**Table 12. Verification of Bankfull Events** 


Little Beaver Creek Strea	am and Wetland Resto	oration Site-Project No. 22	1
Date of Data Collection	Date of Occurrence	Method	Photo #
2006	June 14, 2006	Visual	NA
September 18, 2008	September 7, 2008	Visual (i.e. wrack lines)	NA
April 1, 2014	March 2014	Observation of wrack lines in the floodplain	See below
January 12, 2014	January 12, 2014	Visual Observation	See below





View of stream bankfull event on Little Beaver Creek.























Table 13. Wetland Hydrology Criteria Attainment

Summary of Groundwater Gauge Results for Years 1 through 5

		2007 (MY	<u>′1)</u>	20	008 (M	<u>(2)</u>	20	009 (MY	<u>(3)</u>	20	13(M	<u>Y4)</u>	20	14 (MY	<u>(5)</u>
Gauge #	Max # Consecutive Davs	% Growing Season	Success Criteria Attained	Max # Consecutive	% Growing Season	Success Criteria Attained	Max # Consecutive	% Growing Season	Success Criteria Attained	Max # Consecutive	% Growing Season	Success Criteria Attained	Max # Consecutive Davs	% Growing Season	Success Criteria Attained
2		*			*			*		0	0	No	1	0.4%	No
3		*			*			*			N/A		48	21%	Yes
4		*			*			*			N/A		8	3.5%	No
5		*			*			*			N/A		8	3.5%	No
6	28	12%	Yes		N/A		35	15%	Yes	21	9%	Yes	48	21%	Yes
7	>29	>12.5%	Yes	65	28%	Yes	81	35%	Yes		N/A		118	51%	Yes
8**	>29	>12.5	Yes	75	33%	Yes	99	43%	Yes		N/A		11	5%	Yes
9			No		N/A		15	7%	Yes	5	2%	No	7	3%	No

<sup>\* -</sup> Gauge installed 1/15/10, incomplete growing season

<sup>\*\*-</sup>Gauge 8 was missing when monitoring re-commenced in the fall of 2013; A replacement gauge was installed in the vicinity of the former gauge location where wetland hydrology results are lower

N/A – insufficient data or data not available due to gauge failure or battery exhaustion

## Appendix F.

2013 Supplemental Monitoring Report