



North Carolina Department of Environment and Natural Resources
Division of Energy, Mineral and Land Resources
Land Quality Section

Tracy E. Davis, PE, CPM
Director

Pat McCrory, Governor
John E. Skvarla, III, Secretary

NOTICE OF INSPECTION

Date: March 11, 2014

Duke Energy Corporation
Attention: Sean DeNeale
526 South Church Street, ECI-013
Charlotte, North Carolina 28202

RE: Riverbend Ash Basin Dam 2 (Secondary)
GASTO-098 – High Hazard Potential
Gaston County

Dear Mr. DeNeale:

The "Dam Safety Law of 1967," as amended, provides for the certification and inspection of dams in the interest of public health, safety, and welfare, in order to reduce the risk of failure of such dams; to prevent injuries to persons, damage to property; and to insure the maintenance of stream flows.

Our records indicate that you are the owner and/or responsible for the referenced dam, which is located off NC HWY 16 in Gaston County and were inspected on February 19, 2014 and March 1, 2014 by personnel of the Land Quality Section. This inspection revealed the conditions outlined below. Please note that references to "right" and "left" in descriptions of the dam structure are referenced while looking in the downstream direction.

1. The overland drainage patterns appear to be creating surface erosion in two rip rap-lined areas on the downstream slope. (Refer to Coordinates 35° 22' 09.70", -80° 57' 36.60" and 35° 22' 09.20, -80° 57' 36.34). It is recommended that you monitor this area periodically, and notify this office of any sudden changes. It is also recommended that you provide measures to arrest the surface erosion in the area. Please be advised that the Division of Energy, Mineral and Land Resources must approve any repair requiring excavation, modification, or major repair work to this dam before the work commences.
2. Standing water and saturated soils were observed at various points along the bench on the downstream slope. It is recommended that plant personnel continue to monitor these areas periodically to confirm wetness on

the benches corresponds with rainfall patterns, and report any changes in the extent of wetness or seepage quantity to this office.

3. Wetness with active seepage flow was observed along the downstream toe of the eastern section of the main embankment and at the low point of the dam toe on the northern section of the embankment. It is recommended that plant personnel continue to monitor these areas periodically, and report any changes in the extent of wetness or seepage quantity to this office.
4. Cracks were observed in the concrete-lined spillway channel immediately downstream of the principal spillway outlet and the concrete outlet headwall. Surface erosion was observed left of the outlet wing wall. The outlet area should be routinely inspected for additional cracking and for signs of undermining of the discharge channel. Existing surface erosion should be repaired.

Additionally, the following general maintenance procedures are recommended:

1. Maintain a ground cover sufficient to restrain accelerated erosion on all earthen portions of the structure.
2. Periodically remove undergrowth, woody vegetation, and trees less than six inches in diameter from the slopes and crest of the dam and establish a good grass cover. All limb debris should be removed as well. This will serve to:
 - a. prevent the formation of a root system which might significantly increase seepage through the dam which could ultimately result in failure of the structure;
 - b. reduce the possibility of damage to the dam due to the uprooting of trees by wind or other natural causes; and
 - c. facilitate ease of inspection and increase the likelihood of early detection of more serious problems connected with the dam.

Additional information on the problems associated with undesirable vegetation on dams can be found in free publications such as FEMA 534, *Impacts of Plants on Earthen Dams*. This document can be viewed online at <http://www.damsafety.org/media/Documents/PDF/fema-534.pdf>.

3. Periodically check the operation of all drain valve facilities. This will ensure satisfactory operation of the drains should an emergency situation arise.
4. Periodically monitor the subject dam and appurtenant works with respect to elements affecting its safety. This is in light of the legal duties, obligations, and liabilities arising from the ownership and/or operation of a dam.

During this inspection we also investigated the potential for property damage and loss of life in the event that your dam fails. This investigation determined that failure of your dam could result in significant environmental damage

to Mountain Island Lake and possible interruption of utility service. Therefore, we are listing your dam in the "High Hazard Potential" Note that all hazard classifications are subject to change due to downstream conditions.

Please be advised that the Division of Energy, Mineral and Land Resources must approve any excavation, modification, or major repair work to this dam before the work commences. Also, note that this dam may not be breached, meaning the dam may not be drained by cutting a notch in the dam, without prior engineered breach plans being submitted to and approved by the Division of Energy, Mineral and Land Resources.


The "Dam Operation Maintenance and Inspection Manual" published by this Division provides inspection guidelines and recommended routine dam maintenance activities for the owner as well as emergency procedures in the event of possible dam failure. This document may be viewed online at <http://portal.ncdenr.org/web/lr/dams>.

Although every reasonable effort is made to determine the safety of each dam, our resources generally limit us to a surficial inspection of the dam and its appurtenant structures. This letter carries no implication regarding the internal stability of the dam. Dams, and especially their spillways and conduits, deteriorate with age. You are therefore advised to keep a close watch on the dam and notify us if you detect any changes, especially cracks, ground movements, or changes in seepage rate or color.

Please notify this office in writing if you wish to assert that you have no ownership or otherwise are not responsible for maintenance or repairs to the subject dam. If you have an emergency situation during non-office hours, you should notify 911 and the State Emergency Operations Center at 1 (800) 858-0368. They will notify the appropriate personnel in this Office of the situation.

Your cooperation and consideration in maintaining a safe dam is appreciated. Should you have any questions concerning our inspection, please contact me at (704) 663-1699.

Sincerely,



Zahid S. Khan, CPM, CPESC, CPSWQ
Regional Engineer
Land Quality Section

THE/cys

cc: Steven M. McEvoy, PE, State Dam Safety Engineer

DAM SAFETY INSPECTION REPORT

NAME RIVERBEND ASH BASIN DAM 2 (SECONDARY)	COUNTY GASTO	NO. 098	INSPECTED BY Edna Kormanik, Broadway, Schweiber	DATE 2/19/2014
--	------------------------	-------------------	---	--------------------------

OWNER DUKE ENERGY	ADDRESS See file
-----------------------------	----------------------------

TYPE DAM <input type="checkbox"/> Concrete gravity <input type="checkbox"/> Concrete arch <input checked="" type="checkbox"/> Other <input checked="" type="checkbox"/> Embankment <input type="checkbox"/> Concrete buttress <input type="checkbox"/> Stone masonry Ash Basin	TYPE INSPECTION <input type="checkbox"/> Initial <input type="checkbox"/> Followup <input type="checkbox"/> Periodic <input type="checkbox"/> Other	SITE CONDITIONS <input type="checkbox"/> Dry <input type="checkbox"/> Snowcover <input checked="" type="checkbox"/> Wet <input type="checkbox"/> Other
---	--	--

HAZARD DESCRIPTION See file	HAZARD CLASS <input type="checkbox"/> Low (A) <input type="checkbox"/> Intermediate (B) <input checked="" type="checkbox"/> High (C)
---------------------------------------	---

REMARKS Donna Burrell, Alex Papp, Larry Barley, Mike McAlister, Bob Drum, Alex Vogt, Scott Nordgen in attendance. Heavy rains this morning, 70's Sunny	ACTION <input type="checkbox"/> None <input type="checkbox"/> Maintenance <input type="checkbox"/> Monitoring <input type="checkbox"/> Minor repair <input type="checkbox"/> Engineering	RECOMMENDATIONS <input checked="" type="checkbox"/> Inspection letter <input type="checkbox"/> Deficiency letter <input type="checkbox"/> Enforcement <input checked="" type="checkbox"/> Periodic reinspection <input type="checkbox"/> Other reinspection <input type="checkbox"/> Inspection by DSE <input type="checkbox"/> Dam safety order
--	---	--

AREA	PROBLEMS	COMMENTS
UPSTREAM SLOPE / FACE	<input checked="" type="checkbox"/> 1. None <input type="checkbox"/> 11. Displaced rip rap <input type="checkbox"/> 2. Trees <input type="checkbox"/> 12. Cracks <input type="checkbox"/> 3. High bushes <input type="checkbox"/> 13. Undermining <input type="checkbox"/> 4. Burrows <input type="checkbox"/> 14. Holes <input type="checkbox"/> 5. Wave erosion <input type="checkbox"/> 15. Spalling <input type="checkbox"/> 6. Livestock damage <input type="checkbox"/> 16. Displaced joints <input type="checkbox"/> 7. Slides <input type="checkbox"/> 17. Deteriorated joints <input type="checkbox"/> 8. Depressions <input type="checkbox"/> 18. Exposed reinforcement <input type="checkbox"/> 9. Bulges <input type="checkbox"/> 19. Other <input type="checkbox"/> 10. Sparse rip rap	COVER: <input checked="" type="checkbox"/> Vegetation <input type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Asphalt <input type="checkbox"/> Other
TOP OF DAM	<input checked="" type="checkbox"/> 1. None <input type="checkbox"/> 11. Cracks <input type="checkbox"/> 2. Trees <input type="checkbox"/> 12. Spalling <input type="checkbox"/> 3. High bushes <input type="checkbox"/> 13. Deteriorated joints <input type="checkbox"/> 4. Burrows <input type="checkbox"/> 14. Displaced joints <input type="checkbox"/> 5. Ruts <input type="checkbox"/> 15. Exposed reinforcement <input type="checkbox"/> 6. Livestock damage <input type="checkbox"/> 16. Other <input type="checkbox"/> 7. Depressions <input type="checkbox"/> 8. Uneven <input type="checkbox"/> 9. Misalignment <input type="checkbox"/> 10. Has overtopped	COVER: <input checked="" type="checkbox"/> Vegetation <input type="checkbox"/> Gravel <input type="checkbox"/> Concrete <input type="checkbox"/> Asphalt <input type="checkbox"/> Other
DOWNSTREAM SLOPE / FACE	<input type="checkbox"/> 1. None <input type="checkbox"/> 11. Seepage <input type="checkbox"/> 2. Trees <input type="checkbox"/> 12. Bolls <input type="checkbox"/> 3. High bushes <input type="checkbox"/> 13. Cracks <input type="checkbox"/> 4. Burrows <input type="checkbox"/> 14. Holes <input type="checkbox"/> 5. Erosion <input type="checkbox"/> 15. Spalling <input type="checkbox"/> 6. Livestock damage <input type="checkbox"/> 16. Displaced joints <input type="checkbox"/> 7. Slides <input type="checkbox"/> 17. Deteriorated joints <input type="checkbox"/> 8. Depressions <input type="checkbox"/> 18. Exposed reinforcement <input type="checkbox"/> 9. Bulges <input type="checkbox"/> 19. Other <input type="checkbox"/> 10. Wetness	COVER: <input checked="" type="checkbox"/> Vegetation <input checked="" type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Other 4) Small suspected mole burrows in d/s slope 2-3" deep mower ruts + slight surface erosion in several areas + toe contact ↓ wetness in toe northern section - in riprap
TOE CONTACT	<input type="checkbox"/> 1. None <input type="checkbox"/> 11. Seepage <input type="checkbox"/> 2. Trees <input type="checkbox"/> 12. Bolls <input type="checkbox"/> 3. High bushes <input type="checkbox"/> 13. Cracks <input type="checkbox"/> 4. Burrows <input type="checkbox"/> 14. Holes <input type="checkbox"/> 5. Erosion <input type="checkbox"/> 15. Spalling <input type="checkbox"/> 6. Livestock damage <input type="checkbox"/> 16. Displaced joints <input type="checkbox"/> 7. Slides <input type="checkbox"/> 17. Deteriorated joints <input type="checkbox"/> 8. Depressions <input type="checkbox"/> 18. Exposed reinforcement <input type="checkbox"/> 9. Bulges <input type="checkbox"/> 19. Undermining <input type="checkbox"/> 10. Wetness <input type="checkbox"/> 20. Other	COVER: <input checked="" type="checkbox"/> Vegetation <input checked="" type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Other Several areas of active seepage in traditional location and along entire toe of slope! Clear flow observed - Heavy rains this morning contributed to wetness observed. 2 depressions in riprap along toe near d/s toe, left corner area. Coordinates attached monitoring recommended ~ 1 ft - seepage not observed in these areas

AREA	PROBLEMS	COMMENTS
ADJUTMENT CONTACTS	<input checked="" type="checkbox"/> 1. None <input type="checkbox"/> 2. Trees <input type="checkbox"/> 3. High bushes <input type="checkbox"/> 4. Burrows <input type="checkbox"/> 5. Erosion <input type="checkbox"/> 6. Livestock damage <input type="checkbox"/> 7. Slides <input type="checkbox"/> 8. Depressions <input type="checkbox"/> 9. Bulges <input type="checkbox"/> 10. Wetness <input type="checkbox"/> 11. Seepage <input type="checkbox"/> 12. Boils <input type="checkbox"/> 13. Cracks <input type="checkbox"/> 14. Holes <input type="checkbox"/> 15. Spalling <input type="checkbox"/> 16. Displaced joints <input type="checkbox"/> 17. Deteriorated joints <input type="checkbox"/> 18. Exposed reinforcement <input type="checkbox"/> 19. Undermining <input type="checkbox"/> 20. Other	COVER: <input checked="" type="checkbox"/> Vegetation <input type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Other
PRINCIPAL SPILLWAY	<input type="checkbox"/> 1. None <input type="checkbox"/> 2. No trashguard <input type="checkbox"/> 3. Obstructed <input type="checkbox"/> 4. Plugged <input type="checkbox"/> 5. Rusted <input type="checkbox"/> 6. Damaged <input type="checkbox"/> 7. Gates leaking <input type="checkbox"/> 8. Joints leaking <input type="checkbox"/> 9. Cracks <input type="checkbox"/> 10. Joint deterioration <input type="checkbox"/> 11. Joint displacement <input type="checkbox"/> 12. Undermined <input type="checkbox"/> 13. Voids <input type="checkbox"/> 14. Erosion <input type="checkbox"/> 15. Holes <input type="checkbox"/> 16. Conduit collapsed <input type="checkbox"/> 17. Spalling <input type="checkbox"/> 18. Outlet undercutting <input type="checkbox"/> 19. Misalignment <input type="checkbox"/> 20. Other	TYPE/SIZE: Concrete riser / CMP barrel. erosion under flume outfall + left side of wingwall, minor crack in concrete headwall above discharge pipe, continue to monitor transverse cracks along flume, historical
EMERGENCY SPILLWAY	<input type="checkbox"/> 1. None <input type="checkbox"/> 2. No ES <input type="checkbox"/> 3. Same as PS <input type="checkbox"/> 4. Obstructed <input type="checkbox"/> 5. Erosion <input type="checkbox"/> 6. Displaced rip rap <input type="checkbox"/> 7. Sparse rip rap <input type="checkbox"/> 8. Joints leaking <input type="checkbox"/> 9. Cracks <input type="checkbox"/> 10. Joint deterioration <input type="checkbox"/> 11. Joint displacement <input type="checkbox"/> 12. Undermining <input type="checkbox"/> 13. Voids <input type="checkbox"/> 14. Holes <input type="checkbox"/> 15. Exposed reinforcement <input type="checkbox"/> 16. Spalling <input type="checkbox"/> 17. Outlet erosion <input type="checkbox"/> 18. Misalignment <input type="checkbox"/> 19. Inadequate capacity <input type="checkbox"/> 20. Other	TYPE/SIZE: None
DRAINS / OTHER OUTLETS	<input type="checkbox"/> 1. None <input type="checkbox"/> 2. No bottom drain <input type="checkbox"/> 3. Bottom drain inoperable <input type="checkbox"/> 4. Subsurface drain dry <input type="checkbox"/> 5. Subsurface drain muddy flow <input type="checkbox"/> 6. Subsurface drain obstructed <input type="checkbox"/> 7. No animal guard <input type="checkbox"/> 8. Other	TYPE: None observed

SKETCHES/COMMENTS


DAM SAFETY INSPECTION REPORT

NAME RIVERBEND ASH BASIN 2 (SECONDARY)		COUNTY GASTO	NO. 098	INSPECTED BY EPLIN, KORMANIK	DATE 3/1/2014
OWNER See file		ADDRESS 			
PHONE 					

TYPE DAM <input checked="" type="checkbox"/> Embankment <input type="checkbox"/> Concrete gravity <input type="checkbox"/> Concrete arch <input checked="" type="checkbox"/> Other <input type="checkbox"/> Concrete buttress <input type="checkbox"/> Stone masonry ANK	TYPE INSPECTION <input type="checkbox"/> Initial <input checked="" type="checkbox"/> Followup <input type="checkbox"/> Periodic <input type="checkbox"/> Other	SITE CONDITIONS <input type="checkbox"/> Dry <input type="checkbox"/> Snowcover <input checked="" type="checkbox"/> Wet <input type="checkbox"/> Low (A) <input checked="" type="checkbox"/> High (C)
---	---	---

HAZARD DESCRIPTION See file	HAZARD CLASS <input type="checkbox"/> Low (A) <input checked="" type="checkbox"/> Intermediate (B) <input checked="" type="checkbox"/> High (C)
---------------------------------------	--

REMARKS Follow-up for outfall characterization Tim Russell, Donna Burrell + Bob Drum in attendance	ACTION <input type="checkbox"/> None <input type="checkbox"/> Maintenance <input type="checkbox"/> Monitoring <input type="checkbox"/> Minor repair <input type="checkbox"/> Engineering	RECOMMENDATIONS <input type="checkbox"/> Inspection letter <input type="checkbox"/> Deficiency letter <input type="checkbox"/> RE notice <input type="checkbox"/> Engineering study <input type="checkbox"/> Inspection by RE <input type="checkbox"/> Inspection by DSE <input type="checkbox"/> Dam safety order <input type="checkbox"/> Enforcement <input type="checkbox"/> Periodic reinspection <input type="checkbox"/> Other reinspection
--	---	--

AREA	PROBLEMS	COMMENTS
UPSTREAM SLOPE / FACE	<input type="checkbox"/> 1. None <input type="checkbox"/> 11. Displaced rip rap <input type="checkbox"/> 2. Trees <input type="checkbox"/> 12. Cracks <input type="checkbox"/> 3. High bushes <input type="checkbox"/> 13. Undermining <input type="checkbox"/> 4. Burrows <input type="checkbox"/> 14. Holes <input type="checkbox"/> 5. Wave erosion <input type="checkbox"/> 15. Spalling <input type="checkbox"/> 6. Livestock damage <input type="checkbox"/> 16. Displaced joints <input type="checkbox"/> 7. Slides <input type="checkbox"/> 17. Deteriorated joints <input type="checkbox"/> 8. Depressions <input type="checkbox"/> 18. Exposed reinforcement <input type="checkbox"/> 9. Bulges <input type="checkbox"/> 19. Other <input type="checkbox"/> 10. Sparse rip rap	COVER: <input type="checkbox"/> Vegetation <input type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Asphalt <input type="checkbox"/> Other <div style="font-size: 2em; text-align: center;">DNI</div>
TOP OF DAM	<input type="checkbox"/> 1. None <input type="checkbox"/> 11. Cracks <input type="checkbox"/> 2. Trees <input type="checkbox"/> 12. Spalling <input type="checkbox"/> 3. High bushes <input type="checkbox"/> 13. Deteriorated joints <input type="checkbox"/> 4. Burrows <input type="checkbox"/> 14. Displaced joints <input type="checkbox"/> 5. Ruts <input type="checkbox"/> 15. Exposed reinforcement <input type="checkbox"/> 6. Livestock damage <input type="checkbox"/> 16. Other <input type="checkbox"/> 7. Depressions <input type="checkbox"/> 8. Uneven <input type="checkbox"/> 9. Misalignment <input type="checkbox"/> 10. Has overtopped	COVER: <input type="checkbox"/> Vegetation <input type="checkbox"/> Gravel <input type="checkbox"/> Concrete <input type="checkbox"/> Asphalt <input type="checkbox"/> Other <div style="font-size: 2em; text-align: center;">DNI</div>
DOWNSTREAM SLOPE / FACE	<input type="checkbox"/> 1. None <input type="checkbox"/> 11. Seepage <input type="checkbox"/> 2. Trees <input type="checkbox"/> 12. Bolls <input type="checkbox"/> 3. High bushes <input type="checkbox"/> 13. Cracks <input type="checkbox"/> 4. Burrows <input type="checkbox"/> 14. Holes <input type="checkbox"/> 5. Erosion <input type="checkbox"/> 15. Spalling <input type="checkbox"/> 6. Livestock damage <input type="checkbox"/> 16. Displaced joints <input type="checkbox"/> 7. Slides <input type="checkbox"/> 17. Deteriorated joints <input type="checkbox"/> 8. Depressions <input type="checkbox"/> 18. Exposed reinforcement <input type="checkbox"/> 9. Bulges <input type="checkbox"/> 19. Other <input type="checkbox"/> 10. Wetness	COVER: <input type="checkbox"/> Vegetation <input type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Other <div style="font-size: 1.2em;">2 areas of depression noted in 2/19/2014 inspection. No wetness observed in the area, erosion (surface) observed. Should be monitored</div> <div style="text-align: center;">  </div>
TOE CORNERS	<input type="checkbox"/> 1. None <input type="checkbox"/> 11. Seepage <input type="checkbox"/> 2. Trees <input type="checkbox"/> 12. Bolls <input type="checkbox"/> 3. High bushes <input type="checkbox"/> 13. Cracks <input type="checkbox"/> 4. Burrows <input type="checkbox"/> 14. Holes <input type="checkbox"/> 5. Erosion <input type="checkbox"/> 15. Spalling <input type="checkbox"/> 6. Livestock damage <input type="checkbox"/> 16. Displaced joints <input type="checkbox"/> 7. Slides <input type="checkbox"/> 17. Deteriorated joints <input type="checkbox"/> 8. Depressions <input type="checkbox"/> 18. Exposed reinforcement <input type="checkbox"/> 9. Bulges <input type="checkbox"/> 19. Undermining <input type="checkbox"/> 10. Wetness <input type="checkbox"/> 20. Other	COVER: <input type="checkbox"/> Vegetation <input type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Other <div style="font-size: 2em; text-align: center;">DNI</div>

AREA	PROBLEMS	COMMENTS
ADJUTMENT CONTACTS	<input type="checkbox"/> 1. None <input type="checkbox"/> 2. Trees <input type="checkbox"/> 3. High bushes <input type="checkbox"/> 4. Burrows <input type="checkbox"/> 5. Erosion <input type="checkbox"/> 6. Livestock damage <input type="checkbox"/> 7. Slides <input type="checkbox"/> 8. Depressions <input type="checkbox"/> 9. Bulges <input type="checkbox"/> 10. Wetness <input type="checkbox"/> 11. Seepage <input type="checkbox"/> 12. Boils <input type="checkbox"/> 13. Cracks <input type="checkbox"/> 14. Holes <input type="checkbox"/> 15. Spalling <input type="checkbox"/> 16. Displaced joints <input type="checkbox"/> 17. Deteriorated joints <input type="checkbox"/> 18. Exposed reinforcement <input type="checkbox"/> 19. Undermining <input type="checkbox"/> 20. Other	COVER: <input type="checkbox"/> Vegetation <input type="checkbox"/> Rip rap <input type="checkbox"/> Concrete <input type="checkbox"/> Other DNI
PRINCIPAL SPILLWAY	<input type="checkbox"/> 1. None <input type="checkbox"/> 2. No trashguard <input type="checkbox"/> 3. Obstructed <input type="checkbox"/> 4. Plugged <input type="checkbox"/> 5. Rusted <input type="checkbox"/> 6. Damaged <input type="checkbox"/> 7. Gates leaking <input type="checkbox"/> 8. Joints leaking <input type="checkbox"/> 9. Cracks <input type="checkbox"/> 10. Joint deterioration <input type="checkbox"/> 11. Joint displacement <input type="checkbox"/> 12. Undermined <input type="checkbox"/> 13. Voids <input type="checkbox"/> 14. Erosion <input type="checkbox"/> 15. Holes <input type="checkbox"/> 16. Conduit collapsed <input type="checkbox"/> 17. Spalling <input type="checkbox"/> 18. Outlet undercutting <input type="checkbox"/> 19. Misalignment <input type="checkbox"/> 20. Other	TYPE/SIZE: Cast in place concrete riser with 30" CMP barrel DNI
EMERGENCY SPILLWAY	<input type="checkbox"/> 1. None <input type="checkbox"/> 2. No ES <input type="checkbox"/> 3. Same as PS <input type="checkbox"/> 4. Obstructed <input type="checkbox"/> 5. Erosion <input type="checkbox"/> 6. Displaced rip rap <input type="checkbox"/> 7. Sparse rip rap <input type="checkbox"/> 8. Joints leaking <input type="checkbox"/> 9. Cracks <input type="checkbox"/> 10. Joint deterioration <input type="checkbox"/> 11. Joint displacement <input type="checkbox"/> 12. Undermining <input type="checkbox"/> 13. Voids <input type="checkbox"/> 14. Holes <input type="checkbox"/> 15. Exposed reinforcement <input type="checkbox"/> 16. Spalling <input type="checkbox"/> 17. Outlet erosion <input type="checkbox"/> 18. Misalignment <input type="checkbox"/> 19. Inadequate capacity <input type="checkbox"/> 20. Other	TYPE/SIZE: Same as 1 DNI
DRAINS / OTHER OUTLETS	<input type="checkbox"/> 1. None <input type="checkbox"/> 2. No bottom drain <input type="checkbox"/> 3. Bottom drain inoperable <input type="checkbox"/> 4. Subsurface drain dry <input type="checkbox"/> 5. Subsurface drain muddy flow <input type="checkbox"/> 6. Subsurface drain obstructed <input type="checkbox"/> 7. No animal guard <input type="checkbox"/> 8. Other	TYPE: DNI

SKETCHES/COMMENTS