

Before redevelopment, the soccer field was undulating.



Basically the same view as the previous photo, after the surface has been smoothed and re-vegetated.



This is the way the ballfield looked prior to redevelopment; minimal seating and fencing around the uneven field. The infield and spectator areas were very basic.



After redevelopment, the ball field has been upgraded. This photo also taken looking north, as was the previous photo.



Another photo of the finished ballfield area.



A sign and landscaping in front of the new fence surrounding the recreational fields.



Passive methane vents were installed; final plans include vegetation and other protection around these pipes.

