

## North Carolina Department of Environment and Natural Resources

Pat McCrory Governor John E. Skvarla, III Secretary

August 6, 2014

## NOTICE OF DEFICIENCY

CERTIFIED MAIL
RETURN RECEIPT REQUESTED
7014 0150 0000 7802 4720

Duke Energy Progress, Inc. ATTN: Mr. John Elnitsky, Vice President 550 South Tryon Street Charlotte, North Carolina 28201-1007

RE: H. F. Lee Ash Pond

WAYNE-022 Wayne County Neuse River Basin

Dear Sir:

The "Dam Safety Law of 1967" provides for the certification and inspection of dams in the interest of public health, safety, and welfare, in order to reduce the risk of failure of such dams; to prevent injuries to persons, damage to property; and to insure the maintenance of stream flows. Our records indicate Duke Energy Progress, Inc. is the owner of the referenced high hazard dam. This dam is listed in the "High Hazard" category because sudden failure of the dam could result in serious property damage, and possible loss of life.

On August 1, 2014, this office received a copy of the July 25, 2014 engineering report and recommendations prepared by AMEC Environment and Infrastructure, Inc. for the riser and outlet pipe for the referenced structure. This report was requested in a Notice of Inspection dated June 26, 2014. The report concluded that the pipe was in reasonably good condition. However, there was some minor corrosion in portions of the steel pipe and some exposed gaskets and "slightly misaligned joints large enough for tree roots to penetrate" within the concrete pipes. It was their recommendation that the riser and outlet pipe be lined with appropriate lining materials.

It is requested that by October 13, 2014 you prepare a repair plan for this facility that addresses the recommendations provided by your consultant and submit two copies of the plan to the Land Quality Section Central Office. The repair plans at minimum must include: (A.) Construction drawings depicting plan layout, profile and necessary construction details in

**CERTIFIED MAIL** 

Duke Energy Progress, Inc.

ATTN: Mr. John Elnitsky, Vice President

August 6, 2014

Page 2

accordance with 15A NCAC 2K .0201 (b) (2); (B.) Construction specifications in accordance with 15A NCAC 2K .0201 (e) (4), (5), and (6); and, (C.) An Engineer's Report addressing any calculations necessary to support the repair design in general compliance with 15A NCAC 2K .0201.

Please advise this office of your intended action in this matter. If positive action is not taken on or before October 13, 2014, your case will be referred for appropriate enforcement action. Enforcement could include a civil penalty of up to \$500.00 per day of violation, and/or issuance of a Dam Safety Order requiring the repair or removal of this dam, and/or injunctive relief to gain compliance.

Should you have any questions, please contact me at 252-946-6481.

Sincerely

Patrick H. McClain, P.E.

Regional Supervisor

:pm

CC:

David May, PG, Water Resources Regional Supervisor Mr. Steve McEvoy, PE, State Dam Safety Engineer

LQ Files