used as a mulch anchoring tool. Maintenance Maintenance Maintenance		used as a mulch anchoring tool. Maintenance Refertilize if growth is not fully adequa	ID EARLY SPRING Rate (Ib/acre) 120 50 of temporary cover is not to - May 15 May 1 w by tacking with asphalt, netting, blades set nearly straight can be te. Reseed, refertilize and mulch	Seeding Mixture Species German millet In the Piedmont and Mountains, a substituted at a rate of 50 lb/acre. Seeding Dates Mountains — May 15 - Aug. 15 Piedmont — May 1 - Aug. 15 Coastal Plain — Apr. 15 - Aug. 15 Mulch Apply 4,000 lb/acre straw. Anchor netting, or a mulch anchoring tool. straight can be used as a mulch an Maintenance Refertilize if growth is not fully ade	straw by tacking with asphalt, A disk with blades set nearly nchoring tool. equate. Reseed, refertilize and mulch	
---	--	--	--	---	--	--

SEED BED PREPARATION:

LIMING- Apply lime according to soil test recommendations. If the pH (acidity) of the soil is not known, an application of ground agricultural limestone at the rate of $1-1\frac{1}{2}$ tons/acre on coarse-textured soils and 2-3 tons/acre on fine-textured soils is usually sufficient. Apply limestone uniformly and incorporate into the top 4-6 inches of soil. Soils with a pH of 6 or higher need not be limed.

FERTILIZER- Base application rates on soil tests. When these are not possible, apply a 10-10-10 grade fertilizer at 700 - 1,000 lb/acre. Both fertilizer and lime should be incorporated into the top 4-6 inches of soil. If a hydraulic seeder is used, do not mix seed and fertilizer more than 30 minutes before application. SURFACE ROUGHENING- If recent tillage operations have resulted in a loose surface additional roughening may not be required, except to break up large clods. If rainfall causes the surface to become sealed or crusted, loosen it just prior to seeding by raking, harrowing, or other suitable methods for fine grading. The finished grade shall be a smooth even soil surface with a loosen uniformly fine texture. All ridges and depressions shall be removed and filled to provide the approved surface drainage. Planting is to be done immediately after finished grades are obtained and seedbed preparation is completed.



TEMPORARY SEEDING

PAGE:

RARY SEEDING RECOMMENDATIONS FOR FALL xture

Rate (lb/acre) 120

Aug. 15 - Dec. 15 and Piedmont — Aug. 15 - Dec. 31

acre straw. Anchor straw by tacking with asphalt, ulch anchoring tool. A disk with blades set nearly used as a mulch anchoring tool.

ertilize damaged areas immediately. Topdress with 50 gen in March. If it is necessary to extend temporary June 15, overseed with 50 lb/acre Kobe (Piedmont and or Korean (Mountains) lespedeza in late February or

Effective Date: 9/1/2023	3
In accordance with the 2013	
Design Manual Updates	;
	_