## Underground Storage Tanks (USTs) Public Record - Summary Information

## **General Information**

Dublic	Dagard	Dootod	Data
Public	Record	Posted	Date:

To:

10/1/2022

Total Number Of Active UST Facilities: 7,245

Total Number Of USTs: 23,497

**Summary Information For On-Site Inspections** 

Number Of UST Facilities Inspected: 3,443

Inspection Period Dates: 10/1/2021

Percent Compliance (Combined Measure): 58%

**Summary Information For Releases** 

Number Of Confirmed UST Releases: 243

Release Reporting Period Dates 10/1/2021 To: 10/1/2022

**Summary Information For Release Sources And Causes** 

			Cause													
Source		Spill		Overfill		Corrosion		Phys/Mech Damage		Install Problem		Other		Unknown		
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	114	47	0	0%	2	2%	15	10%	16	14%	0	0%	6	6%	75	68%
Piping	29	12	0	0%	0	0%	0	0%	19	66%	0	0%	0	0%	10	34%
Dispenser	37	15	2	5%	0	0%	1	2%	7	19%	0	0%	2	5%	25	69%
STP**	0	0	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%
Delivery																
Problem	2	1	1	50%	0	0%	0	0%	0	0%	0	0%	0	0%	1	50%
Other	27	11	2	6%	0	0%	2	6%	5	19%	0	0%	12	45%	6	24%
Unknown	34	14	0	0%	0	0%	0	0%	2	7%	0	0%	32	93%	0	0%
Totals	243	100	5	4%	2	0%	18	9%	49	37%	0	0%	52	13%	117	37%

<sup>\*</sup>Additionally, there were 261 confirmed releases from non-regulated USTs, primarily heating oil tanks. There are also 258 confirmed releases from non-usts during the reporting period.

To obtain site-specific information on UST releases contact the Regional DEQ Office for the county in which the release occurred. To obtain UST compliance information contact the UST Section Central Office, Permits and Inspection Branch

<sup>\*\*</sup>STP - Submersible Turbine Pump