UST Service Provider List (All) - Corrosion Protection Companies Only

Company	Listing Submitted	10/25/2026	Area of state conducts work
Bay Compliance and Testing LLC 315 Great Bridge Blvd. (Unit B) Chesapeake, VA 23320-	**Phone** (757) 410-5974 **Fax** **Website** https://baycomplianceandtesting.com		**Coastal (East of I-95):** Yes **Central (West of I-95 and East of I-77):** No **Mountains (West of I-77):** No

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	**Yes**	Overfill Prevention Equipment Operability Check:	**Yes**
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	**Yes**
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	**Yes**
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	**Yes**	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	Dri-Sump
Line Tightness Testing:	**Yes**		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	**Yes**
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

Company	Listing Submitted	10/27/2026	Area of state conducts work
Bunnell Lammons Engineering, Inc. 30 Park Ridge Drive Fletcher, NC 28732-	**Phone** (828) 277-0100 **Fax** **Website** www.blecorp.com		**Coastal (East of I-95):** No **Central (West of I-95 and East of I-77):** Yes **Mountains (West of I-77):** Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	**Yes**	Overfill Prevention Equipment Operability Check:	**Yes**
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	**Yes**
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	**Yes**
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	**Yes**
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	**Yes**
Leak Detection Equipment Operability Check:	**Yes**	UST Internal Lining Inspections:	**Yes**
Leak Detection Monitoring Services:	**Yes**	Other:	
Line Tightness Testing:	**Yes**		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	**Yes**
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	**Yes**
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	**Yes**	Other:	
Soil and Water Testing Lab:	**Yes**		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (All) - Corrosion Protection Companies Only

Company — **Listing Submitted** 11/14/2026

Conklin Corrosion Control LLC
118 Oak Point Lane
Stony Point, NC 28678

Phone (704) 560-9154
Fax
Website

Area of state conducts work

Coastal (East of I-95): Yes
Central (West of I-95 and East of I-77): Yes
Mountains (West of I-77): Yes

Compliance Testing and Monitoring

Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	**Yes**	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	**Yes**	Tank Tightness Testing:	No
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms

Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors

Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

Company — **Listing Submitted** 5/14/2024

Environmental Petroleum Services
1234 Gordon Park Rd
Augusta, GA 30901

Phone (877) 297-6763
Fax
Website www.keepmecompliant.net

Area of state conducts work

Coastal (East of I-95): No
Central (West of I-95 and East of I-77): Yes
Mountains (West of I-77): Yes

Compliance Testing and Monitoring

Automatic Line Leak Detector Testing:	**Yes**	Overfill Prevention Equipment Operability Check:	**Yes**
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	**Yes**	Spill Prevention Equipment Testing:	**Yes**
Corrosion Protection System Repairs:	**Yes**	Tank Tightness Testing:	**Yes**
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	**Yes**	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	**Yes**		

Environmental Service Firms

Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors

Dispenser Meter Repair/Calibration:	**Yes**
Leak Detection Equipment Installation Servicing:	**Yes**
Spill Bucket Installation Repair:	**Yes**
UST Equipment Installation - Other:	**Yes**
UST Equipment Repair:	**Yes**
UST System Installation - Complete Systems:	**Yes**
UST Piping/Sump Installation:	**Yes**
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (All) - Corrosion Protection Companies Only

Company	Listing Submitted	10/20/2026	Area of state conducts work
JBL Solutions Inc. 418 W. State St. Black Mountain, North Carolina 28711-	**Phone** (603) 690-9071 **Fax** **Website** JBLsolutionsinc.com		**Coastal (East of I-95):** Yes **Central (West of I-95 and East of I-77):** Yes **Mountains (West of I-77):** Yes

Compliance Testing and Monitoring				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	**Yes**	Overfill Prevention Equipment Operability Check:	**Yes**	Dispenser Meter Repair/Calibration:	**Yes**
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	**Yes**	Leak Detection Equipment Installation Servicing:	**Yes**
Corrosion Protection Design Experts:	**Yes**	Spill Prevention Equipment Testing:	**Yes**	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	**Yes**	Tank Tightness Testing:	**Yes**	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	**Yes**	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	**Yes**			UST System Removal:	No
				Other:	

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

Company	Listing Submitted	10/23/2026	Area of state conducts work
OWL Services USA 1815 Gallagher Road Plymouth Meeting, PA 19462-	**Phone** (800) 646-3161 **Fax** (610) 278-7621 **Website** www.owlservices.com		**Coastal (East of I-95):** Yes **Central (West of I-95 and East of I-77):** Yes **Mountains (West of I-77):** Yes

Compliance Testing and Monitoring				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	**Yes**	Overfill Prevention Equipment Operability Check:	**Yes**	Dispenser Meter Repair/Calibration:	**Yes**
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	**Yes**	Leak Detection Equipment Installation Servicing:	**Yes**
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	**Yes**	Spill Bucket Installation Repair:	**Yes**
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	**Yes**	UST Equipment Installation - Other:	**Yes**
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	**Yes**
Leak Detection Equipment Operability Check:	**Yes**	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	**Yes**
Leak Detection Monitoring Services:	**Yes**	Other:		UST Piping/Sump Installation:	**Yes**
Line Tightness Testing:	**Yes**			UST System Removal:	**Yes**
				Other:	

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	**Yes**
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (All) - Corrosion Protection Companies Only

Company | **Listing Submitted** 10/26/2026 | **Area of state conducts work**

PetroTest, Inc
7 Dawn Road
Benson, NC 27504-

Phone (919) 874-5843
Fax
Website https://petrotest.net/

Coastal (East of I-95): Yes
Central (West of I-95 and East of I-77): Yes
Mountains (West of I-77): Yes

Compliance Testing and Monitoring

Automatic Line Leak Detector Testing:	**Yes**	Overfill Prevention Equipment Operability Check:	**Yes**
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	**Yes**
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	**Yes**
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	**Yes**
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	**Yes**	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	**Yes**	Other:	Secondary Line and Tank Testing.
Line Tightness Testing:	**Yes**		

Environmental Service Firms

Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	No	Other:	Water removal from UST Sumps and UDCs.
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors

Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	**Yes**
Spill Bucket Installation Repair:	**Yes**
UST Equipment Installation - Other:	**Yes**
UST Equipment Repair:	**Yes**
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	ATG/ Fill Riser replacements.

Company | **Listing Submitted** 10/23/2026 | **Area of state conducts work**

Rick Rogers Consulting LLC
2764 Pleasant Rd. #405
Fort Mill, SC 29708-

Phone (803) 280-0741
Fax
Website

Coastal (East of I-95): Yes
Central (West of I-95 and East of I-77): Yes
Mountains (West of I-77): Yes

Compliance Testing and Monitoring

Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	**Yes**	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	**Yes**	Tank Tightness Testing:	No
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms

Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors

Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.