

## UST Service Provider List (All) - Corrosion Protection Companies Only

Company	Listing Submitted	10/14/2025	Area of state conducts work
<b>Bay Compliance and Testing LLC</b> 315 Great Bridge Boulevard, Unit B Chesapeake, VA 23320	<b>Phone</b> (757) 410-5974  <b>Fax</b>  <b>Website</b> <a href="https://baycomplianceandtesting.com">https://baycomplianceandtesting.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> No <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	10/13/2025	Area of state conducts work
<b>Bunnell-Lammons Engineering (BLE)</b> 6004 Ponders Court Greenville, SC 29615	<b>Phone</b> (864) 288-1265  <b>Fax</b>  <b>Website</b> <a href="https://www.blecorp.com/">https://www.blecorp.com/</a>		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other:		

## UST Service Provider List (All) - Corrosion Protection Companies Only

Company	Listing Submitted	10/16/2025	Area of state conducts work
<b>Bunnell-Lammons Engineering (BLE)</b> 6004 Ponders Court Greenville, SC 29615	<b>Phone</b> (864) 288-1265  <b>Fax</b>  <b>Website</b> <a href="https://www.blecorp.com/">https://www.blecorp.com/</a>		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other:		
Company	Listing Submitted	11/1/2023	Area of state conducts work
<b>Cathodic Protection Services, Inc.</b> 916 Egypt Rd. Bluff City, NC 37618	<b>Phone</b> (423) 895-1500  <b>Fax</b>  <b>Website</b>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All) - Corrosion Protection Companies Only

Company	Listing Submitted			Area of state conducts work
<b>Conklin Corrosion Control LLC</b> 118 Oak Point Lane Stony Point, NC 28678	<b>Listing Submitted</b> 11/21/2023	<b>Phone</b> (704) 560-9154  <b>Fax</b>  <b>Website</b> <a href="mailto:benconklincc@gmail.com">benconklincc@gmail.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:	
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			
Company	Listing Submitted			Area of state conducts work
<b>EIS Holding, LLC.</b> 5621 Departure Drive Suite 101 Raleigh, NC 27616	<b>Listing Submitted</b> 6/30/2025	<b>Phone</b> (984) 284-5571  <b>Fax</b>  <b>Website</b> <a href="http://www.eisholdings.com">www.eisholdings.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: <b>Yes</b> Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: <b>Yes</b> Other:		Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:	
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other:			

## UST Service Provider List (All) - Corrosion Protection Companies Only

Company	Listing Submitted	10/27/2025	Area of state conducts work
<b>Environmental Laboratories, INC</b> 15 Sulphur Springs Rd Greenville, SC 29617  <b>Phone</b> (864) 370-0637 <b>Fax</b> <b>Website</b> <a href="https://www.elabsinc.net/">https://www.elabsinc.net/</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b>	Dispenser Meter Repair/Calibration: <b>Yes</b>	Leak Detection Equipment Installation Servicing: <b>Yes</b>
Containment Sump Testing: <b>Yes</b>	Statistical Inventory Reconciliation Services: <b>Yes</b>	Spill Bucket Installation Repair: <b>Yes</b>	UST Equipment Installation - Other: No
Corrosion Protection Design Experts: <b>Yes</b>	Spill Prevention Equipment Testing: <b>Yes</b>	UST Equipment Repair: <b>Yes</b>	UST System Installation - Complete Systems: No
Corrosion Protection System Repairs: <b>Yes</b>	Tank Tightness Testing: <b>Yes</b>	UST Piping/Sump Installation: <b>Yes</b>	UST System Removal: <b>Yes</b>
Corrosion Protection System Testing: <b>Yes</b>	UST Internal Inspections (Integrity Assessments): <b>Yes</b>	Other: <b>Yes</b>	
Leak Detection Equipment Operability Check: <b>Yes</b>	UST Internal Lining Inspections: <b>Yes</b>		
Leak Detection Monitoring Services: <b>Yes</b>	Other: <b>Yes</b>		
Line Tightness Testing: <b>Yes</b>			
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b>		
Environmental Engineer/Geologist - Site Checks: No	UST Equipment Verification: <b>Yes</b>		
Environmental Engineer/Geologist Soil and GW Cleanu: No	Waste Disposal and Treatment: <b>Yes</b>		
Oil and Solvent Recycling: No	Other: <b>Yes</b>		
Soil and Water Testing Lab: <b>Yes</b>			
Company	Listing Submitted	5/14/2024	Area of state conducts work
<b>Environmental Petroleum Services</b> 1234 Gordon Park Rd Augusta, GA 30901  <b>Phone</b> (877) 297-6763 <b>Fax</b> <b>Website</b> <a href="http://www.keepmecompliant.net">www.keepmecompliant.net</a>			<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b>	Dispenser Meter Repair/Calibration: <b>Yes</b>	Leak Detection Equipment Installation Servicing: <b>Yes</b>
Containment Sump Testing: <b>Yes</b>	Statistical Inventory Reconciliation Services: No	Spill Bucket Installation Repair: <b>Yes</b>	UST Equipment Installation - Other: <b>Yes</b>
Corrosion Protection Design Experts: <b>Yes</b>	Spill Prevention Equipment Testing: <b>Yes</b>	UST Equipment Repair: <b>Yes</b>	UST System Installation - Complete Systems: <b>Yes</b>
Corrosion Protection System Repairs: <b>Yes</b>	Tank Tightness Testing: <b>Yes</b>	UST Piping/Sump Installation: <b>Yes</b>	UST System Removal: <b>Yes</b>
Corrosion Protection System Testing: <b>Yes</b>	UST Internal Inspections (Integrity Assessments): No	Other: <b>Yes</b>	
Leak Detection Equipment Operability Check: <b>Yes</b>	UST Internal Lining Inspections: No		
Leak Detection Monitoring Services: No	Other: <b>Yes</b>		
Line Tightness Testing: <b>Yes</b>			
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No	UST Compliance Consultants: No		
Environmental Engineer/Geologist - Site Checks: No	UST Equipment Verification: No		
Environmental Engineer/Geologist Soil and GW Cleanu: No	Waste Disposal and Treatment: No		
Oil and Solvent Recycling: No	Other: <b>Yes</b>		
Soil and Water Testing Lab: No			

## UST Service Provider List (All) - Corrosion Protection Companies Only

Company	Listing Submitted	10/14/2025	Area of state conducts work
<b>OWL Services USA</b> 1815 Gallagher Road Plymouth Meeting, PA 19462	<b>Phone</b> (610) 633-9732 <b>Fax</b> (610) 278-7621 <b>Website</b> <a href="http://www.owlservices.com">www.owlservices.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: <b>Yes</b> Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	10/14/2025	Area of state conducts work
<b>Rick Rogers Consulting, LLC.</b> 2764 Pleasant Road #405 Fort Mill, SC 29708	<b>Phone</b> (803) 280-0741 <b>Fax</b> <b>Website</b>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All) - Corrosion Protection Companies Only

Company	Listing Submitted	12/12/2025	Area of state conducts work
<b>SPATCO Energy Solutions</b> 301 McCullough Dr Suite 500 Charlotte, NC 28262	<b>Phone</b> (800) 477-8286  <b>Fax</b>  <b>Website</b> <a href="http://spatco.com">spatco.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b><u>Yes</u></b> Containment Sump Testing: <b><u>Yes</u></b> Corrosion Protection Design Experts: <b><u>Yes</u></b> Corrosion Protection System Repairs: <b><u>Yes</u></b> Corrosion Protection System Testing: <b><u>Yes</u></b> Leak Detection Equipment Operability Check: <b><u>Yes</u></b> Leak Detection Monitoring Services: <b><u>Yes</u></b> Line Tightness Testing: <b><u>Yes</u></b>	Overfill Prevention Equipment Operability Check: <b><u>Yes</u></b> Statistical Inventory Reconciliation Services: <b><u>Yes</u></b> Spill Prevention Equipment Testing: <b><u>Yes</u></b> Tank Tightness Testing: <b><u>Yes</u></b> UST Internal Inspections (Integrity Assessments): <b><u>Yes</u></b> UST Internal Lining Inspections: <b><u>Yes</u></b> Other:		Dispenser Meter Repair/Calibration: <b><u>Yes</u></b> Leak Detection Equipment Installation Servicing: <b><u>Yes</u></b> Spill Bucket Installation Repair: <b><u>Yes</u></b> UST Equipment Installation - Other: <b><u>Yes</u></b> UST Equipment Repair: <b><u>Yes</u></b> UST System Installation - Complete Systems: <b><u>Yes</u></b> UST Piping/Sump Installation: <b><u>Yes</u></b> UST System Removal: <b><u>Yes</u></b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b><u>Yes</u></b> Environmental Engineer/Geologist - Site Checks: <b><u>Yes</u></b> Environmental Engineer/Geologist Soil and GW Cleanu: <b><u>Yes</u></b> Oil and Solvent Recycling: <b><u>Yes</u></b> Soil and Water Testing Lab: <b><u>Yes</u></b>	UST Compliance Consultants: <b><u>Yes</u></b> UST Equipment Verification: <b><u>Yes</u></b> Waste Disposal and Treatment: <b><u>Yes</u></b> Other:		