

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	1/18/2024	Area of state conducts work		
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Phone (336) 282-3586 Fax (336) 282-3587 Website AdadvancedEnvironmental.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes		
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted	6/26/2024	Area of state conducts work		
BUCKEYE ELM CONTRACTING, LLC PO Box 1026 MOCKSVILLE, NC 27028 Phone (336) 337-6001 Fax Website www.buckeye-elm.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes		
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	1/10/2022	Area of state conducts work
Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704	Phone (828) 277-0100 Fax (828) 277-0110 Website www.blecorp.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: Yes Corrosion Protection System Repairs: Yes Corrosion Protection System Testing: Yes Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: Yes Line Tightness Testing: Yes	Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: Yes Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): Yes UST Internal Lining Inspections: Yes Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: Yes Other: Trust Fund Projects		
Company	Listing Submitted	5/18/2022	Area of state conducts work
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451	Phone (910) 383-1044 Fax Website www.capefearengineering.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:		

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	5/18/2022	Area of state conducts work
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451	Phone (910) 383-1044 Fax Website www.capefearengineering.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
			Dispenser Meter Repair/Calibration: No
			Leak Detection Equipment Installation Servicing: No
			Spill Bucket Installation Repair: No
			UST Equipment Installation - Other: No
			UST Equipment Repair: No
			UST System Installation - Complete Systems: No
			UST Piping/Sump Installation: No
			UST System Removal: No
			Other:
Company	Listing Submitted	4/5/2023	Area of state conducts work
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405	Phone (910) 452-5861 Fax Website www.CatlinUSA.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
			Dispenser Meter Repair/Calibration: No
			Leak Detection Equipment Installation Servicing: No
			Spill Bucket Installation Repair: No
			UST Equipment Installation - Other: No
			UST Equipment Repair: No
			UST System Installation - Complete Systems: No
			UST Piping/Sump Installation: No
			UST System Removal: <u>Yes</u>
			Other:

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	4/5/2023	Area of state conducts work
CDG, Inc. 4301 Taggart Creek Road Charlotte, NC 28208	Phone (704) 394-6913 Fax Website www.cdge.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <u>Yes</u> Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu: <u>Yes</u> Oil and Solvent Recycling: <u>Yes</u> Soil and Water Testing Lab: <u>Yes</u>	UST Compliance Consultants: <u>Yes</u> UST Equipment Verification: <u>Yes</u> Waste Disposal and Treatment: <u>Yes</u> Other:		
Company	Listing Submitted	1/20/2022	Area of state conducts work
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606	Phone (919) 233-8626 Fax Website WWW.COHESION-INC.COM		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <u>Yes</u> Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: <u>Yes</u>	UST Compliance Consultants: <u>Yes</u> UST Equipment Verification: No Waste Disposal and Treatment: No Other: QED MOBILE LAB TPH - SOIL		

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	12/30/2021	Area of state conducts work
Crompco, LLC 1815 Gallagher Road Plymouth Meeting, PA 19462 Phone (610) 278-7203 Fax (610) 278-7621 Website www.crompco.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	Yes	Other:	
Line Tightness Testing:	Yes		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	9/28/2022	Area of state conducts work
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Phone (336) 214-9012 Fax Website www.dhgriffin.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes
Oil and Solvent Recycling:	Yes	Other:	Vacuum Truck Services
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	4/5/2023	Area of state conducts work
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603	Phone (919) 349-5969 Fax Website eastcoastenv.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: Yes UST Equipment Installation - Other: Yes UST Equipment Repair: Yes UST System Installation - Complete Systems: No UST Piping/Sump Installation: Yes UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	7/2/2024	Area of state conducts work
Environmental Hydrogeological Consultants, Inc. DB PO Box 902 Red Springs, NC 28377	Phone (910) 843-4456 Fax (910) 843-5376 Website www.environmentalinc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other: Liquid/Hydro Excavate Vac Truck Services
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: Yes Soil and Water Testing Lab: Yes	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other: OSRO Certified US Coast Guard Contractor		

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	1/4/2022	Area of state conducts work
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410	Phone (336) 763-6025 Fax Website envirotrac.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: Yes	UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	1/3/2022	Area of state conducts work
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107	Phone (336) 725-5844 Fax Website www.evocorp.net		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other: Vacuum Truck Services
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: Yes Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other: Transportation Services		

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	7/12/2023	Area of state conducts work
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Phone (704) 853-0800 Fax (704) 853-3949 Website www.excelengr.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	1/1/2022	Area of state conducts work
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Phone (303) 770-8884 Fax (303) 770-3636 Website www.Gallowayus.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	UST/AST System Design
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	UST/AST System Design
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	12/30/2021	Area of state conducts work
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208	Phone (704) 837-7174 Fax Website www.geohydro.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu: <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	1/3/2022	Area of state conducts work
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112	Phone (704) 845-4010 Fax (704) 845-4012 Website grienv.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <u>Yes</u> Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu: <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	11/16/2023	Area of state conducts work		
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834	Phone (252) 758-3310 Fax Website www.gma-nc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes		
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	Yes
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted	4/20/2023	Area of state conducts work		
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226	Phone (704) 553-2300 Fax (704) 553-2400 Website www.gtaeng.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No		
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	12/30/2021	Area of state conducts work
Highlands Environmental Solutions, Inc. 8410-d Falls of Neuse Raleigh, NC 27615	Phone (919) 848-3155 Fax Website www.HESfast.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	4/11/2023	Area of state conducts work
INENCO, Inc. 132 W. Statesville Avenue Mooresville, NC 27115	Phone (704) 662-8192 Fax (704) 662-8194 Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	5/15/2023	Area of state conducts work
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560 Phone (919) 744-4391 Fax Website jfpetrogroup.com/services/environmentalcompliance			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	Yes	Other:	
Line Tightness Testing:	Yes		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

Company	Listing Submitted	1/5/2022	Area of state conducts work
Johnson, Spellman & Associates, Inc. 350 Research Ct. Suite 130 Peachtree Corners, GA 30092 Phone (770) 447-4555 Fax Website			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Yes
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	Engineering- Design Services
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	Engineering-Design Services
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	12/20/2022	Area of state conducts work
Jones Covey Group 9595 Lucas Ranch Rd STE 100 Rancho Cucamonga, CA 91730 Phone (888) 972-7581 Fax (909) 484-0300 Website			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: Yes Corrosion Protection System Repairs: Yes Corrosion Protection System Testing: Yes Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: Yes Line Tightness Testing: Yes	Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: Yes Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): Yes UST Internal Lining Inspections: Yes Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: Yes UST Equipment Installation - Other: Yes UST Equipment Repair: Yes UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	8/10/2021	Area of state conducts work
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734 Phone 8286347741 Fax Website martinandslagle.com			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:		

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	1/31/2022	Area of state conducts work
McCallum, P.C. 1808 Hayward Avenue Chesapeake, VA 23320	Phone (757) 420-9252 Fax (757) 424-2874 Website www.mccallumtestinglabs.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	4/20/2023	Area of state conducts work
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732	Phone (904) 814-3680 Fax Website mgfenvironmental.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	9/8/2022	Area of state conducts work
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610 Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration:
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing:
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair:
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other:
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair:
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems:
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation:
Line Tightness Testing:	No		UST System Removal:
			Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	12/30/2021	Area of state conducts work
NCCPM 7300 glenwood ave. raleigh, NC 27612 Phone (919) 782-4411 Fax (919) 782-4414 Website www.ncpcm.org			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration:
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing:
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair:
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other:
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair:
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems:
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation:
Line Tightness Testing:	No		UST System Removal:
			Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	Engineering on UST Installations
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	7/2/2024	Area of state conducts work		
Paragon Environmental Consultants, Inc. P.O. Box 157 Thomasville, NC 27361 Phone (336) 669-6037 Fax (336) 476-7708 Website			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No		
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted	11/1/2023	Area of state conducts work		
Peak Hydrogeologic, PLLC 470 Hogback Mtn Rd Tryon, NC 28782 Phone (828) 817-5209 Fax Website https://peakhydrogeologic.com			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes		
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	12/30/2021	Area of state conducts work	
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037	Phone (704) 335-8801 Fax (704) 342-1672 Website www.petroleumequipment.net		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: Yes Line Tightness Testing: Yes	Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): Yes UST Internal Lining Inspections: Yes Other:		Dispenser Meter Repair/Calibration: Yes Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: Yes UST Equipment Installation - Other: Yes UST Equipment Repair: Yes UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST System Removal: Yes Other:	
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:			
Company	Listing Submitted	3/31/2022	Area of state conducts work	
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027	Phone (980) 781-1000 Fax Website www.petroleumtec.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: Tank Cleaning		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: Tank Cleaning	
Environmental Service Firms				
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other: Tank Cleaning			

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	11/1/2023	Area of state conducts work
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285	Phone (336) 870-3095 Fax (336) 310-4527 Website www.pilotenviro.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <u>Yes</u> Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu: <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <u>Yes</u> UST Equipment Verification: No Waste Disposal and Treatment: <u>Yes</u> Other:		
Company	Listing Submitted	10/12/2022	Area of state conducts work
Practical Environmental Solutions. PC 5634 Harvest Grove Ln Wilmington, NC 28409	Phone (910) 790-8265 Fax Website www.oil-tank.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu: <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: <u>Yes</u>	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	12/30/2021	Area of state conducts work
Precision Tank Service 737 Zimmer Road Fort Mill , SC 29707 Phone (704) 892-8600 Fax (704) 892-8711 Website www.precisiontankservice.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	Yes	Other:	
Line Tightness Testing:	Yes		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	1/3/2022	Area of state conducts work
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406 Phone (336) 335-3174 Fax (336) 691-0648 Website www.PyramidEnvironmental.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	Yes		

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	4/4/2023	Area of state conducts work
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526	Phone (704) 694-8359 Fax Website www.regionalenv.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation: No
Line Tightness Testing:	No		UST System Removal: No
Environmental Service Firms			Other:
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	<u>Yes</u>		
Company	Listing Submitted	12/30/2021	Area of state conducts work
Sensible Solutions Environmental, P. C. P. O. Box 3074 Chapel Hill, NC 27515	Phone (336) 263-0965 Fax Website www.sensible-solutions-environmental.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation: No
Line Tightness Testing:	No		UST System Removal: No
Environmental Service Firms			Other:
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	Residential USTs
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted	12/30/2021	Area of state conducts work
Singleton Environmental, Inc. PO Box 604 Fletcher, NC 28732	Phone (828) 508-4510 Fax Website singletonenvironmental.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	12/30/2021	Area of state conducts work
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302	Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	Yes		

UST Service Provider List (All) - Environmental Service Firms Only

Company	Listing Submitted		Area of state conducts work
Titan Environmental Group 2005 Citation Drive Garner, NC 27529	Phone (984) 200-6825 Fax Website www.titanenvirogroup.com	3/6/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration:
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing:
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair:
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other:
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair:
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems:
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation:
Line Tightness Testing:	No		UST System Removal:
			<u>Yes</u>
			Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>
Oil and Solvent Recycling:	<u>Yes</u>	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted		Area of state conducts work
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591	Phone (919) 469-3340 Fax Website www.withersravenel.com	11/1/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration:
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing:
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair:
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other:
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair:
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems:
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation:
Line Tightness Testing:	No		UST System Removal:
			<u>Yes</u>
			Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		