

UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted		Area of state conducts work	
Bay Compliance and Testing LLC 315 Great Bridge Boulevard, Unit B Chesapeake, VA 23320	Phone (757) 410-5974 Fax Website https://baycomplianceandtesting.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No	
Compliance Testing and Monitoring				
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overflow Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation: No
Line Tightness Testing:	<u>Yes</u>			UST System Removal: No
Environmental Service Firms				
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No	Other:
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	No			
Company	Listing Submitted		Area of state conducts work	
Bunnell-Lammons Engineering (BLE) 6004 Ponders Court Greenville, SC 29615	Phone (864) 288-1265 Fax Website https://www.blecorp.com/		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overflow Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation: No
Line Tightness Testing:	<u>Yes</u>			UST System Removal: Yes
Environmental Service Firms				
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>	Other:
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>	
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	<u>Yes</u>			

UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	10/16/2025	Area of state conducts work
Bunnell-Lammons Engineering (BLE) 6004 Ponders Court Greenville, SC 29615	Phone (864) 288-1265 Fax Website https://www.blecorp.com/		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:	
Line Tightness Testing:	<u>Yes</u>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	<u>Yes</u>		
Company	Listing Submitted	6/27/2024	Area of state conducts work
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802	Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenvy.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	6/30/2025	Area of state conducts work
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616	Phone (984) 284-5571 Fax Website www.eisholdings.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:	
Line Tightness Testing:	<u>Yes</u>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>
Oil and Solvent Recycling:	<u>Yes</u>	Other:	
Soil and Water Testing Lab:	<u>Yes</u>		
Company	Listing Submitted	10/27/2025	Area of state conducts work
Environmental Laboratories, INC 15 Sulphur Springs Rd Greenville, SC 29617	Phone (864) 370-0637 Fax Website https://www.elabsinc.net/		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:	
Line Tightness Testing:	<u>Yes</u>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	<u>Yes</u>		

UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	5/14/2024	Area of state conducts work
Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901	Phone (877) 297-6763 Fax Website www.keeptmecompliant.net		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	<u>Yes</u>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	12/12/2025	Area of state conducts work
JBL Solutions Inc. 806 Appii Rd Moncks Corner, SC 29461	Phone (603) 690-9071 Fax Website jblsolutionsinc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:	
Line Tightness Testing:	<u>Yes</u>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>
Oil and Solvent Recycling:	No	Other:	Filtration and Polishing
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	5/15/2023	Area of state conducts work
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560	Phone (919) 744-4391 Fax Website jfpetrogrou.com/services/environmentalcompliance		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:	
Line Tightness Testing:	<u>Yes</u>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	10/14/2025	Area of state conducts work
OWL Services USA 1815 Gallagher Road Plymouth Meeting, PA 19462	Phone (610) 633-9732 Fax (610) 278-7621 Website www.owlservices.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:	
Line Tightness Testing:	<u>Yes</u>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	12/12/2025	Area of state conducts work
SPATCO Energy Solutions 301 McCullough Dr Suite 500 Charlotte, NC 28262	Phone (800) 477-8286 Fax Website spatco.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overflow Prevention Equipment Operability Check:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:	
Line Tightness Testing:	<u>Yes</u>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>
Oil and Solvent Recycling:	<u>Yes</u>	Other:	
Soil and Water Testing Lab:	<u>Yes</u>		
UST Equipment Service Contractors			
Dispenser Meter Repair/Calibration:			<u>Yes</u>
Leak Detection Equipment Installation Servicing:			<u>Yes</u>
Spill Bucket Installation Repair:			<u>Yes</u>
UST Equipment Installation - Other:			<u>Yes</u>
UST Equipment Repair:			<u>Yes</u>
UST System Installation - Complete Systems:			<u>Yes</u>
UST Piping/Sump Installation:			<u>Yes</u>
UST System Removal:			
Other:			