

## UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	12/30/2021	Area of state conducts work
<b>Petroleum Equipment Service of Wilson, Inc.</b> PO Box 502 711 S. Goldsboro St. Wilson, NC 27893	<b>Phone</b> (252) 237-6047  <b>Fax</b> (252) 237-5507  <b>Website</b> <a href="http://www.peswilson.com">www.peswilson.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	12/30/2021	Area of state conducts work
<b>Bay Compliance and Testing LLC</b> P.O. Box 16628 Chesapeake, VA 23328	<b>Phone</b> (757) 410-5974  <b>Fax</b>  <b>Website</b> <a href="https://baycomplianceandtesting.com/">https://baycomplianceandtesting.com/</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> No <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: No Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	1/10/2022	Area of state conducts work
<b>Bunnell-Lammons Engineering, Inc.</b> 130 Oval Road Arden, NC 28704	<b>Phone</b> (828) 277-0100 <b>Fax</b> (828) 277-0110 <b>Website</b> <a href="http://www.blecorp.com">www.blecorp.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: <b>Yes</b> Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: <b>Yes</b> Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other: Trust Fund Projects		
Company	Listing Submitted	6/27/2024	Area of state conducts work
<b>Cobb Environmental &amp; Technical Services, Inc.</b> P. O. Box 1602 Tupelo, MS 38802	<b>Phone</b> (662) 841-0995 <b>Fax</b> (662) 841-0810 <b>Website</b> <a href="http://cobbenv.com">cobbenv.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: No UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	12/30/2021	Area of state conducts work
<b>Crompco, LLC</b> 1815 Gallagher Road Plymouth Meeting, PA 19462  <b>Phone</b> (610) 278-7203 <b>Fax</b> (610) 278-7621  <b>Website</b> <a href="http://www.crompco.com">www.crompco.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	<b>Yes</b>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<b>Yes</b>	Other:	
Line Tightness Testing:	<b>Yes</b>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<b>Yes</b>
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	9/24/2021	Area of state conducts work
<b>C-Store Services, Inc.</b> 7129 Hidden Valley Trail Garner, NC 27529  <b>Phone</b> (919) 662-0798 <b>Fax</b> (919) 662-0711  <b>Website</b>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	UST-27 monthly inspection
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

## UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	5/14/2024	Area of state conducts work
<b>Environmental Petroleum Services</b> 1234 Gordon Park Rd Augusta, GA 30901  <b>Phone</b> (877) 297-6763 <b>Fax</b> <b>Website</b> <a href="http://www.keepmecompliant.net">www.keepmecompliant.net</a>			<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: No Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	10/26/2021	Area of state conducts work
<b>Guardian Fueling Technologies</b> 5116 Departure Drive Raleigh, NC 27616  <b>Phone</b> (919) 729-6980 <b>Fax</b> (919) 769-2919 <b>Website</b> <a href="http://www.guardianfueltech.com">www.guardianfueltech.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: SafeGuard UST Inspection Services		Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: No Other: FuelGuard fuel polishing / tank cleaning
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All) - Leak Detection Testing Companies Only

<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>JF Petroleum Group</b> 100 Perimeter Park Drive Suite H Morrisville, NC 27560	<b>Phone</b> (919) 744-4391		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
	<b>Fax</b>		
	<b>Website</b> <a href="http://jfpetrogroup.com/services/environmentalcompliance">jfpetrogroup.com/services/environmentalcompliance</a>		
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<b>Yes</b>	Other:	
Line Tightness Testing:	<b>Yes</b>		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<b>Yes</b>
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>Johnson, Spellman &amp; Associates, Inc.</b> 350 Research Ct. Suite 130 Peachtree Corners, GA 30092	<b>Phone</b> (770) 447-4555		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
	<b>Fax</b>		
	<b>Website</b>		
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other: Engineering- Design Services	
Line Tightness Testing:	No		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<b>Yes</b>
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other: Engineering-Design Services	
Soil and Water Testing Lab:	No		
			Other: Engineering-Design Services

## UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	12/20/2022	Area of state conducts work
<b>Jones Covey Group</b> 9595 Lucas Ranch Rd STE 100 Rancho Cucamonga, CA 91730  <b>Phone</b> (888) 972-7581 <b>Fax</b> (909) 484-0300  <b>Website</b>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b>	Dispenser Meter Repair/Calibration: No	Leak Detection Equipment Installation Servicing: <b>Yes</b>
Containment Sump Testing: <b>Yes</b>	Statistical Inventory Reconciliation Services: <b>Yes</b>	Leak Detection Equipment Installation Servicing: <b>Yes</b>	Spill Bucket Installation Repair: <b>Yes</b>
Corrosion Protection Design Experts: <b>Yes</b>	Spill Prevention Equipment Testing: <b>Yes</b>	UST Equipment Installation - Other: <b>Yes</b>	UST Equipment Repair: <b>Yes</b>
Corrosion Protection System Repairs: <b>Yes</b>	Tank Tightness Testing: <b>Yes</b>	UST System Installation - Complete Systems: <b>Yes</b>	UST Piping/Sump Installation: <b>Yes</b>
Corrosion Protection System Testing: <b>Yes</b>	UST Internal Inspections (Integrity Assessments): <b>Yes</b>	UST System Removal: No	Other:
Leak Detection Equipment Operability Check: <b>Yes</b>	UST Internal Lining Inspections: <b>Yes</b>		
Leak Detection Monitoring Services: <b>Yes</b>	Other:		
Line Tightness Testing: <b>Yes</b>			
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No	UST Compliance Consultants: <b>Yes</b>		
Environmental Engineer/Geologist - Site Checks: No	UST Equipment Verification: <b>Yes</b>		
Environmental Engineer/Geologist Soil and GW Cleanu: No	Waste Disposal and Treatment: No		
Oil and Solvent Recycling: No	Other:		
Soil and Water Testing Lab: No			
Company	Listing Submitted	12/30/2021	Area of state conducts work
<b>Petroleum Equipment and Service, Inc.</b> 4125 Sinclair Street PO Box 1949 Denver, NC 28037  <b>Phone</b> (704) 335-8801 <b>Fax</b> (704) 342-1672  <b>Website</b> <a href="http://www.petroleumequipment.net">www.petroleumequipment.net</a>			<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b>	Dispenser Meter Repair/Calibration: <b>Yes</b>	Leak Detection Equipment Installation Servicing: <b>Yes</b>
Containment Sump Testing: <b>Yes</b>	Statistical Inventory Reconciliation Services: No	Leak Detection Equipment Installation Servicing: <b>Yes</b>	Spill Bucket Installation Repair: <b>Yes</b>
Corrosion Protection Design Experts: No	Spill Prevention Equipment Testing: <b>Yes</b>	UST Equipment Installation - Other: <b>Yes</b>	UST Equipment Repair: <b>Yes</b>
Corrosion Protection System Repairs: No	Tank Tightness Testing: <b>Yes</b>	UST System Installation - Complete Systems: <b>Yes</b>	UST Piping/Sump Installation: <b>Yes</b>
Corrosion Protection System Testing: No	UST Internal Inspections (Integrity Assessments): <b>Yes</b>	UST System Removal: <b>Yes</b>	Other:
Leak Detection Equipment Operability Check: <b>Yes</b>	UST Internal Lining Inspections: <b>Yes</b>		
Leak Detection Monitoring Services: <b>Yes</b>	Other:		
Line Tightness Testing: <b>Yes</b>			
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No	UST Compliance Consultants: No		
Environmental Engineer/Geologist - Site Checks: No	UST Equipment Verification: No		
Environmental Engineer/Geologist Soil and GW Cleanu: No	Waste Disposal and Treatment: <b>Yes</b>		
Oil and Solvent Recycling: No	Other:		
Soil and Water Testing Lab: No			

## UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	12/30/2021	Area of state conducts work
<b>Precision Tank Service</b> 737 Zimmer Road Fort Mill , SC 29707  <b>Phone</b> (704) 892-8600 <b>Fax</b> (704) 892-8711  <b>Website</b> <a href="http://www.precisiontankservice.com">www.precisiontankservice.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<b>Yes</b>	Other:	
Line Tightness Testing:	<b>Yes</b>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	12/30/2021	Area of state conducts work
<b>Superior Services</b> PO Box 982 Hendersonville, NC  <b>Phone</b> (828) 698-6286 <b>Fax</b> (828) 698-6294  <b>Website</b> <a href="http://www.superiorservices.com">www.superiorservices.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	<b>Yes</b>	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	<b>Yes</b>	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	<b>Yes</b>
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	<b>Yes</b>
Leak Detection Monitoring Services:	No	Other: repair and lining, AST Inspections, Repairs and Lining	
Line Tightness Testing:	<b>Yes</b>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

## UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	12/30/2021	Area of state conducts work
<b>Terraquest Environmental Consultants, P.C.</b> 100 E. Ruffin Street Mebane, NC 27302	<b>Phone</b> (919) 563-9091 <b>Fax</b> (919) 563-9095 <b>Website</b> <a href="http://www.terraquestpc.com">www.terraquestpc.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:		
Company	Listing Submitted	7/14/2022	Area of state conducts work
<b>VALLEY TANK TESTING</b> 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572	<b>Phone</b> (813) 671-9065 <b>Fax</b> (866) 328-9796 <b>Website</b> <a href="http://WWW.VALLEYTANK.COM">WWW.VALLEYTANK.COM</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		