UST Service Provider List (All) - Leak Detection Testing Companies Only

Company — **Listing Submitted** 6/27/2024

Cobb Environmental & Technical Services, Inc.
P. O. Box 1602
Tupelo, MS 38802

Phone (662) 841-0995
Fax (662) 841-0810
Website cobbenv.com

Area of state conducts work

Coastal (East of I-95): Yes
Central (West of I-95 and East of I-77): Yes
Mountains (West of I-77): Yes

Compliance Testing and Monitoring

Automatic Line Leak Detector Testing:	**Yes**	Overfill Prevention Equipment Operability Check:	**Yes**
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	**Yes**
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	**Yes**	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms

Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors

Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	**Yes**
Spill Bucket Installation Repair:	**Yes**
UST Equipment Installation - Other:	**Yes**
UST Equipment Repair:	No
UST System Installation - Complete Systems:	**Yes**
UST Piping/Sump Installation:	**Yes**
UST System Removal:	**Yes**
Other:	

Company — **Listing Submitted** 5/14/2024

Environmental Petroleum Services
1234 Gordon Park Rd
Augusta, GA 30901

Phone (877) 297-6763
Fax
Website www.keepmecompliant.net

Area of state conducts work

Coastal (East of I-95): No
Central (West of I-95 and East of I-77): Yes
Mountains (West of I-77): Yes

Compliance Testing and Monitoring

Automatic Line Leak Detector Testing:	**Yes**	Overfill Prevention Equipment Operability Check:	**Yes**
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	**Yes**	Spill Prevention Equipment Testing:	**Yes**
Corrosion Protection System Repairs:	**Yes**	Tank Tightness Testing:	**Yes**
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	**Yes**	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	**Yes**		

Environmental Service Firms

Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors

Dispenser Meter Repair/Calibration:	**Yes**
Leak Detection Equipment Installation Servicing:	**Yes**
Spill Bucket Installation Repair:	**Yes**
UST Equipment Installation - Other:	**Yes**
UST Equipment Repair:	**Yes**
UST System Installation - Complete Systems:	**Yes**
UST Piping/Sump Installation:	**Yes**
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.