

## UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	10/14/2025	Area of state conducts work
<b>Bay Compliance and Testing LLC</b> 315 Great Bridge Boulevard, Unit B Chesapeake, VA 23320	<b>Phone</b> (757) 410-5974  <b>Fax</b>  <b>Website</b> <a href="https://baycomplianceandtesting.com">https://baycomplianceandtesting.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> No <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	10/13/2025	Area of state conducts work
<b>Bunnell-Lammons Engineering (BLE)</b> 6004 Ponders Court Greenville, SC 29615	<b>Phone</b> (864) 288-1265  <b>Fax</b>  <b>Website</b> <a href="https://www.blecorp.com/">https://www.blecorp.com/</a>		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other:		

## UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	10/16/2025	Area of state conducts work
<b>Bunnell-Lammons Engineering (BLE)</b> 6004 Ponders Court Greenville, SC 29615	<b>Phone</b> (864) 288-1265  <b>Fax</b>  <b>Website</b> <a href="https://www.blecorp.com/">https://www.blecorp.com/</a>		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other:		
Company	Listing Submitted	6/27/2024	Area of state conducts work
<b>Cobb Environmental &amp; Technical Services, Inc.</b> P. O. Box 1602 Tupelo, MS 38802	<b>Phone</b> (662) 841-0995  <b>Fax</b> (662) 841-0810  <b>Website</b> <a href="http://cobben.com">cobben.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: No UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	6/30/2025	Area of state conducts work
<b>EIS Holding, LLC.</b> 5621 Departure Drive Suite 101 Raleigh, NC 27616	<b>Phone</b> (984) 284-5571  <b>Fax</b>  <b>Website</b> <a href="http://www.eisholdings.com">www.eisholdings.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: <b>Yes</b> Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: <b>Yes</b> Other:		Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other:		
Company	Listing Submitted	10/27/2025	Area of state conducts work
<b>Environmental Laboratories, INC</b> 15 Sulphur Springs Rd Greenville, SC 29617	<b>Phone</b> (864) 370-0637  <b>Fax</b>  <b>Website</b> <a href="https://www.elabsinc.net/">https://www.elabsinc.net/</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: <b>Yes</b> Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: <b>Yes</b> Other:		Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: No UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: No UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other:		

## UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	5/14/2024	Area of state conducts work
<b>Environmental Petroleum Services</b> 1234 Gordon Park Rd Augusta, GA 30901	<b>Phone</b> (877) 297-6763  <b>Fax</b>  <b>Website</b> <a href="http://www.keepmecompliant.net">www.keepmecompliant.net</a>		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: No Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	12/12/2025	Area of state conducts work
<b>JBL Solutions Inc.</b> 806 Appii Rd Moncks Corner, SC 29461	<b>Phone</b> (603) 690-9071  <b>Fax</b>  <b>Website</b> <a href="http://jblsolutionsinc.com">jblsolutionsinc.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: <b>Yes</b> Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other: Filtration and Polishing		

## UST Service Provider List (All) - Leak Detection Testing Companies Only

<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>JF Petroleum Group</b> 100 Perimeter Park Drive Suite H Morrisville, NC 27560	<b>Phone</b> (919) 744-4391  <b>Fax</b>  <b>Website</b> <a href="http://jfpetrogroup.com/services/environmentalcompliance">jfpetrogroup.com/services/environmentalcompliance</a>	5/15/2023	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<b>Yes</b>	Other:	
Line Tightness Testing:	<b>Yes</b>		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<b>Yes</b>
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
<b>OWL Services USA</b> 1815 Gallagher Road Plymouth Meeting, PA 19462	<b>Phone</b> (610) 633-9732  <b>Fax</b> (610) 278-7621  <b>Website</b> <a href="http://www.owlservices.com">www.owlservices.com</a>	10/14/2025	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	<b>Yes</b>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	<b>Yes</b>	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	<b>Yes</b>
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<b>Yes</b>	Other:	
Line Tightness Testing:	<b>Yes</b>		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<b>Yes</b>
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

## UST Service Provider List (All) - Leak Detection Testing Companies Only

Company	Listing Submitted	12/12/2025	Area of state conducts work
<b>SPATCO Energy Solutions</b> 301 McCullough Dr Suite 500 Charlotte, NC 28262	<b>Phone</b> (800) 477-8286  <b>Fax</b>  <b>Website</b> <a href="http://spatco.com">spatco.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b><u>Yes</u></b> Containment Sump Testing: <b><u>Yes</u></b> Corrosion Protection Design Experts: <b><u>Yes</u></b> Corrosion Protection System Repairs: <b><u>Yes</u></b> Corrosion Protection System Testing: <b><u>Yes</u></b> Leak Detection Equipment Operability Check: <b><u>Yes</u></b> Leak Detection Monitoring Services: <b><u>Yes</u></b> Line Tightness Testing: <b><u>Yes</u></b>	Overfill Prevention Equipment Operability Check: <b><u>Yes</u></b> Statistical Inventory Reconciliation Services: <b><u>Yes</u></b> Spill Prevention Equipment Testing: <b><u>Yes</u></b> Tank Tightness Testing: <b><u>Yes</u></b> UST Internal Inspections (Integrity Assessments): <b><u>Yes</u></b> UST Internal Lining Inspections: <b><u>Yes</u></b> Other:		Dispenser Meter Repair/Calibration: <b><u>Yes</u></b> Leak Detection Equipment Installation Servicing: <b><u>Yes</u></b> Spill Bucket Installation Repair: <b><u>Yes</u></b> UST Equipment Installation - Other: <b><u>Yes</u></b> UST Equipment Repair: <b><u>Yes</u></b> UST System Installation - Complete Systems: <b><u>Yes</u></b> UST Piping/Sump Installation: <b><u>Yes</u></b> UST System Removal: <b><u>Yes</u></b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b><u>Yes</u></b> Environmental Engineer/Geologist - Site Checks: <b><u>Yes</u></b> Environmental Engineer/Geologist Soil and GW Cleanu: <b><u>Yes</u></b> Oil and Solvent Recycling: <b><u>Yes</u></b> Soil and Water Testing Lab: <b><u>Yes</u></b>	UST Compliance Consultants: <b><u>Yes</u></b> UST Equipment Verification: <b><u>Yes</u></b> Waste Disposal and Treatment: <b><u>Yes</u></b> Other:		