Company		Listing Submitted	10/13/2025	Area of state conducts work	
A&D Environmental Services, Inc.	Phon	e (800) 434-7750		Coastal (East of I-95): Yes	
2718 Uwharrie Road	Fa	x (336) 434-7752		Central (West of I-95 and East of I-77): Yes	
Archdale, NC 27263				Mountains (West of I-77): Yes	
	Website	www.adenviro.com		Modificants (West Of 1-77). 103	
Сотр	liance Testing ar	d Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Overf	ill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		tical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spill I	Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		nternal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No UST	nternal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Other			UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
En	vironmental Serv	vice Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes UST	Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:		Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		e Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	Yes Other	•			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/19/2024	Area of state conducts work	
A1 Environmental Services Inc	Phon	e (252) 531-1284		Coastal (East of I-95): Yes	
PO Box 59		( )		Contral (West of I-95 and East of I-77): No	
	Phon Fa	` '		Central (West of I-95 and East of I-77): No	
PO Box 59		x			
PO Box 59 Greenville, NC 27835	Fa	www.aes-nc.com		Central (West of I-95 and East of I-77): No	
PO Box 59 Greenville, NC 27835	Fa Website liance Testing ar	www.aes-nc.com	No	Central (West of I-95 and East of I-77): No Mountains (West of I-77): No	No
PO Box 59 Greenville, NC 27835	Website Value Testing are No Overl	www.aes-nc.com  d Monitoring	No No	Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors	No No
PO Box 59 Greenville, NC 27835  Comp Automatic Line Leak Detector Testing:	Website  Web	www.aes-nc.com  ad Monitoring  ill Prevention Equipment Operability Check:		Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
PO Box 59 Greenville, NC 27835  Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	Website  Viliance Testing ar  No Overl  No Statis  No Spill I	www.aes-nc.com  ad Monitoring  ill Prevention Equipment Operability Check: tical Iventory Reconciliation Services:	No	Central (West of I-95 and East of I-77): No  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	No
PO Box 59 Greenville, NC 27835  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Website  Viliance Testing ar  No Overl  No Statis  No Spill I  No Tank	www.aes-nc.com  Id Monitoring  Iill Prevention Equipment Operability Check:  Itical Iventory Reconciliation Services:  Prevention Equipment Testing:	No No	Central (West of I-95 and East of I-77): No Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
PO Box 59 Greenville, NC 27835  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Website  Viliance Testing ar  No Overl  No Statis  No Spill I  No Tank  No UST	www.aes-nc.com  Id Monitoring  Ill Prevention Equipment Operability Check:  Itical Iventory Reconciliation Services:  Prevention Equipment Testing:  Tightness Testing:	No No No	Central (West of I-95 and East of I-77): No Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
PO Box 59 Greenville, NC 27835  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Website  Viliance Testing ar  No Overl  No Statis  No Spill I  No Tank  No UST	www.aes-nc.com  Ind Monitoring  Ind Monitoring	No No No No	Central (West of I-95 and East of I-77): No  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
PO Box 59 Greenville, NC 27835  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Website  Valiance Testing ar  No Overfi No Statis No Spill I No Tank No UST No UST	www.aes-nc.com  Ind Monitoring  Ind Monitoring	No No No No	Central (West of I-95 and East of I-77): No  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
PO Box 59 Greenville, NC 27835  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Website  Viliance Testing ar  No Overl  No Statis  No Spill I  No Tank  No UST  No UST  No Other	www.aes-nc.com  Id Monitoring  Ill Prevention Equipment Operability Check: tical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): No  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
PO Box 59 Greenville, NC 27835  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Website  Viliance Testing ar  No Overl  No Statis  No Spill I  No Tank  No UST  No UST  No Other  No	www.aes-nc.com  Id Monitoring  Id Monitoring  Ill Prevention Equipment Operability Check:  Itical Iventory Reconciliation Services:  Prevention Equipment Testing:  Tightness Testing:  Internal Inspections (Integrity Assessments):  Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): No  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
PO Box 59 Greenville, NC 27835  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En  Emergency Cleanup - Spill/Release:	Website  Viliance Testing ar  No Overl  No Statis  No Spill I  No Tank  No UST  No UST  No Other  No UST  No Other  No UST	www.aes-nc.com  Ind Monitoring Ill Prevention Equipment Operability Check: Itical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: Internal Compliance Consultants:	No No No No No	Central (West of I-95 and East of I-77): No  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
PO Box 59 Greenville, NC 27835  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Website  Viliance Testing ar  No Overl  No Statis  No Spill I  No Tank  No UST  No UST  No Other  No UST	www.aes-nc.com  Id Monitoring Ill Prevention Equipment Operability Check: tical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: :  Vice Firms Compliance Consultants: Equipment Verification:	No No No No	Central (West of I-95 and East of I-77): No  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
PO Box 59 Greenville, NC 27835  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Website  Viliance Testing ar  No Overl  No Statis  No Spill I  No Tank  No UST  No UST  No Other  No UST	www.aes-nc.com  Ind Monitoring  Ill Prevention Equipment Operability Check:  Itical Iventory Reconciliation Services:  Prevention Equipment Testing:  Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections:  Internal Lining Inspections:  Internal Compliance Consultants:  Equipment Verification:  In Disposal and Treatment:	No No No No No	Central (West of I-95 and East of I-77): No  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company		Listing Submitted	1/18/2024	Area of state conducts work	
Advanced Environmental Services, Inc.		Phone (336) 282-3586		Coastal (East of I-95): Yes	
PO Box 38218		Fax (336) 282-3587		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27438		,		Mountains (West of I-77): Yes	
	١	Website AdavancedEnvironmental.com		mountains (West of 1-77).	
Com	pliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	Yes	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	6/26/2024	Area of state conducts work	
BUCKEYE ELM CONTRACTING, LLC		Phone (336) 337-6001		Coastal (East of I-95): Yes	
PO Box 1026		Fax		Central (West of I-95 and East of I-77): Yes	
MOCKSVILLE, NC 27028		rax		Central (West of 1-95 and East of 1-77). Tes	
	١	Website www.buckeye-elm.com		Mountains (West of I-77): Yes	
Com		·			
		sting and Monitoring	No	UST Equipmment Service Contractors	No
Automatic Line Leak Detector Testing:	ipliance Tes	Sting and Monitoring Overfill Prevention Equipment Operability Check:		UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Tes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	npliance Tes No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No <b>Yes</b>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No <u>Yes</u> <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No <b>Yes</b>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  E Emergency Cleanup - Spill/Release:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms UST Compliance Consultants:	No No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  E Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  E Emergency Cleanup - Spill/Release:	No The provious of the pro	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms UST Compliance Consultants:	No No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>

Company		Listing Submitted	10/13/2025	Area of state conducts work	
Bunnell-Lammons Engineering (BLE)	P	Phone (864) 288-1265		Coastal (East of I-95): No	
6004 Ponders Court		Fax		Central (West of I-95 and East of I-77): Yes	
Greenville, SC 29615				Mountains (West of I-77): Yes	
	We	bsite https://www.blecorp.com/		mountaino (1700) 01111).	
Comp	liance Testin	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes S	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:		UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
En	vironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No (	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	10/16/2025	Area of state conducts work	
Bunnell-Lammons Engineering (BLE)	P	Phone (864) 288-1265		Coastal (East of I-95): No	
6004 Ponders Court		Fax		Central (West of I-95 and East of I-77): Yes	
Greenville, SC 29615				Mountains (West of I-77): Yes	
	We	bsite https://www.blecorp.com/		Wouldains (West Of 1-77). 165	
Comp	liance Testir				
Automotic Line Leels Detector Teetings		ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		ng and Monitoring Overfill Prevention Equipment Operability Check:	Yes	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>		<u>Yes</u> No		No No
	Yes Yes	Overfill Prevention Equipment Operability Check:		Dispenser Meter Repair/Calibration:	
Containment Sump Testing:	Yes Yes No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Containment Sump Testing: Corrosion Protection Design Experts:	Yes Yes No S	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No <u>Yes</u>	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes Yes No No Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No <u>Yes</u> <u>Yes</u>	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Yes No No Yes Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No Yes Yes Yes	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No No Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No Yes Yes Yes	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No Yes Yes Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No Yes Yes Yes	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No Yes Yes Yes Yes Yes Yes Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No Yes Yes Yes No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms UST Compliance Consultants:	No Yes Yes Yes No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes No No Yes Yes Yes Yes Yes Yes Ovironmental Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms UST Compliance Consultants: UST Equipment Verification:	No Yes Yes No Yes No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En Emergency Cleanup - Spill/Release:	Yes Yes No No Yes Yes Yes Yes Yes Yes Ovironmental Yes Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms UST Compliance Consultants:	No Yes Yes Yes No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company		Listing Submitted	4/5/2023	Area of state conducts work	
CATLIN Engineers and Scientists	Pho	one (910) 452-5861		Coastal (East of I-95): Yes	
220 Old Dairy Road	F	ax		Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28405				Mountains (West of I-77): No	
	Websi	ite <u>www.CatlinUSA.com</u>		mountains (West of 1-77).	
Comp	liance Testing a	and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No Ove	erfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No Stat	tistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spil	I Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Tan	ık Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No UST	T Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No UST	T Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Oth	er:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
En	vironmental Se	rvice Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes US1	T Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:		Γ Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		ste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No Oth	•			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	6/27/2024	Area of state conducts work	
Cobb Environmental & Technical Services, Inc	. Pho		0/21/2024	Coastal (East of I-95): Yes	
P. O. Box 1602		` ,		,	
Tupelo, MS 38802	F	ax (662) 841-0810		Central (West of I-95 and East of I-77): Yes	
	Websi	ite cobbenv.com		Mountains (West of I-77): Yes	
Comp	liance Testing a	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	manice resulting a	and wontoning			
	Voc Ove		Vos		No
_		erfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes Stat	erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	Yes
Containment Sump Testing: Corrosion Protection Design Experts:	Yes Stat	erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing:	No <u>Yes</u>	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	Yes Yes
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes Stat No Spil No Tan	erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: uk Tightness Testing:	No <u>Yes</u> No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Stat No Spil No Tan No US7	erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: Ik Tightness Testing: I Internal Inspections (Integrity Assessments):	No Yes No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Stat No Spil No Tan No UST Yes UST	erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections:	No <u>Yes</u> No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes No Yes
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	YesStateNoSpilNoTanNoUSTYesUSTNoOther	erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections:	No Yes No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes No Yes Yes Yes
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	YesStatNoSpilNoTanNoUSTYesUSTNoOthNoNo	erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: sk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: er:	No Yes No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes No Yes
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	YesStateNoSpilNoTanNoUSTYesUSTNoOther	erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: sk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: er:	No Yes No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes No Yes Yes Yes
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes         Stat           No         Spil           No         Tan           No         UST           Yes         UST           No         Oth           No         ovironmental Se	erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: sk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: er:	No Yes No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes No Yes Yes
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes         State           No         Spil           No         Tan           No         UST           Yes         UST           No         Oth           No         UST           No         UST           No         UST	erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: If Internal Inspections (Integrity Assessments): If Internal Lining Inspections: er:	No Yes No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes No Yes Yes Yes
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En Emergency Cleanup - Spill/Release:	Yes         Stat           No         Spil           No         Tan           No         UST           No         Oth           No         UST           No         UST           No         UST           No         UST	erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: tk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: er:  rvice Firms T Compliance Consultants:	No Yes No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes No Yes Yes Yes
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes         Stat           No         Spil           No         Tan           No         UST           No         Oth           No         UST           No         UST           No         UST           No         UST	erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: er:  rvice Firms T Compliance Consultants: T Equipment Verification: ste Disposal and Treatment:	No Yes No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes No Yes Yes Yes

Company		Listing Submitted	10/14/2025	Area of state conducts work	
C-Store Services, Inc.		Phone (919) 662-0798		Coastal (East of I-95): Yes	
7129 Hidden Valley Trail		Fax		Central (West of I-95 and East of I-77): Yes	
Garner, NC 27529				Mountains (West of I-77): No	
		Website		Wountains (West of 1-77). No	
Comp	liance T	esting and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironme	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listina Submitte	10/13/2025	Area of state conducts work	
D. H. Griffin Wrecking Company		Phone (336) 214-9012	10/13/2025		
D. H. Griffin Wrecking Company		Phone (336) 214-9012	d 10/13/2025	Coastal (East of I-95): Yes	
			d 10/13/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
D. H. Griffin Wrecking Company 4716 Hilltop Road		Phone (336) 214-9012	d 10/13/2025	Coastal (East of I-95): Yes	
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407	oliance T	Phone (336) 214-9012 Fax Website www.dhgriffin.com	d 10/13/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407	<mark>oliance T</mark>	Phone (336) 214-9012  Fax	d 10/13/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407		Phone (336) 214-9012 Fax  Website www.dhgriffin.com esting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407  Company Automatic Line Leak Detector Testing: Containment Sump Testing:	No	Phone (336) 214-9012 Fax  Website www.dhgriffin.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No	Phone (336) 214-9012 Fax  Website www.dhgriffin.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No	Phone (336) 214-9012 Fax  Website www.dhgriffin.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407  Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone (336) 214-9012  Fax  Website www.dhgriffin.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Phone (336) 214-9012 Fax  Website www.dhgriffin.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407  Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No	Phone (336) 214-9012 Fax  Website www.dhgriffin.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No No No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407  Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Phone (336) 214-9012 Fax  Website www.dhgriffin.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No	Phone (336) 214-9012 Fax  Website www.dhgriffin.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	No Vo	Phone (336) 214-9012 Fax  Website www.dhgriffin.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Intal Service Firms  UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No No No No No Vironme Yes No	Phone (336) 214-9012 Fax  Website www.dhgriffin.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Intal Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407  Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No No No No No No No No Vironme Yes No No	Phone (336) 214-9012 Fax  Website www.dhgriffin.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  ental Service Firms  UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No No No No No Vironme Yes No	Phone (336) 214-9012 Fax  Website www.dhgriffin.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Intal Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

Company		Listing Submitte	d 4/5/2023	Area of state conducts work	
East Coast Environmental, PA		Phone (919) 349-5969		Coastal (East of I-95): Yes	
3815 Junction Boulevard		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27603				Mountains (West of I-77): No	
	W	ebsite eastcoastenv.com		Mountains (West of 1-77). No	
Comp	liance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
En	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Con and Water resulty Lab.	No				
Company	INU	Listing Submitte	d 1/6/2025	Area of state conducts work	
	INO	Listing Submitte Phone (919) 861-9910	d 1/6/2025	Area of state conducts work  Coastal (East of I-95): Yes	
Company ECS Southeast, LLC 5260 Greens Dairy Road	INU	Phone (919) 861-9910	d 1/6/2025	Coastal (East of I-95): Yes	
Company ECS Southeast, LLC	INU		d 1/6/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company  ECS Southeast, LLC 5260 Greens Dairy Road		Phone (919) 861-9910	d 1/6/2025	Coastal (East of I-95): Yes	
Company  ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616	W	Phone (919) 861-9910  Fax	d 1/6/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company  ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616	W	Phone (919) 861-9910 Fax  /ebsite ecslimited.com	d 1/6/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Company  ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616  Comp	W bliance Test	Phone (919) 861-9910 Fax  /ebsite ecslimited.com ing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Company  ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616  Comp	W bliance Test	Phone (919) 861-9910  Fax  /ebsite ecslimited.com  ing and Monitoring  Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Company  ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing:	W bliance Test No No	Phone (919) 861-9910  Fax  /ebsite ecslimited.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Company  ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No	Phone (919) 861-9910  Fax  /ebsite ecslimited.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:	No No No
Company  ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Phone (919) 861-9910  Fax  /ebsite ecslimited.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:  UST Equipment Installation - Other:	No No No No
Company  ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone (919) 861-9910  Fax  Vebsite ecslimited.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Company  ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (919) 861-9910  Fax  /ebsite ecslimited.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Company  ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (919) 861-9910  Fax  /ebsite ecslimited.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Company  ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 861-9910  Fax  /ebsite ecslimited.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Company  ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 861-9910  Fax  /ebsite ecslimited.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Company  ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release:	No N	Phone (919) 861-9910  Fax  /ebsite ecslimited.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  al Service Firms  UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Company  ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (919) 861-9910  Fax  /ebsite ecslimited.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  al Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

Company		Listing Submitte	d 6/30/2025	Area of state conducts work	
EIS Holding, LLC.		Phone (984) 284-5571		Coastal (East of I-95): Yes	
5621 Departure Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Suite 101				Mountains (West of I-77): Yes	
Raleigh, NC 27616		Website www.eisholdings.com		Mountains (West of 1-77). Tes	
Com	pliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
E	nvironmer	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	u <u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitte	d 7/2/2024	Area of state conducts work	
Company Environmental Hydrogeological Consultants,	Inc. DB	Phone (910) 843-4456	d 7/2/2024	Area of state conducts work  Coastal (East of I-95): Yes	
Environmental Hydrogeological Consultants, PO Box 902	Inc. DB	Phone (910) 843-4456	d 7/2/2024	Coastal (East of I-95): Yes	
Environmental Hydrogeological Consultants,	Inc. DB		d 7/2/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Environmental Hydrogeological Consultants, PO Box 902		Phone (910) 843-4456	d 7/2/2024	Coastal (East of I-95): Yes	
Environmental Hydrogeological Consultants, PO Box 902 Red Springs, NC 28377		Phone (910) 843-4456  Fax (910) 843-5376	d 7/2/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Environmental Hydrogeological Consultants, PO Box 902 Red Springs, NC 28377		Phone (910) 843-4456 Fax (910) 843-5376  Website www.environmentalnc.com	d 7/2/2024 No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Environmental Hydrogeological Consultants, PO Box 902 Red Springs, NC 28377	pliance Te	Phone (910) 843-4456 Fax (910) 843-5376  Website www.environmentalnc.com esting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Environmental Hydrogeological Consultants, PO Box 902 Red Springs, NC 28377  Com Automatic Line Leak Detector Testing:	pliance Te	Phone (910) 843-4456 Fax (910) 843-5376  Website www.environmentalnc.com  esting and Monitoring  Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	No
Environmental Hydrogeological Consultants, PO Box 902 Red Springs, NC 28377  Com Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Te No No	Phone (910) 843-4456 Fax (910) 843-5376  Website www.environmentalnc.com esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	No No
Environmental Hydrogeological Consultants, PO Box 902 Red Springs, NC 28377  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	<b>pliance Te</b> No No No	Phone (910) 843-4456 Fax (910) 843-5376  Website www.environmentalnc.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:	No No No
Environmental Hydrogeological Consultants, PO Box 902 Red Springs, NC 28377  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	pliance Te No No No No	Phone (910) 843-4456 Fax (910) 843-5376  Website www.environmentalnc.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:  UST Equipment Installation - Other:	No No No
Environmental Hydrogeological Consultants, PO Box 902 Red Springs, NC 28377  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	pliance Te No No No No No	Phone (910) 843-4456 Fax (910) 843-5376  Website www.environmentalnc.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Environmental Hydrogeological Consultants, PO Box 902 Red Springs, NC 28377  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	pliance Te No No No No No No No No	Phone (910) 843-4456 Fax (910) 843-5376  Website www.environmentalnc.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Environmental Hydrogeological Consultants, PO Box 902 Red Springs, NC 28377  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	pliance Te  No  No  No  No  No  No  No  No  No  N	Phone (910) 843-4456 Fax (910) 843-5376  Website www.environmentalnc.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No No
Environmental Hydrogeological Consultants, PO Box 902 Red Springs, NC 28377  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	pliance Te  No  No  No  No  No  No  No  No  No  N	Phone (910) 843-4456 Fax (910) 843-5376  Website www.environmentalnc.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Environmental Hydrogeological Consultants, PO Box 902 Red Springs, NC 28377  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	pliance Te No	Phone (910) 843-4456 Fax (910) 843-5376  Website www.environmentalnc.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Environmental Hydrogeological Consultants, PO Box 902 Red Springs, NC 28377  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release:	pliance Te No	Phone (910) 843-4456 Fax (910) 843-5376  Website www.environmentalnc.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Intal Service Firms  UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Environmental Hydrogeological Consultants, PO Box 902 Red Springs, NC 28377  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	pliance Te No	Phone (910) 843-4456 Fax (910) 843-5376  Website www.environmentalnc.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Intal Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No

Company		Listing Submitte	d 10/27/2025	Area of state conducts work	
Environmental Laboratories, INC		Phone (864) 370-0637		Coastal (East of I-95): Yes	
15 Sulphur Springs Rd		Fax		Central (West of I-95 and East of I-77): Yes	
Greenville, SC 29617				Mountains (West of I-77): Yes	
	V	Website <a href="https://www.elabsinc.net/">https://www.elabsinc.net/</a>		wiountains (west of 1-77). Tes	
Comp	liance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
En	vironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
	Yes	Listing Submitte	ed 5/14/2024	Area of state conducts work	
Soil and Water Testing Lab:  Company  Environmental Petroleum Services	Yes		ed 5/14/2024		
Company	Yes	Phone (877) 297-6763	ed 5/14/2024	Coastal (East of I-95): No	
Company Environmental Petroleum Services	Yes		ed 5/14/2024	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
Company Environmental Petroleum Services 1234 Gordon Park Rd		Phone (877) 297-6763	ed 5/14/2024	Coastal (East of I-95): No	
Company Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901	V	Phone (877) 297-6763  Fax	ed 5/14/2024	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
Company Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901	V	Phone (877) 297-6763  Fax  Nebsite www.keepmecompliant.net	ed 5/14/2024 Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	Yes
Company Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901 Comp	V bliance Tes	Phone (877) 297-6763 Fax  Website www.keepmecompliant.net  ting and Monitoring		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	Yes Yes
Company  Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901  Comp  Automatic Line Leak Detector Testing:	V bliance Tes Yes	Phone (877) 297-6763  Fax  Website www.keepmecompliant.net  Iting and Monitoring  Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	
Company Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901  Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	V pliance Tes Yes Yes	Phone (877) 297-6763  Fax  Nebsite www.keepmecompliant.net  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	<u>Yes</u> No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Company  Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Ves Yes Yes Yes	Phone (877) 297-6763  Fax  Website www.keepmecompliant.net  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	<u>Yes</u> No <u>Yes</u>	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	Yes Yes
Company  Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Veliance Tes Yes Yes Yes Yes Yes Yes	Phone (877) 297-6763  Fax  Website www.keepmecompliant.net  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes No Yes Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	<u>Yes</u> <u>Yes</u> <u>Yes</u>
Company  Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Ves Yes Yes Yes Yes Yes Yes	Phone (877) 297-6763  Fax  Website www.keepmecompliant.net  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes
Company  Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Ves Yes Yes Yes Yes Yes Yes	Phone (877) 297-6763  Fax  Website www.keepmecompliant.net  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes
Company  Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Ves Yes Yes Yes Yes Yes Yes No Yes	Phone (877) 297-6763  Fax  Website www.keepmecompliant.net  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
Company  Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Ves Yes Yes Yes Yes Yes Yes No Yes	Phone (877) 297-6763  Fax  Website www.keepmecompliant.net  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Company  Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Ves Yes Yes Yes Yes Yes No Yes	Phone (877) 297-6763  Fax  Website www.keepmecompliant.net  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Company  Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Ves Yes Yes Yes Yes Yes Yes Yes No Yes No No No	Phone (877) 297-6763  Fax  Website www.keepmecompliant.net  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Ital Service Firms  UST Compliance Consultants:	Yes No Yes Yes No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Company  Environmental Petroleum Services  1234 Gordon Park Rd Augusta, GA 30901  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Ves Yes Yes Yes Yes Yes Yes Yes No Yes No No No	Phone (877) 297-6763  Fax  Website www.keepmecompliant.net  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants: UST Equipment Verification:	Yes No Yes Yes No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes

Company		Listing Submitted	7/16/2024	Area of state conducts work	
EnviroSouth, Inc.	F	Phone (864) 236-9010		Coastal (East of I-95): No	
3440 Augusta Road		Fax		Central (West of I-95 and East of I-77): Yes	
Greenville, SC 29605				Mountains (West of I-77): Yes	
	We	bsite www.envirosouth.com		modificants (West of 1-17).	
Comp	oliance Testir	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	10/13/2025	Area of state conducts work	
Evo Corporation	F	Phone (336) 725-5844		Coastal (East of I-95): Yes	
1703 Vargrave Street		Fax		Central (West of I-95 and East of I-77): Yes	
Winston-Salem, NC 27107				Mountains (West of I-77): Yes	
	We	bsite www.evocorp.net			
Comp	oliance Testir	g and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
				UCT Favings and Danain	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	
Corrosion Protection System Testing: Leak Detection Equipment Operability Check:		UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No	UST System Installation - Complete Systems:	No
	No	, , , , , , , , , , , , , , , , , , , ,			No No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:		UST System Installation - Complete Systems:	
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No	UST Internal Lining Inspections:		UST System Installation - Complete Systems: UST Piping/Sump Installation:	No
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No nvironmental	UST Internal Lining Inspections: Other:		UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er	No No No nvironmental Yes	UST Internal Lining Inspections: Other: Service Firms	No	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er  Emergency Cleanup - Spill/Release:	No No No nvironmental Yes No	UST Internal Lining Inspections: Other:  Service Firms UST Compliance Consultants:	No No	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No nvironmental Yes No No	UST Internal Lining Inspections: Other:  Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No

Company		Listing Submitte	d 10/14/2025	Area of state conducts work	
Geological Resources, Inc.	F	Phone (704) 845-4010		Coastal (East of I-95): Yes	
3502 Hayes Road		Fax (704) 845-4012		Central (West of I-95 and East of I-77): Yes	
Monroe, NC 28110		144 (101) 010 1012		Mountains (West of I-77): Yes	
	We	bsite <u>www.grienv.com</u>		Mountains (West of 1-77). Tes	
Comp	oliance Testir	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitte	d 11/16/2023	Area of state conducts work	
Company Groundwater Management Associates, Inc.	F	Listing Submitte Phone (252) 758-3310	d 11/16/2023	Area of state conducts work  Coastal (East of I-95): Yes	
Groundwater Management Associates, Inc. 4300 Sapphire Court	F	Phone (252) 758-3310	d 11/16/2023	Coastal (East of I-95): Yes	
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100	F		d 11/16/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Groundwater Management Associates, Inc. 4300 Sapphire Court		Phone (252) 758-3310	d 11/16/2023	Coastal (East of I-95): Yes	
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834	We	Phone (252) 758-3310  Fax	d 11/16/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834	We	Phone (252) 758-3310  Fax  bsite www.gma-nc.com	d 11/16/2023 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834  Comp	We bliance Testin	Phone (252) 758-3310  Fax  bsite www.gma-nc.com  ng and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834  Comp Automatic Line Leak Detector Testing:	We bliance Testin No	Phone (252) 758-3310  Fax  bsite www.gma-nc.com  g and Monitoring  Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834  Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	We bliance Testin No No	Phone (252) 758-3310  Fax  bsite www.gma-nc.com  ag and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	We pliance Testin No No No	Phone (252) 758-3310  Fax  bsite www.gma-nc.com  ag and Monitoring  Overfill Prevention Equipment Operability Check:  Statistical Iventory Reconciliation Services:  Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:	No No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Webliance Testin	bsite www.gma-nc.com  g and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Webliance Testin	bsite www.gma-nc.com  g and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Webliance Testin	Phone (252) 758-3310  Fax  bsite www.gma-nc.com  Ig and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Webliance Testin	Phone (252) 758-3310  Fax  bsite www.gma-nc.com  Ig and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	We pliance Testir No	bsite www.gma-nc.com  g and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er  Emergency Cleanup - Spill/Release:	We pliance Testin	Phone (252) 758-3310  Fax  bsite www.gma-nc.com  Ig and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms  UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	We pliance Testir No	bsite www.gma-nc.com  Ig and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	We bliance Testir No	bsite www.gma-nc.com  g and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

Company		Listing Submitte	11/14/2025	Area of state conducts work	
HARCO Services LLC	Pho	ne (770) 917-8846		Coastal (East of I-95): Yes	
2 Kelli Clark Ct SE	F	(770) 917-0921		Central (West of I-95 and East of I-77): Yes	
Cartersville, GA 30121	•	(176) 617 6621		Mountains (West of I-77): Yes	
	Websi	<u>harcoservices.com</u>		Mountains (West of 1-77). Tes	
Comp	liance Testing a	nd Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Ove	fill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No Stati	stical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spill	Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No UST	Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No Othe	er:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
En	vironmental Ser	vice Firms		Other:	
Emergency Cleanup - Spill/Release:	No UST	Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No UST	Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No Was	te Disposal and Treatment:	No		
Oil and Solvent Recycling:	No Othe	er:			
Soil and Water Testing Lab:	No				
Soil and Water Testing Lab:  Company	No	Listing Submitte	d 3/31/2025	Area of state conducts work	
	Phoi		d 3/31/2025	Area of state conducts work  Coastal (East of I-95): Yes	
Company Hart & Hickman, PC 2923 S. Tryon Street	Pho	ne (704) 586-0007	d 3/31/2025	Coastal (East of I-95): Yes	
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100		ne (704) 586-0007	d 3/31/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company Hart & Hickman, PC 2923 S. Tryon Street	Pho	ne (704) 586-0007	d 3/31/2025	Coastal (East of I-95): Yes	
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203	Pho	ne (704) 586-0007  ax  te https://harthickman.com/	d 3/31/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203	Pho Fa Websit Iliance Testing a	ne (704) 586-0007  ax  te https://harthickman.com/	d 3/31/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Comp	Pho Fa Websit Sliance Testing a No Over	ne (704) 586-0007  ax  te https://harthickman.com/ nd Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Comp Automatic Line Leak Detector Testing:	Phone Factoring a No Over No Stati	ne (704) 586-0007  ax  te https://harthickman.com/  nd Monitoring  fill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing:	Phone For Websit Siliance Testing at No Over No Stati	ne (704) 586-0007  te https://harthickman.com/  nd Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Phone For Websit	ne (704) 586-0007  te https://harthickman.com/  nd Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:	No No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Phone For Websit Viliance Testing at No Over No Stati No Spill No Tank No UST	ne (704) 586-0007  te https://harthickman.com/  nd Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing:  taliant Testing:	No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:  UST Equipment Installation - Other:	No No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Phone For Websit Viliance Testing at No Over No Stati No Spill No Tank No UST	ne (704) 586-0007  ax  te https://harthickman.com/  nd Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: a Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Phone Factor of Phone Factor o	ne (704) 586-0007  ax  te https://harthickman.com/  nd Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: a Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Phone Figure 1	te https://harthickman.com/ ax  te https://harthickman.com/ ad Monitoring fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: a Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Phone Factoring and No Over No Statis No Spill No Tank No UST No UST No Other No Over No Other No Othe	te https://harthickman.com/ ax  te https://harthickman.com/ ad Monitoring fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: a Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En  Emergency Cleanup - Spill/Release:	Phone Factoring and No Over No Statis No Spill No Tank No UST No UST No Other No Ustronmental Ser	ne (704) 586-0007  ax  te https://harthickman.com/  nd Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: a Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: er:  vice Firms  Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Phone File Websit  Websit  Wiliance Testing a  No Over No Stati No Spill No Tank No UST No UST No Othe No  Invironmental Ser  Yes UST Yes UST	ne (704) 586-0007  ax  te https://harthickman.com/  nd Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: a Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections:  vice Firms	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Phone Figure 1	te https://harthickman.com/ ax  te https://harthickman.com/ ad Monitoring  fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: a Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: ar:  vice Firms  Compliance Consultants: Equipment Verification: te Disposal and Treatment:	No No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

Company		Listing Submitte	d 4/11/2023	Area of state conducts work	
INENCO, Inc.		Phone (704) 662-8192		Coastal (East of I-95): Yes	
132 W. Statesville Avenue		Fax (704) 662-8194		Central (West of I-95 and East of I-77): Yes	
Mooresville, NC 27115		(101) 002 0101		Mountains (West of I-77): Yes	
		Website		wountains (west of 1-77). Tes	
Comp	liance Te	sting and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmen	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitte	d 5/15/2023	Area of state conducts work	
JF Petroleum Group		Phone (919) 744-4391		Coastal (East of I-95): Yes	
JF Petroleum Group 100 Perimeter Park Drive		,			
100 Perimeter Park Drive Suite H		Phone (919) 744-4391  Fax		Central (West of I-95 and East of I-77): Yes	
100 Perimeter Park Drive		,	alcompliance		
100 Perimeter Park Drive Suite H Morrisville, NC 27560		Fax	<u>alcompliance</u>	Central (West of I-95 and East of I-77): Yes	
100 Perimeter Park Drive Suite H Morrisville, NC 27560		Fax  Website jfpetrogroup.com/services/environmenta	alcompliance Yes	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
100 Perimeter Park Drive Suite H Morrisville, NC 27560 Comp	oliance Te	Fax  Website jfpetrogroup.com/services/environments  sting and Monitoring	·	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors	
100 Perimeter Park Drive Suite H Morrisville, NC 27560  Comp Automatic Line Leak Detector Testing:	oliance Te	Fax  Website jfpetrogroup.com/services/environmenta  sting and Monitoring  Overfill Prevention Equipment Operability Check:	Yes	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	<u>Yes</u>
100 Perimeter Park Drive Suite H Morrisville, NC 27560  Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	oliance Te Yes Yes	Fax  Website jfpetrogroup.com/services/environments  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	<u>Yes</u> No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	Yes Yes
100 Perimeter Park Drive Suite H Morrisville, NC 27560  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Yes Yes No	Fax  Website jfpetrogroup.com/services/environments  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Yes No Yes	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:	Yes Yes Yes
100 Perimeter Park Drive Suite H Morrisville, NC 27560  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes Yes No	Fax  Website jfpetrogroup.com/services/environments  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes No Yes Yes	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes Yes
100 Perimeter Park Drive Suite H Morrisville, NC 27560  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Yes No No	Fax  Website jfpetrogroup.com/services/environments  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes Yes	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes Yes
100 Perimeter Park Drive Suite H Morrisville, NC 27560  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No No No Yes	Fax  Website jfpetrogroup.com/services/environments  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes
100 Perimeter Park Drive Suite H Morrisville, NC 27560  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No No Yes Yes Yes Yes Yes Yes	Fax  Website jfpetrogroup.com/services/environments  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes
100 Perimeter Park Drive Suite H Morrisville, NC 27560  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No No Yes Yes Yes Yes Yes Yes	Fax  Website jfpetrogroup.com/services/environments  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
100 Perimeter Park Drive Suite H Morrisville, NC 27560  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No No Yes Yes Yes Yes Yes Yes	Fax  Website jfpetrogroup.com/services/environments  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
100 Perimeter Park Drive Suite H Morrisville, NC 27560  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	Yes Yes No No No Yes Yes Yes Yes Yes Your	Fax  Website jfpetrogroup.com/services/environments  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Ital Service Firms  UST Compliance Consultants:	Yes No Yes Yes No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
100 Perimeter Park Drive Suite H Morrisville, NC 27560  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes No No No Yes Yes Yes Yes Yes No No No	Fax  Website ifpetrogroup.com/services/environments  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  utal Service Firms  UST Compliance Consultants: UST Equipment Verification:	Yes No Yes Yes No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes

Company		Listing Submitted	12/20/2022	Area of state conducts work	
Jones Covey Group		Phone (888) 972-7581		Coastal (East of I-95): Yes	
9595 Lucas Ranch Rd STE 100		Fax (909) 484-0300		Central (West of I-95 and East of I-77): Yes	
Rancho Cucamonga, CA 91730		(555) .5. 5555		Mountains (West of I-77): Yes	
	V	/ebsite		Wountains (West of 1-77). Tes	
Comp	liance Test	ing and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
En	vironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	10/16/2025	Area of state conducts work	
Lamar Contractors, LLC		(00=) =0= =101			
		Phone (985) 785-7121		Coastal (East of I-95): Yes	
481 Judge Edward Dufresne Pkwy.		,			
		Phone (985) 785-7121  Fax (985) 785-7124		Central (West of I-95 and East of I-77): Yes	
481 Judge Edward Dufresne Pkwy.	V	,			
481 Judge Edward Dufresne Pkwy. Luling , LA 70070		Fax (985) 785-7124		Central (West of I-95 and East of I-77): Yes	
481 Judge Edward Dufresne Pkwy. Luling , LA 70070		Fax (985) 785-7124  /ebsite www.lamarcontractors.com	No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	No
481 Judge Edward Dufresne Pkwy. Luling , LA 70070  Comp	liance Test	Fax (985) 785-7124  /ebsite www.lamarcontractors.com  ing and Monitoring	No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors	No No
481 Judge Edward Dufresne Pkwy. Luling , LA 70070  Comp  Automatic Line Leak Detector Testing:	liance Test	Fax (985) 785-7124  /ebsite www.lamarcontractors.com  ing and Monitoring  Overfill Prevention Equipment Operability Check:		Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	
481 Judge Edward Dufresne Pkwy. Luling , LA 70070  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Fax (985) 785-7124  /ebsite www.lamarcontractors.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	No
481 Judge Edward Dufresne Pkwy. Luling , LA 70070  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Fax (985) 785-7124  /ebsite www.lamarcontractors.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No <u>Yes</u>
481 Judge Edward Dufresne Pkwy. Luling , LA 70070  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Fax (985) 785-7124  /ebsite www.lamarcontractors.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No <u>Yes</u> <u>Yes</u>
481 Judge Edward Dufresne Pkwy. Luling , LA 70070  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No	Fax (985) 785-7124  /ebsite www.lamarcontractors.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No Yes Yes Yes
481 Judge Edward Dufresne Pkwy. Luling , LA 70070  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Fax (985) 785-7124  /ebsite www.lamarcontractors.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No Yes Yes Yes Yes
481 Judge Edward Dufresne Pkwy. Luling , LA 70070  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax (985) 785-7124  /ebsite www.lamarcontractors.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes Yes Yes Yes Yes Yes
481 Judge Edward Dufresne Pkwy. Luling , LA 70070  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax (985) 785-7124  /ebsite www.lamarcontractors.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes Yes Yes Yes Yes Yes
481 Judge Edward Dufresne Pkwy. Luling , LA 70070  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax (985) 785-7124  /ebsite www.lamarcontractors.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes Yes Yes Yes Yes Yes
481 Judge Edward Dufresne Pkwy. Luling , LA 70070  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release:	No N	Fax (985) 785-7124  /ebsite www.lamarcontractors.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  al Service Firms  UST Compliance Consultants:	No No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes Yes Yes Yes Yes Yes
481 Judge Edward Dufresne Pkwy. Luling , LA 70070  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Fax (985) 785-7124  /ebsite www.lamarcontractors.com  ing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  al Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes Yes Yes Yes Yes Yes

Company		Listing Submitted	5/30/2024	Area of state conducts work	
Marley Trucking & Demolition Inc.		Phone (336) 382-7132		Coastal (East of I-95): Yes	
1768 Old Humble Mill Road		Fax		Central (West of I-95 and East of I-77): Yes	
Asheboro, NC 27205		I da			
		Website		Mountains (West of I-77): Yes	
Com	pliance	Testing and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironr	nental Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleans		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
0 - 11-11					
Company		Listing Submitted	5/30/2024	Area of state conducts work	
MERRITT COMMERCIAL SERVICES LLC			5/30/2024		
MERRITT COMMERCIAL SERVICES LLC		Phone (228) 516-0498	5/30/2024	Coastal (East of I-95): Yes	
			5/30/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD		Phone (228) 516-0498	5/30/2024	Coastal (East of I-95): Yes	
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897	pliance	Phone (228) 516-0498  Fax	5/30/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897	<b>pliance</b> No	Phone (228) 516-0498  Fax  Website https://www.mcs-petroleum-div.com/	5/30/2024 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897  Com		Phone (228) 516-0498  Fax  Website https://www.mcs-petroleum-div.com/  Testing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897  Com Automatic Line Leak Detector Testing:	No	Phone (228) 516-0498  Fax  Website https://www.mcs-petroleum-div.com/  Testing and Monitoring  Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	<u>Yes</u>
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897  Com Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (228) 516-0498  Fax  Website https://www.mcs-petroleum-div.com/  Testing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	Yes Yes
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No	Phone (228) 516-0498  Fax  Website https://www.mcs-petroleum-div.com/  Testing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	Yes Yes Yes
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No	Phone (228) 516-0498  Fax  Website https://www.mcs-petroleum-div.com/  Testing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes Yes
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No	Phone (228) 516-0498  Fax  Website https://www.mcs-petroleum-div.com/  Testing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Phone (228) 516-0498  Fax  Website https://www.mcs-petroleum-div.com/  Testing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Phone (228) 516-0498  Fax  Website https://www.mcs-petroleum-div.com/  Testing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Phone (228) 516-0498  Fax  Website https://www.mcs-petroleum-div.com/  Testing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Phone (228) 516-0498  Fax  Website https://www.mcs-petroleum-div.com/  Testing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (228) 516-0498  Fax  Website https://www.mcs-petroleum-div.com/  Testing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  mental Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release:	No N	Phone (228) 516-0498  Fax  Website https://www.mcs-petroleum-div.com/  Testing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  mental Service Firms  UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897  Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanup	No N	Phone (228) 516-0498  Fax  Website https://www.mcs-petroleum-div.com/  Testing and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Mental Service Firms  UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes

Company		Listing Submitte	ed 4/20/2023	Area of state conducts work	
MGF Environmental, PLLC	Ph	none (904) 814-3680		Coastal (East of I-95): No	
288 Gap Creek Rd		Fax		Central (West of I-95 and East of I-77): Yes	
Fletcher, NC 28732				Mountains (West of I-77): Yes	
	Web	site mgfenvironmental.com		Wouldains (West Of 1-77). 103	
Сотр	liance Testinç	and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No O	verfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		tatistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	pill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Ta	ank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No U	ST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No U	ST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No O	ther:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
En	vironmental S	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No U	ST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes U	ST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		aste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:		ther:			
Soil and Water Testing Lab:	No				
Company		Listing Submitte	ed 10/14/2025	Area of state conducts work	
OWL Services USA	Pł	ione (610) 633-9732		Coastal (East of I-95): Yes	
1815 Gallagher Road		Fax (610) 278-7621		Central (West of I-95 and East of I-77): Yes	
Dhymouth Mosting DA 10462					
Plymouth Meeting, PA 19462		(0.0) 2.0 . 02.			
Figinodin Meeting, FA 19402	Web	•		Mountains (West of I-77): Yes	
		•			
	oliance Testing	site www.owlservices.com	<u>Yes</u>	Mountains (West of I-77): Yes	Yes
Сотр	liance Testing	site www.owlservices.com  and Monitoring	Yes Yes	Mountains (West of I-77): Yes  UST Equipmment Service Contractors	Yes Yes
Comp Automatic Line Leak Detector Testing:	Ves S	site www.owlservices.com  J and Monitoring  verfill Prevention Equipment Operability Check:		Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	
Comp  Automatic Line Leak Detector Testing: Containment Sump Testing:	Yes O Yes S No S	site www.owlservices.com  J and Monitoring  verfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services:	Yes	Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Yes O Yes S No S Yes Ta	site www.owlservices.com  J and Monitoring  verfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: pill Prevention Equipment Testing:	Yes Yes	Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:	<u>Yes</u> Yes
Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes O Yes S No S Yes Tes	y and Monitoring  verfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: pill Prevention Equipment Testing: ank Tightness Testing:	Yes Yes Yes	Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	<u>Yes</u> <u>Yes</u> <u>Yes</u>
Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes O Yes S No S Yes Ta Yes U Yes U	y and Monitoring  verfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: pill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity Assessments):	Yes Yes Yes Yes	Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes
Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes O Yes S No S Yes Ta Yes U Yes U	yerfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: pill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections:	Yes Yes Yes Yes	Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes O Yes S No S Yes To Yes U Yes U Yes O	y and Monitoring  verfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: pill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther:	Yes Yes Yes Yes	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes O Yes U Yes U Yes U Yes O	y and Monitoring verfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: bill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther:	Yes Yes Yes Yes No	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En Emergency Cleanup - Spill/Release:	Yes O Yes U Yes U Yes U Yes O No U	y and Monitoring  I and Monitoring  I verfill Prevention Equipment Operability Check: Itatistical Iventory Reconciliation Services: I poill Prevention Equipment Testing: I ank Tightness Testing: I Internal Inspections (Integrity Assessments): I Internal Lining Inspections: Ither:  Service Firms  ST Compliance Consultants:	Yes Yes Yes Yes No	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes O Yes U Yes U Yes U Yes O Yes U Yes O Yes O Yes O Yes O Yes O No U No U	y and Monitoring  I and Monitoring  I and Monitoring  I verfill Prevention Equipment Operability Check: Itatistical Iventory Reconciliation Services: I poill Prevention Equipment Testing: I ank Tightness Testing: I Internal Inspections (Integrity Assessments): Internal Lining Inspections: Ither:  I service Firms I Compliance Consultants: I Equipment Verification:	Yes Yes Yes No Yes Yes	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes O Yes U No U No U No W	y and Monitoring  I and Monitoring  I verfill Prevention Equipment Operability Check: Itatistical Iventory Reconciliation Services: I poill Prevention Equipment Testing: I ank Tightness Testing: I Internal Inspections (Integrity Assessments): I Internal Lining Inspections: Ither:  Service Firms  ST Compliance Consultants:	Yes Yes Yes Yes No	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes

Company		Listing Submitte	10/21/2025	Area of state conducts work	
Parliament Petroleum Services LLC		Phone (864) 871-8058		Coastal (East of I-95): No	
3277 Neely Ferry Road		Fax		Central (West of I-95 and East of I-77): No	
Laurens, SC 29360				Mountains (West of I-77): Yes	
	We	ebsite parliamentpetroleumservices.com		Mountains (West Of 1-77). Tes	
Comp	oliance Testi	ng and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Eı	nvironmenta	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitte	11/1/2023	Area of state conducts work	
Peak Hydrogeologic, PLLC	-	Phone (828) 817-5209		Coastal (East of I-95): No	
470 Hogback Mtn Rd					
		Fax		Central (West of I-95 and East of I-77): Yes	
Tryon, NC 28782		Fax		Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
	We	Fax  ebsite https://peakhydrogeologic.com		Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Tryon, NC 28782					
Tryon, NC 28782		ebsite https://peakhydrogeologic.com	No	Mountains (West of I-77): Yes	No
Tryon, NC 28782	oliance Testi	ebsite https://peakhydrogeologic.com ng and Monitoring	No No	Mountains (West of I-77): Yes  UST Equipmment Service Contractors	No No
Tryon, NC 28782  Comp  Automatic Line Leak Detector Testing:	oliance Testi No	ebsite <a href="https://peakhydrogeologic.com">https://peakhydrogeologic.com</a> <a href="mailto:ng">ng and Monitoring</a> Overfill Prevention Equipment Operability Check:		Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	
Tryon, NC 28782  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing:	No No No No	ebsite <a href="https://peakhydrogeologic.com">https://peakhydrogeologic.com</a> <a href="mailto:ng">ng and Monitoring</a> <a href="https://peakhydrogeologic.com">Overfill Prevention Equipment Operability Check:</a> <a href="mailto:Statistical Iventory Reconciliation Services">Statistical Iventory Reconciliation Services</a> :	No	Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	No
Tryon, NC 28782  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No No No	ebsite <a href="https://peakhydrogeologic.com">https://peakhydrogeologic.com</a> <a href="mailto:ng">ng and Monitoring</a> Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:	No No
Tryon, NC 28782  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Tryon, NC 28782  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Tryon, NC 28782  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	ebsite https://peakhydrogeologic.com  ng and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Tryon, NC 28782  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	ebsite https://peakhydrogeologic.com  ng and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Tryon, NC 28782  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Tryon, NC 28782  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	ng and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Tryon, NC 28782  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En  Emergency Cleanup - Spill/Release:	No N	ng and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms UST Compliance Consultants:	No No No No No	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Tryon, NC 28782  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No vironmental Yes Yes Yes	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company		Listing Submitte	ed 10/13/2025	Area of state conducts work	
Petroleum Equipment and Service, Inc	Pho	one (704) 335-8801		Coastal (East of I-95): No	
PO Box 1949	F	- ax		Central (West of I-95 and East of I-77): Yes	
Denver, NC 28037				Mountains (West of I-77): Yes	
	Webs	ite <u>www.petroleumequipment.net</u>		Wouldtains (West Of 1-77). 103	
Сотр	liance Testing a	and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No Ove	erfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:		tistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No Spil	Il Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Tan	nk Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No US	T Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No US	T Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No Oth	er:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
En	vironmental Se	rvice Firms		Other:	
Emergency Cleanup - Spill/Release:	No US	T Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:		T Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		ste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No Oth	•			
Soil and Water Testing Lab:	No	o			
Company		Listing Submitte	ed 10/14/2025	Area of state conducts work	
	Pho	/	10/14/2023	Coastal (East of I-95): Yes	
Petroleum Equipment Service of Wilson, Inc.	FIIU				
	_	` '			
PO Box 502	_	Fax (252) 237-5507		Central (West of I-95 and East of I-77): Yes	
	F	Fax (252) 237-5507			
PO Box 502 711 S. Goldsboro St. Wilson, NC 27894	F Webs	ite www.peswilson.com		Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No	
PO Box 502 711 S. Goldsboro St. Wilson, NC 27894	Webs	ite www.peswilson.com and Monitoring		Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No  UST Equipmment Service Contractors	
PO Box 502 711 S. Goldsboro St. Wilson, NC 27894  Comp Automatic Line Leak Detector Testing:	Webs  Voliance Testing a  No Ove	ite www.peswilson.com and Monitoring erfill Prevention Equipment Operability Check:	No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	Yes
PO Box 502 711 S. Goldsboro St. Wilson, NC 27894  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing:	Webs  Voliance Testing at No Over No State	ite www.peswilson.com and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services:	No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	<u>Yes</u>
PO Box 502 711 S. Goldsboro St. Wilson, NC 27894  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Webs  Valiance Testing at the No Over No State No Spil	ite www.peswilson.com and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing:	No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	<u>Yes</u> <u>Yes</u>
PO Box 502 711 S. Goldsboro St. Wilson, NC 27894  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Websi No Ove No Star No Spil No Tan	ite www.peswilson.com and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing:	No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes
PO Box 502 711 S. Goldsboro St. Wilson, NC 27894  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No Ove No Star No Spil No Tan No US	ite www.peswilson.com  and Monitoring  erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Ill Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessments):	No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:  UST Equipment Installation - Other:  UST Equipment Repair:	Yes Yes Yes Yes
PO Box 502 711 S. Goldsboro St. Wilson, NC 27894  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Ove No Star No Spil No Tan No US	ite www.peswilson.com  and Monitoring  erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections:	No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes
PO Box 502 711 S. Goldsboro St. Wilson, NC 27894  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No Ove No Star No Spil No Tan No US	ite www.peswilson.com  and Monitoring  erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections:	No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes
PO Box 502 711 S. Goldsboro St. Wilson, NC 27894  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Ove No Star No Spil No Tan No US	ite www.peswilson.com  and Monitoring  erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections:	No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes
PO Box 502 711 S. Goldsboro St. Wilson, NC 27894  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Ove No Star No Spil No Tan No US' No US' No Oth	ite www.peswilson.com  and Monitoring  erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Ill Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: Ier:	No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
PO Box 502 711 S. Goldsboro St. Wilson, NC 27894  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Webs  No Ove No Star No Spil No Tan No US No US No Oth No Oth	ite www.peswilson.com  and Monitoring  erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Ill Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: Ier:	No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
PO Box 502 711 S. Goldsboro St. Wilson, NC 27894  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Over No UST No Oth N	ite www.peswilson.com  and Monitoring  erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: ter:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
PO Box 502 711 S. Goldsboro St. Wilson, NC 27894  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En  Emergency Cleanup - Spill/Release:	No Over No UST No Oth No Oth No UST No UST No Oth No Oth No UST No UST No Oth No UST N	ite www.peswilson.com  and Monitoring  arfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: aer:  arvice Firms T Compliance Consultants:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
PO Box 502 711 S. Goldsboro St. Wilson, NC 27894  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Over No UST No Oth No Oth No UST No UST No Oth No Oth No UST No UST No Oth No UST N	ite www.peswilson.com  and Monitoring  erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: er:  ervice Firms T Compliance Consultants: T Equipment Verification: ste Disposal and Treatment:	No No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes

Company			Listing Sub	bmitted	8/19/2024	Area of state conducts work	
Piedmont Geologic, P.C.	F	Phone (	919) 954-9700			Coastal (East of I-95): Yes	
6003-145 Chapel Hill Road		Fax				Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27607						Mountains (West of I-77): Yes	
	We	bsite <u>v</u>	www.piedmontgeologic.com			Wouldains (West Of 1-77). Tes	
Сотр	liance Testir	ng and M	onitoring			<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No	Overfill Pro	evention Equipment Operability Che	eck: N	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:			Iventory Reconciliation Services:	١	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Preve	ention Equipment Testing:	١	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		_	tness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:			nal Inspections (Integrity Assessmen	nts): N	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Interr	nal Lining Inspections:	1	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No
Line Tightness Testing:	No					UST System Removal:	<u>Yes</u>
En	vironmental	Service	Firms			Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Com	pliance Consultants:	)	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:		UST Equip	oment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	<del></del>		posal and Treatment:	1	No		
Oil and Solvent Recycling:		Other:					
Soil and Water Testing Lab:	No						
Company			Listing Sub	bmitted	11/1/2023	Area of state conducts work	
Company Pilot Geological , PLLC	F	Phone (	Listing Sub 336) 870-3095	bmitted	11/1/2023	Area of state conducts work  Coastal (East of I-95): Yes	
Pilot Geological , PLLC PO Box 128	F	`	336) 870-3095	bmitted	11/1/2023	Coastal (East of I-95): Yes	
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court	F	`		bmitted	11/1/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Pilot Geological , PLLC PO Box 128		Fax (	336) 870-3095	bmitted	11/1/2023	Coastal (East of I-95): Yes	
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285		Fax (	336) 870-3095 336) 310-4527 www.pilotenviro.com	bmitted	11/1/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285	We	Fax ( bsite <u>v</u>	336) 870-3095 336) 310-4527 www.pilotenviro.com		11/1/2023	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285	We bliance Testin	Fax ( bsite value of the state	336) 870-3095 336) 310-4527 www.pilotenviro.com onitoring	eck: N		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comp	We pliance Testin No No	Fax ( bsite v ng and M Overfill Pro Statistical	336) 870-3095 336) 310-4527  www.pilotenviro.com  onitoring  evention Equipment Operability Chec	eck: N	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	We viliance Testin No No	Fax (  bsite y  ng and M  Overfill Pro Statistical  Spill Prevent	336) 870-3095 336) 310-4527  www.pilotenviro.com  onitoring  evention Equipment Operability Check Iventory Reconciliation Services:	eck: N	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	We pliance Testin No No No	Fax (  Posite variable of the second of the	336) 870-3095 336) 310-4527  www.pilotenviro.com  onitoring  evention Equipment Operability Check Iventory Reconciliation Services: ention Equipment Testing:	eck: N	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	We bliance Testin No No No No	Fax (  bsite variable of the state of the st	336) 870-3095 336) 310-4527  www.pilotenviro.com  onitoring  evention Equipment Operability Check Iventory Reconciliation Services: ention Equipment Testing: tness Testing:	eck: N	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Webliance Testin	Fax (  bsite variable of the state of the st	336) 870-3095 336) 310-4527  www.pilotenviro.com  onitoring  evention Equipment Operability Cher Iventory Reconciliation Services: ention Equipment Testing: tness Testing: nal Inspections (Integrity Assessment	eck: N	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Webliance Testin	Fax (  bsite variable of the state of the st	336) 870-3095 336) 310-4527  www.pilotenviro.com  onitoring  evention Equipment Operability Cher Iventory Reconciliation Services: ention Equipment Testing: tness Testing: nal Inspections (Integrity Assessment	eck: N	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	We bliance Testin	Fax (  bsite v  ng and M  Overfill Prove Statistical Spill Preve Tank Tight UST Interr UST Interr Other:	336) 870-3095 336) 310-4527  www.pilotenviro.com  onitoring  evention Equipment Operability Check Iventory Reconciliation Services: ention Equipment Testing: tness Testing: nal Inspections (Integrity Assessmental Lining Inspections:	eck: N	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	We bliance Testir No	Fax (  bsite variable of the state of the st	336) 870-3095 336) 310-4527  www.pilotenviro.com  onitoring  evention Equipment Operability Check Iventory Reconciliation Services: ention Equipment Testing: tness Testing: nal Inspections (Integrity Assessmental Lining Inspections:	eck: N	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	We bliance Testir No	Fax (  bsite variable of the state of the st	336) 870-3095 336) 310-4527  www.pilotenviro.com  onitoring  evention Equipment Operability Check Iventory Reconciliation Services: ention Equipment Testing: tness Testing: nal Inspections (Integrity Assessment In Inspections) al Lining Inspections:	eck: N N N nts): N	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En Emergency Cleanup - Spill/Release:	We bliance Testir No	Fax (  bsite variable of the state of the st	336) 870-3095 336) 310-4527   www.pilotenviro.com  onitoring  evention Equipment Operability Check Iventory Reconciliation Services: ention Equipment Testing: tness Testing: nal Inspections (Integrity Assessmental Lining Inspections:  Firms pliance Consultants:	eck: N	No No No No No Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	We bliance Testir No Vironmental Yes Yes	Fax (  bsite variable of the state of the st	336) 870-3095 336) 310-4527  www.pilotenviro.com  onitoring  evention Equipment Operability Check Iventory Reconciliation Services: ention Equipment Testing: tness Testing: nal Inspections (Integrity Assessment al Lining Inspections:  Firms pliance Consultants: oment Verification:	eck: N	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

Company		Listing Submitted		Area of state conducts work	
Pyramid Environmental & Engineering, PC		Phone (336) 335-3174		Coastal (East of I-95): Yes	
503 Industrial Avenue		Fax (336) 691-0648		Central (West of I-95 and East of I-77): Yes	
P.O. Box 16265		(000) 00 1 00 10		Mountains (West of I-77): Yes	
Greensboro, NC 27406	V	/ebsite <u>www.pyramidenvironmental.com</u>		Mountains (West of 1-77). Tes	
Comp	oliance Test	ing and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	12/12/2025	Area of state conducts work	
SPATCO Energy Solutions		Phone (800) 477-8286	12/12/2020	Coastal (East of I-95): Yes	
301 McCullough Dr		,			
Suite 500		Fax		Central (West of I-95 and East of I-77): Yes	
Charlotte, NC 28262	V	/ebsite spatco.com		Mountains (West of I-77): Yes	
Comr	oliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:					
	Yes	Statistical Iventory Reconciliation Services:	Yes	Leak Detection Equipment Installation, Servicing	
	<u>Yes</u> Yes	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	<u>Yes</u> Yes	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	<u>Yes</u> Yes
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	Yes
Corrosion Protection Design Experts: Corrosion Protection System Repairs:	<u>Yes</u> <u>Yes</u>	Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes Yes	Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Yes Yes	Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes Yes Yes	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes Yes Yes	Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes Yes	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	Yes Yes Yes Yes Yes	Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes Yes Yes	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes Yes Yes Yes	Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes Yes Yes	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes Yes Yes Yes Yes Yes	Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes Yes Yes Yes	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	Yes Yes Yes Yes Yes Yes Yes Yes Yes	Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Al Service Firms UST Compliance Consultants:	Yes Yes Yes Yes Yes	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes Yes Yes Yes Yes Yes Yes Tes Yes Yes Yes Yes	Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  al Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes Yes Yes Yes Yes Yes	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	Yes Yes Yes Yes Yes Yes Yes Yes  Yes Yes	Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	Yes Yes Yes Yes Yes	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes Yes Yes Yes Yes Yes Yes Tes Yes Yes Yes Yes	Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  al Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes Yes Yes Yes Yes Yes	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes

UST Service Provider Lis	(All) - UST Equipment	t Service Contractors Only
--------------------------	-----------------------	----------------------------

Company		Listing Submi	itted 7/30/2024	Area of state conducts work	
SR&R Environmental, Inc.	Р	hone (910) 763-6274		Coastal (East of I-95): Yes	i
4920 Highway 421 N.		Fax (910) 763-6132		Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28401		(610) 100 0102		Mountains (West of I-77): Yes	
	Wel	osite <u>www.srrenviro.com</u>		Mountains (West of 1-77). Tes	1
Comp	liance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No (	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	tatistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	pill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		ank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No l	IST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No l	IST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No (	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes U	IST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:		IST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No V	Vaste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	<u>Yes</u>	Other: F	uel Polishing		
Soil and Water Testing Lab:	No		-		
Company		Listing Submi	itted 3/6/2024	Area of state conducts work	
	P	Listing Submi	itted 3/6/2024	Area of state conducts work  Coastal (East of I-95): Yes	·
Company Titan Environmental Group 2005 Citation Drive	P	hone (984) 200-6825	itted 3/6/2024	Coastal (East of I-95): Yes	
Titan Environmental Group	P		itted 3/6/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Titan Environmental Group 2005 Citation Drive		hone (984) 200-6825	itted 3/6/2024	Coastal (East of I-95): Yes	
Titan Environmental Group 2005 Citation Drive Garner, NC 27529	We	hone (984) 200-6825 Fax	itted 3/6/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Titan Environmental Group 2005 Citation Drive Garner, NC 27529	We	hone (984) 200-6825  Fax  psite www.titanenvirogroup.com	itted 3/6/2024	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Titan Environmental Group 2005 Citation Drive Garner, NC 27529  Comp	Wel	hone (984) 200-6825  Fax  psite www.titanenvirogroup.com  g and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	:
Titan Environmental Group 2005 Citation Drive Garner, NC 27529  Comp Automatic Line Leak Detector Testing:	Wel	hone (984) 200-6825  Fax  Disite www.titanenvirogroup.com  g and Monitoring  Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529  Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	Wel	hone (984) 200-6825  Fax  Desite www.titanenvirogroup.com  g and Monitoring  Overfill Prevention Equipment Operability Check: statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Welliance Testin No G No S No S No S	hone (984) 200-6825  Fax  psite www.titanenvirogroup.com  g and Monitoring  Overfill Prevention Equipment Operability Check: statistical Iventory Reconciliation Services: spill Prevention Equipment Testing:	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:	No No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Well Diliance Testin No G No S No S No T No No C	hone (984) 200-6825  Fax  psite www.titanenvirogroup.com  g and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Sank Tightness Testing:	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Welliance Testin No C No S No S No S No N	hone (984) 200-6825  Fax  posite www.titanenvirogroup.com  g and Monitoring  Overfill Prevention Equipment Operability Check: statistical Iventory Reconciliation Services: spill Prevention Equipment Testing: sank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Welliance Testin No C No S No S No S No N	hone (984) 200-6825  Fax  Desite www.titanenvirogroup.com  g and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Sp	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Soliance Testin	hone (984) 200-6825  Fax  Desite www.titanenvirogroup.com  g and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Sp	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Welliance Testin No (No S) No S) No (No No N	hone (984) 200-6825  Fax  Desite www.titanenvirogroup.com  g and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Sank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er  Emergency Cleanup - Spill/Release:	Welliance Testin No (No S) No (S) No	hone (984) 200-6825  Fax  Desite www.titanenvirogroup.com  g and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Service Firms  UST Internal Lining Inspections: Other:  Description Service Firms  UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Well  No (No S)  No (No No N	hone (984) 200-6825  Fax  psite www.titanenvirogroup.com  g and Monitoring  Dverfill Prevention Equipment Operability Check: statistical Iventory Reconciliation Services: spill Prevention Equipment Testing: sank Tightness Testing: IST Internal Inspections (Integrity Assessments): IST Internal Lining Inspections: Other:  Service Firms IST Compliance Consultants: IST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er  Emergency Cleanup - Spill/Release:	Welliance Testin  No Conversion C	hone (984) 200-6825  Fax  Desite www.titanenvirogroup.com  g and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Service Firms  UST Internal Lining Inspections: Other:  Description Service Firms  UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

Place Construction LLC	Company		Listing Submitted	1/31/2023	Area of state conducts work	
PO Box 680654 Fort Payne, AL 35968 Website  Compliance Testing and Monitoring  Automatic Line Leak Detector Testing: No Overfile Prevention Equipment Operability Check: No Statistical Ventroly Reconcilation Services: No Spill Bucket Installation Repairs: No Statistical Ventroly Reconcilation Services: No Use Teach Detection Equipment Installation Servicing: No Use Teach Detection System Repairs: No Statistical Ventor Repairs: No Statistical Ventor Repair System Repairs: No Teach Teach System Repairs: No Statistical Ventor Repair System Repairs: No Use Teach Detection System Repairs: No Teach Teach System Repairs: No Use Teach Detection System Repairs: No Detection Design Exports: No Use Teach Detection System Repairs: No Use Teach Detection Sy	Valor Construction LLC		Phone (205) 577-1035		Coastal (East of I-95): Yes	
Website   Webs	PO Box 680654		,			
Compilance Testing and Monitoring	Fort Payne, AL 35968					
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconcilation Services: No Spill Prevention Equipment Services: No Spill Prevention Equipment Services: No Spill Evention Equipment Services: No Spill Evention Equipment Services: No Spill Evention Equipment Services: No UST internal Inspire Evention Equipment Services: No UST Equipment Installation Servicing: No UST System Repair: No UST System Installation Servicing: No UST System Removal: UST System Rem			Website		Mountains (West of 1-77): Tes	
Contrainment Sump Testing: No Substitucial brentory Reconcilation Services: No Spill Prevention Equipment Testing: No Spill Bucket Installation Equipment Installation Servicing: No Corrosion Protection Design Experts: No Spill Bucket Installation Repair: No Tark Tightness Testing: No UST Internal Inspections (Height) Assessments): No UST Equipment Installation - Orther: No UST Equipment Repair: Vest UST System Installation - Complete Systems: Vest UST System Removal: UST Compliance Consultants: No Other:  Oiler:  Company  Listing Submitted  11/1/2023  Area of state conducts work  Withers Revenel, Inc. Phone (919) 469-3340  Fax  Coastal (East of 1-95): Yes  Company  Website www.withersravenel.com  Compliance Testing Lab: Website www.withersravenel.com  Website www.withersravenel.com  UST Equipment Service Contractors  Mountains (West of 1-77): Yes  Worksoft of 1-77): Yes  Website www.withersravenel.com  No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Bucket Installation Papair: No UST Equipment Installation: No UST Equipment Installation: No UST Equipment Installation: No UST Equipment Installation: No UST Equipment Repair: No UST Repair Installation: No UST Equipment Repair: No UST Repair Installation: No UST Equipment Installation: No UST System Repairs: No UST Repair Installation: No UST System Repairs: No UST Repair Installation: No UST	Comp	oliance To	esting and Monitoring		<b>UST Equipmment Service Contractors</b>	
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: Yes UST System Removal: Yes UST System Removal: Yes UST Equipment Repair: No UST Compliance Consultants: No UST Equipment Repair: No UST Equipment Service: No UST Equipment Service Contractors  Automatic Line Leak Detector Testing: No Overill Prevention Equipment Deprability Check: No UST Equipment Service Contractors No Equipment Equipment Repair: No UST Equipment Installation Services: No UST Internal Lining Inspections: No UST Equipment Installation Pepair: No UST Equipment Repair: No UST Equ	Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Internal Inspections (Integrity Assessments): No UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST System Installation: Yes UST System Installation: Yes UST System Installation: Yes UST System Installation: Yes UST Piping/Sump Installation: Yes UST System Removal: Yes UST Piping/Sump Installation: No UST Equipment Reposition: No UST Installation: No UST Equipment Installation: No UST Installation: No UST Installation: No UST Installation: Yes UST Piping/Sump Installation: No UST Equipment Installation Repair: No UST Equipment Piping: No UST Installation: No UST	Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST System Installation: Complete Systems: Yes UST PlpingSump Installation: Complete Systems: Yes UST System Installation: Complete Systems: Yes UST System Removal: Yes UST Compliance Consultants: No UST Equipment Verification: No UST Equipment Verification: No UST Equipment Verification: No UST Compliance Consultants: No UST Equipment Verification: No UST Compliance Testing and Tevatment: No UST Internal Inspections (Integrity Assessments): No UST Equipment Service Contractors    Value	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Leak Detection Equipment Operability Check: No Other: Wo Other: UST piping/Sump Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST Piping/Sump Installation: Yes UST Piping/Sump Installation: Yes UST Piping/Sump Installation: Yes UST System Removal: Other: UST Piping/Sump Installation: Yes UST System Removal: Other: UST Equipment Performance Consultants: No Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Environmental Engineer/Geologist - Site Checks: No Other: No Other: No Other: Other: Verification: No Other: No		No	Tank Tightness Testing:	No	• •	No
Leak Detection Monitoring Services: No Other:  Line Tightness Testing: No Other:  Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Other:  Oli and Solvent Recycling: No Other:  No Other:  Listing Submitted 11/1/2023 Area of state conducts work  Company Listing Submitted 11/1/2023 Area of state conducts work  Withers Ravenel, Inc. Phone (919) 469-3340 Capta No Other:  Website www.withersravenel.com  Containment Sump Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Statistical Ventory Recycling: No Statistical Ventory Recycling: No Spill Prevention Equipment Testing: No Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repairs: No Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repairs: No Leak Detection Equipment Operability Check: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repairs: No UST Equipment Repairs: No UST Equipment Inspections (Integrity Assessments): No UST Equipment Repairs:	Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Line Tightness Testing: No	Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Environmental Service Firms  Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Oil and Solvent Recycling: Soil and Water Testing Lab: No Other:  Listing Submitted 11/1/2023  Area of state conducts work Withers Ravenel, Inc. Phone (919) 469-3340  Fax  Company  Listing Submitted 11/1/2023  Area of state conducts work  Withers Ravenel, Inc. Phone (919) 469-3340  Coastal (East of I-95): Yes Carly, NC 27591  Website www.withersravenel.com  Compliance Testing and Monitoring  Website www.withersravenel.com  UST Equipment Service Contractors  Wountains (West of I-77): Yes Mountains (West of I-77): Yes Mountains (West of I-77): Yes  Corrosion Protection Design Experts: No Spill Prevention Equipment Operability Check: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST Equipment Installation - Cher: No UST Equipment Pessing: No UST Equipment Installation - Cher: No UST Equipment Installation: No UST Equipment Installation: No UST Equipment Installation - Cher: No UST Equipment Installation Repair: No UST Equipment Installation - Cher: No UST System Installation - Cher:	Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Emergency Cleanup - Spill/Release:  No UST Compliance Consultants: No UST Compliance Consultants: No UST Compliance Consultants: No UST Compliance Consultants: No UST Equipment Verification: No Other:  Company  Listing Submitted 11/1/2023  Area of state conducts work  Constant (East of 1-95): Yes  Contrait (West of 1-77): Yes  Website www.withersravenel.com  Automatic Line Leak Detector Testing: No Other:  Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST System Repair: No UST Internal Lining Inspections: No UST System Repair: No UST System Removal: No UST System Removal	Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Other:  No Other:  O	E	nvironme	ntal Service Firms		Other:	
Environmental Engineer/Geologist Soil and GW Cleanu No Other:  Oil and Solvent Recycling:  No Other:  No Other:  Soil and Water Testing Lab:  No Other:  Company  Withers Ravenel, Inc.  115 MacKenan Drive Cary, NC 27591  Complance Testing and Monitoring  Automatic Line Leak Detector Testing:  No Overfill Prevention Equipment Operability Check:  No Statistical Iventory Reconciliation Services:  No Spill Prevention Equipment Testing:  No Tank Tightness Testing:  No UST Internal Lining Inspections:  No UST Internal Lining Inspections:  No UST System Removal:  No UST System Remova	Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Oil and Solvent Recycling: Soil and Water Testing Lab: No  Listing Submitted 11/1/2023 Area of state conducts work  Company Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Fax Website www.withersravenel.com  Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Corrosion Protection Design Experts: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Equipment Operability Check: No Leak Detection Equipment Installation - Other: No Leak Detection Equipment Operability Check: No Leak Detection Equipment Installation - Other: No Leak Detection Monitoring Services: No UST Equipment Repair: No UST Equipment Installation - Other: No UST System Installation - Other: No UST System Installation - Other: No UST System Installation: No UST System Removal: Yes UST System Removal: Yes UST System Removal: Yes UST System Removal: No Oil and Solvent Recycling: No Other:	Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Company   Listing Submitted   11/1/2023   Area of state conducts work	Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Company  Listing Submitted  11/1/2023  Area of state conducts work  Withers Ravenel, Inc.  115 MacKenan Drive Cary, NC 27591  Website  Www.withersravenel.com  Compliance Testing and Monitoring  Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No UST System Removal: Yes  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Other: No Other:	Oil and Solvent Recycling:	No	Other:			
Withers Ravenel, Inc.  Phone (919) 469-3340  Coastal (East of I-95): Yes  Cary, NC 27591  Website www.withersravenel.com  Website www.withersravenel.com  UST Equipmment Service Contractors  Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Servicing: No Corrosion Protection System Repairs: No UST Equipment Installation - Other: No Corrosion Protection System Repairs: No UST Equipment Operability Check: No UST Equipment Installation - Other: No Corrosion Protection System Repairs: No UST Equipment Operability Check: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Omplete Systems: No UST Piping/Sump Installation: No UST System Removal: UST System Rem	Soil and Water Testing Lab:	No				
Withers Ravenel, Inc.  115 MacKenan Drive Cary, NC 27591  Website www.withersravenel.com  Wobsite www.withersravenel.com  Wobsite www.withersravenel.com  Wobsite www.withersravenel.com  Wobsite www.withersravenel.com  Wobsite www.withersravenel.com  Wountains (West of I-95; Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes Wolf Internal Lines of I-70; Yes Wolf Internal Lines of Internal Lines of Internal Lines of Internal Lines of Internal L						
Website www.withersravenel.com  Website www.withersravenel.com  Website www.withersravenel.com  Website www.withersravenel.com  Website www.withersravenel.com  Website www.withersravenel.com  West of I-77): Yes  Mountains (West of I-77): Yes  Mountains (West of I-77): Yes  Wountains (West of I-77): Yes  Website www.withersravenel.com  Wountains (West of I-77): Yes  Mountains (West of I-77): Yes  Website www.withersravenel.com  UST Equipment Service Contractors  No  Dispenser Meter Repair/Calibration: No  Leak Detection Design Experts: No Spill Prevention Equipment Testing: No  Spill Bucket Installation Servicing: No  UST Equipment Installation - Other: No  UST Equipment Repair: No  UST Equipment Repair: No  UST Equipment Repair: No  UST Equipment Repair: No  UST System Installation - Complete Systems: No  UST System Installation - Complete Systems: No  UST System Removal: Yes  Emergency Cleanup - Spill/Release: Yes  Environmental Service Firms  Emergency Cleanup - Spill/Release: Yes  UST Equipment Verification: No  Oil and Solvent Recycling: No  Other:	Company		Listing Submitted	11/1/2023	Area of state conducts work	
Website www.withersravenel.com  Compliance Testing and Monitoring  Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No UST Equipment Installation Servicing: No UST Equipment Installation Repair: No UST Equipment Installation Repair: No UST Equipment Installation Repair: No UST Equipment Installation Prevention Equipment Operability Check: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: Yes UST System Removal: Yes UST System Removal: Yes UST System Removal: Yes Other:			<b>-</b>	11/1/2023		
Compliance Testing and Monitoring  Automatic Line Leak Detector Testing:  No Overfill Prevention Equipment Operability Check:  No Containment Sump Testing:  No Statistical Iventory Recordiliation Services:  No Spill Prevention Equipment Testing:  No Spill Prevention Equipment Testing:  No Spill Prevention Equipment Testing:  No Spill Bucket Installation Repair:  No Spill Bucket Installation Repair:  No Spill Bucket Installation - Other:  No UST Internal Inspections (Integrity Assessments):  No UST Equipment Installation:  No UST Equipment Installation:  No UST Equipment Installation:  No UST Equipment Installation:  No UST Equipment Nepair:  No UST Equipment Repair:  No UST System Installation - Complete Systems:  No UST System Installation:  No UST System Removal:  Yes  Emergency Cleanup - Spill/Release:  Environmental Service Firms  Emergency Cleanup - Spill/Release:  Environmental Engineer/Geologist - Site Checks:  Yes  UST Compliance Consultants:  Environmental Engineer/Geologist Soil and GW Cleanu Yes  Waste Disposal and Treatment:  No  Oil and Solvent Recycling:  No  Other:	Withers Ravenel, Inc.		Phone (919) 469-3340	11/1/2023	Coastal (East of I-95): Yes	
Automatic Line Leak Detector Testing:  No Overfill Prevention Equipment Operability Check:  No Containment Sump Testing:  No Statistical Iventory Reconciliation Services:  No Corrosion Protection Design Experts:  No Spill Prevention Equipment Testing:  No Spill Prevention Equipment Testing:  No Spill Prevention Equipment Testing:  No Spill Bucket Installation Repair:  No Spill Bucket Installation Repair:  No UST Equipment Installation - Other:  No UST Equipment Installation - Other:  No UST Equipment Repair:  No UST Equipment Repair:  No UST Equipment Repair:  No UST System Installation - Complete Systems:  No UST System Installation - Complete Systems:  No UST Piping/Sump Installation:  No UST System Removal:  Yes  Environmental Service Firms  Emergency Cleanup - Spill/Release:  Environmental Engineer/Geologist - Site Checks:  Yes  UST Compliance Consultants:  Yes  Environmental Engineer/Geologist Soil and GW Cleanu Yes  Waste Disposal and Treatment:  No Other:	Withers Ravenel, Inc. 115 MacKenan Drive		Phone (919) 469-3340	11/1/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Containment Sump Testing:  No Statistical Iventory Reconciliation Services:  No Corrosion Protection Design Experts:  No Spill Prevention Equipment Testing:  No Spill Prevention Equipment Testing:  No Corrosion Protection System Repairs:  No Tank Tightness Testing:  No UST Internal Inspections (Integrity Assessments):  No UST Equipment Installation - Other:  No UST Equipment Repair:  No UST Equipment Repair:  No UST Equipment Repair:  No UST System Installation - Complete Systems:  No UST System Installation:  No UST System Removal:  Other:  Emergency Cleanup - Spill/Release:  Environmental Engineer/Geologist - Site Checks:  Yes UST Compliance Consultants:  Yes UST Equipment Verification:  No Other:  No Other:	Withers Ravenel, Inc. 115 MacKenan Drive		Phone (919) 469-3340  Fax	11/1/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other: No Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No Leak Detection Monitoring Services: No Other: UST Piping/Sump Installation: No UST System Removal: Yes  Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: Yes Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Other:  Dil and Solvent Recycling: No Other:	Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591	oliance To	Phone (919) 469-3340 Fax Website www.withersravenel.com	11/1/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No Leak Detection System Testing: No UST Internal Lining Inspections: No Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No Leak Detection Monitoring Services: No Other:  Line Tightness Testing: No Other:  Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: Yes Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Other:  Oil and Solvent Recycling: No Other:  No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: UST System Removal: Yes UST System Removal: Yes UST System Removal: No UST System Removal: Yes UST System Removal: No Other:	Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591		Phone (919) 469-3340  Fax  Website www.withersravenel.com esting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Corrosion Protection System Testing:  Leak Detection Equipment Operability Check:  No UST Internal Inspections (Integrity Assessments):  No Leak Detection Equipment Operability Check:  No Other:  No UST System Installation - Complete Systems:  No UST Piping/Sump Installation:  No UST Piping/Sump Installation:  No UST System Removal:  Ves Other:  Emergency Cleanup - Spill/Release:  Environmental Engineer/Geologist - Site Checks:  Yes UST Compliance Consultants:  Yes Environmental Engineer/Geologist Soil and GW Cleanu Oil and Solvent Recycling:  No Other:	Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591  Comparison Compariso	No	Phone (919) 469-3340  Fax  Website www.withersravenel.com  esting and Monitoring  Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No Leak Detection Monitoring Services: No Other: UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Installation: No UST System Installation: No UST System Installation: No UST System Installation: No UST System Removal: Yes  Environmental Service Firms  Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: Yes UST Equipment Verification: No Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Oil and Solvent Recycling: No Other:	Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591  Comparison Leak Detector Testing: Containment Sump Testing:	No No	Phone (919) 469-3340  Fax  Website www.withersravenel.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Leak Detection Monitoring Services:  No Other:  No UST Piping/Sump Installation:  Ves UST System Removal:  Yes Other:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu Oil and Solvent Recycling: No Other:  UST Piping/Sump Installation:  No UST System Removal:  Yes UST Compliance Consultants: Yes UST Equipment Verification: No Other:	Withers Ravenel, Inc.  115 MacKenan Drive Cary, NC 27591  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No	Phone (919) 469-3340  Fax  Website www.withersravenel.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
Line Tightness Testing:    Environmental Service Firms	Withers Ravenel, Inc.  115 MacKenan Drive Cary, NC 27591  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No	Phone (919) 469-3340  Fax  Website www.withersravenel.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Emergency Cleanup - Spill/Release:  Emergency Cleanup - Spill/Release:  Environmental Engineer/Geologist - Site Checks:  Environmental Engineer/Geologist Soil and GW Cleanu  Yes  Waste Disposal and Treatment:  Other:  Other:	Withers Ravenel, Inc.  115 MacKenan Drive Cary, NC 27591  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone (919) 469-3340  Fax  Website www.withersravenel.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Emergency Cleanup - Spill/Release:  Environmental Engineer/Geologist - Site Checks:  Environmental Engineer/Geologist Soil and GW Cleanu  Yes  Waste Disposal and Treatment:  No  Oil and Solvent Recycling:  No  Other:	Withers Ravenel, Inc.  115 MacKenan Drive Cary, NC 27591  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Phone (919) 469-3340  Fax  Website www.withersravenel.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other:	Withers Ravenel, Inc.  115 MacKenan Drive Cary, NC 27591  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No	Phone (919) 469-3340  Fax  Website www.withersravenel.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other:	Withers Ravenel, Inc.  115 MacKenan Drive Cary, NC 27591  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Phone (919) 469-3340  Fax  Website www.withersravenel.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other:	Withers Ravenel, Inc.  115 MacKenan Drive Cary, NC 27591  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 469-3340  Fax  Website www.withersravenel.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Oil and Solvent Recycling: No Other:	Withers Ravenel, Inc.  115 MacKenan Drive Cary, NC 27591  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release:	No Vo	Phone (919) 469-3340  Fax  Website www.withersravenel.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Intal Service Firms  UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Soil and Water Testing Lab: No	Withers Ravenel, Inc.  115 MacKenan Drive Cary, NC 27591  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No No No No No Vo  revironme Yes Yes	Phone (919) 469-3340  Fax  Website www.withersravenel.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Intal Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
	Withers Ravenel, Inc.  115 MacKenan Drive Cary, NC 27591  Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanup	No No No No No No No Vo  rvironme Yes Yes Yes	Phone (919) 469-3340  Fax  Website www.withersravenel.com  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Intal Service Firms  UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No