# UST Service Provider List (All)

| Company | Listing Submitted | 8/19/2024 | Area of state conducts work | |
|---|---|---|---|---|
| **A1 Environmental Services Inc**<br>PO Box 59<br>Greenville, NC 27835 | **Phone**<br>**Fax**<br>**Website** | (252) 531-1284<br><br>www.aes-nc.com | **Coastal (East of I-95):**<br>**Central (West of I-95 and East of I-77):**<br>**Mountains (West of I-77):** | Yes<br>No<br>No |

| Compliance Testing and Monitoring | | | | UST Equipmment Service Contractors | |
|---|---|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | **Yes** |
| | | | | Other: | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | **Yes** |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| Company | Listing Submitted | 1/18/2024 | Area of state conducts work | |
|---|---|---|---|---|
| **Advanced Environmental Services, Inc.**<br>PO Box 38218<br>Greensboro, NC 27438 | **Phone**<br>**Fax**<br>**Website** | (336) 282-3586<br>(336) 282-3587<br>AdavancedEnvironmental.com | **Coastal (East of I-95):**<br>**Central (West of I-95 and East of I-77):**<br>**Mountains (West of I-77):** | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | | UST Equipmment Service Contractors | |
|---|---|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | **Yes** |
| | | | | Other: | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | **Yes** | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | **Yes** |
| Oil and Solvent Recycling: | **Yes** | Other: | |
| Soil and Water Testing Lab: | No | | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 10/25/2026 | Area of state conducts work | |
|---|---|---|---|---|
| **Bay Compliance and Testing LLC**<br>315 Great Bridge Blvd. (Unit B)<br>Chesapeake, VA 23320- | Phone<br>Fax<br>Website | (757) 410-5974<br><br>https://baycomplianceandtesting.com | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | Yes<br>No<br>No |

| Compliance Testing and Monitoring | | | | UST Equipmment Service Contractors | |
|---|---|---|---|---|---|
| Automatic Line Leak Detector Testing: | **Yes** | Overfill Prevention Equipment Operability Check: | **Yes** | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | **Yes** | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | **Yes** | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | **Yes** | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | **Yes** | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | **Yes** | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | Dri-Sump | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | **Yes** | | | UST System Removal: | No |
| | | | | Other: | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | **Yes** |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| Company | Listing Submitted | 6/26/2024 | Area of state conducts work | |
|---|---|---|---|---|
| **BUCKEYE ELM CONTRACTING, LLC**<br>PO Box 1026<br>MOCKSVILLE, NC 27028 | Phone<br>Fax<br>Website | (336) 337-6001<br><br>www.buckeye-elm.com | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | | UST Equipmment Service Contractors | |
|---|---|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | **Yes** |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | **Yes** |
| Line Tightness Testing: | No | | | UST System Removal: | **Yes** |
| | | | | Other: | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | **Yes** | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | **Yes** |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 10/27/2026 | Area of state conducts work | |
|---|---|---|---|---|
| **Bunnell Lammons Engineering, Inc.**<br>30 Park Ridge Drive<br>Fletcher, NC 28732- | Phone<br>Fax<br>Website | (828) 277-0100<br><br>www.blecorp.com | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | No<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | **Yes** | Overfill Prevention Equipment Operability Check: | **Yes** |
| Containment Sump Testing: | **Yes** | Statistical Iventory Reconciliation Services: | **Yes** |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | **Yes** |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | **Yes** |
| Corrosion Protection System Testing: | **Yes** | UST Internal Inspections (Integrity Assessments): | **Yes** |
| Leak Detection Equipment Operability Check: | **Yes** | UST Internal Lining Inspections: | **Yes** |
| Leak Detection Monitoring Services: | **Yes** | Other: | |
| Line Tightness Testing: | **Yes** | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | **Yes** |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | **Yes** |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | **Yes** |
| Oil and Solvent Recycling: | **Yes** | Other: | |
| Soil and Water Testing Lab: | **Yes** | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | No |
| Other: | |

| Company | Listing Submitted | 6/27/2024 | Area of state conducts work | |
|---|---|---|---|---|
| **Cobb Environmental & Technical Services, Inc.**<br>P. O. Box 1602<br>Tupelo, MS 38802 | Phone<br>Fax<br>Website | (662) 841-0995<br>(662) 841-0810<br>cobbenv.com | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | **Yes** | Overfill Prevention Equipment Operability Check: | **Yes** |
| Containment Sump Testing: | **Yes** | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | **Yes** |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | **Yes** | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | **Yes** |
| Spill Bucket Installation Repair: | **Yes** |
| UST Equipment Installation - Other: | **Yes** |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | **Yes** |
| UST Piping/Sump Installation: | **Yes** |
| UST System Removal: | **Yes** |
| Other: | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 11/14/2026 | Area of state conducts work |
|---|---|---|---|
| **Conklin Corrosion Control LLC**<br>118 Oak Point Lane<br>Stony Point, NC 28678 | **Phone** (704) 560-9154<br>**Fax**<br>**Website** | | **Coastal (East of I-95):** Yes<br>**Central (West of I-95 and East of I-77):** Yes<br>**Mountains (West of I-77):** Yes |

| Compliance Testing and Monitoring | | | | UST Equipmment Service Contractors | |
|---|---|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | **Yes** | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | **Yes** | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | **Yes** | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | No |
| | | | | Other: | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| Company | Listing Submitted | 10/26/2026 | Area of state conducts work |
|---|---|---|---|
| **D. H. Griffin Wrecking Company**<br>4716 Hilltop Road<br>Greensboro, NC 27407- | **Phone** (336) 214-9012<br>**Fax**<br>**Website** www.dhgriffin.com | | **Coastal (East of I-95):** Yes<br>**Central (West of I-95 and East of I-77):** Yes<br>**Mountains (West of I-77):** Yes |

| Compliance Testing and Monitoring | | | | UST Equipmment Service Contractors | |
|---|---|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | **Yes** |
| | | | | Other: | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | **Yes** | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | **Yes** |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 1/6/2025 | Area of state conducts work | |
|---|---|---|---|---|
| **ECS Southeast, LLC**<br>5260 Greens Dairy Road<br>Raleigh, NC 27616 | Phone<br>Fax<br>Website | (919) 861-9910<br><br>ecslimited.com | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | **Yes** | UST Compliance Consultants: | **Yes** |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | **Yes** |
| Other: | |

| Company | Listing Submitted | 7/2/2024 | Area of state conducts work | |
|---|---|---|---|---|
| **Environmental Hydrogeological Consultants, Inc. DB**<br>PO Box 902<br>Red Springs, NC 28377 | Phone<br>Fax<br>Website | (910) 843-4456<br>(910) 843-5376<br>www.environmentalnc.com | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | **Yes** | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | **Yes** |
| Oil and Solvent Recycling: | **Yes** | Other: | OSRO Certified US Coast Guard Contractor |
| Soil and Water Testing Lab: | **Yes** | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | **Yes** |
| Other: | Liquid/Hydro Excavate Vac Truck Services |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 5/14/2024 | Area of state conducts work | |
|---|---|---|---|---|
| **Environmental Petroleum Services**<br>1234 Gordon Park Rd<br>Augusta, GA 30901 | Phone<br>Fax<br>Website | (877) 297-6763<br><br>www.keepmecompliant.net | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | No<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | **Yes** | Overfill Prevention Equipment Operability Check: | **Yes** |
| Containment Sump Testing: | **Yes** | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | **Yes** | Spill Prevention Equipment Testing: | **Yes** |
| Corrosion Protection System Repairs: | **Yes** | Tank Tightness Testing: | **Yes** |
| Corrosion Protection System Testing: | **Yes** | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | **Yes** | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | **Yes** | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | **Yes** |
| Leak Detection Equipment Installation Servicing: | **Yes** |
| Spill Bucket Installation Repair: | **Yes** |
| UST Equipment Installation - Other: | **Yes** |
| UST Equipment Repair: | **Yes** |
| UST System Installation - Complete Systems: | **Yes** |
| UST Piping/Sump Installation: | **Yes** |
| UST System Removal: | **Yes** |
| Other: | |

| Company | Listing Submitted | 7/16/2024 | Area of state conducts work | |
|---|---|---|---|---|
| **EnviroSouth, Inc.**<br>3440 Augusta Road<br>Greenville, SC 29605 | Phone<br>Fax<br>Website | (864) 236-9010<br><br>www.envirosouth.com | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | No<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | **Yes** |
| Other: | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 8/10/2026 | Area of state conducts work | |
|---|---|---|---|---|
| **Excel Environmental Associates, PLLC**<br>625 Huntsman Court<br>Gastonia, NC 28054 | Phone<br>Fax<br>Website | (704) 853-0800<br>(704) 853-3949<br>www.excelengr.com | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | **Yes** |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | No |
| Other: | |

| Company | Listing Submitted | 10/26/2026 | Area of state conducts work | |
|---|---|---|---|---|
| **Geological Resources, Inc.**<br>3502 Hayes Road<br>Monroe, NC 28110- | Phone<br>Fax<br>Website | (704) 845-4010<br>(704) 845-4012<br>www.grienv.com | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | **Yes** | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | **Yes** |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | **Yes** | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | **Yes** |
| Other: | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 7/3/2024 | Area of state conducts work | |
|---|---|---|---|---|
| **Groundwater Management Associates, Inc.**<br>4300 Sapphire Court<br>Suite 100<br>Greenville, NC 27834 | Phone<br>Fax<br>Website | (252) 758-3310<br><br>www.gma-nc.com | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | No |
| Other: | |

| Company | Listing Submitted | 10/23/2026 | Area of state conducts work | |
|---|---|---|---|---|
| **Harco Services LLC**<br>2 Kelli Clark Ct. SE<br>Cartersville, GA 30121- | Phone<br>Fax<br>Website | (770) 917-8846<br><br>harcoservices.com | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | **Yes** |
| UST Piping/Sump Installation: | No |
| UST System Removal: | **Yes** |
| Other: | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 10/26/2026 | Area of state conducts work |
|---|---|---|---|
| **INENCO Inc.**<br>132 W. Statesville Ave.<br>Mooresville, NC 28115- | **Phone** (704) 662-8192<br>**Fax** (704) 662-8194<br>**Website** | | **Coastal (East of I-95):** No<br>**Central (West of I-95 and East of I-77):** Yes<br>**Mountains (West of I-77):** Yes |

**Compliance Testing and Monitoring**

| | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

**Environmental Service Firms**

| | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | **Yes** |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

**UST Equipmment Service Contractors**

| | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | **Yes** |
| Other: | |

| Company | Listing Submitted | 10/20/2026 | Area of state conducts work |
|---|---|---|---|
| **JBL Solutions Inc.**<br>418 W. State St.<br>Black Mountain, North Carolina 28711- | **Phone** (603) 690-9071<br>**Fax**<br>**Website** JBLsolutionsinc.com | | **Coastal (East of I-95):** Yes<br>**Central (West of I-95 and East of I-77):** Yes<br>**Mountains (West of I-77):** Yes |

**Compliance Testing and Monitoring**

| | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | **Yes** | Overfill Prevention Equipment Operability Check: | **Yes** |
| Containment Sump Testing: | **Yes** | Statistical Iventory Reconciliation Services: | **Yes** |
| Corrosion Protection Design Experts: | **Yes** | Spill Prevention Equipment Testing: | **Yes** |
| Corrosion Protection System Repairs: | **Yes** | Tank Tightness Testing: | **Yes** |
| Corrosion Protection System Testing: | **Yes** | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | **Yes** | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | **Yes** | | |

**Environmental Service Firms**

| | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

**UST Equipmment Service Contractors**

| | |
|---|---|
| Dispenser Meter Repair/Calibration: | **Yes** |
| Leak Detection Equipment Installation Servicing: | **Yes** |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | No |
| Other: | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 5/30/2024 | Area of state conducts work |
|---|---|---|---|
| **Marley Trucking & Demolition Inc.**<br>1768 Old Humble Mill Road<br>Asheboro, NC 27205 | Phone<br>Fax<br>Website | (336) 382-7132 | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | **Yes** |
| Other: | |

| Company | Listing Submitted | 11/9/2026 | Area of state conducts work |
|---|---|---|---|
| **Martin & Slagle Geosciences, PA**<br>173 Sloan Road<br>Franklin, NC 28734- | Phone<br>Fax<br>Website | (828) 712-1115<br>martinandslagle.com | Coastal (East of I-95): No<br>Central (West of I-95 and East of I-77): No<br>Mountains (West of I-77): Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | No |
| Other: | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 10/26/2026 | Area of state conducts work | |
|---|---|---|---|---|
| **McCallum, P.C.**<br>1808 Hayward Avenue<br>Chesapeake, VA 23320- | **Phone**<br>**Fax**<br>**Website** | (757) 420-2520<br>(757) 424-2874<br>www.mccallumtestinglabs.com | **Coastal (East of I-95):**<br>**Central (West of I-95 and East of I-77):**<br>**Mountains (West of I-77):** | Yes<br>No<br>No |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | No |
| Other: | |

| Company | Listing Submitted | 5/30/2024 | Area of state conducts work | |
|---|---|---|---|---|
| **MERRITT COMMERCIAL SERVICES LLC**<br>217 STRICKLAND RD<br>WHIGHAM, GA 39897 | **Phone**<br>**Fax**<br>**Website** | (228) 516-0498<br><br>https://www.mcs-petroleum-div.com/ | **Coastal (East of I-95):**<br>**Central (West of I-95 and East of I-77):**<br>**Mountains (West of I-77):** | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | **Yes** |
| Leak Detection Equipment Installation Servicing: | **Yes** |
| Spill Bucket Installation Repair: | **Yes** |
| UST Equipment Installation - Other: | **Yes** |
| UST Equipment Repair: | **Yes** |
| UST System Installation - Complete Systems: | **Yes** |
| UST Piping/Sump Installation: | **Yes** |
| UST System Removal: | No |
| Other: | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 10/26/2026 | Area of state conducts work |
|---|---|---|---|
| **Oilmens Petroleum Systems**<br>711 S. Goldsboro St.<br>PO Box 502<br>Wilson, NC 27893- | **Phone**<br>**Fax**<br>**Website** | (252) 237-6047<br>(252) 237-5507<br>https://gaspumps.com/ | **Coastal (East of I-95):** Yes<br>**Central (West of I-95 and East of I-77):** No<br>**Mountains (West of I-77):** No |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | **Yes** |
| Leak Detection Equipment Installation Servicing: | **Yes** |
| Spill Bucket Installation Repair: | **Yes** |
| UST Equipment Installation - Other: | **Yes** |
| UST Equipment Repair: | **Yes** |
| UST System Installation - Complete Systems: | **Yes** |
| UST Piping/Sump Installation: | **Yes** |
| UST System Removal: | **Yes** |
| Other: | |

| Company | Listing Submitted | 10/23/2026 | Area of state conducts work |
|---|---|---|---|
| **OWL Services USA**<br>1815 Gallagher Road<br>Plymouth Meeting, PA 19462- | **Phone**<br>**Fax**<br>**Website** | (800) 646-3161<br>(610) 278-7621<br>www.owlservices.com | **Coastal (East of I-95):** Yes<br>**Central (West of I-95 and East of I-77):** Yes<br>**Mountains (West of I-77):** Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | **Yes** | Overfill Prevention Equipment Operability Check: | **Yes** |
| Containment Sump Testing: | **Yes** | Statistical Iventory Reconciliation Services: | **Yes** |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | **Yes** |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | **Yes** |
| Corrosion Protection System Testing: | **Yes** | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | **Yes** | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | **Yes** | Other: | |
| Line Tightness Testing: | **Yes** | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | **Yes** |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | **Yes** |
| Leak Detection Equipment Installation Servicing: | **Yes** |
| Spill Bucket Installation Repair: | **Yes** |
| UST Equipment Installation - Other: | **Yes** |
| UST Equipment Repair: | **Yes** |
| UST System Installation - Complete Systems: | **Yes** |
| UST Piping/Sump Installation: | **Yes** |
| UST System Removal: | **Yes** |
| Other: | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 7/2/2024 | Area of state conducts work | |
|---|---|---|---|---|
| **Paragon Environmental Consultants, Inc.**<br>P.O. Box 157<br>Thomasville, NC 27361 | Phone<br>Fax<br>Website | (336) 669-6037<br>(336) 476-7708 | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | No<br>Yes<br>No |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | No |
| Other: | |

| Company | Listing Submitted | 10/26/2026 | Area of state conducts work | |
|---|---|---|---|---|
| **Peak Hydrogeologic PLLC**<br>470 Hogback Mountain Road<br>Tryon, NC 28782- | Phone<br>Fax<br>Website | (828) 817-5209<br><br>www.peakhydrogeologic.com | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | No |
| Other: | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 10/26/2026 | Area of state conducts work | |
|---|---|---|---|---|
| **PetroTest, Inc**<br>7 Dawn Road<br>Benson, NC 27504- | Phone<br>Fax<br>Website | (919) 874-5843<br><br>https://petrotest.net/ | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | | UST Equipmment Service Contractors | |
|---|---|---|---|---|---|
| Automatic Line Leak Detector Testing: | **Yes** | Overfill Prevention Equipment Operability Check: | **Yes** | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | **Yes** | Statistical Iventory Reconciliation Services: | **Yes** | Leak Detection Equipment Installation Servicing: | **Yes** |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | **Yes** | Spill Bucket Installation Repair: | **Yes** |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | **Yes** | UST Equipment Installation - Other: | **Yes** |
| Corrosion Protection System Testing: | **Yes** | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | **Yes** |
| Leak Detection Equipment Operability Check: | **Yes** | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | **Yes** | Other: | Secondary Line and Tank Testing. | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | **Yes** | | | UST System Removal: | No |
| | | | | Other: | ATG/ Fill Riser replacements. |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | **Yes** |
| Oil and Solvent Recycling: | No | Other: | Water removal from UST Sumps and UDCs. |
| Soil and Water Testing Lab: | No | | |

| Company | Listing Submitted | 8/19/2024 | Area of state conducts work | |
|---|---|---|---|---|
| **Piedmont Geologic, P.C.**<br>6003-145 Chapel Hill Road<br>Raleigh, NC 27607 | Phone<br>Fax<br>Website | (919) 954-9700<br><br>www.piedmontgeologic.com | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | | UST Equipmment Service Contractors | |
|---|---|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | **Yes** |
| | | | | Other: | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | **Yes** | UST Compliance Consultants: | **Yes** |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 10/23/2026 | Area of state conducts work |
|---|---|---|---|
| **Pilot Geological, PLLC**<br>PO Box 128<br>743 Park Lawn Court<br>Kernersville, NC 27285- | **Phone** (336) 870-3095<br>**Fax**<br>**Website** www.pilotenviro.com | | **Coastal (East of I-95):** Yes<br>**Central (West of I-95 and East of I-77):** Yes<br>**Mountains (West of I-77):** Yes |

| Compliance Testing and Monitoring | | | | UST Equipmment Service Contractors | |
|---|---|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | **Yes** |
| | | | | Other: | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | **Yes** | UST Compliance Consultants: | **Yes** |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | **Yes** |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| Company | Listing Submitted | 10/28/2026 | Area of state conducts work |
|---|---|---|---|
| **Practical Environmental Solutions**<br>5634 Harvest Grove Lane<br>Wilmington, NC 28409- | **Phone** (910) 790-8265<br>**Fax**<br>**Website** www.oil-tank.com | | **Coastal (East of I-95):** Yes<br>**Central (West of I-95 and East of I-77):** Yes<br>**Mountains (West of I-77):** No |

| Compliance Testing and Monitoring | | | | UST Equipmment Service Contractors | |
|---|---|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | **Yes** | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | **Yes** |
| | | | | Other: | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | **Yes** |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 10/26/2026 | Area of state conducts work |
|---|---|---|---|
| **Pyramid Environmental & Engineering PC**<br>503 Industrial Ave.<br>Greensboro, NC 27406- | **Phone** (336) 335-3174<br>**Fax**<br>**Website** www.pyramidenvironmental.com | | **Coastal (East of I-95):** Yes<br>**Central (West of I-95 and East of I-77):** Yes<br>**Mountains (West of I-77):** Yes |

| Compliance Testing and Monitoring | | | | UST Equipmment Service Contractors | |
|---|---|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | **Yes** |
| | | | | Other: | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | **Yes** | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | **Yes** |
| Oil and Solvent Recycling: | **Yes** | Other: | |
| Soil and Water Testing Lab: | **Yes** | | |

| Company | Listing Submitted | 10/23/2026 | Area of state conducts work |
|---|---|---|---|
| **Rick Rogers Consulting LLC**<br>2764 Pleasant Rd. #405<br>Fort Mill, SC 29708- | **Phone** (803) 280-0741<br>**Fax**<br>**Website** | | **Coastal (East of I-95):** Yes<br>**Central (West of I-95 and East of I-77):** Yes<br>**Mountains (West of I-77):** Yes |

| Compliance Testing and Monitoring | | | | UST Equipmment Service Contractors | |
|---|---|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | **Yes** | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | **Yes** | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | **Yes** | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | No |
| | | | | Other: | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 7/30/2024 | Area of state conducts work | |
|---|---|---|---|---|
| **SR&R Environmental, Inc.**<br>4920 Highway 421 N.<br>Wilmington, NC 28401 | **Phone**<br>**Fax**<br>**Website** | (910) 763-6274<br>(910) 763-6132<br>www.srrenviro.com | **Coastal (East of I-95):**<br>**Central (West of I-95 and East of I-77):**<br>**Mountains (West of I-77):** | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | **Yes** | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | **Yes** |
| Oil and Solvent Recycling: | **Yes** | Other: | Fuel Polishing |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | **Yes** |
| Other: | |

| Company | Listing Submitted | 8/15/2024 | Area of state conducts work | |
|---|---|---|---|---|
| **Terracon**<br>7327- G West Friendly Avenue<br>Greensboro, NC 27410 | **Phone**<br>**Fax**<br>**Website** | (336) 854-8135<br><br>https://www.terracon.com/ | **Coastal (East of I-95):**<br>**Central (West of I-95 and East of I-77):**<br>**Mountains (West of I-77):** | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | **Yes** | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | **Yes** |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | No |
| Other: | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 10/7/2026 | Area of state conducts work | |
|---|---|---|---|---|
| **Terraquest Environmental Consultants, P.C.**<br>100 E. Ruffin Street<br>Mebane, NC 27302 | Phone<br>Fax<br>Website | (919) 563-9091<br>(919) 563-9095<br>www.terraquestpc.com | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | **Yes** | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | **Yes** | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | **Yes** |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | **Yes** | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | No |
| Other: | |

| Company | Listing Submitted | 3/6/2024 | Area of state conducts work | |
|---|---|---|---|---|
| **Titan Environmental Group**<br>2005 Citation Drive<br>Garner, NC 27529 | Phone<br>Fax<br>Website | (984) 200-6825<br><br>www.titanenvirogroup.com | Coastal (East of I-95):<br>Central (West of I-95 and East of I-77):<br>Mountains (West of I-77): | Yes<br>Yes<br>Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | **Yes** | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | **Yes** |
| Oil and Solvent Recycling: | **Yes** | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | **Yes** |
| Other: | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

# UST Service Provider List (All)

| Company | Listing Submitted | 8/27/2024 | Area of state conducts work |
|---|---|---|---|
| **UES Professional Solutions 29, Inc.**<br>10121 Pineville Distribution Street<br>Pineville, NC 28134 | **Phone** (704) 504-1717<br>**Fax** (704) 504-1125<br>**Website** www.teamues.com | | **Coastal (East of I-95):** Yes<br>**Central (West of I-95 and East of I-77):** Yes<br>**Mountains (West of I-77):** Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | **Yes** | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | **Yes** | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | No |
| Leak Detection Equipment Installation Servicing: | No |
| Spill Bucket Installation Repair: | No |
| UST Equipment Installation - Other: | No |
| UST Equipment Repair: | No |
| UST System Installation - Complete Systems: | No |
| UST Piping/Sump Installation: | No |
| UST System Removal: | No |
| Other: | |

| Company | Listing Submitted | 10/27/2026 | Area of state conducts work |
|---|---|---|---|
| **Valor Construction LLC**<br>345 County Road 474<br>Fort Payne, AL 35967- | **Phone** (205) 577-1035<br>**Fax**<br>**Website** www.valorconstructionllc.com | | **Coastal (East of I-95):** Yes<br>**Central (West of I-95 and East of I-77):** Yes<br>**Mountains (West of I-77):** Yes |

| Compliance Testing and Monitoring | | | |
|---|---|---|---|
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |

| Environmental Service Firms | | | |
|---|---|---|---|
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

| UST Equipmment Service Contractors | |
|---|---|
| Dispenser Meter Repair/Calibration: | **Yes** |
| Leak Detection Equipment Installation Servicing: | **Yes** |
| Spill Bucket Installation Repair: | **Yes** |
| UST Equipment Installation - Other: | **Yes** |
| UST Equipment Repair: | **Yes** |
| UST System Installation - Complete Systems: | **Yes** |
| UST Piping/Sump Installation: | **Yes** |
| UST System Removal: | **Yes** |
| Other: | |



The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.