

## UST Service Provider List (All)

Company	Listing Submitted	10/13/2025	Area of state conducts work
<b>A&amp;D Environmental Services, Inc.</b> 2718 Uwharrie Road Archdale, NC 27263  <b>Phone</b> (800) 434-7750 <b>Fax</b> (336) 434-7752  <b>Website</b> <a href="http://www.adenviro.com">www.adenviro.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:		
Company	Listing Submitted	8/19/2024	Area of state conducts work
<b>A1 Environmental Services Inc</b> PO Box 59 Greenville, NC 27835  <b>Phone</b> (252) 531-1284 <b>Fax</b>  <b>Website</b> <a href="http://www.aes-nc.com">www.aes-nc.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> No <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All)

Company	Listing Submitted	1/18/2024	Area of state conducts work
<b>Advanced Environmental Services, Inc.</b> PO Box 38218 Greensboro, NC 27438  <b>Phone</b> (336) 282-3586 <b>Fax</b> (336) 282-3587  <b>Website</b> <a href="http://AdavancedEnvironmental.com">AdavancedEnvironmental.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:	
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:		
Company	Listing Submitted	12/12/2025	Area of state conducts work
<b>American Environmental Engineering of Florida, Inc.</b> 3122 Mahan Drive Suite 801-313 Tallahassee, FL 32308  <b>Phone</b> (850) 832-5361 <b>Fax</b>  <b>Website</b> <a href="http://www.aeeus.com">www.aeeus.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:	
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All)

Company	Listing Submitted			Area of state conducts work
<b>Bay Compliance and Testing LLC</b> 315 Great Bridge Boulevard, Unit B Chesapeake, VA 23320	<b>Phone</b> (757) 410-5974  <b>Fax</b>  <b>Website</b> <a href="https://baycomplianceandtesting.com">https://baycomplianceandtesting.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> No <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			
<b>BUCKEYE ELM CONTRACTING, LLC</b> PO Box 1026 MOCKSVILLE, NC 27028	<b>Phone</b> (336) 337-6001  <b>Fax</b>  <b>Website</b> <a href="http://www.buckeye-elm.com">www.buckeye-elm.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:			

## UST Service Provider List (All)

<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>Bunnell-Lammons Engineering (BLE)</b> 6004 Ponders Court Greenville, SC 29615  <b>Phone</b> (864) 288-1265 <b>Fax</b> <b>Website</b> <a href="https://www.blecorp.com/">https://www.blecorp.com/</a>	10/16/2025		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	<b>No</b>
Corrosion Protection Design Experts:	<b>No</b>	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	<b>No</b>	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	<b>Yes</b>
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	<b>No</b>
Leak Detection Monitoring Services:	<b>Yes</b>	Other:	
Line Tightness Testing:	<b>Yes</b>		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	<b>Yes</b>
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	<b>Yes</b>
Oil and Solvent Recycling:	<b>No</b>	Other:	
Soil and Water Testing Lab:	<b>Yes</b>		
<b>Bunnell-Lammons Engineering (BLE)</b> 6004 Ponders Court Greenville, SC 29615  <b>Phone</b> (864) 288-1265 <b>Fax</b> <b>Website</b> <a href="https://www.blecorp.com/">https://www.blecorp.com/</a>	10/13/2025		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	<b>No</b>
Corrosion Protection Design Experts:	<b>No</b>	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	<b>No</b>	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	<b>Yes</b>
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	<b>No</b>
Leak Detection Monitoring Services:	<b>Yes</b>	Other:	
Line Tightness Testing:	<b>Yes</b>		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	<b>Yes</b>
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	<b>Yes</b>
Oil and Solvent Recycling:	<b>No</b>	Other:	
Soil and Water Testing Lab:	<b>Yes</b>		

## UST Service Provider List (All)

Company	Listing Submitted	10/14/2025	Area of state conducts work
<b>Cape Fear Engineering</b> 151 Poole Road Suite 100 Leland, NC 28451	<b>Phone</b> (910) 383-1044  <b>Fax</b>  <b>Website</b> <a href="http://www.capefearengineering.com">www.capefearengineering.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:		
Company	Listing Submitted	11/1/2023	Area of state conducts work
<b>Cathodic Protection Services, Inc.</b> 916 Egypt Rd. Bluff City, NC 37618	<b>Phone</b> (423) 895-1500  <b>Fax</b>  <b>Website</b>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All)

Company	Listing Submitted	4/5/2023	Area of state conducts work
<b>CATLIN Engineers and Scientists</b> 220 Old Dairy Road Wilmington, NC 28405	<b>Phone</b> (910) 452-5861  <b>Fax</b>  <b>Website</b> <a href="http://www.CatlinUSA.com">www.CatlinUSA.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	4/5/2023	Area of state conducts work
<b>CDG, Inc.</b> 4301 Taggart Creek Road Charlotte, NC 28208	<b>Phone</b> (704) 394-6913  <b>Fax</b>  <b>Website</b> <a href="http://www.cdge.com">www.cdge.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other:		

## UST Service Provider List (All)

Company	Listing Submitted	6/27/2024	Area of state conducts work
<b>Cobb Environmental &amp; Technical Services, Inc.</b> P. O. Box 1602 Tupelo, MS 38802  <b>Phone</b> (662) 841-0995 <b>Fax</b> (662) 841-0810  <b>Website</b> <a href="http://cobbenv.com">cobbenv.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: No UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:	
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	11/21/2023	Area of state conducts work
<b>Conklin Corrosion Control LLC</b> 118 Oak Point Lane Stony Point, NC 28678  <b>Phone</b> (704) 560-9154 <b>Fax</b>  <b>Website</b> <a href="mailto:benconklincc@gmail.com">benconklincc@gmail.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:	
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All)

<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>C-Store Services, Inc.</b> 7129 Hidden Valley Trail Garner, NC 27529  <b>Phone</b> (919) 662-0798 <b>Fax</b> <b>Website</b>		10/14/2025	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
<b>D. H. Griffin Wrecking Company</b> 4716 Hilltop Road Greensboro, NC 27407  <b>Phone</b> (336) 214-9012 <b>Fax</b> <b>Website</b> <a href="http://www.dhgriffin.com">www.dhgriffin.com</a>		10/13/2025	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<b>Yes</b>
Oil and Solvent Recycling:	<b>Yes</b>	Other:	
Soil and Water Testing Lab:	No		

## UST Service Provider List (All)

<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>East Coast Environmental, PA</b> 3815 Junction Boulevard Raleigh, NC 27603  <b>Phone</b> (919) 349-5969 <b>Fax</b> <b>Website</b> <a href="http://eastcoastenv.com">eastcoastenv.com</a>	4/5/2023		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	<b>Yes</b>
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
<b>ECS Southeast, LLC</b> 5260 Greens Dairy Road Raleigh, NC 27616  <b>Phone</b> (919) 861-9910 <b>Fax</b> <b>Website</b> <a href="http://ecslimited.com">ecslimited.com</a>	1/6/2025		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

## UST Service Provider List (All)

<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>EIS Holding, LLC.</b> 5621 Departure Drive Suite 101 Raleigh, NC 27616	<b>Phone</b> (984) 284-5571  <b>Fax</b>  <b>Website</b> <a href="http://www.eisholdings.com">www.eisholdings.com</a>	6/30/2025	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	<b>Yes</b>
Corrosion Protection Design Experts:	<b>Yes</b>	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	<b>Yes</b>	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	<b>Yes</b>
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	<b>Yes</b>
Leak Detection Monitoring Services:	<b>Yes</b>	Other:	
Line Tightness Testing:	<b>Yes</b>		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	<b>Yes</b>
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	<b>Yes</b>
Oil and Solvent Recycling:	<b>Yes</b>	Other:	
Soil and Water Testing Lab:	<b>Yes</b>		
<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>Environmental Hydrogeological Consultants, Inc. DB</b> PO Box 902 Red Springs, NC 28377	<b>Phone</b> (910) 843-4456  <b>Fax</b> (910) 843-5376  <b>Website</b> <a href="http://www.environmentalinc.com">www.environmentalinc.com</a>	7/2/2024	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<b>Yes</b>
Oil and Solvent Recycling:	<b>Yes</b>	Other: OSRO Certified US Coast Guard Contractor	
Soil and Water Testing Lab:	<b>Yes</b>		
			Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other: Liquid/Hydro Excavate Vac Truck Services

## UST Service Provider List (All)

Company	Listing Submitted	10/27/2025	Area of state conducts work
<b>Environmental Laboratories, INC</b> 15 Sulphur Springs Rd Greenville, SC 29617	<b>Phone</b> (864) 370-0637  <b>Fax</b>  <b>Website</b> <a href="https://www.elabsinc.net/">https://www.elabsinc.net/</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: <b>Yes</b> Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: <b>Yes</b> Other:		Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: No UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: No UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other:		
Company	Listing Submitted	5/14/2024	Area of state conducts work
<b>Environmental Petroleum Services</b> 1234 Gordon Park Rd Augusta, GA 30901	<b>Phone</b> (877) 297-6763  <b>Fax</b>  <b>Website</b> <a href="http://www.keepmecompliant.net">www.keepmecompliant.net</a>		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: No Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All)

Company	Listing Submitted	2/27/2026	Area of state conducts work
<b>EnviroSouth, Inc.</b> 3440 Augusta Rd Greenville, SC 29605	<b>Phone</b> (864) 236-9010  <b>Fax</b>  <b>Website</b> <a href="http://www.envirosouth.com">www.envirosouth.com</a>		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:		
Company	Listing Submitted	7/16/2024	Area of state conducts work
<b>EnviroSouth, Inc.</b> 3440 Augusta Road Greenville, SC 29605	<b>Phone</b> (864) 236-9010  <b>Fax</b>  <b>Website</b> <a href="http://www.envirosouth.com">www.envirosouth.com</a>		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All)

Company	Listing Submitted			Area of state conducts work
<b>ESNC Environmental Consulting, P.C.</b> 1408 Christian Avenue Suite 11 Durham, NC 27705	<b>Phone</b> (919) 910-7767  <b>Fax</b>  <b>Website</b> <a href="http://www.earthsys.net">www.earthsys.net</a>	5/6/2025		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			
<b>Evo Corporation</b> 1703 Vargrave Street Winston-Salem, NC 27107	<b>Phone</b> (336) 725-5844  <b>Fax</b>  <b>Website</b> <a href="http://www.evocorp.net">www.evocorp.net</a>	10/13/2025		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			

## UST Service Provider List (All)

Company	Listing Submitted	7/12/2023	Area of state conducts work
<b>Excel Environmental Associates, PLLC</b> 625 Huntsman Court Gastonia, NC 28054	<b>Phone</b> (704) 853-0800  <b>Fax</b> (704) 853-3949  <b>Website</b> <a href="http://www.excelengr.com">www.excelengr.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	10/14/2025	Area of state conducts work
<b>Geological Resources, Inc.</b> 3502 Hayes Road Monroe, NC 28110	<b>Phone</b> (704) 845-4010  <b>Fax</b> (704) 845-4012  <b>Website</b> <a href="http://www.grienv.com">www.grienv.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:		

## UST Service Provider List (All)

Company	Listing Submitted		Area of state conducts work
<b>Groundwater Manage. Associates</b> 4300 Sapphire Court Suite 100 Greenville, NC 27834	<b>Phone</b> (252) 758-3310  <b>Fax</b>  <b>Website</b> <a href="http://www.gma-nc.com">www.gma-nc.com</a>	7/3/2024	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted		Area of state conducts work
<b>Groundwater Management Associates, Inc.</b> 4300 Sapphire Court Suite 100 Greenville, NC 27834	<b>Phone</b> (252) 758-3310  <b>Fax</b>  <b>Website</b> <a href="http://www.gma-nc.com">www.gma-nc.com</a>	11/16/2023	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All)

Company	Listing Submitted	4/20/2023	Area of state conducts work
<b>GTA Associates, Inc.</b> 701 Peninsula Lane, Suite B Charlotte, NC 28226  <b>Phone</b> (704) 553-2300 <b>Fax</b> (704) 553-2400  <b>Website</b> <a href="http://www.gtaeng.com">www.gtaeng.com</a>			<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:	
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	11/14/2025	Area of state conducts work
<b>HARCO Services LLC</b> 2 Kelli Clark Ct SE Cartersville, GA 30121  <b>Phone</b> (770) 917-8846 <b>Fax</b> (770) 917-0921  <b>Website</b> <a href="http://harcoservices.com">harcoservices.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:	
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All)

Company	Listing Submitted	3/31/2025	Area of state conducts work
<b>Hart &amp; Hickman, PC</b> 2923 S. Tryon Street Suite 100 Charlotte, NC 28203	<b>Phone</b> (704) 586-0007  <b>Fax</b>  <b>Website</b> <a href="https://harthickman.com/">https://harthickman.com/</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	4/11/2023	Area of state conducts work
<b>INENCO, Inc.</b> 132 W. Statesville Avenue Mooresville, NC 27115	<b>Phone</b> (704) 662-8192  <b>Fax</b> (704) 662-8194  <b>Website</b>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All)

<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>JBL Solutions Inc.</b> 806 Appii Rd Moncks Corner, SC 29461	<b>Phone</b> (603) 690-9071  <b>Fax</b>  <b>Website</b> <a href="http://jblsolutionsinc.com">jblsolutionsinc.com</a>	12/12/2025	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	<b>Yes</b>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<b>Yes</b>	Other:	
Line Tightness Testing:	<b>Yes</b>		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<b>Yes</b>
Oil and Solvent Recycling:	No	Other:	Filtration and Polishing
Soil and Water Testing Lab:	No		
<b>JF Petroleum Group</b> 100 Perimeter Park Drive Suite H Morrisville, NC 27560	<b>Phone</b> (919) 744-4391  <b>Fax</b>  <b>Website</b> <a href="http://jfpetrogroup.com/services/environmentalcompliance">jfpetrogroup.com/services/environmentalcompliance</a>	5/15/2023	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<b>Yes</b>	Other:	
Line Tightness Testing:	<b>Yes</b>		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<b>Yes</b>
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

## UST Service Provider List (All)

Company	Listing Submitted	10/16/2025	Area of state conducts work
<b>Lamar Contractors, LLC</b> 481 Judge Edward Dufresne Pkwy. Luling , LA 70070  <b>Phone</b> (985) 785-7121 <b>Fax</b> (985) 785-7124  <b>Website</b> <a href="http://www.lamarcontractors.com">www.lamarcontractors.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:	
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	5/30/2024	Area of state conducts work
<b>Marley Trucking &amp; Demolition Inc.</b> 1768 Old Humble Mill Road Asheboro, NC 27205  <b>Phone</b> (336) 382-7132 <b>Fax</b>  <b>Website</b>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:	
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All)

Company	Listing Submitted	1/27/2026	Area of state conducts work
<b>McCallum, P.C.</b> 1808 Hayward Avenue Chesapeake, VA 23320	<b>Phone</b> (757) 420-2520  <b>Fax</b> (757) 424-2874  <b>Website</b> <a href="http://www.mccallumtestinglabs.com">www.mccallumtestinglabs.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> No <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	5/30/2024	Area of state conducts work
<b>MERRITT COMMERCIAL SERVICES LLC</b> 217 STRICKLAND RD WHIGHAM, GA 39897	<b>Phone</b> (228) 516-0498  <b>Fax</b>  <b>Website</b> <a href="https://www.mcs-petroleum-div.com/">https://www.mcs-petroleum-div.com/</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All)

Company	Listing Submitted			Area of state conducts work
<b>MGF Environmental, PLLC</b> 288 Gap Creek Rd Fletcher, NC 28732	<b>Phone</b> (904) 814-3680  <b>Fax</b>  <b>Website</b> <a href="http://mgfenvironmental.com">mgfenvironmental.com</a>	4/20/2023	<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:	
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:			
Company	Listing Submitted			Area of state conducts work
<b>Mid-Atlantic Associates, Inc.</b> 409 Rogers View Court Raleigh, NC 27610	<b>Phone</b> (919) 250-9918  <b>Fax</b>  <b>Website</b> <a href="http://www.maaonline.com">www.maaonline.com</a>	10/14/2025	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:	
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			

## UST Service Provider List (All)

Company	Listing Submitted			Area of state conducts work
<b>NCPCM</b> 7300 Glenwood Avenue Raleigh, NC 27612	<b>Phone</b> (919) 782-4411  <b>Fax</b>  <b>Website</b> <a href="http://www.ncpcm.org">www.ncpcm.org</a>	10/14/2025		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:			
Company	Listing Submitted			Area of state conducts work
<b>NV5 Engineers and Consultants, Inc.</b> 3300 Regency Parkway, Suite 100 Cary, NC 27518	<b>Phone</b> (919) 618-7792  <b>Fax</b>  <b>Website</b> <a href="https://www.nv5.com/">https://www.nv5.com/</a>	1/27/2026		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:			

## UST Service Provider List (All)

Company	Listing Submitted			Area of state conducts work
<b>OMNI PROFESSIONAL</b> Post Office Box 13404 Research Triangle Park, NC 27709	<b>Listing Submitted</b> 3/30/2026	<b>Phone</b> (919) 544-5442  <b>Fax</b>  <b>Website</b>	<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No	
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
<b>Environmental Service Firms</b>				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: No Other:			
<b>OWL Services USA</b> 1815 Gallagher Road Plymouth Meeting, PA 19462	<b>Listing Submitted</b> 10/14/2025	<b>Phone</b> (610) 633-9732  <b>Fax</b> (610) 278-7621  <b>Website</b> <a href="http://www.owlservices.com">www.owlservices.com</a>	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>	
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: <b>Yes</b> Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:		
<b>Environmental Service Firms</b>				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: No Other:			

## UST Service Provider List (All)

Company	Listing Submitted			Area of state conducts work
<b>Paragon Environmental Consultants, Inc.</b> P.O. Box 157 Thomasville, NC 27361	<b>Phone</b> (336) 669-6037  <b>Fax</b> (336) 476-7708  <b>Website</b>	7/2/2024	<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			
Company	Listing Submitted			Area of state conducts work
<b>Parliament Petroleum Services LLC</b> 3277 Neely Ferry Road Laurens, SC 29360	<b>Phone</b> (864) 871-8058  <b>Fax</b>  <b>Website</b> <a href="http://parliamentpetroleumservices.com">parliamentpetroleumservices.com</a>	10/21/2025	<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> No <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			

## UST Service Provider List (All)

Company	Listing Submitted			Area of state conducts work
<b>Peak Hydrogeologic, PLLC</b> 470 Hogback Mtn Rd Tryon, NC 28782	<b>Phone</b> (828) 817-5209  <b>Fax</b>  <b>Website</b> <a href="https://peakhydrogeologic.com">https://peakhydrogeologic.com</a>	11/1/2023		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:			
Company	Listing Submitted			Area of state conducts work
<b>Petroleum Equipment and Service, Inc</b> PO Box 1949 Denver, NC 28037	<b>Phone</b> (704) 335-8801  <b>Fax</b>  <b>Website</b> <a href="http://www.petroleumequipment.net">www.petroleumequipment.net</a>	10/13/2025		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			

## UST Service Provider List (All)

<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>Petroleum Equipment Service of Wilson, Inc.</b> PO Box 502 711 S. Goldsboro St. Wilson, NC 27894	<b>Phone</b> (252) 237-6047 <b>Fax</b> (252) 237-5507 <b>Website</b> <a href="http://www.peswilson.com">www.peswilson.com</a>	10/14/2025	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
<b>Piedmont Geologic, P.C.</b> 6003-145 Chapel Hill Road Raleigh, NC 27607	<b>Phone</b> (919) 954-9700 <b>Fax</b> <b>Website</b> <a href="http://www.piedmontgeologic.com">www.piedmontgeologic.com</a>	8/19/2024	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

## UST Service Provider List (All)

Company	Listing Submitted			Area of state conducts work
<b>Pilot Geological , PLLC</b> PO Box 128 743 Park Lawn Court Kernersville, NC 27285	<b>Phone</b> (336) 870-3095  <b>Fax</b> (336) 310-4527  <b>Website</b> <a href="http://www.pilotenviro.com">www.pilotenviro.com</a>	11/1/2023	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:	
<b>Environmental Service Firms</b>				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:			
Company	Listing Submitted			Area of state conducts work
<b>Pyramid Environmental &amp; Engineering, PC</b> 503 Industrial Avenue P.O. Box 16265 Greensboro, NC 27406	<b>Phone</b> (336) 335-3174  <b>Fax</b> (336) 691-0648  <b>Website</b> <a href="http://www.pyramidenvironmental.com">www.pyramidenvironmental.com</a>	10/14/2025	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:	
<b>Environmental Service Firms</b>				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:			

## UST Service Provider List (All)

Company	Listing Submitted			Area of state conducts work
<b>Regional Environmental PLLC</b> 9016 Hazel Forest Drive Fuquay Varina, NC 27526	<b>Phone</b> (704) 694-8359  <b>Fax</b>  <b>Website</b> <a href="http://www.regionalenv.com">www.regionalenv.com</a>	4/4/2023		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:			
Company	Listing Submitted			Area of state conducts work
<b>Rick Rogers Consulting, LLC.</b> 2764 Pleasent Road #405 Fort Mill, SC 29708	<b>Phone</b> (803) 280-0741  <b>Fax</b>  <b>Website</b>	10/14/2025		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			

## UST Service Provider List (All)

Company	Listing Submitted	10/14/2025		Area of state conducts work	
<b>Singleton Environmental, Inc.</b> PO Box 604 Fletcher, NC 28732  <b>Phone</b> (828) 508-4510 <b>Fax</b> <b>Website</b> <a href="http://www.singletonenvironmental.com">www.singletonenvironmental.com</a>				<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted	10/14/2025		Area of state conducts work	
<b>Singleton Environmental, Inc.</b> PO Box 604 Fletcher, NC 28732  <b>Phone</b> (828) 508-4510 <b>Fax</b> <b>Website</b> <a href="http://www.singletonenvironmental.com">www.singletonenvironmental.com</a>				<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

## UST Service Provider List (All)

Company	Listing Submitted			Area of state conducts work
<b>SPATCO Energy Solutions</b> 301 McCullough Dr Suite 500 Charlotte, NC 28262	<b>Phone</b> (800) 477-8286  <b>Fax</b>  <b>Website</b> <a href="http://spatco.com">spatco.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>	
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: <b>Yes</b> Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: <b>Yes</b> Other:	Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:		
<b>Environmental Service Firms</b>				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other:			
Company	Listing Submitted			Area of state conducts work
<b>SR&amp;R Environmental, Inc.</b> 4920 Highway 421 N. Wilmington, NC 28401	<b>Phone</b> (910) 763-6274  <b>Fax</b> (910) 763-6132  <b>Website</b> <a href="http://www.srrenviro.com">www.srrenviro.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>	
Automatic Line Leak Detector Testing: <b>No</b> Containment Sump Testing: <b>No</b> Corrosion Protection Design Experts: <b>No</b> Corrosion Protection System Repairs: <b>No</b> Corrosion Protection System Testing: <b>No</b> Leak Detection Equipment Operability Check: <b>No</b> Leak Detection Monitoring Services: <b>No</b> Line Tightness Testing: <b>No</b>	Overfill Prevention Equipment Operability Check: <b>No</b> Statistical Inventory Reconciliation Services: <b>No</b> Spill Prevention Equipment Testing: <b>No</b> Tank Tightness Testing: <b>No</b> UST Internal Inspections (Integrity Assessments): <b>No</b> UST Internal Lining Inspections: <b>No</b> Other:	Dispenser Meter Repair/Calibration: <b>No</b> Leak Detection Equipment Installation Servicing: <b>No</b> Spill Bucket Installation Repair: <b>No</b> UST Equipment Installation - Other: <b>No</b> UST Equipment Repair: <b>No</b> UST System Installation - Complete Systems: <b>No</b> UST Piping/Sump Installation: <b>No</b> UST System Removal: <b>Yes</b> Other:		
<b>Environmental Service Firms</b>				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>No</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>No</b> Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: <b>No</b>	UST Compliance Consultants: <b>No</b> UST Equipment Verification: <b>No</b> Waste Disposal and Treatment: <b>Yes</b> Other: <b>Fuel Polishing</b>			

## UST Service Provider List (All)

Company	Listing Submitted	3/9/2026	Area of state conducts work
<b>SynTerra Corporation</b> 148 River Street Suite 220 Greenville, SC 29601	<b>Phone</b> (864) 421-9999  <b>Fax</b>  <b>Website</b> <a href="http://www.synterracorp.com">www.synterracorp.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other:		
Company	Listing Submitted	8/15/2024	Area of state conducts work
<b>Terracon</b> 7327- G West Friendly Avenue Greensboro, NC 27410	<b>Phone</b> (336) 854-8135  <b>Fax</b>  <b>Website</b> <a href="https://www.terracon.com/">https://www.terracon.com/</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:		

## UST Service Provider List (All)

Company	Listing Submitted	10/14/2025	Area of state conducts work
<b>Terraquest Environmental Consultants, P.C.</b> 100 E. Ruffin St. Mebane, NC 27302  <b>Phone</b> (919) 563-9091 <b>Fax</b> (919) 563-9095  <b>Website</b> <a href="http://www.terraquestpc.com">www.terraquestpc.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:		
Company	Listing Submitted	3/6/2024	Area of state conducts work
<b>Titan Environmental Group</b> 2005 Citation Drive Garner, NC 27529  <b>Phone</b> (984) 200-6825 <b>Fax</b>  <b>Website</b> <a href="http://www.titanenvirogroup.com">www.titanenvirogroup.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:		

## UST Service Provider List (All)

Company	Listing Submitted	8/27/2024	Area of state conducts work
<b>UES Professional Solutions 29, Inc.</b> 10121 Pineville Distribution Street Pineville, NC 28134  <b>Phone</b> (704) 504-1717 <b>Fax</b> (704) 504-1125  <b>Website</b> <a href="http://www.teamues.com">www.teamues.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	11/1/2023	Area of state conducts work
<b>Withers Ravenel, Inc.</b> 115 MacKenan Drive Cary, NC 27591  <b>Phone</b> (919) 469-3340 <b>Fax</b>  <b>Website</b> <a href="http://www.withersravenel.com">www.withersravenel.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:		