

UST Service Provider List (Central)

Company				Listing Submitted	1/18/2024	Area of state conducts work	
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438				Phone (336) 282-3586 Fax (336) 282-3587 Website AdadvancedEnvironmental.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	Yes	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	7/19/2022	Area of state conducts work	
B & M WEST CONSTRUCTION CO OF TEXAS DBA D. 209 E BADCOCK BLVD MULBERRY, FL 33860				Phone (863) 519-4441 Fax (863) 519-4407 Website DWSHOUPE.COM		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		Yes	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		Yes	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Central)

Company				Listing Submitted	6/26/2024	Area of state conducts work	
BUCKEYE ELM CONTRACTING, LLC PO Box 1026 MOCKSVILLE, NC 27028				Phone (336) 337-6001 Fax Website www.buckeye-elm.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		<u>Yes</u>	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		<u>Yes</u>	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	11/1/2023	Area of state conducts work	
Cathodic Protection Services, Inc. 916 Egypt Rd. Bluff City, NC 37618				Phone (423) 895-1500 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Central)

Company		Listing Submitted		4/5/2023		Area of state conducts work	
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405		Phone (910) 452-5861 Fax Website www.CatlinUSA.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			<u>Yes</u>
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		4/5/2023		Area of state conducts work	
CDG, Inc. 4301 Taggart Creek Road Charlotte, NC 28208		Phone (704) 394-6913 Fax Website www.cdge.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			No
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

Company		Listing Submitted		4/5/2023		Area of state conducts work	
CDG, Inc. 4301 Taggart Creek Road Charlotte, NC 28208		Phone (704) 394-6913 Fax Website www.cdge.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

UST Service Provider List (Central)

Company			Listing Submitted	6/27/2024	Area of state conducts work
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802			Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenvironment.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	Yes
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	Yes
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	Yes
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	Yes
Line Tightness Testing:	No			UST System Removal:	Yes
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

Company			Listing Submitted	11/21/2023	Area of state conducts work
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678			Phone (704) 560-9154 Fax Website benconklincc@gmail.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Central)

Company				Listing Submitted	9/28/2022	Area of state conducts work	
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407				Phone (336) 214-9012 Fax Website www.dhgriffin.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	Yes	Other:	Vacuum Truck Services				
Soil and Water Testing Lab:	No						

Company				Listing Submitted	4/5/2023	Area of state conducts work	
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603				Phone (919) 349-5969 Fax Website eastcoastenv.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		Yes	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		Yes	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		Yes	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		Yes	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		Yes	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	Yes				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Central)

Company				Listing Submitted	1/6/2025	Area of state conducts work	
ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616				Phone (919) 861-9910 Fax Website ecslimited.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	6/30/2025	Area of state conducts work	
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616				Phone (984) 284-5571 Fax Website www.eisholdings.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:		<u>Yes</u>	
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:		<u>Yes</u>	
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:		<u>Yes</u>	
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:		<u>Yes</u>	
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:		<u>Yes</u>	
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:		<u>Yes</u>	
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:		<u>Yes</u>	
Line Tightness Testing:	<u>Yes</u>			UST System Removal:		<u>Yes</u>	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

UST Service Provider List (Central)

Company				Listing Submitted	7/2/2024	Area of state conducts work	
Environmental Hydrogeological Consultants, Inc. DB PO Box 902 Red Springs, NC 28377		Phone (910) 843-4456 Fax (910) 843-5376 Website www.environmentalinc.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:	Liquid/Hydro Excavate Vac Truck Services		
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	Yes	Other:	OSRO Certified US Coast Guard Contractor				
Soil and Water Testing Lab:	Yes						

Company				Listing Submitted	5/14/2024	Area of state conducts work	
Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901		Phone (877) 297-6763 Fax Website www.keepmecompliant.net				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	Yes		
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	Yes		
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	Yes		
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	Yes		
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes		
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	Yes		
Line Tightness Testing:	Yes			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Central)

Company				Listing Submitted	7/16/2024	Area of state conducts work	
EnviroSouth, Inc. 3440 Augusta Road Greenville, SC 29605		Phone (864) 236-9010 Fax Website www.envirosouth.com				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	5/6/2025	Area of state conducts work	
ESNC Environmental Consulting, P.C. 1408 Christian Avenue Suite 11 Durham, NC 27705		Phone (919) 910-7767 Fax Website www.earthsys.net				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Central)

Company				Listing Submitted	7/12/2023	Area of state conducts work	
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054				Phone (704) 853-0800 Fax (704) 853-3949 Website www.excelengr.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	7/3/2024	Area of state conducts work	
Groundwater Manage. Associates 4300 Sapphire Court Suite 100 Greenville, NC 27834				Phone (252) 758-3310 Fax Website www.gma-nc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Central)

Company				Listing Submitted	11/16/2023	Area of state conducts work	
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834		Phone (252) 758-3310 Fax Website www.gma-nc.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	4/20/2023	Area of state conducts work	
GTA Associates, Inc. 701 Peninsula Lane, Suite B Charlotte, NC 28226		Phone (704) 553-2300 Fax (704) 553-2400 Website www.gtaeng.com				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Central)

Company				Listing Submitted	3/31/2025	Area of state conducts work	
Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203		Phone (704) 586-0007 Fax Website https://harthickman.com/				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	4/11/2023	Area of state conducts work	
INENCO, Inc. 132 W. Statesville Avenue Mooresville, NC 27115		Phone (704) 662-8192 Fax (704) 662-8194 Website				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Central)

Company			Listing Submitted	5/15/2023	Area of state conducts work
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560			Phone (919) 744-4391 Fax Website jfpetrogroup.com/services/environmentalcompliance		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

Company			Listing Submitted	12/20/2022	Area of state conducts work
Jones Covey Group 9595 Lucas Ranch Rd STE 100 Rancho Cucamonga, CA 91730			Phone (888) 972-7581 Fax (909) 484-0300 Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Central)

Company				Listing Submitted	5/30/2024	Area of state conducts work	
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205				Phone (336) 382-7132 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>		
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						
Company				Listing Submitted	5/30/2024	Area of state conducts work	
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897				Phone (228) 516-0498 Fax Website https://www.mcs-petroleum-div.com/		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	<u>Yes</u>		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Central)

Company				Listing Submitted	4/20/2023	Area of state conducts work	
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732		Phone (904) 814-3680 Fax Website mgfenvironmental.com				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	9/8/2022	Area of state conducts work	
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610		Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Central)

Company				Listing Submitted	7/2/2024	Area of state conducts work	
Paragon Environmental Consultants, Inc. P.O. Box 157 Thomasville, NC 27361		Phone (336) 669-6037 Fax (336) 476-7708 Website				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						
Company				Listing Submitted	11/1/2023	Area of state conducts work	
Peak Hydrogeologic, PLLC 470 Hogback Mtn Rd Tryon, NC 28782		Phone (828) 817-5209 Fax Website https://peakhydrogeologic.com				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	Yes						

UST Service Provider List (Central)

Company				Listing Submitted	8/19/2024	Area of state conducts work	
Piedmont Geologic, P.C. 6003-145 Chapel Hill Road Raleigh, NC 27607		Phone (919) 954-9700 Fax Website www.piedmontgeologic.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	11/1/2023	Area of state conducts work	
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285		Phone (336) 870-3095 Fax (336) 310-4527 Website www.pilotenviro.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Central)

Company				Listing Submitted	10/12/2022	Area of state conducts work	
Practical Environmental Solutions. PC 5634 Harvest Grove Ln Wilmington, NC 28409				Phone (910) 790-8265 Fax Website www.oil-tank.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No			
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No			
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No			
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No			
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No			
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No			
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No			
Line Tightness Testing:	No			UST System Removal: <u>Yes</u>			
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

Company				Listing Submitted	4/4/2023	Area of state conducts work	
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526				Phone (704) 694-8359 Fax Website www.regionalenv.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No			
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No			
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No			
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No			
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No			
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No			
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No			
Line Tightness Testing:	No			UST System Removal: No			
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

UST Service Provider List (Central)

Company				Listing Submitted	7/30/2024	Area of state conducts work	
SR&R Environmental, Inc. 4920 Highway 421 N. Wilmington, NC 28401				Phone (910) 763-6274 Fax (910) 763-6132 Website www.srrenviro.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:	Fuel Polishing				
Soil and Water Testing Lab:	No						

Company				Listing Submitted	8/15/2024	Area of state conducts work	
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410				Phone (336) 854-8135 Fax Website https://www.terracon.com/		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Central)

Company				Listing Submitted	3/6/2024	Area of state conducts work	
Titan Environmental Group 2005 Citation Drive Garner, NC 27529		Phone (984) 200-6825 Fax Website www.titanenvirogroup.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	Yes	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	8/27/2024	Area of state conducts work	
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134		Phone (704) 504-1717 Fax (704) 504-1125 Website www.teamues.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Central)

Company			Listing Submitted	7/14/2022	Area of state conducts work
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572			Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	Yes			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

Company			Listing Submitted	1/31/2023	Area of state conducts work
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968			Phone (205) 577-1035 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	Yes
Line Tightness Testing:	No			UST System Removal:	Yes
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Central)

Company		Listing Submitted		11/1/2023	Area of state conducts work	
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591		Phone (919) 469-3340 Fax Website www.withersravenel.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring				UST Equipmment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No		
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No		
Line Tightness Testing:	No			UST System Removal: <u>Yes</u>		
Environmental Service Firms				Other:		
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>			
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No			
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No			
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					