

## UST Service Provider List (Central)

Company				Listing Submitted	1/18/2024	Area of state conducts work	
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438				Phone (336) 282-3586 Fax (336) 282-3587 Website <a href="http://AdadvancedEnvironmental.com">AdadvancedEnvironmental.com</a>		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	7/19/2022	Area of state conducts work	
B & M WEST CONSTRUCTION CO OF TEXAS DBA D. 209 E BADCOCK BLVD MULBERRY, FL 33860				Phone (863) 519-4441 Fax (863) 519-4407 Website <a href="http://DWSHOUPE.COM">DWSHOUPE.COM</a>		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		<u>Yes</u>	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		<u>Yes</u>	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company				Listing Submitted	6/26/2024	Area of state conducts work	
BUCKEYE ELM CONTRACTING, LLC PO Box 1026 MOCKSVILLE, NC 27028		Phone (336) 337-6001  Fax  Website <a href="http://www.buckeye-elm.com">www.buckeye-elm.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		Yes	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		Yes	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	11/1/2023	Area of state conducts work	
Cathodic Protection Services, Inc. 916 Egypt Rd. Bluff City, NC 37618		Phone (423) 895-1500  Fax  Website				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		11/1/2023		Area of state conducts work	
Cathodic Protection Services, Inc. 916 Egypt Rd. Bluff City, NC 37618		Phone (423) 895-1500  Fax  Website			Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes		
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company				Listing Submitted	4/5/2023	Area of state conducts work	
<b>CATLIN Engineers and Scientists</b> 220 Old Dairy Road Wilmington, NC 28405		<b>Phone</b> (910) 452-5861  <b>Fax</b>  <b>Website</b> <a href="http://www.CatlinUSA.com">www.CatlinUSA.com</a>				<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	4/5/2023	Area of state conducts work	
<b>CDG, Inc.</b> 4301 Taggart Creek Road Charlotte, NC 28208		<b>Phone</b> (704) 394-6913  <b>Fax</b>  <b>Website</b> <a href="http://www.cdge.com">www.cdge.com</a>				<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

Company		Listing Submitted		4/5/2023		Area of state conducts work	
CDG, Inc. 4301 Taggart Creek Road Charlotte, NC 28208		Phone (704) 394-6913				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
		Fax					
		Website	www.cdge.com				
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	Yes				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	Yes	Other:					
Soil and Water Testing Lab:	Yes						

## UST Service Provider List (Central)

Company			Listing Submitted	6/27/2024	Area of state conducts work
<b>Cobb Environmental &amp; Technical Services, Inc.</b> P. O. Box 1602 Tupelo, MS 38802			<b>Phone</b> (662) 841-0995 <b>Fax</b> (662) 841-0810 <b>Website</b> <a href="http://cobbenv.com">cobbenv.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<b>Yes</b>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>	Spill Bucket Installation Repair:	<b>Yes</b>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<b>Yes</b>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<b>Yes</b>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<b>Yes</b>
Line Tightness Testing:	No			UST System Removal:	<b>Yes</b>
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

Company			Listing Submitted	11/21/2023	Area of state conducts work
<b>Conklin Corrosion Control LLC</b> 118 Oak Point Lane Stony Point, NC 28678			<b>Phone</b> (704) 560-9154 <b>Fax</b> <b>Website</b> <a href="mailto:benconklincc@gmail.com">benconklincc@gmail.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<b>Yes</b>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<b>Yes</b>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

## UST Service Provider List (Central)

Company				Listing Submitted		9/28/2022		Area of state conducts work	
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407				Phone (336) 214-9012  Fax  Website <a href="http://www.dhgriffin.com">www.dhgriffin.com</a>		Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No			Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No			Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No			UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No		
Line Tightness Testing:	No					UST System Removal:	<u>Yes</u>		
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No						
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No						
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>						
Oil and Solvent Recycling:	<u>Yes</u>	Other:		Vacuum Truck Services					
Soil and Water Testing Lab:	No								

Company				Listing Submitted		4/5/2023		Area of state conducts work	
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603				Phone (919) 349-5969  Fax  Website <a href="http://eastcoastenv.com">eastcoastenv.com</a>		Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No			Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	<u>Yes</u>		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No			Spill Bucket Installation Repair:	<u>Yes</u>		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No			UST Equipment Installation - Other:	<u>Yes</u>		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	<u>Yes</u>		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	<u>Yes</u>		
Line Tightness Testing:	No					UST System Removal:	<u>Yes</u>		
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>						
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>						
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No						
Oil and Solvent Recycling:	No	Other:							
Soil and Water Testing Lab:	No								

## UST Service Provider List (Central)

Company				Listing Submitted		1/6/2025		Area of state conducts work	
ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616				Phone (919) 861-9910  Fax  Website <a href="http://ecslimited.com">ecslimited.com</a>		Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No			Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No			Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No			UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No		
Line Tightness Testing:	No					UST System Removal:	<u>Yes</u>		
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>						
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No						
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No						
Oil and Solvent Recycling:	No	Other:							
Soil and Water Testing Lab:	No								

Company				Listing Submitted		7/2/2024		Area of state conducts work	
Environmental Hydrogeological Consultants, Inc. DB PO Box 902 Red Springs, NC 28377				Phone (910) 843-4456  Fax (910) 843-5376  Website <a href="http://www.environmentalinc.com">www.environmentalinc.com</a>		Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No			Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No			Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No			UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No		
Line Tightness Testing:	No					UST System Removal:	<u>Yes</u>		
Environmental Service Firms						Other: Liquid/Hydro Excavate Vac Truck Services			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No						
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No						
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>						
Oil and Solvent Recycling:	<u>Yes</u>	Other: OSRO Certified US Coast Guard Contractor							
Soil and Water Testing Lab:	<u>Yes</u>								



## UST Service Provider List (Central)

Company			Listing Submitted	5/14/2024	Area of state conducts work
<b>Environmental Petroleum Services</b> 1234 Gordon Park Rd Augusta, GA 30901			<b>Phone</b> (877) 297-6763 <b>Fax</b> <b>Website</b> <a href="http://www.keepmecompliant.net">www.keepmecompliant.net</a>		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>		
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>	Dispenser Meter Repair/Calibration:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<b>Yes</b>
Corrosion Protection Design Experts:	<b>Yes</b>	Spill Prevention Equipment Testing:	<b>Yes</b>	Spill Bucket Installation Repair:	<b>Yes</b>
Corrosion Protection System Repairs:	<b>Yes</b>	Tank Tightness Testing:	<b>Yes</b>	UST Equipment Installation - Other:	<b>Yes</b>
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<b>Yes</b>
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<b>Yes</b>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<b>Yes</b>
Line Tightness Testing:	<b>Yes</b>			UST System Removal:	<b>Yes</b>
<b>Environmental Service Firms</b>			Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company			Listing Submitted	7/16/2024	Area of state conducts work
<b>EnviroSouth, Inc.</b> 3440 Augusta Road Greenville, SC 29605			<b>Phone</b> (864) 236-9010 <b>Fax</b> <b>Website</b> <a href="http://www.envirosouth.com">www.envirosouth.com</a>		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<b>Yes</b>
<b>Environmental Service Firms</b>			Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

## UST Service Provider List (Central)

Company		Listing Submitted		7/12/2023		Area of state conducts work	
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054		Phone (704) 853-0800 Fax (704) 853-3949 Website <a href="http://www.excelengr.com">www.excelengr.com</a>				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		7/3/2024		Area of state conducts work	
Groundwater Manage. Associates 4300 Sapphire Court Suite 100 Greenville, NC 27834		Phone	(252) 758-3310			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
		Fax					
		Website	<a href="http://www.gma-nc.com">www.gma-nc.com</a>				
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			No
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						



## UST Service Provider List (Central)

Company				Listing Submitted	11/16/2023	Area of state conducts work	
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834		Phone (252) 758-3310  Fax  Website <a href="http://www.gma-nc.com">www.gma-nc.com</a>				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	4/20/2023	Area of state conducts work	
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226		Phone (704) 553-2300  Fax (704) 553-2400  Website <a href="http://www.gtaeng.com">www.gtaeng.com</a>				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company				Listing Submitted		4/11/2023		Area of state conducts work	
<b>INENCO, Inc.</b> 132 W. Statesville Avenue Mooresville, NC 27115				<b>Phone</b> (704) 662-8192 <b>Fax</b> (704) 662-8194 <b>Website</b>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No			Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No			Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No			UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No		
Line Tightness Testing:	No					UST System Removal:	<u>Yes</u>		
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>						
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No						
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No						
Oil and Solvent Recycling:	No	Other:							
Soil and Water Testing Lab:	No								

Company				Listing Submitted		5/15/2023		Area of state conducts work	
<b>JF Petroleum Group</b> 100 Perimeter Park Drive Suite H Morrisville, NC 27560				<b>Phone</b> (919) 744-4391 <b>Fax</b> <b>Website</b> <a href="http://jfpetrogroup.com/services/environmentalcompliance">jfpetrogroup.com/services/environmentalcompliance</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>			Dispenser Meter Repair/Calibration:	<u>Yes</u>		
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	<u>Yes</u>		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>			Spill Bucket Installation Repair:	<u>Yes</u>		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>			UST Equipment Installation - Other:	<u>Yes</u>		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	<u>Yes</u>		
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	<u>Yes</u>		
Leak Detection Monitoring Services:	<u>Yes</u>	Other:				UST Piping/Sump Installation:	<u>Yes</u>		
Line Tightness Testing:	<u>Yes</u>					UST System Removal:	<u>Yes</u>		
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>						
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>						
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No						
Oil and Solvent Recycling:	No	Other:							
Soil and Water Testing Lab:	No								

## UST Service Provider List (Central)

Company			Listing Submitted	12/20/2022	Area of state conducts work	
Jones Covey Group 9595 Lucas Ranch Rd STE 100 Rancho Cucamonga, CA 91730			Phone (888) 972-7581 Fax (909) 484-0300 Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	No	
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes	Leak Detection Equipment Installation Servicing:	Yes	
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	Yes	
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	Yes	
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	Yes	UST Equipment Repair:	Yes	
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	Yes	UST System Installation - Complete Systems:	Yes	
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:	Yes	
Line Tightness Testing:	Yes			UST System Removal:	No	
Environmental Service Firms				Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes			
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes			
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No			
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					

Company			Listing Submitted	5/30/2024	Area of state conducts work	
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205			Phone (336) 382-7132 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No	
Line Tightness Testing:	No			UST System Removal:	Yes	
Environmental Service Firms				Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No			
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No			
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No			
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					

## UST Service Provider List (Central)

Company		Listing Submitted		5/30/2024		Area of state conducts work	
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897		Phone (228) 516-0498  Fax  Website https://www.mcs-petroleum-div.com/				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	Yes		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	Yes		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	Yes		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	Yes		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	Yes		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		4/20/2023		Area of state conducts work	
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732		Phone (904) 814-3680  Fax  Website mgfenvironmental.com				Coastal (East of I-95): No  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company		Listing Submitted		9/8/2022		Area of state conducts work	
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610		Phone (919) 250-9918  Fax (919) 250-9950  Website <a href="http://www.maaonline.com">www.maaonline.com</a>			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes		
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		7/2/2024		Area of state conducts work	
Paragon Environmental Consultants, Inc. P.O. Box 157 Thomasville, NC 27361		Phone (336) 669-6037 Fax (336) 476-7708 Website			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No		
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company		Listing Submitted		11/1/2023		Area of state conducts work	
Peak Hydrogeologic, PLLC 470 Hogback Mtn Rd Tryon, NC 28782		Phone (828) 817-5209  Fax  Website <a href="https://peakhydrogeologic.com">https://peakhydrogeologic.com</a>				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			<u>Yes</u>
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

Company		Listing Submitted		3/31/2022		Area of state conducts work	
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027		Phone (980) 781-1000  Fax  Website <a href="http://www.petroleumtec.com">www.petroleumtec.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:	Tank Cleaning	UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:		Tank Cleaning	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:	Tank Cleaning				
Soil and Water Testing Lab:	No						



## UST Service Provider List (Central)

Company				Listing Submitted		8/19/2024		Area of state conducts work	
<b>Piedmont Geologic, P.C.</b> 6003-145 Chapel Hill Road Raleigh, NC 27607				<b>Phone</b> (919) 954-9700 <b>Fax</b> <b>Website</b> <a href="http://www.piedmontgeologic.com">www.piedmontgeologic.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No			
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No			
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No			
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No			
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No			
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No			
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No			
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>			
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>						
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No						
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No						
Oil and Solvent Recycling:	No	Other:							
Soil and Water Testing Lab:	No								

Company				Listing Submitted		11/1/2023		Area of state conducts work	
<b>Pilot Geological , PLLC</b> PO Box 128 743 Park Lawn Court Kernersville, NC 27285				<b>Phone</b> (336) 870-3095 <b>Fax</b> (336) 310-4527 <b>Website</b> <a href="http://www.pilotenviro.com">www.pilotenviro.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No			
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No			
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No			
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No			
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No			
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No			
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No			
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>			
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>						
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No						
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>						
Oil and Solvent Recycling:	No	Other:							
Soil and Water Testing Lab:	No								

Company		Listing Submitted		11/1/2023		Area of state conducts work	
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285		Phone (336) 870-3095  Fax (336) 310-4527  Website <a href="http://www.pilotenviro.com">www.pilotenviro.com</a>		Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company				Listing Submitted		10/12/2022		Area of state conducts work	
Practical Environmental Solutions. PC 5634 Harvest Grove Ln Wilmington, NC 28409				Phone (910) 790-8265  Fax  Website <a href="http://www.oil-tank.com">www.oil-tank.com</a>		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:		No	Overfill Prevention Equipment Operability Check:		No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:		No	Statistical Inventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:		No	Spill Prevention Equipment Testing:		No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:		No	Tank Tightness Testing:		No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:		No	UST Internal Inspections (Integrity Assessments):		No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:		No	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:		No	Other:			UST Piping/Sump Installation:		No	
Line Tightness Testing:		No				UST System Removal:		Yes	
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:		No	UST Compliance Consultants:		No				
Environmental Engineer/Geologist - Site Checks:		Yes	UST Equipment Verification:		No				
Environmental Engineer/Geologist Soil and GW Cleanu		Yes	Waste Disposal and Treatment:		No				
Oil and Solvent Recycling:		No	Other:						
Soil and Water Testing Lab:		Yes							

Company				Listing Submitted		4/4/2023		Area of state conducts work	
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526				Phone (704) 694-8359  Fax  Website <a href="http://www.regionalenv.com">www.regionalenv.com</a>		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:		No	Overfill Prevention Equipment Operability Check:		No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:		No	Statistical Inventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:		No	Spill Prevention Equipment Testing:		No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:		No	Tank Tightness Testing:		No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:		No	UST Internal Inspections (Integrity Assessments):		No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:		No	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:		No	Other:			UST Piping/Sump Installation:		No	
Line Tightness Testing:		No				UST System Removal:		No	
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:		No	UST Compliance Consultants:		Yes				
Environmental Engineer/Geologist - Site Checks:		Yes	UST Equipment Verification:		No				
Environmental Engineer/Geologist Soil and GW Cleanu		Yes	Waste Disposal and Treatment:		Yes				
Oil and Solvent Recycling:		No	Other:						
Soil and Water Testing Lab:		Yes							

## UST Service Provider List (Central)

Company				Listing Submitted	7/30/2024	Area of state conducts work	
SR&R Environmental, Inc. 4920 Highway 421 N. Wilmington, NC 28401		Phone (910) 763-6274  Fax (910) 763-6132  Website <a href="http://www.srrenviro.com">www.srrenviro.com</a>		Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:	Fuel Polishing				
Soil and Water Testing Lab:	No						

Company				Listing Submitted	8/15/2024	Area of state conducts work	
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410		Phone (336) 854-8135  Fax  Website <a href="https://www.terracon.com/">https://www.terracon.com/</a>		Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		8/15/2024		Area of state conducts work	
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410		Phone (336) 854-8135  Fax  Website <a href="https://www.terracon.com/">https://www.terracon.com/</a>		Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company				Listing Submitted	3/6/2024	Area of state conducts work	
Titan Environmental Group 2005 Citation Drive Garner, NC 27529		Phone (984) 200-6825  Fax  Website <a href="http://www.titanenvirogroup.com">www.titanenvirogroup.com</a>		Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	8/27/2024	Area of state conducts work	
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134		Phone (704) 504-1717  Fax (704) 504-1125  Website <a href="http://www.teamues.com">www.teamues.com</a>		Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		8/27/2024		Area of state conducts work	
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134		Phone (704) 504-1717  Fax (704) 504-1125  Website <a href="http://www.teamues.com">www.teamues.com</a>		Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company			Listing Submitted	7/14/2022	Area of state conducts work
<b>VALLEY TANK TESTING</b> 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572			<b>Phone</b> (813) 671-9065 <b>Fax</b> (866) 328-9796 <b>Website</b> <a href="http://WWW.VALLEYTANK.COM">WWW.VALLEYTANK.COM</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<b>Yes</b>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<b>Yes</b>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<b>Yes</b>			UST System Removal:	No
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company			Listing Submitted	1/31/2023	Area of state conducts work
<b>Valor Construction LLC</b> PO Box 680654 Fort Payne, AL 35968			<b>Phone</b> (205) 577-1035 <b>Fax</b> <b>Website</b>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<b>Yes</b>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<b>Yes</b>
Line Tightness Testing:	No			UST System Removal:	<b>Yes</b>
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

## UST Service Provider List (Central)

Company		Listing Submitted		11/1/2023		Area of state conducts work	
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591		Phone (919) 469-3340  Fax  Website <a href="http://www.withersravenel.com">www.withersravenel.com</a>		Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						