		UST Service Provider List (C	oastal)		
Company		Listing Submitte	d 8/19/2024	Area of state conducts work	
A1 Environmental Services Inc		Phone (252) 531-1284		Coastal (East of I-95): Yes	
PO Box 59		Fax		Central (West of I-95 and East of I-77): No	
Greenville, NC 27835				Mountains (West of I-77): No	
	W	ebsite www.aes-nc.com		,	
Comp	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Ei	nvironmenta	Il Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitte	d 1/18/2024	Area of state conducts work	
Company Advanced Environmental Services, Inc.		Phone (336) 282-3586	d 1/18/2024	Area of state conducts work Coastal (East of I-95): Yes	
Advanced Environmental Services, Inc. PO Box 38218		Phone (336) 282-3586	d 1/18/2024	Coastal (East of I-95): Yes	
Advanced Environmental Services, Inc.			d 1/18/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Advanced Environmental Services, Inc. PO Box 38218	w	Phone (336) 282-3586	d 1/18/2024	Coastal (East of I-95): Yes	
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438		Phone (336) 282-3586 Fax (336) 282-3587	d 1/18/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438		Phone (336) 282-3586 Fax (336) 282-3587 Pebsite AdavancedEnvironmental.com	d 1/18/2024 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Comp	pliance Test	Phone (336) 282-3586 Fax (336) 282-3587 Pebsite AdavancedEnvironmental.com ing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Compatible Line Leak Detector Testing:	pliance Test No	Phone (336) 282-3586 Fax (336) 282-3587 /ebsite AdavancedEnvironmental.com ing and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Comparison Comparison Comparison Comparison Comparison Comparison Containment Sump Testing:	pliance Test No No	Phone (336) 282-3586 Fax (336) 282-3587 Lebsite AdavancedEnvironmental.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Comparison of	pliance Test No No No	Phone (336) 282-3586 Fax (336) 282-3587 Lebsite AdavancedEnvironmental.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Comparison Comparison Comparison Comparison Comparison Protection Design Experts: Corrosion Protection System Repairs:	pliance Test No No No No	Phone (336) 282-3586 Fax (336) 282-3587 Lebsite AdavancedEnvironmental.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone (336) 282-3586 Fax (336) 282-3587 Website AdavancedEnvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (336) 282-3586 Fax (336) 282-3587 Pebsite AdavancedEnvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 282-3586 Fax (336) 282-3587 Pebsite AdavancedEnvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 282-3586 Fax (336) 282-3587 Website AdavancedEnvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 282-3586 Fax (336) 282-3587 Lebsite AdavancedEnvironmental.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Enemore Protection System Testing: Enemore	No N	Phone (336) 282-3586 Fax (336) 282-3587 Lebsite AdavancedEnvironmental.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: LIST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (336) 282-3586 Fax (336) 282-3587 Lebsite AdavancedEnvironmental.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: LIST Compliance Consultants: UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Co	astal)		
Company		Listing Submitted	7/19/2022	Area of state conducts work	
B & M WEST CONSTRUCTION CO OF TEXAS	DBA D.	Phone (863) 519-4441		Coastal (East of I-95): Yes	
209 E BADCOCK BLVD		Fax (863) 519-4407		Central (West of I-95 and East of I-77): Yes	
MULBERRY, FL 33860				Mountains (West of I-77): Yes	
	W	ebsite <u>DWSHOUPPE.COM</u>		,	
Comp	pliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	6/26/2024	Area of state conducts work	
BUCKEYE ELM CONTRACTING, LLC		Phone (336) 337-6001		Coastal (East of I-95): Yes	
PO Box 1026		Fax		Central (West of I-95 and East of I-77): Yes	
MOCKSVILLE, NC 27028				Mountains (West of I-77): Yes	
	W			mountains (west of 177). 100	
	•••	ebsite <u>www.buckeye-elm.com</u>			
Comp		ebsite <u>www.buckeye-elm.com</u> ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:			No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
	pliance Testi	ng and Monitoring	No No		No No
Automatic Line Leak Detector Testing:	pliance Testi No	ng and Monitoring Overfill Prevention Equipment Operability Check:		Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Testi No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	pliance Testi No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	pliance Testi No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No No <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No N	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No <u>Yes</u> <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No <u>Yes</u> <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release:	No N	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>

		UST Service Provider List (Co	astal)		
Company		Listing Submitted	5/18/2022	Area of state conducts work	
Cape Fear Engineering, Inc.		Phone (910) 383-1044		Coastal (East of I-95): Yes	
151 Poole Road		Fax		Central (West of I-95 and East of I-77): No	
Suite 100				Mountains (West of I-77): No	
Leland, NC 28451	V	Vebsite www.capefearengineering.com		mountains (West St 177). No	
Com	pliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı <u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/18/2022	Area of state conducts work	
Company Cape Fear Engineering, Inc.		Listing Submitted Phone (910) 383-1044	5/18/2022	Area of state conducts work Coastal (East of I-95): Yes	
		Phone (910) 383-1044	5/18/2022	Coastal (East of I-95): Yes	
Cape Fear Engineering, Inc. 151 Poole Road Suite 100			5/18/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No	
Cape Fear Engineering, Inc. 151 Poole Road	V	Phone (910) 383-1044	5/18/2022	Coastal (East of I-95): Yes	
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451		Phone (910) 383-1044 Fax	5/18/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No	
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451		Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com	5/18/2022 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No	No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com	pliance Tes	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors	
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing:	pliance Tes No	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Tes No No	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	pliance Tes No No No	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	No N	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

		UST Service Provider List (Co	astal)		
Company		Listing Submitted	11/1/2023	Area of state conducts work	
Cathodic Protection Services, Inc.		Phone (423) 895-1500		Coastal (East of I-95): Yes	
916 Egypt Rd.		Fax		Central (West of I-95 and East of I-77): Yes	
Bluff City, NC 37618				Mountains (West of I-77): Yes	
	V	Vebsite			
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/5/2023	Area of state conducts work	
• •			4/5/2023		
Company CATLIN Engineers and Scientists 220 Old Dairy Road		Phone (910) 452-5861	4/5/2023	Coastal (East of I-95): Yes	
CATLIN Engineers and Scientists			4/5/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
CATLIN Engineers and Scientists 220 Old Dairy Road	V	Phone (910) 452-5861	4/5/2023	Coastal (East of I-95): Yes	
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405		Phone (910) 452-5861 Fax	4/5/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405		Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com	4/5/2023 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp	oliance Tes	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comparison Comp	oliance Tes No	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comparison Comparison Comparison Containment Sump Testing:	No No	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Engergency Cleanup - Spill/Release:	No N	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Vo No	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Coastal)		
Company		Listing Submit		Area of state conducts work	
CDG, Inc.		Phone (704) 394-6913		Coastal (East of I-95): Yes	
4301 Taggart Creek Road		Fax		Central (West of I-95 and East of I-77): Yes	
Charlotte, NC 28208	V	Website www.cdge.com		Mountains (West of I-77): Yes	
	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironment	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submit	ted 6/27/2024	Area of state conducts work	
Company Cobb Environmental & Technical Services, Inc	>.	Phone (662) 841-0995	ted 6/27/2024	Area of state conducts work Coastal (East of I-95): Yes	
Cobb Environmental & Technical Services, Inc P. O. Box 1602	>.	Phone (662) 841-0995	ted 6/27/2024	Coastal (East of I-95): Yes	
Cobb Environmental & Technical Services, Inc	>.		ted 6/27/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Cobb Environmental & Technical Services, Inc P. O. Box 1602		Phone (662) 841-0995	ted 6/27/2024	Coastal (East of I-95): Yes	
Cobb Environmental & Technical Services, Inc P. O. Box 1602 Tupelo, MS 38802	V	Phone (662) 841-0995 Fax (662) 841-0810	ted 6/27/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Cobb Environmental & Technical Services, Inc P. O. Box 1602 Tupelo, MS 38802	V	Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenv.com	ted 6/27/2024 Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802 Comp	V oliance Tes	Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenv.com sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802 Comp. Automatic Line Leak Detector Testing:	V Oliance Tes Yes	Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenv.com Sting and Monitoring Overfill Prevention Equipment Operability Check:	Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802 Comp. Automatic Line Leak Detector Testing: Containment Sump Testing:	V Dliance Tes Yes Yes	Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenv.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	<u>Yes</u> No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No <u>Yes</u>
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802 Comp. Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Violiance Tes Yes Yes No	Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenv.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Yes No Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No <u>Yes</u> <u>Yes</u>
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802 Comp. Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Ves Yes Yes No No No No Yes	Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenv.com Iting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No Yes Yes Yes No Yes
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802 Comp. Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Ves Yes Yes No No No	Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenv.com Iting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes Yes No Yes Yes
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802 Comp. Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Ves Yes Yes No No No No Yes	Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenv.com Iting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes Yes Yes No Yes
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802 Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Ves Yes Yes No No No No Yes No	Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenv.com Iting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes Yes No Yes Yes
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802 Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Ves Yes Yes No No No No Yes No	Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenv.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes Yes No Yes Yes
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802 Comp. Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Ves Yes No No No Yes No No	Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenv.com Iting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes Yes No Yes Yes
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release:	Ves No	Phone (662) 841-0995 Fax (662) 841-0810 Nebsite cobbenv.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Stal Service Firms UST Compliance Consultants:	Yes No Yes No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes Yes No Yes Yes
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Ves No	Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenv.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	Yes No Yes No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes Yes No Yes Yes

		UST Service Provider List (Co	pastal)		
Company		Listing Submitted	11/21/2023	Area of state conducts work	
Conklin Corrosion Control LLC		Phone (704) 560-9154		Coastal (East of I-95): Yes	
118 Oak Point Lane		Fax		Central (West of I-95 and East of I-77): Yes	
Stony Point, NC 28678				Mountains (West of I-77): Yes	
	V	Vebsite benconklincc@gmail.com		mountains (violes 1117).	
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	9/28/2022	Area of state conducts work	
D. H. Griffin Wrecking Company		Phone (336) 214-9012		Coastal (East of I-95): Yes	
4716 Hilltop Road		Fax		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27407					
	V	Vebsite www.dhgriffin.com		Mountains (West of I-77): Yes	
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	<u>Yes</u> No	UST Compliance Consultants: UST Equipment Verification:	No No		
	No	·			
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No <u>Yes</u>		
Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No No	UST Equipment Verification: Waste Disposal and Treatment:	No <u>Yes</u>		

		UST Service Provider List (C	oastal)		
Company		Listing Submitte	d 4/5/2023	Area of state conducts work	
East Coast Environmental, PA		Phone (919) 349-5969		Coastal (East of I-95): Yes	
3815 Junction Boulevard		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27603				Mountains (West of I-77): No	
		Website <u>eastcoastenv.com</u>		, , ,	
Comp	pliance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmen	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	ı <u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
$oldsymbol{arphi}$					
Company		Listing Submitte	d 1/6/2025	Area of state conducts work	
		Listing Submitted Phone (919) 861-9910	d 1/6/2025	Area of state conducts work Coastal (East of I-95): Yes	
Company ECS Southeast, LLC 5260 Greens Dairy Road		Phone (919) 861-9910	d 1/6/2025	Coastal (East of I-95): Yes	
Company ECS Southeast, LLC			d 1/6/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company ECS Southeast, LLC 5260 Greens Dairy Road		Phone (919) 861-9910	d 1/6/2025	Coastal (East of I-95): Yes	
Company ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616		Phone (919) 861-9910 Fax	d 1/6/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616		Phone (919) 861-9910 Fax Website ecslimited.com	d 1/6/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Company ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616	pliance Te	Phone (919) 861-9910 Fax Website ecslimited.com sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Company ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616 Company Automatic Line Leak Detector Testing:	pliance Te	Phone (919) 861-9910 Fax Website ecslimited.com sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Company ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616 Company Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Te	Phone (919) 861-9910 Fax Website ecslimited.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Company ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	pliance Tea No No No	Phone (919) 861-9910 Fax Website ecslimited.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
Company ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	pliance Te No No No No	Phone (919) 861-9910 Fax Website ecslimited.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Company ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	pliance Te No No No No No	Phone (919) 861-9910 Fax Website ecslimited.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Company ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (919) 861-9910 Fax Website ecslimited.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	pliance Tes No No No No No No No No No N	Phone (919) 861-9910 Fax Website ecslimited.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Company ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	pliance Tes No No No No No No No No No N	Phone (919) 861-9910 Fax Website ecslimited.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Company ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 861-9910 Fax Website ecslimited.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Company ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	No N	Phone (919) 861-9910 Fax Website ecslimited.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: ottal Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Company ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (919) 861-9910 Fax Website ecslimited.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: ottal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

		UST Service Provider List (Co	astal)		
Company		Listing Submitted	7/3/2024	Area of state conducts work	
Groundwater Manage. Associates		Phone (252) 758-3310		Coastal (East of I-95): Yes	
4300 Sapphire Court		Fax		Central (West of I-95 and East of I-77): Yes	
Suite 100				Mountains (West of I-77): Yes	
Greenville, NC 27834	V	Vebsite www.gma-nc.com		would all s (West Of 1-77). 163	
Com	pliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/16/2023	Area of state conducts work	
Groundwater Management Associates, Inc.		Phone (252) 758-3310		Coastal (East of I-95): Yes	
4300 Sapphire Court		Fax		Central (West of I-95 and East of I-77): Yes	
Suite 100		I dx			
Greenville, NC 27834	V	Vebsite www.gma-nc.com		Mountains (West of I-77): Yes	
Comp	pliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Efficiency Cleanup - Spill/Release.		•			
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
		UST Equipment Verification: Waste Disposal and Treatment:	No No		
Environmental Engineer/Geologist - Site Checks:		· ·			
Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:			

		UST Service Provider List (Co	astal)		
Company		Listing Submitted	4/11/2023	Area of state conducts work	
INENCO, Inc.		Phone (704) 662-8192		Coastal (East of I-95): Yes	
132 W. Statesville Avenue		Fax (704) 662-8194		Central (West of I-95 and East of I-77): Yes	
Mooresville, NC 27115				Mountains (West of I-77): Yes	
	W	ebsite		,	
Com	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmenta	Il Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/15/2023	Area of state conducts work	
Company JF Petroleum Group		Phone (919) 744-4391	5/15/2023		
Company JF Petroleum Group 100 Perimeter Park Drive		Phone (919) 744-4391	5/15/2023	Coastal (East of I-95): Yes	
JF Petroleum Group			5/15/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
JF Petroleum Group 100 Perimeter Park Drive		Phone (919) 744-4391		Coastal (East of I-95): Yes	
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560	W	Phone (919) 744-4391 Fax		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560	W	Phone (919) 744-4391 Fax besite ifpetrogroup.com/services/environmentale		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	Yes
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560 Com	W pliance Test	Phone (919) 744-4391 Fax /ebsite ifpetrogroup.com/services/environmentaleing and Monitoring	compliance	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	Yes Yes
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560 Com Automatic Line Leak Detector Testing:	W pliance Test Yes	Phone (919) 744-4391 Fax 'ebsite ifpetrogroup.com/services/environmentale ing and Monitoring Overfill Prevention Equipment Operability Check:	compliance Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	W pliance Test Yes Yes	Phone (919) 744-4391 Fax Lebsite ifpetrogroup.com/services/environmentals ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	compliance Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u>
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560 Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts:	W pliance Test Yes Yes No	Phone (919) 744-4391 Fax Lebsite ifpetrogroup.com/services/environmentale ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Compliance Yes No Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	<u>Yes</u> <u>Yes</u>
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560 Comparite Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Wind pliance Test Yes Yes No No	Phone (919) 744-4391 Fax Lebsite ifpetrogroup.com/services/environmentale ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	pliance Test Yes Yes No No No	Phone (919) 744-4391 Fax Pebsite ifpetrogroup.com/services/environmentale ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Wind pliance Test Yes Yes No No No No Yes	Phone (919) 744-4391 Fax Pebsite ifpetrogroup.com/services/environmentale Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560 Comparition Comparition Containment Sump Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	With position of the position	Phone (919) 744-4391 Fax Pebsite ifpetrogroup.com/services/environmentale Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560 Comparition Comparition Containment Sump Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	With position of the position	Phone (919) 744-4391 Fax Lebsite ifpetrogroup.com/services/environmentale ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Pliance Test Yes Yes No No No Yes Yes Yes Yes Yes Yes Novironmenta	Phone (919) 744-4391 Fax Pebsite ifpetrogroup.com/services/environmentale Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	VV pliance Test Yes Yes No No No Yes Yes Yes Yes No No No	Phone (919) 744-4391 Fax Lebsite ifpetrogroup.com/services/environmentale Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: LIST Compliance Consultants:	Yes No Yes Yes No No Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	VV pliance Test Yes Yes No No No Yes Yes Yes Yes No No No	Phone (919) 744-4391 Fax Lebsite ifpetrogroup.com/services/environmentale Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: LIST Compliance Consultants: UST Compliance Consultants: UST Equipment Verification:	Yes No Yes No No No Yes Yes No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes

		UST Service Provider List (Co	astal)		
Company		Listing Submitted		Area of state conducts work	
Jones Covey Group		Phone (888) 972-7581		Coastal (East of I-95): Yes	
9595 Lucas Ranch Rd STE 100		Fax (909) 484-0300		Central (West of I-95 and East of I-77): Yes	
Rancho Cucamonga, CA 91730		F. F. St.		Mountains (West of I-77): Yes	
	VV	/ebsite			
Comp	oliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/30/2024	Area of state conducts work	
Marley Trucking & Demolition Inc.		Phone (336) 382-7132	5/30/2024	Area of state conducts work Coastal (East of I-95): Yes	
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road			5/30/2024		
Marley Trucking & Demolition Inc.		Phone (336) 382-7132 Fax	5/30/2024	Coastal (East of I-95): Yes	
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205		Phone (336) 382-7132 Fax /ebsite	5/30/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205		Phone (336) 382-7132 Fax	5/30/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205		Phone (336) 382-7132 Fax /ebsite	5/30/2024 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205	oliance Test	Phone (336) 382-7132 Fax /ebsite ing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	oliance Test No	Phone (336) 382-7132 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No	Phone (336) 382-7132 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone (336) 382-7132 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Phone (336) 382-7132 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone (336) 382-7132 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (336) 382-7132 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 382-7132 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	Phone (336) 382-7132 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (336) 382-7132 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	Phone (336) 382-7132 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (336) 382-7132 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Co	pastal)		
Company		Listing Submitted		Area of state conducts work	
MERRITT COMMERCIAL SERVICES LLC		Phone (228) 516-0498		Coastal (East of I-95): Yes	
217 STRICKLAND RD		Fax		Central (West of I-95 and East of I-77): Yes	
WHIGHAM, GA 39897				Mountains (West of I-77): Yes	
	1	Website https://www.mcs-petroleum-div.com/		mountains (west of 177). Tes	
Com	pliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	No
E	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	9/8/2022	Area of state conducts work	
• •		Phone (919) 250-9918	9/8/2022		
Company Mid-Atlantic Associates, Inc. 409 Rogers View Ct		Phone (919) 250-9918	9/8/2022	Coastal (East of I-95): Yes	
Mid-Atlantic Associates, Inc.			9/8/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Mid-Atlantic Associates, Inc. 409 Rogers View Ct	,	Phone (919) 250-9918	9/8/2022	Coastal (East of I-95): Yes	
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610		Phone (919) 250-9918 Fax (919) 250-9950	9/8/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610		Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com	9/8/2022 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610	pliance Tes	Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610 Com Automatic Line Leak Detector Testing:	pliance Tes	Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com Sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Tes No No	Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610 Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts:	pliance Tes No No No	Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	pliance Tes No No No No	Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No	Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	No N	Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company Petroleum Tec 5420 Powerhouse Ct		UST Service Provider List		Area of state conducts work	
		(222) =24 4222			
5420 Powerhouse Ct		Phone (980) 781-1000		Coastal (East of I-95): Yes	3
		Fax		Central (West of I-95 and East of I-77): Yes	6
Concord, NC 28027				Mountains (West of I-77): Yes	3
		Website www.petroleumtec.com		,	
Com	oliance T	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	. No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other: T	ank Cleaning	UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironme	ental Service Firms		Other: Tank	Cleaning
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No		ank Cleaning		
Soil and Water Testing Lab:	No		_		
Company		Listing Subm	itted 8/19/2024	Area of state conducts work	
Piedmont Geologic, P.C.		Phone (919) 954-9700		Coastal (East of I-95): Yes	6
6003-145 Chapel Hill Road		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27607		I un			
		Website www.piedmontgeologic.com		Mountains (West of I-77): Yes	5
Com	oliance T	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironme	ental Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Linergency Cleanup - Spill/Release.		UST Equipment Verification:	No		
	<u>Ye</u> s	OST Equipment verification.			
Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u> <u>Yes</u>	Waste Disposal and Treatment:	No		
Environmental Engineer/Geologist - Site Checks:					
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

Company Listing Submitted 11/1/2023 Area of state conducts work			UST Service Provider List (Co	pastal)		
PO Box 128 /	Company		,		Area of state conducts work	
PO Box 128 / A39 Ark Lawn Court Kernersville, NC 27285	Pilot Geological , PLLC	F	Phone (336) 870-3095		Coastal (East of I-95): Yes	
Mountains (West of I-77): Yes	PO Box 128		Fax (336) 310-4527		Central (West of I-95 and East of I-77): Yes	
Compliance Testing and Monitoring						
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Cortialment Sump Testing: No Statissical Idvantory Recombilitation Services: No Corrosion Protection Design Experts: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Repairs: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No UST Internal Injury Inspections: No UST Internal Injury Inspections (Integrity Assessments): No UST Internal Protection Equipment Operability Check: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Removal: No UST System Removal: No UST Equipment Restallation: No UST Removal System Installation Services: No UST Removal Design System	Kernersville, NC 27285	We	ebsite <u>www.pilotenviro.com</u>		mountains (West of 177). 163	
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Servicing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST Equipment Installation Other: No UST Equipment Repair: No UST Equipment Installation Complete Systems: No UST Equipment Repair: No UST System Repairs: No UST Pipmig/Sump Installation: No UST System Repairs: No UST System Repairs: No UST System Repairs: No UST System Repairs: No UST Equipment Repair: No UST Equipment Service Systems: No UST Equipment Service No UST Equipment Installation Repair: No Spill Prevention Equipment Operability Check: No UST Equipment Installation Repair: No UST Equipment	Comp	oliance Testir	ng and Monitoring		UST Equipmment Service Contractors	
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No UST Equipment Installation Repair: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Equipment Monitoring Services: No Other: UST System Removal: UST System Installation - Complete Systems: No UST System Removal: UST System Removal: UST System Removal: VST S	Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Depairs (No Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repairs: No UST System Installation - Other: No UST System Installation - Other: No UST System Installation - Other: No UST System Installation - Other - No Other System Installation - Other - No Other - System Installation - Other - No	Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No Leak Detection Equipment Operability Check: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation: No UST System Installation: No UST System Installation: No UST System Removal: UST System Removal: UST System Removal: Other: Cher:	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Leak Detection Equipment Operability Check: No Other: No UST System Removal: No UST System Removal: No UST System Removal: U	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Leak Detection Monitoring Services: No Other: UST Piping/Sump Installation: No Yes Control	Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Line Tightness Testing:	Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Emergency Cleanup - Spill/Release: Emvironmental Engineer/Geologist - Site Checks: Emvironmental Engineer/Geologist - Site Checks: Ves UST Compliance Consultants: Ves UST Equipment Verification: No Other: UST Equipment Verification: No Other: Ves Waste Disposal and Treatment: Ves Central (West of 1-95 and East of 1-77): Yes Waste Central (West of 1-95 and East of 1-77): Yes Waste Central (West of 1-95 and East of 1-77): Yes Waste Central (West of 1-95 and East of 1-77): Yes Waste Disposal And Treatment Disposal President Central Waste Office Disposal President (West of 1-95 a	Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Environmental Engineer/Geologist - Site Checks: Yes UST Compliance Consultants: Yes UST Compliance Consultants: Yes UST Equipment Verification: No Chervironmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Chervironmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Yes Other: Soil and Water Testing Lab: No Cher: Soil and Water Testing Lab: No Chervironmental Solutions. PC	Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks: Yes Waste Disposal and Treatment: Yes Waste Disposal and Treatment: Yes Other: Company	Er	nvironmental	Service Firms		Other:	
Environmental Engineer/Geologist - Site Checks: Yes Waste Disposal and Treatment: Yes Waste Disposal and Treatment: Yes Other: Company	Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Other: Oil and Solvent Recycling: Soil and Water Testing Lab: No Company Practical Environmental Solutions. PC Phone (910) 790-8265 Fax Fax Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Wountains (West of I-77): No Website www.oil-tank.com Website www.oil-tank.com UST Equipment Service Contractors Automatic Line Leak Detector Testing: No Corrosion Protection Design Experts: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Lining Inspections (Hegrity Assessments): No Leak Detection Equipment Operability Check: No UST Equipment Installation - Coher: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation: No UST System Installation: No UST System Repairs: No UST System Removal: Yes Temergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No						
Oil and Solvent Recycling: Soil and Water Testing Lab: No Company Listing Submitted 10/12/2022 Area of state conducts work Coastal (East of I-95): Yes 5634 Harvest Grove Ln Wilmington, NC 28409 Website www.oil-tank.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Corrosion Protection System Testing: No Corrosion Protection Equipment Operability Check: No Course Protection System Testing: No Corrosion Protection System Repairs: No Corrosion Protection System Repairs: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Corrosion Protection System Testing: No Corrosion Protection System Repairs: No Corrosion Pro						
Company Listing Submitted 10/12/2022 Area of state conducts work						
Practical Environmental Solutions. PC 5634 Harvest Grove Ln Wilmington, NC 28409 Website www.oil-tank.com UST Equipment Service Contractors No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Corrosion Protection Design Experts: No Statistical Iventory Reconciliation Services: No Corrosion Protection Design Experts: No Tank Tightness Testing: No UST Equipment Installation Servicing: No Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No Line Tightness Testing: No UST System Removal: Yes Environmental Service Firms Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No	Soil and Water Testing Lab:	No				
Practical Environmental Solutions. PC 5634 Harvest Grove Ln Wilmington, NC 28409 Website www.oil-tank.com UST Equipment Service Contractors No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Brevention Equipment Testing: No Spill Brevention Equipment Testing: No UST Equipment Installation Repair: No Corrosion Protection System Repairs: No UST Equipment Installation - Other: No Corrosion Protection System Testing: No UST Equipment Operability Check: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Removal: Yes Tenvironmental Service Firms Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No	Company		Listing Submitted	10/12/2022	Area of state conducts work	
Fax Website www.oil-tank.com Website www.oil-tank.com Website www.oil-tank.com Website www.oil-tank.com Website www.oil-tank.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Ocorrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Other: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: Yes Other:		F	<u> </u>		Coastal (East of I-95): Yes	
Website www.oil-tank.com Compliance Testing and Monitoring UST Equipment Service Contractors	5634 Harvest Grove Ln					
Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Servicing: No Overfill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Overrosion Protection Design Experts: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Removal: Yes Environmental Service Firms Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No	Wilmington, NC 28409		I dx			
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Removal: Yes Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No UST Equipment Verification: No UST Equipment No UST Equipment Operability Check: No UST Compliance Consultants: No UST Compliance Consultants: No UST Equipment Verification: No UST Equipment Verification: No UST Equipment Verification: No UST Equipment No UST Equipment Verification: No UST System Removal: Other:		We	ebsite <u>www.oil-tank.com</u>		Mountains (West of I-77): No	
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Spill Bucket Installation Repair: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Therefore, Geologist - Site Checks: Yes UST Equipment Verification: No No UST Compliance Consultants: No No UST Equipment Installation Repair: No No UST Equipment Installation Repair: No UST Equipment Installation - Other: No UST Equipment Installation Repair: No UST Equipment Installation Perair. No UST Equipment Install	Comp	oliance Testir	ng and Monitoring		UST Equipmment Service Contractors	
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Environmental Service Firms Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No UST Equipment Verification: No No UST Compliance Consultants: No No UST Equipment Repair: No No UST System Installation - Complete Systems: No UST System Removal: Other:	Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Ves Environmental Service Firms Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST System Installation - Complete Systems: No UST System Removal: Ves Other:	Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Environmental Service Firms UST System Removal: Yes Other: Other: No UST Compliance Consultants: No UST Compliance Consultants: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Removal: Yes Other:	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Environmental Service Firms UST System Removal: No UST System Removal: Yes Other: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: Yes Other:	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Leak Detection Monitoring Services: No Other: UST Piping/Sump Installation: UST System Removal: Yes Cher: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: Yes UST Piping/Sump Installation: No UST System Removal: Yes Other:	Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Line Tightness Testing: No UST System Removal: Other: Yes	Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Environmental Service Firms Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No	Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Emergency Cleanup - Spill/Release: No UST Compliance Consultants: Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No	Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No	Er	nvironmental	Service Firms		Other:	
Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No	Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
	Environmental Engineer/Geologist - Site Checks:			No		
Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No				No		
	Environmental Engineer/Geologist Soil and GW Cleanu	res	Waste Disposal and Treatment.			
Soil and Water Testing Lab: Yes	Oil and Solvent Recycling:			110		

The provided in the provided i	Phone (704) 694-8359 Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No Compliance Testing and Monitoring Compliance Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No Spill Bucket Installation - Other:	UST Service Provider List (Coastar)			UST Service Provider List (C	Coastal)		
Fax Website www.regionalenv.com Compliance Testing and Monitoring UST Equipmment Service Contractors Atic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST System Installation - Complete Systems:	Central (West of I-95 and East of I-77): Yes Website www.regionalenv.com Compliance Testing and Monitoring UST Equipmment Service Contractors Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No	Company Listing Submitted 4/4/2023 Area of state conducts work	Company		Listing Submitte	ed 4/4/2023	Area of state conducts work	
Website www.regionalenv.com Compliance Testing and Monitoring UST Equipmment Service Contractors atic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: On Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: On Protection System Repairs: No UST Equipment Installation - Other: On Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST System Installation - Complete Systems:	Website www.regionalenv.com Compliance Testing and Monitoring Detector Testing: No Overfill Prevention Equipment Operability Check: No Sesting: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No System Repairs: No UST Equipment Service Contractors No Dispenser Meter Repair/Calibration: No Spill Bucket Installation Repair: No UST Equipment Installation Servicing: No System Repairs: No UST Equipment Installation - Other: No		Regional Environmental PLLC		Phone (704) 694-8359		Coastal (East of I-95): Yes	
Website www.regionalenv.com Compliance Testing and Monitoring UST Equipmment Service Contractors atic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: Inment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: On Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: On Protection System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other: On Protection System Testing: No UST Equipment Repair: etection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems:	Website www.regionalenv.com Compliance Testing and Monitoring UST Equipmment Service Contractors Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No System Repairs: No UST Equipment Installation - Other: No	Regional Environmental PLLC Phone (704) 694-8359 Coastal (East of I-95): Yes	9016 Hazel Forest Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Compliance Testing and Monitoring UST Equipmment Service Contractors atic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: On Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: On Protection System Repairs: No UST Equipment Installation - Other: On Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: On Protection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems:	Compliance Testing and Monitoring UST Equipmment Service Contractors Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No	9016 Hazel Forest Drive Fax Central (West of I-95 and East of I-77): Yes	Fuquay Varina, NC 27526					
Attic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: On Protection System Repairs: No UST Equipment Installation - Other: On Protection System Testing: No UST Equipment Repair: UST Equipment Repair: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems:	Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Statistical Iventory Reconciliation Services: No Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No	9016 Hazel Forest Drive Fuguay Varina, NC 27526 Central (West of I-95 and East of I-77): Yes		V	Vebsite www.regionalenv.com		mountains (West of 1-17). No	
nment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: UST Equipment Repair: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems:	sesting: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other: No	9016 Hazel Forest Drive Fuquay Varina, NC 27526 Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	Com	pliance Test	ting and Monitoring		UST Equipmment Service Contractors	
on Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No	9016 Hazel Forest Drive Fuquay Varina, NC 27526 Website www.regionalenv.com Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
on Protection System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems:	System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other: No	Ponde Hazel Forest Drive Fuquay Varina, NC 27526 Website www.regionalenv.com Compliance Testing and Monitoring Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
on Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: UST System Installation - Complete Systems:		Po16 Hazel Forest Drive Fuquay Varina, NC 27526 Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
etection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems:	System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No	Ponde Hazel Forest Drive Fuquay Varina, NC 27526 Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Leak Detection Equipment Installation Servicing: No	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
		Fax Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Statistical Iventory Reconciliation Services: No Spill Bucket Installation Repair:	Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
etection Manitoring Convince: No. Other:	nent Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No	Fuquay Varina, NC 27526 Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Statistical Iventory Reconciliation Services: No Spill Bucket Installation Repair: No Tank Tightness Testing: No UST Equipment Service Contractors Leak Detection Equipment Installation - Other: No UST Equipment Installation - Other: No Overfill Prevention Equipment Testing: No Overrosion Protection System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other: No	Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
etection Monitoring Services. No Other.	ring Services: No Other: UST Piping/Sump Installation: No	Fax Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No UST Equipment Installation - Other: No Ocorrosion Protection System Testing: No UST Equipment Repair: No No UST Equipment Repair:	Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
ghtness Testing: No UST System Removal:		Fax Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems:	Line Tightness Testing:	No			UST System Removal:	No
Environmental Service Firms Other:		Fax Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Spill Prevention Equipment Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST System Installation - Complete Systems: No Leak Detection Equipment Repairs: No UST System Installation - Complete Systems: No Leak Detection System Installation - Complete Systems: No Leak Detection Equipment Installation - Complete Systems: No Leak Detection Monitoring Services: No UST Internal Lining Inspections: No UST Piping/Sump Installation: No UST Piping/Sump Installation: No	E	invironment	al Service Firms		Other:	
ency Cleanup - Spill/Release: No UST Compliance Consultants: Yes	g: No UST System Removal: No	Fax Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Lining Inspections: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Removal:	Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
imental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No	Programmental Service Firms UST System Removal: Other:	Fax Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Equipment Installation Other: No UST Equipment Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Prevention Equipment	Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
mental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Yes	Spill/Release: No UST System Removal: No UST Compliance Consultants: Yes UST System Removal: No UST Compliance Consultants: No UST Compliance Consultants: Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes Mountains (West of I-77): No Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No UST Equipment Installation Protect: No UST System Installation Protect: No UST System Installation Protect: No UST Piping/Sump Installation: No UST System Removal:	Environmental Engineer/Geologist Soil and GW Clean	u <u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
	UST System Removal: No Environmental Service Firms Spill/Release: No UST Compliance Consultants: Yes er/Geologist - Site Checks: Yes UST Equipment Verification: No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes Mountains (West of I-77): No Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Brevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Brevention Equipment Testing: No Spill Brevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST System Installation - Other: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: No US	Oil and Solvent Recycling:	No	Other:			
Solvent Recycling: No Other:	Environmental Service Firms Spill/Release: No UST Compliance Consultants: Yes er/Geologist - Site Checks: Yes Waste Disposal and Treatment: Yes UST System Removal: Other:	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No UST Equipment Installation Servicing: No Spill Bucket Installation Repair: No Orrosion Protection Design Experts: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Removal: No UST	Soil and Water Testing Lab:	<u>Yes</u>				
	Environmental Service Firms Spill/Release: No UST Compliance Consultants: Yes er/Geologist - Site Checks: Yes UST Equipment Verification: No er/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No Other:	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes Mountains (West of I-77): No Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No UST Equipment Installation Servicing: No UST Equipment Installation Servicing: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: No UST System Removal: No Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: Yes Dil and Solvent Recycling: No Other:	Company		Listing Submitte	ed 7/30/2024	Area of state conducts work	
d Water Testing Lab: Yes	Environmental Service Firms Spill/Release: No UST Compliance Consultants: Yes er/Geologist - Site Checks: Yes UST Equipment Verification: No er/Geologist Soil and GW Cleanu Yes No Other: Yes UST System Removal: Yes Other:	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Servicing: No Spill Bucket Installation Repair: No Spill Bucket Installation Protection System Repairs: No UST Equipment Installation Other: No UST Equipment Installation Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No UST Sy	SR&R Environmental, Inc.		Phone (910) 763-6274		Coastal (East of I-95): Yes	
d Water Testing Lab: Yes Listing Submitted 7/30/2024 Area of state conducts work	Environmental Service Firms Spill/Release: No UST Compliance Consultants: Yes er/Geologist - Site Checks: Yes UST Equipment Verification: No er/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Yes UST System Removal: No Other: Yes Listing Submitted 7/30/2024 Area of state conducts work	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes Mountains (West of I-77): No Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Spill Bucket Installation - Other: No UST Equipment Installation Servicing: No UST Equipment Installation Repair: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Installation Repair: No UST Equipment Installation Repair: No UST Equipment Installation Servicing: No UST Equipment Installation Repair: No UST Equipment Installation - Other: No UST Equipment Installation Servicing: No UST Equipment Installation Repair: No UST Equipment Installation Servicing: No UST Equipment Installation Repair: No UST Equipment Installation Repa						
Mater Testing Lab: Yes Listing Submitted 7/30/2024 Area of state conducts work Environmental, Inc. Phone (910) 763-6274 Coastal (East of I-95): Yes	Spill/Release: No UST Compliance Consultants: Yes er/Geologist - Site Checks: Yes UST Equipment Verification: No er/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Yes Usber: Listing Submitted 7/30/2024 Area of state conducts work tal, Inc. Phone (910) 763-6274 UST System Removal: No Other: Yes Listing Submitted 7/30/2024 Area of state conducts work Coastal (East of I-95): Yes	Central (West of I-95 and East of I-77): Yes Mountains, NC 27526 Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation Repair: No UST Equipment Installation Prepair: No UST Equipment Repair: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST System Installation - Other: No UST System Installation - Other: No UST System Installation - Omplete Systems: No UST System Removal: No UST System Removal: No UST System Removal: No UST System Removal: No Other: Emergency Cleanup - Spill/Release: No UST Equipment Verification: No UST Equipment Installation: No UST System Removal: No Other: Emergency Cleanup - Spill/Release: No UST Equipment Installation: No UST System Removal: No Other: Emergency Cleanup - Spill/Release: No UST Equipment Verification: No UST System Removal: No Other: Emergency Cleanup - Spill/Release: No UST Equipment Verification: No UST System Removal: No Other: Emergency Cleanup - Spill/Release: No Other: Emergency Cleanup - Spill/Release: No Other: Emergency Cleanup - Spill/Release: No Other: Soil and Water Testing Lab: Phone (910) 763-6274 Existing Submitted 7/30/2024 Entation Submitted	Wilmington, NC 28401		1 dx (310) 703-0132			
tiny Listing Submitted 7/30/2024 Area of state conducts work Environmental, Inc. Phone (910) 763-6274 Coastal (East of I-95): Yes dighway 421 N. Fax (910) 763-6132 Central (West of I-95 and East of I-77): Yes dignoral forms of the state conducts work Coastal (East of I-77): Yes dignoral forms of the state conducts work Coastal (East of I-77): Yes dignoral forms of the state conducts work Coastal (East of I-95): Yes dignoral forms of the state conducts work Coastal (East of I-95): Yes dignoral forms of the state conducts work	Spill/Release: No UST Compliance Consultants: Yes er/Geologist - Site Checks: Yes UST Equipment Verification: No er/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Yes ling: No Other: Listing Submitted 7/30/2024 Area of state conducts work tal, Inc. Phone (910) 763-6132 Listing Submitted 7/30/2024 Central (West of I-95 and East of I-77): Yes	### Central (West of I-95 and East of I-77): Yes Mountains, NC 27526 ### Website www.regionalenv.com Compliance Testing and Monitoring		V	Vebsite www.srrenviro.com		Mountains (West of I-77): Yes	
Mountains (West of I-77): Yes Listing Submitted 7/30/2024 Area of state conducts work Listing Submitted 7/30/2024 Area of state conducts work Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	Spill/Release: No UST Compliance Consultants: Yes Environmental Service Firms	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Bucket Installation Servicing: No Corrosion Protection Design Experts: No Tank Tightness Testing: No UST Internal Inspections: No UST Internal Lining Inspections: No UST Equipment Repair: No UST Equipment Installation - Other: No Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST	Com	pliance Test	ting and Monitoring		UST Equipmment Service Contractors	
Water Testing Lab: Yes Listing Submitted 7/30/2024 Area of state conducts work Environmental, Inc. Phone (910) 763-6274 Coastal (East of I-95): Yes dighway 421 N. Fax (910) 763-6132 Website www.srrenviro.com Website www.srrenviro.com	Environmental Service Firms Spill/Release: No UST Compliance Consultants: Yes er/Geologist - Site Checks: Yes UST Equipment Verification: No er/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Yes ling: No Other: Listing Submitted 7/30/2024 Area of state conducts work tal, Inc. Phone (910) 763-6274 No Website www.srrenviro.com UST System Removal: Other: Yes Cother: Area of state conducts work Coastal (East of I-95): Yes Mountains (West of I-77): Yes	## Central (West of I-95 and East of I-77): Yes Mountains, NC 27526 ## Website www.regionalenv.com Compliance Testing and Monitoring	Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Mater Testing Lab: Yes Inny Listing Submitted 7/30/2024 Area of state conducts work Environmental, Inc. Phone (910) 763-6274 Coastal (East of I-95): Yes dighway 421 N. Ington, NC 28401 Website www.srrenviro.com Compliance Testing and Monitoring UST Equipmment Service Contractors	Spil/Release: No UST Compliance Consultants: Yes	## Prugay Varina, NC 27526 Website www.regionalenv.com Website www.regionalenv.com	Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Mater Testing Lab: Yes Listing Submitted 7/30/2024 Area of state conducts work Environmental, Inc. Phone (910) 763-6274 Coastal (East of I-95): Yes dighway 421 N. Fax (910) 763-6132 Central (West of I-95 and East of I-77): Yes Website www.srrenviro.com Website www.srrenviro.com UST Equipmment Service Contractors atic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration:	Environmental Service Firms Spill/Release: No UST Compliance Consultants: Yes er/Geologist - Site Checks: Yes UST Equipment Verification: No Other: Yes ling: No Other: Listing Submitted 7/30/2024 Area of state conducts work tal, Inc. Phone (910) 763-6274 Coastal (East of I-95): Yes Listing Submitted Verification: Website www.srrenviro.com Compliance Testing and Monitoring Verector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Dispenser Meter Repair/Calibration: No Dispenser Meter Repair/Calibration: No	## Central (West of I-95 and East of I-77): Yes ## Mountains (West of I-77): No Website	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Listing Submitted 7/30/2024 Area of state conducts work Environmental, Inc. Phone (910) 763-6274 Coastal (East of I-95): Yes dighway 421 N. Fax (910) 763-6132 Website www.srrenviro.com Compliance Testing and Monitoring West of I-77): Yes dict Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: Indeed Detection Equipment Installation Servicing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing:	Spill/Release: No UST Compliance Consultants: Yes Brown	## Central (West of I-95 and East of I-77): Yes ## Mountains (West of I-77): No ## Mountains (West of I-77): Yes #	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Water Testing Lab: Yes Listing Submitted 7/30/2024 Area of state conducts work Environmental, Inc. Phone (910) 763-6274 Coastal (East of I-95): Yes dighway 421 N. Fax (910) 763-6132 Website www.srrenviro.com Compliance Testing and Monitoring UST Equipmment Service Contractors atic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair:	UST System Removal: No UST Compliance Firms	### Automatic Line Leak Detector Testing: No	Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Water Testing Lab: Yes Listing Submitted 7/30/2024 Area of state conducts work Environmental, Inc. Phone (910) 763-6274 Coastal (East of I-95): Yes dighway 421 N. Ington, NC 28401 Website www.srrenviro.com Wountains (West of I-77): Yes Compliance Testing and Monitoring UST Equipmment Service Contractors atic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: On Protection Design Experts: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Equipment Installation - Other:	Spill/Release: No UST Compliance Consultants: Yes	### Azel Forest Drive Fuquay Varina, NC 27526 #### Website www.regionalenv.com Compilance Testing and Monitoring UST Equipment Service Contractors	Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Listing Submitted 7/30/2024 Area of state conducts work Environmental, Inc. Phone (910) 763-6274 Coastal (East of I-95): Yes Highway 421 N. Ington, NC 28401 Website www.srrenviro.com Compliance Testing and Monitoring UST Equipmment Service Contractors Attic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Protection System Repairs: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair:	Spill/Release: No UST Compliance Consultants: Yes er/Geologist - Site Checks: Yes UST Equipment Verification: No Other:	## Central (West of I-95 and East of I-77); Yes Fuquay Varina, NC 27526 ## Website www.regionalenv.com Compliance Testing and Monitoring	Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Listing Submitted 7/30/2024 Area of state conducts work Environmental, Inc. Phone (910) 763-6274 Coastal (East of I-95): Yes Highway 421 N. Igiton, NC 28401 Website www.srrenviro.com Website www.srrenviro.com UST Equipment Service Contractors And Dispenser Meter Repair/Calibration: Leak Detector Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Equipment Installation - Other: On Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair:	Spill/Release: No UST Compliance Consultants: Yes UST Equipment Verification: No Verification: Verifica	### Park Park	Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Listing Submitted 7/30/2024 Area of state conducts work Environmental, Inc. Phone (910) 763-6274 Coastal (East of I-95): Yes Gentral (West of I-95 and East of I-77): Yes Gentral (West of I-95 and East of I-77): Yes Website www.srrenviro.com Website www.srrenviro.com Website www.srrenviro.com UST Equipmment Service Contractors And Compliance Testing and Monitoring UST Equipmment Service Contractors And Compliance Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: Indicate the Compliance Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No UST Equipment Installation - Other: On Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: On Protection Equipment Operability Check: No UST System Installation - Complete Systems: etection Monitoring Services: No Other: UST Piping/Sump Installation:	Spill/Release: No UST Compliance Consultants: Yes	### Programment Programment		nvironment	al Service Firms		Other:	
Listing Submitted 7/30/2024 Area of state conducts work Environmental, Inc. Phone (910) 763-6274 Environmental, Inc. Phone (910) 763-6274 Environmental, Inc. Fax (910) 763-6132 Website www.srrenviro.com Website www.srrenviro.com UST Equipmment Service Contractors Attic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No UST Equipment Installation Servicing: No Spill Bucket Installation Repair: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: Leak Detection Equipment Repair: No UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: Leak Detection Equipment Repair: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: Leak Detection Equipment Repair: UST System Installation - Complete Systems: Leak Detection Equipment Repair: UST System Installation - Complete Systems: Leak Detection Equipment Repair: UST System Installation: UST System Removal:	Spill/Release: No UST Compliance Consultants: Yes UST System Removal: No Other:	## Central (West of I-95 and East of I-77): Yes ## Veryagay Varina, NC 27526 ## Website	E					
Listing Submitted 7/30/2024 Area of state conducts work Environmental, Inc. Phone (910) 763-6274 Gentral (West of I-95 and East of I-77): Yes of Indiana (West of I-78): Indiana (West of I-77): Yes of Indiana (West	Spill/Release: No UST Compilance Consultants: Yes	Central (West of 1-95 and East of 1-77); Yes Mountains (West of 1-77); No Website www.regionalenv.com UST Equipment Service Contractors Website www.regionalenv.com UST Equipment Service Contractors UST Equipment Installation Services; No Containment Sump Testing; No Spill Prevention Equipment Operability Check: No Leak Detection Equipment Installation Servicing; No Spill Prevention Equipment (Services); No UST Internal Lining Inspections (Internal Lin			UST Compliance Consultants:	No		
Listing Submitted 7/30/2024 Area of state conducts work Environmental, Inc. Environmental, Inc. Elighway 421 N. Engton, NC 28401 Website www.srrenviro.com Website www.srrenviro.com Compliance Testing and Monitoring Website www.srrenviro.com Website www.srrenviro.com UST Equipment Service Contractors atic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: UST System Installation: UST System Removal: Other:	Spill/Release: No UST Compliance Consultants: Yes UST System Removal: No Other:	## Central (West of 1-95 and East of 1-77): Yes Fuguray Yarina, NC 27526 Website www.regionalenv.com Website www.regionalenv.com	Emergency Cleanup - Spill/Release:	<u>Yes</u>				
Listing Submitted 7/30/2024 Area of state conducts work Environmental, Inc. Phone (910) 763-6274 fighway 421 N. Igton, NC 28401 Website WWW.srrenviro.com Compliance Testing and Monitoring titic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Spill Prevention Equipment Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST Equipment Poperability Check: No UST Equipment Installation - Other: UST Equipment Installation - Complete Systems: etection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: etection Monitoring Services: No Other: UST System Installation: UST System Removal: Other: UST System Removal: Other: UST System Removal: Other: UST System Removal: Other:	Spill/Release: No UST Compliance Consultants: Yes	Contrail (West of I-95 and East of I-77): Yes Fuquery Varina, NC 27526 Website www.regionalenv.com	Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	<u>Yes</u> No	UST Equipment Verification:	No		
Listing Submitted 7/30/2024 Area of state conducts work Environmental, Inc. Phone (910) 763-6274 Environmental, Inc. Igidoway 421 N. Igidon, NC 28401 Website www.srrenviro.com Website www.srrenviro.com Website www.srrenviro.com UST Equipment Service Contractors attic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Protection Design Experts: No Spill Prevention Equipment Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: who Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST Equipment Installation - Other: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: UST System Removal: Other: Wes UST Compliance Consultants: No UST Equipment Verification: No Wested Installation: UST System Removal: UST System Removal: Other:	Spill/Release: No UST Compliance Consultants: Yes	Central (West of I-95 and East of I-77): Yes	Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes No u No	UST Equipment Verification: Waste Disposal and Treatment:	No <u>Yes</u>		
Solvent Recycling: No Other:	Environmental Service Firms Spill/Release: No UST Compliance Consultants: Yes er/Geologist - Site Checks: Yes UST Equipment Verification: No er/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Yes UST System Removal: Other:	Central (West of I-95 and East of I-77): Yes Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No UST Equipment Installation Servicing: Corrosion Protection Design Experts: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: UST System Installation - Complete Systems: UST System Installation - Complete Systems: UST System Installation: UST System Removal: UST System Removal: Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: Yes Emergency Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Yes	Company SR&R Environmental, Inc. 4920 Highway 421 N. Wilmington, NC 28401 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	Yes V pliance Test No No No No No No No No No N	Phone (910) 763-6274 Fax (910) 763-6132 Vebsite www.srrenviro.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	
		Fax Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair:						No
etection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems:	System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No	Pontal (West of I-95 and East of I-77): Yes Fuquay Varina, NC 27526 Website www.regionalenv.com Compliance Testing and Monitoring UST Equipmment Service Contractors Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
on Protection System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems:	System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other: No	Po16 Hazel Forest Drive Fuquay Varina, NC 27526 Website www.regionalenv.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No		No		No		No
on Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No System Repairs: No UST Equipment Installation - Other: No	Ponde Hazel Forest Drive Fuquay Varina, NC 27526 Website www.regionalenv.com Compliance Testing and Monitoring Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	3					
nment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: UST Equipment Repair: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems:	sesting: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other: No	9016 Hazel Forest Drive Fuquay Varina, NC 27526 Website www.regionalenv.com Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No		_		No		No
Attic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: On Protection System Repairs: No UST Equipment Installation - Other: On Protection System Testing: No UST Equipment Repair: UST Equipment Repair: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems:	Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No System Repairs: No UST Equipment Installation - Other: No	9016 Hazel Forest Drive Fuquay Varina, NC 27526 Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	Com				LIST Equipment Service Contractors	
Compliance Testing and Monitoring Atic Line Leak Detector Testing: Ano Overfill Prevention Equipment Operability Check: Ano Dispenser Meter Repair/Calibration: Ano D	Compliance Testing and Monitoring Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No System Repairs: No UST Equipment Service Contractors No Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No	204011 15 (D)	Fuquay Varina, NC 27526	10				
Website www.regionalenv.com Compliance Testing and Monitoring UST Equipmment Service Contractors atic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: On Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: On Protection System Repairs: No UST Equipment Installation - Other: On Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST System Installation - Complete Systems:	Website www.regionalenv.com Compliance Testing and Monitoring Detector Testing: No Overfill Prevention Equipment Operability Check: No Sesting: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No System Repairs: No UST Equipment Service Contractors No Dispenser Meter Repair/Calibration: No Spill Bucket Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No	Regional Environmental PLLC Phone (704) 694-8359 Coastal (East of I-95): Yes	•		,			
Fax Website www.regionalenv.com Compliance Testing and Monitoring UST Equipmment Service Contractors Atic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST System Installation - Complete Systems:	Prive 27526 Website www.regionalenv.com Compliance Testing and Monitoring Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other: No		Regional Environmental PLLC		Phone (704) 694-8359		Coastal (East of I-95): Yes	
Fax Website www.regionalenv.com Compliance Testing and Monitoring UST Equipmment Service Contractors Atic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST System Installation - Complete Systems:	Prive 27526 Website www.regionalenv.com Compliance Testing and Monitoring Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other: No	Company Listing Submitted 4/4/2023 Area of state conducts work	Company		Listing Submitte	ed 4/4/2023	Area of state conducts work	

		UST Service Provider List (Co	pastal)		
Company		Listing Submitted		Area of state conducts work	
Terracon		Phone (336) 854-8135		Coastal (East of I-95): Yes	
7327- G West Friendly Avenue		Fax		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27410		Websites I am III		Mountains (West of I-77): Yes	
		Website https://www.terracon.com/			
Com	pliance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company			- /- /	Area of state conducts work	
		Listing Submitted	3/6/2024	Area of State Conducts work	
			3/6/2024		
Titan Environmental Group 2005 Citation Drive		Phone (984) 200-6825	3/6/2024	Coastal (East of I-95): Yes	
Titan Environmental Group			3/6/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Titan Environmental Group 2005 Citation Drive		Phone (984) 200-6825	3/6/2024	Coastal (East of I-95): Yes	
Titan Environmental Group 2005 Citation Drive Garner, NC 27529		Phone (984) 200-6825 Fax	3/6/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Titan Environmental Group 2005 Citation Drive Garner, NC 27529		Phone (984) 200-6825 Fax Website www.titanenvirogroup.com	3/6/2024 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529 Com	pliance Te	Phone (984) 200-6825 Fax Website www.titanenvirogroup.com sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529 Com Automatic Line Leak Detector Testing:	pliance Te	Phone (984) 200-6825 Fax Website www.titanenvirogroup.com sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Titan Environmental Group 2005 Citation Drive Garner, NC 27529 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Te No No	Phone (984) 200-6825 Fax Website www.titanenvirogroup.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529 Comparison Comparison Comparison Comparison Comparison Protection Design Experts:	No No No No	Phone (984) 200-6825 Fax Website www.titanenvirogroup.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Phone (984) 200-6825 Fax Website www.titanenvirogroup.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone (984) 200-6825 Fax Website www.titanenvirogroup.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (984) 200-6825 Fax Website www.titanenvirogroup.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (984) 200-6825 Fax Website www.titanenvirogroup.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (984) 200-6825 Fax Website www.titanenvirogroup.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529 Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (984) 200-6825 Fax Website www.titanenvirogroup.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	No N	Phone (984) 200-6825 Fax Website www.titanenvirogroup.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: ottal Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Titan Environmental Group 2005 Citation Drive Garner, NC 27529 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (984) 200-6825 Fax Website www.titanenvirogroup.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: utal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Co	pastal)		
Company		Listing Submitted	8/27/2024	Area of state conducts work	
UES Professional Solutions 29, Inc.		Phone (704) 504-1717		Coastal (East of I-95): Yes	
10121 Pineville Distribution Street		Fax (704) 504-1125		Central (West of I-95 and East of I-77): Yes	
Pineville, NC 28134	1	Website www.teamues.com		Mountains (West of I-77): Yes	
Comr	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Containment Sump Testing: Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:		Spill Bucket Installation Repair:	No
Corrosion Protection Design Experts. Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No No	UST Equipment Installation - Other:	
Corrosion Protection System Repairs. Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Equipment Operability Check. Leak Detection Monitoring Services:	No	Other:	INO	UST Piping/Sump Installation:	No
Line Tightness Testing:	No	Outer.		UST System Removal:	No
		tal Service Firms		Other:	140
			NI-		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company					
Company		Listing Submitted	7/14/2022	Area of state conducts work	
VALLEY TANK TESTING		Phone (813) 671-9065	7/14/2022	Coastal (East of I-95): Yes	
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD			7/14/2022		
VALLEY TANK TESTING		Phone (813) 671-9065 Fax (866) 328-9796	7/14/2022	Coastal (East of I-95): Yes	
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572		Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM	7/14/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comp	pliance Tes	Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparing Compa	oliance Tes Yes	Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM Sting and Monitoring Overfill Prevention Equipment Operability Check:	Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Compa Automatic Line Leak Detector Testing: Containment Sump Testing:	oliance Tes Yes Yes	Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	<u>Yes</u> No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Yes Yes No	Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Yes No Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparison of the comparison of	yes Yes No	Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparing Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Yes No No Yes	Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No No Yes Yes Yes	Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	Yes Yes No No Yes Yes Yes Yes Yes Yes	Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No Yes Yes Yes Yes Yes Yes	Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No Yes	Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	Yes Yes No No Yes Yes Yes Yes Yes Yes Yes Yes You	Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants:	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes No No Yes Yes Yes Yes Yes Yos Yos No No No No No	Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes No Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	Yes Yes No No Yes Yes Yes Yes Yes You	Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	Yes No Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes No No Yes Yes Yes Yes Yes Yos Yos No No No No No	Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes No Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

	UST Service Provider List (Co	astal)		
	Listing Submitted	1/31/2023	Area of state conducts work	
	Phone (205) 577-1035		Coastal (East of I-95): Yes	
	Fax		Central (West of I-95 and East of I-77): Yes	
			Mountains (West of I-77): Yes	
V	/ebsite		,	
oliance Test	ing and Monitoring		UST Equipmment Service Contractors	
No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
No			UST System Removal:	<u>Yes</u>
nvironment	al Service Firms		Other:	
No	UST Compliance Consultants:	No		
No		No		
No		No		
No	Other:			
No				
	Listing Submitted	11/1/2022	Area of state conducts work	
	Listing Submitted	11/1/2023	Alou of state contacts work	
		11/1/2023		
	Phone (919) 469-3340	11/1/2023	Coastal (East of I-95): Yes	
		11/1/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
V	Phone (919) 469-3340	11/1/2023	Coastal (East of I-95): Yes	
	Phone (919) 469-3340 Fax	11/1/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
	Phone (919) 469-3340 Fax Vebsite www.withersravenel.com	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
oliance Test	Phone (919) 469-3340 Fax Vebsite www.withersravenel.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
No	Phone (919) 469-3340 Fax Vebsite www.withersravenel.com ting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
No No	Phone (919) 469-3340 Fax Vebsite www.withersravenel.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
No No No No	Phone (919) 469-3340 Fax Vebsite www.withersravenel.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
No No No No No	Phone (919) 469-3340 Fax Vebsite www.withersravenel.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
No No No No No No No	Phone (919) 469-3340 Fax Vebsite www.withersravenel.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
No No No No No No No No	Phone (919) 469-3340 Fax Vebsite www.withersravenel.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
No No No No No No No No No No	Phone (919) 469-3340 Fax Vebsite www.withersravenel.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
No N	Phone (919) 469-3340 Fax Vebsite www.withersravenel.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
No No No No No No No No No No	Phone (919) 469-3340 Fax Vebsite www.withersravenel.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
No N	Phone (919) 469-3340 Fax Vebsite www.withersravenel.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
No Vo Tvironment:	Phone (919) 469-3340 Fax Vebsite www.withersravenel.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
	No N	Phone (205) 577-1035 Fax Website Diance Testing and Monitoring No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: No Invironmental Service Firms No UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:	Phone (205) 577-1035 Fax Website Diance Testing and Monitoring No Overfill Prevention Equipment Operability Check: No No Statistical Iventory Reconciliation Services: No No Spill Prevention Equipment Testing: No No Tank Tightness Testing: No No UST Internal Inspections (Integrity Assessments): No No UST Internal Lining Inspections: No No Other: No Divironmental Service Firms No UST Compliance Consultants: No No UST Equipment Verification: No No Waste Disposal and Treatment: No No Other:	Listing Submitted 1/31/2023 Area of state conducts work Phone (205) 577-1035 Fax Website West of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes Westiel Westiel