

UST Service Provider List (Mountains)

Company	Listing Submitted 10/13/2025			Area of state conducts work
A&D Environmental Services, Inc. 2718 Uwharrie Road Archdale, NC 27263	Phone (800) 434-7750 Fax (336) 434-7752 Website www.adenviro.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:
Line Tightness Testing:	No			UST System Removal:
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No	
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>	
Oil and Solvent Recycling:	<u>Yes</u>	Other:		
Soil and Water Testing Lab:	No			
Company	Listing Submitted 1/18/2024			Area of state conducts work
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438	Phone (336) 282-3586 Fax (336) 282-3587 Website AdavancedEnvironmental.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:
Line Tightness Testing:	No			UST System Removal:
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No	
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>	
Oil and Solvent Recycling:	<u>Yes</u>	Other:		
Soil and Water Testing Lab:	No			

UST Service Provider List (Mountains)

Company	Listing Submitted	Area of state conducts work			
American Environmental Engineering of Florida, Inc. 3122 Mahan Drive Suite 801-313 Tallahassee, FL 32308	Phone (850) 832-5361 Fax Website www.aeeus.com	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring					
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted	Area of state conducts work			
BUCKEYE ELM CONTRACTING, LLC PO Box 1026 MOCKSVILLE, NC 27028	Phone (336) 337-6001 Fax Website www.buckeye-elm.com	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring					
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company	Listing Submitted 10/16/2025			Area of state conducts work
Bunnell-Lammons Engineering (BLE) 6004 Ponders Court Greenville, SC 29615	Phone (864) 288-1265 Fax Website https://www.blecorp.com/			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:
Line Tightness Testing:	<u>Yes</u>			UST System Removal:
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>	
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>	
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	<u>Yes</u>			
Company	Listing Submitted 10/13/2025			Area of state conducts work
Bunnell-Lammons Engineering (BLE) 6004 Ponders Court Greenville, SC 29615	Phone (864) 288-1265 Fax Website https://www.blecorp.com/			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:
Line Tightness Testing:	<u>Yes</u>			UST System Removal:
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>	
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>	
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	<u>Yes</u>			

UST Service Provider List (Mountains)

Company	Listing Submitted	11/1/2023	Area of state conducts work	
Cathodic Protection Services, Inc. 916 Egypt Rd. Bluff City, NC 37618	Phone (423) 895-1500 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No
Line Tightness Testing:	No			UST System Removal: No
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No	
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	No			
Company	Listing Submitted	4/5/2023	Area of state conducts work	
CDG, Inc. 4301 Taggart Creek Road Charlotte, NC 28208	Phone (704) 394-6913 Fax Website www.cdge.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No
Line Tightness Testing:	No			UST System Removal: No
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>	
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>	
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>	
Oil and Solvent Recycling:	<u>Yes</u>	Other:		
Soil and Water Testing Lab:	<u>Yes</u>			

UST Service Provider List (Mountains)

Company	Listing Submitted	6/27/2024	Area of state conducts work
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802	Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenv.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	11/21/2023	Area of state conducts work
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678	Phone (704) 560-9154 Fax Website benconklincc@gmail.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Service Provider List (Mountains)

Company	Listing Submitted 10/13/2025			Area of state conducts work
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407	Phone (336) 214-9012 Fax Website www.dhgriffin.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:
Line Tightness Testing:	No			UST System Removal:
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No	
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes	
Oil and Solvent Recycling:	Yes	Other:		
Soil and Water Testing Lab:	No			
Company	Listing Submitted 1/6/2025			Area of state conducts work
ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616	Phone (919) 861-9910 Fax Website ecslimited.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:
Line Tightness Testing:	No			UST System Removal:
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes	
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	No			

UST Service Provider List (Mountains)

Company	Listing Submitted	6/30/2025	Area of state conducts work
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616	Phone (984) 284-5571 Fax Website www.eisholdings.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:	
Line Tightness Testing:	<u>Yes</u>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>
Oil and Solvent Recycling:	<u>Yes</u>	Other:	
Soil and Water Testing Lab:	<u>Yes</u>		
Company	Listing Submitted	7/2/2024	Area of state conducts work
Environmental Hydrogeological Consultants, Inc. DB PO Box 902 Red Springs, NC 28377	Phone (910) 843-4456 Fax (910) 843-5376 Website www.environmentalinc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>
Oil and Solvent Recycling:	<u>Yes</u>	Other:	OSRO Certified US Coast Guard Contractor
Soil and Water Testing Lab:	<u>Yes</u>		

UST Service Provider List (Mountains)

Company	Listing Submitted 10/27/2025			Area of state conducts work
Environmental Laboratories, INC 15 Sulphur Springs Rd Greenville, SC 29617	Phone (864) 370-0637 Fax Website https://www.elabsinc.net/			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration: <u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing: <u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair: <u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair: <u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation: <u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal: <u>Yes</u>
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>	
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>	
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	<u>Yes</u>			
Company	Listing Submitted 5/14/2024			Area of state conducts work
Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901	Phone (877) 297-6763 Fax Website www.keeptmecompliant.net			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration: <u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: <u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair: <u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other: <u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: <u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: <u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: <u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal: <u>Yes</u>
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No	
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	No			

UST Service Provider List (Mountains)

Company	Listing Submitted 7/16/2024			Area of state conducts work	
EnviroSouth, Inc. 3440 Augusta Road Greenville, SC 29605	Phone (864) 236-9010 Fax Website www.envirosouth.com			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted 5/6/2025			Area of state conducts work	
ESNC Environmental Consulting, P.C. 1408 Christian Avenue Suite 11 Durham, NC 27705	Phone (919) 910-7767 Fax Website www.earthsyst.net			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company	Listing Submitted 10/13/2025			Area of state conducts work
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107	Phone (336) 725-5844 Fax Website www.evocorp.net			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No
Line Tightness Testing:	No			UST System Removal: Yes
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No	
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No	
Oil and Solvent Recycling:	Yes	Other:		
Soil and Water Testing Lab:	No			
Company	Listing Submitted 7/12/2023			Area of state conducts work
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054	Phone (704) 853-0800 Fax (704) 853-3949 Website www.excelengr.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No
Line Tightness Testing:	No			UST System Removal: No
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes	
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	No			

UST Service Provider List (Mountains)

Company	Listing Submitted	Area of state conducts work
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28110	Phone (704) 845-4010 Fax (704) 845-4012 Website www.grienv.com	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring		
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No		
Environmental Service Firms		
Emergency Cleanup - Spill/Release: <u>Yes</u> Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: <u>Yes</u>		
Company	Listing Submitted	Area of state conducts work
Groundwater Manage. Associates 4300 Sapphire Court Suite 100 Greenville, NC 27834	Phone (252) 758-3310 Fax Website www.gma-nc.com	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring		
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No		
Environmental Service Firms		
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No		

UST Service Provider List (Mountains)

Company	Listing Submitted 11/16/2023			Area of state conducts work	
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834	Phone (252) 758-3310 Fax Website www.gma-nc.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted 11/14/2025			Area of state conducts work	
HARCO Services LLC 2 Kelli Clark Ct SE Cartersville, GA 30121	Phone (770) 917-8846 Fax (770) 917-0921 Website harcoservices.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company	Listing Submitted	3/31/2025	Area of state conducts work
Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203	Phone (704) 586-0007 Fax Website https://harthickman.com/		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	4/11/2023	Area of state conducts work
INENCO, Inc. 132 W. Statesville Avenue Mooresville, NC 27115	Phone (704) 662-8192 Fax (704) 662-8194 Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Service Provider List (Mountains)

Company	Listing Submitted 12/12/2025			Area of state conducts work
JBL Solutions Inc. 806 Appii Rd Moncks Corner, SC 29461	Phone (603) 690-9071 Fax Website jblsolutionsinc.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:
Line Tightness Testing:	<u>Yes</u>			UST System Removal:
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>	
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>	
Oil and Solvent Recycling:	No	Other:	Filtration and Polishing	
Soil and Water Testing Lab:	No			
Company	Listing Submitted 5/15/2023			Area of state conducts work
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560	Phone (919) 744-4391 Fax Website jfpetrogroupp.com/services/environmentalcompliance			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:
Line Tightness Testing:	<u>Yes</u>			UST System Removal:
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>	
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>	
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	No			

UST Service Provider List (Mountains)

Company	Listing Submitted 10/16/2025			Area of state conducts work	
Lamar Contractors, LLC 481 Judge Edward Dufresne Pkwy. Luling , LA 70070	Phone (985) 785-7121 Fax (985) 785-7124 Website www.lamarcontractors.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	Yes
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	Yes
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	Yes
Line Tightness Testing:	No			UST System Removal:	
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted 5/30/2024			Area of state conducts work	
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205	Phone (336) 382-7132 Fax Website			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	Yes
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company	Listing Submitted 5/30/2024			Area of state conducts work
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897	Phone (228) 516-0498 Fax Website https://www.mcs-petroleum-div.com/			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: <u>Yes</u>
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: <u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: <u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: <u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: <u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: <u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: <u>Yes</u>
Line Tightness Testing:	No			UST System Removal: <u>No</u>
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No	
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	No			
Company	Listing Submitted 4/20/2023			Area of state conducts work
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732	Phone (904) 814-3680 Fax Website mgfenvironmental.com			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: <u>No</u>
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: <u>No</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: <u>No</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: <u>No</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: <u>No</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: <u>No</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: <u>No</u>
Line Tightness Testing:	No			UST System Removal: <u>Yes</u>
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No	
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	No			

UST Service Provider List (Mountains)

Company	Listing Submitted	10/14/2025	Area of state conducts work		
Mid-Atlantic Associates, Inc. 409 Rogers View Court Raleigh, NC 27610	Phone	(919) 250-9918	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes		
	Fax				
	Website	www.maaonline.com			
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No	
Line Tightness Testing:	No			UST System Removal: No	
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted	10/14/2025	Area of state conducts work		
NCPCM 7300 Glenwood Avenue Raleigh, NC 27612	Phone	(919) 782-4411	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes		
	Fax				
	Website	www.ncpcm.org			
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No	
Line Tightness Testing:	No			UST System Removal: No	
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company	Listing Submitted		1/27/2026	Area of state conducts work	
NV5 Engineers and Consultants, Inc. 3300 Regency Parkway, Suite 100 Cary, NC 27518	Phone (919) 618-7792 Fax Website https://www.nv5.com/			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted		10/14/2025	Area of state conducts work	
OWL Services USA 1815 Gallagher Road Plymouth Meeting, PA 19462	Phone (610) 633-9732 Fax (610) 278-7621 Website www.owlservices.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company	Listing Submitted	Area of state conducts work			
Parliament Petroleum Services LLC 3277 Neely Ferry Road Laurens, SC 29360	Phone (864) 871-8058 Fax Website parliamentpetroleumservices.com	Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes			
Compliance Testing and Monitoring					
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted	Area of state conducts work			
Peak Hydrogeologic, PLLC 470 Hogback Mtn Rd Tryon, NC 28782	Phone (828) 817-5209 Fax Website https://peakhydrogeologic.com	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring					
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				

UST Service Provider List (Mountains)

Company	Listing Submitted 10/13/2025			Area of state conducts work
Petroleum Equipment and Service, Inc PO Box 1949 Denver, NC 28037	Phone (704) 335-8801 Fax Website www.petroleumequipment.net			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: Yes
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: Yes
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: Yes
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: Yes
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No
Line Tightness Testing:	No			UST System Removal: Yes
Environmental Service Firms				
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No	
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	No			
Company	Listing Submitted 8/19/2024			Area of state conducts work
Piedmont Geologic, P.C. 6003-145 Chapel Hill Road Raleigh, NC 27607	Phone (919) 954-9700 Fax Website www.piedmontgeologic.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No
Line Tightness Testing:	No			UST System Removal: Yes
Environmental Service Firms				
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes	
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	No			

UST Service Provider List (Mountains)

Company	Listing Submitted 11/1/2023			Area of state conducts work	
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285	Phone (336) 870-3095 Fax (336) 310-4527 Website www.pilotenviro.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted 10/14/2025			Area of state conducts work	
Pyramid Environmental & Engineering, PC 503 Industrial Avenue P.O. Box 16265 Greensboro, NC 27406	Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company	Listing Submitted 10/14/2025			Area of state conducts work
Rick Rogers Consulting, LLC. 2764 Pleasant Road #405 Fort Mill, SC 29708	Phone (803) 280-0741 Fax Website			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No
Line Tightness Testing:	No			UST System Removal: No
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No	
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	No			
Company	Listing Submitted 10/14/2025			Area of state conducts work
Singleton Environmental, Inc. PO Box 604 Fletcher, NC 28732	Phone (828) 508-4510 Fax Website www.singletonenvironmental.com			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No
Line Tightness Testing:	No			UST System Removal: No
Environmental Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No	
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No	
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No	
Oil and Solvent Recycling:	No	Other:		
Soil and Water Testing Lab:	No			

UST Service Provider List (Mountains)

Company	Listing Submitted 10/14/2025			Area of state conducts work	
Singleton Environmental, Inc. PO Box 604 Fletcher, NC 28732	Phone (828) 508-4510 Fax Website www.singletonenvironmental.com			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No	Other:	
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted 12/12/2025			Area of state conducts work	
SPATCO Energy Solutions 301 McCullough Dr Suite 500 Charlotte, NC 28262	Phone (800) 477-8286 Fax Website spatco.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes	Leak Detection Equipment Installation Servicing:	Yes
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	Yes
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	Yes
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	Yes	UST Equipment Repair:	Yes
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	Yes	UST System Installation - Complete Systems:	Yes
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:	Yes
Line Tightness Testing:	Yes			UST System Removal:	Yes
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes	Other:	
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	Yes	Other:			
Soil and Water Testing Lab:	Yes				

UST Service Provider List (Mountains)

Company	Listing Submitted 7/30/2024			Area of state conducts work	
SR&R Environmental, Inc. 4920 Highway 421 N. Wilmington, NC 28401	Phone (910) 763-6274 Fax (910) 763-6132 Website www.srenviro.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:	Fuel Polishing		
Soil and Water Testing Lab:	No				
Company	Listing Submitted 8/15/2024			Area of state conducts work	
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410	Phone (336) 854-8135 Fax Website https://www.terracon.com/			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company	Listing Submitted	Area of state conducts work			
Terraquest Environmental Consultants, P.C. 100 E. Ruffin St. Mebane, NC 27302	Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring					
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted	Area of state conducts work			
Titan Environmental Group 2005 Citation Drive Garner, NC 27529	Phone (984) 200-6825 Fax Website www.titanenvirogroup.com	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company	Listing Submitted 8/27/2024			Area of state conducts work	
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134	Phone (704) 504-1717 Fax (704) 504-1125 Website www.teamues.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted 1/31/2023			Area of state conducts work	
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968	Phone (205) 577-1035 Fax Website			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	Yes
Line Tightness Testing:	No			UST System Removal:	Yes
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company	Listing Submitted	11/1/2023	Area of state conducts work
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591	Phone (919) 469-3340 Fax Website www.withersravenel.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overflow Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		