UST Service Provider List (Mountains)

Company	Listing Submitted	1/18/2024	Area of state conducts work	
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438	Phone Fax Website	(336) 282-3586 (336) 282-3587 AdvancedEnvironmental.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	**Yes**	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

Company	Listing Submitted	6/26/2024	Area of state conducts work	
BUCKEYE ELM CONTRACTING, LLC PO Box 1026 MOCKSVILLE, NC 27028	Phone Fax Website	(336) 337-6001 www.buckeye-elm.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	**Yes**
UST Piping/Sump Installation:	**Yes**
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	10/27/2026	Area of state conducts work	
Bunnell Lammons Engineering, Inc. 30 Park Ridge Drive Fletcher, NC 28732-	Phone Fax Website	(828) 277-0100 www.blecorp.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	No Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	**Yes**	Overfill Prevention Equipment Operability Check:	**Yes**
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	**Yes**
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	**Yes**
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	**Yes**
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	**Yes**
Leak Detection Equipment Operability Check:	**Yes**	UST Internal Lining Inspections:	**Yes**
Leak Detection Monitoring Services:	**Yes**	Other:	
Line Tightness Testing:	**Yes**		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	**Yes**
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	**Yes**
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	**Yes**	Other:	
Soil and Water Testing Lab:	**Yes**		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

Company	Listing Submitted	11/1/2023	Area of state conducts work	
Cathodic Protection Services, Inc. 916 Egypt Rd. Bluff City, NC 37618	Phone Fax Website	(423) 895-1500	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	**Yes**	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	**Yes**	Tank Tightness Testing:	No
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	6/27/2024	Area of state conducts work	
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802	Phone Fax Website	(662) 841-0995 (662) 841-0810 cobbenv.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	**Yes**	Overfill Prevention Equipment Operability Check:	**Yes**	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	**Yes**
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	**Yes**	Spill Bucket Installation Repair:	**Yes**
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	**Yes**
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	**Yes**	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	**Yes**
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	**Yes**
Line Tightness Testing:	No			UST System Removal:	**Yes**
				Other:	

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

Company	Listing Submitted	11/21/2023	Area of state conducts work	
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678	Phone Fax Website	(704) 560-9154 benconklincc@gmail.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	**Yes**	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	**Yes**	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	10/26/2026	Area of state conducts work	
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407-	Phone Fax Website	(336) 214-9012 www.dhgriffin.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

Company	Listing Submitted	1/6/2025	Area of state conducts work	
ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616	Phone Fax Website	(919) 861-9910 ecslimited.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	**Yes**
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	7/2/2024	Area of state conducts work	
Environmental Hydrogeological Consultants, Inc. DB PO Box 902 Red Springs, NC 28377	Phone Fax Website	(910) 843-4456 (910) 843-5376 www.environmentalnc.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	**Yes**	Other:	OSRO Certified US Coast Guard Contractor
Soil and Water Testing Lab:	**Yes**		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	Liquid/Hydro Excavate Vac Truck Services

Company	Listing Submitted	5/14/2024	Area of state conducts work	
Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901	Phone Fax Website	(877) 297-6763 www.keepmecompliant.net	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	No Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	**Yes**	Overfill Prevention Equipment Operability Check:	**Yes**
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	**Yes**	Spill Prevention Equipment Testing:	**Yes**
Corrosion Protection System Repairs:	**Yes**	Tank Tightness Testing:	**Yes**
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	**Yes**	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	**Yes**		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	**Yes**
Leak Detection Equipment Installation Servicing:	**Yes**
Spill Bucket Installation Repair:	**Yes**
UST Equipment Installation - Other:	**Yes**
UST Equipment Repair:	**Yes**
UST System Installation - Complete Systems:	**Yes**
UST Piping/Sump Installation:	**Yes**
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	7/16/2024	Area of state conducts work	
EnviroSouth, Inc. 3440 Augusta Road Greenville, SC 29605	Phone Fax Website	(864) 236-9010 www.envirosouth.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	No Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

Company	Listing Submitted	8/10/2026	Area of state conducts work	
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054	Phone Fax Website	(704) 853-0800 (704) 853-3949 www.excelengr.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	**Yes**
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	10/26/2026	Area of state conducts work	
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28110-	Phone Fax Website	(704) 845-4010 (704) 845-4012 www.grienv.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	**Yes**		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

Company	Listing Submitted	7/3/2024	Area of state conducts work	
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834	Phone Fax Website	(252) 758-3310 www.gma-nc.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	10/23/2026	Area of state conducts work	
Harco Services LLC 2 Kelli Clark Ct. SE Cartersville, GA 30121-	Phone Fax Website	(770) 917-8846 harcoservices.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	**Yes**
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	**Yes**
				Other:	

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

Company	Listing Submitted	10/26/2026	Area of state conducts work	
INENCO Inc. 132 W. Statesville Ave. Mooresville, NC 28115-	Phone Fax Website	(704) 662-8192 (704) 662-8194	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	No Yes Yes

Compliance Testing and Monitoring				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	**Yes**
				Other:	

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	**Yes**
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	10/20/2026	Area of state conducts work	
JBL Solutions Inc. 418 W. State St. Black Mountain, North Carolina 28711-	Phone Fax Website	(603) 690-9071 JBLsolutionsinc.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	**Yes**	Overfill Prevention Equipment Operability Check:	**Yes**
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	**Yes**
Corrosion Protection Design Experts:	**Yes**	Spill Prevention Equipment Testing:	**Yes**
Corrosion Protection System Repairs:	**Yes**	Tank Tightness Testing:	**Yes**
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	**Yes**	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	**Yes**		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	**Yes**
Leak Detection Equipment Installation Servicing:	**Yes**
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

Company	Listing Submitted	5/30/2024	Area of state conducts work	
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205	Phone Fax Website	(336) 382-7132	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	5/30/2024	Area of state conducts work	
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897	Phone Fax Website	(228) 516-0498 https://www.mcs-petroleum-div.com/	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	**Yes**
Leak Detection Equipment Installation Servicing:	**Yes**
Spill Bucket Installation Repair:	**Yes**
UST Equipment Installation - Other:	**Yes**
UST Equipment Repair:	**Yes**
UST System Installation - Complete Systems:	**Yes**
UST Piping/Sump Installation:	**Yes**
UST System Removal:	No
Other:	

Company	Listing Submitted	10/23/2026	Area of state conducts work	
OWL Services USA 1815 Gallagher Road Plymouth Meeting, PA 19462-	Phone Fax Website	(800) 646-3161 (610) 278-7621 www.owlservices.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	**Yes**	Overfill Prevention Equipment Operability Check:	**Yes**
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	**Yes**
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	**Yes**
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	**Yes**
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	**Yes**	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	**Yes**	Other:	
Line Tightness Testing:	**Yes**		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	**Yes**
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	**Yes**
Leak Detection Equipment Installation Servicing:	**Yes**
Spill Bucket Installation Repair:	**Yes**
UST Equipment Installation - Other:	**Yes**
UST Equipment Repair:	**Yes**
UST System Installation - Complete Systems:	**Yes**
UST Piping/Sump Installation:	**Yes**
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	10/26/2026	Area of state conducts work	
Peak Hydrogeologic PLLC 470 Hogback Mountain Road Tryon, NC 28782-	Phone Fax Website	(828) 817-5209 www.peakhydrogeologic.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring

Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms

Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors

Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

Company	Listing Submitted	10/26/2026	Area of state conducts work	
PetroTest, Inc 7 Dawn Road Benson, NC 27504-	Phone Fax Website	(919) 874-5843 https://petrotest.net/	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring

Automatic Line Leak Detector Testing:	**Yes**	Overfill Prevention Equipment Operability Check:	**Yes**
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	**Yes**
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	**Yes**
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	**Yes**
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	**Yes**	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	**Yes**	Other:	Secondary Line and Tank Testing.
Line Tightness Testing:	**Yes**		

Environmental Service Firms

Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	No	Other:	Water removal from UST Sumps and UDCs.
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors

Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	**Yes**
Spill Bucket Installation Repair:	**Yes**
UST Equipment Installation - Other:	**Yes**
UST Equipment Repair:	**Yes**
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	ATG/ Fill Riser replacements.

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	8/19/2024	Area of state conducts work	
Piedmont Geologic, P.C. 6003-145 Chapel Hill Road Raleigh, NC 27607	Phone Fax Website	(919) 954-9700 www.piedmontgeologic.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	**Yes**
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

Company	Listing Submitted	10/23/2026	Area of state conducts work	
Pilot Geological, PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285-	Phone Fax Website	(336) 870-3095 www.pilotenviro.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	**Yes**
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	10/26/2026	Area of state conducts work	
Pyramid Environmental & Engineering PC 503 Industrial Ave. Greensboro, NC 27406-	Phone Fax Website	(336) 335-3174 www.pyramidenvironmental.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	**Yes**	Other:	
Soil and Water Testing Lab:	**Yes**		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

Company	Listing Submitted	10/23/2026	Area of state conducts work	
Rick Rogers Consulting LLC 2764 Pleasant Rd. #405 Fort Mill, SC 29708-	Phone Fax Website	(803) 280-0741	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	**Yes**	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	**Yes**	Tank Tightness Testing:	No
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	7/30/2024	Area of state conducts work	
SR&R Environmental, Inc. 4920 Highway 421 N. Wilmington, NC 28401	**Phone** **Fax** **Website**	(910) 763-6274 (910) 763-6132 www.srrenviro.com	**Coastal (East of I-95):** **Central (West of I-95 and East of I-77):** **Mountains (West of I-77):**	Yes Yes Yes

Compliance Testing and Monitoring

Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms

Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	**Yes**	Other:	Fuel Polishing
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors

Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

Company	Listing Submitted	8/15/2024	Area of state conducts work	
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410	**Phone** **Fax** **Website**	(336) 854-8135 https://www.terracon.com/	**Coastal (East of I-95):** **Central (West of I-95 and East of I-77):** **Mountains (West of I-77):**	Yes Yes Yes

Compliance Testing and Monitoring

Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms

Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors

Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	10/7/2026	Area of state conducts work	
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302	Phone Fax Website	(919) 563-9091 (919) 563-9095 www.terraquestpc.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	**Yes**		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

Company	Listing Submitted	3/6/2024	Area of state conducts work	
Titan Environmental Group 2005 Citation Drive Garner, NC 27529	Phone Fax Website	(984) 200-6825 www.titanenvirogroup.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	**Yes**	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	8/27/2024	Area of state conducts work	
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134	**Phone**	(704) 504-1717	**Coastal (East of I-95):**	Yes
	Fax	(704) 504-1125	**Central (West of I-95 and East of I-77):**	Yes
	Website	www.teamues.com	**Mountains (West of I-77):**	Yes

Compliance Testing and Monitoring				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

Company	Listing Submitted	10/27/2026	Area of state conducts work	
Valor Construction LLC 345 County Road 474 Fort Payne, AL 35967-	**Phone**	(205) 577-1035	**Coastal (East of I-95):**	Yes
	Fax		**Central (West of I-95 and East of I-77):**	Yes
	Website	www.valorconstructionllc.com	**Mountains (West of I-77):**	Yes

Compliance Testing and Monitoring				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	**Yes**
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	**Yes**
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	**Yes**
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	**Yes**
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	**Yes**
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	**Yes**
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	**Yes**
Line Tightness Testing:	No			UST System Removal:	**Yes**
				Other:	

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	11/1/2023	Area of state conducts work	
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591	**Phone** (919) 469-3340 **Fax** **Website** www.withersravenel.com		**Coastal (East of I-95):** **Central (West of I-95 and East of I-77):** **Mountains (West of I-77):**	Yes Yes Yes

Compliance Testing and Monitoring

Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms

Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	**Yes**
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors

Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.