UST Service Provider List (Mountains)

Company	Listing Submitted	1/18/2024	Area of state conducts work	
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438	Phone Fax Website	(336) 282-3586 (336) 282-3587 AdvancedEnvironmental.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	**Yes**	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

Company	Listing Submitted	6/26/2024	Area of state conducts work	
BUCKEYE ELM CONTRACTING, LLC PO Box 1026 MOCKSVILLE, NC 27028	Phone Fax Website	(336) 337-6001 www.buckeye-elm.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	**Yes**
UST Piping/Sump Installation:	**Yes**
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	11/1/2023	Area of state conducts work	
Cathodic Protection Services, Inc. 916 Egypt Rd. Bluff City, NC 37618	Phone Fax Website	(423) 895-1500	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	**Yes**	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	**Yes**	Tank Tightness Testing:	No
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

Company	Listing Submitted	6/27/2024	Area of state conducts work	
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802	Phone Fax Website	(662) 841-0995 (662) 841-0810 cobbenv.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	**Yes**	Overfill Prevention Equipment Operability Check:	**Yes**
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	**Yes**
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	**Yes**	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	**Yes**
Spill Bucket Installation Repair:	**Yes**
UST Equipment Installation - Other:	**Yes**
UST Equipment Repair:	No
UST System Installation - Complete Systems:	**Yes**
UST Piping/Sump Installation:	**Yes**
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	11/21/2023	Area of state conducts work	
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678	Phone Fax Website	(704) 560-9154 benconklincc@gmail.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	**Yes**	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	**Yes**	Tank Tightness Testing:	No
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

Company	Listing Submitted	1/6/2025	Area of state conducts work	
ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616	Phone Fax Website	(919) 861-9910 ecslimited.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	**Yes**
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company — **Listing Submitted** 7/2/2024

Environmental Hydrogeological Consultants, Inc. D
PO Box 902
Red Springs, NC 28377

Phone (910) 843-4456
Fax (910) 843-5376
Website www.environmentalnc.com

Area of state conducts work

Coastal (East of I-95): Yes
Central (West of I-95 and East of I-77): Yes
Mountains (West of I-77): Yes

Compliance Testing and Monitoring

Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms

Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	**Yes**	Other:	OSRO Certified US Coast Guard Contractor
Soil and Water Testing Lab:	**Yes**		

UST Equipmment Service Contractors

Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	Liquid/Hydro Excavate Vac Truck Services

Company — **Listing Submitted** 5/14/2024

Environmental Petroleum Services
1234 Gordon Park Rd
Augusta, GA 30901

Phone (877) 297-6763
Fax
Website www.keepmecompliant.net

Area of state conducts work

Coastal (East of I-95): No
Central (West of I-95 and East of I-77): Yes
Mountains (West of I-77): Yes

Compliance Testing and Monitoring

Automatic Line Leak Detector Testing:	**Yes**	Overfill Prevention Equipment Operability Check:	**Yes**
Containment Sump Testing:	**Yes**	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	**Yes**	Spill Prevention Equipment Testing:	**Yes**
Corrosion Protection System Repairs:	**Yes**	Tank Tightness Testing:	**Yes**
Corrosion Protection System Testing:	**Yes**	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	**Yes**	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	**Yes**		

Environmental Service Firms

Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors

Dispenser Meter Repair/Calibration:	**Yes**
Leak Detection Equipment Installation Servicing:	**Yes**
Spill Bucket Installation Repair:	**Yes**
UST Equipment Installation - Other:	**Yes**
UST Equipment Repair:	**Yes**
UST System Installation - Complete Systems:	**Yes**
UST Piping/Sump Installation:	**Yes**
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	7/16/2024	Area of state conducts work	
EnviroSouth, Inc. 3440 Augusta Road Greenville, SC 29605	Phone Fax Website	(864) 236-9010 www.envirosouth.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	No Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

Company	Listing Submitted	6/30/2026	Area of state conducts work	
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054	Phone Fax Website	(704) 853-0800 (704) 853-3949 www.excelengr.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	**Yes**
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	7/3/2024	Area of state conducts work	
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834	Phone Fax Website	(252) 758-3310 www.gma-nc.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

Company	Listing Submitted	5/30/2024	Area of state conducts work	
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205	Phone Fax Website	(336) 382-7132	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	5/30/2024	Area of state conducts work	
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897	Phone	(228) 516-0498	Coastal (East of I-95):	Yes
	Fax		Central (West of I-95 and East of I-77):	Yes
	Website	https://www.mcs-petroleum-div.com/	Mountains (West of I-77):	Yes

Compliance Testing and Monitoring				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	**Yes**
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	**Yes**
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	**Yes**
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	**Yes**
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	**Yes**
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	**Yes**
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	**Yes**
Line Tightness Testing:	No			UST System Removal:	No
				Other:	

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

Company	Listing Submitted	11/1/2023	Area of state conducts work	
Peak Hydrogeologic, PLLC 470 Hogback Mtn Rd Tryon, NC 28782	Phone	(828) 817-5209	Coastal (East of I-95):	No
	Fax		Central (West of I-95 and East of I-77):	Yes
	Website	https://peakhydrogeologic.com	Mountains (West of I-77):	Yes

Compliance Testing and Monitoring				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	**Yes**
				Other:	

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	**Yes**
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	**Yes**		

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	8/19/2024	Area of state conducts work	
Piedmont Geologic, P.C. 6003-145 Chapel Hill Road Raleigh, NC 27607	Phone Fax Website	(919) 954-9700 www.piedmontgeologic.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	**Yes**
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

Company	Listing Submitted	11/1/2023	Area of state conducts work	
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285	Phone Fax Website	(336) 870-3095 (336) 310-4527 www.pilotenviro.com	Coastal (East of I-95): Central (West of I-95 and East of I-77): Mountains (West of I-77):	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	**Yes**
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	7/30/2024	Area of state conducts work	
SR&R Environmental, Inc. 4920 Highway 421 N. Wilmington, NC 28401	**Phone** **Fax** **Website**	(910) 763-6274 (910) 763-6132 www.srrenviro.com	**Coastal (East of I-95):** **Central (West of I-95 and East of I-77):** **Mountains (West of I-77):**	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	**Yes**	Other:	Fuel Polishing
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

Company	Listing Submitted	8/15/2024	Area of state conducts work	
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410	**Phone** **Fax** **Website**	(336) 854-8135 https://www.terracon.com/	**Coastal (East of I-95):** **Central (West of I-95 and East of I-77):** **Mountains (West of I-77):**	Yes Yes Yes

Compliance Testing and Monitoring			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors	
Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	No
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	3/6/2024	Area of state conducts work
Titan Environmental Group 2005 Citation Drive Garner, NC 27529	**Phone** (984) 200-6825 **Fax** **Website** www.titanenvirogroup.com		**Coastal (East of I-95):** Yes **Central (West of I-95 and East of I-77):** Yes **Mountains (West of I-77):** Yes

Compliance Testing and Monitoring				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	**Yes**
				Other:	

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	**Yes**
Oil and Solvent Recycling:	**Yes**	Other:	
Soil and Water Testing Lab:	No		

Company	Listing Submitted	8/27/2024	Area of state conducts work
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134	**Phone** (704) 504-1717 **Fax** (704) 504-1125 **Website** www.teamues.com		**Coastal (East of I-95):** Yes **Central (West of I-95 and East of I-77):** Yes **Mountains (West of I-77):** Yes

Compliance Testing and Monitoring				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	

Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.

UST Service Provider List (Mountains)

Company	Listing Submitted	11/1/2023	Area of state conducts work	
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591	**Phone** (919) 469-3340 **Fax** **Website** www.withersravenel.com		**Coastal (East of I-95):** **Central (West of I-95 and East of I-77):** **Mountains (West of I-77):**	Yes Yes Yes

Compliance Testing and Monitoring

Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		

Environmental Service Firms

Emergency Cleanup - Spill/Release:	**Yes**	UST Compliance Consultants:	**Yes**
Environmental Engineer/Geologist - Site Checks:	**Yes**	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	**Yes**	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Equipmment Service Contractors

Dispenser Meter Repair/Calibration:	No
Leak Detection Equipment Installation Servicing:	No
Spill Bucket Installation Repair:	No
UST Equipment Installation - Other:	No
UST Equipment Repair:	No
UST System Installation - Complete Systems:	No
UST Piping/Sump Installation:	No
UST System Removal:	**Yes**
Other:	

The Division of Waste Managment (DWM) does not recommend or endorse the services or products of any particular company on this list.