

UST Service Provider List (Mountains)

Company	Listing Submitted	10/13/2025	Area of state conducts work
A&D Environmental Services, Inc. 2718 Uwharrie Road Archdale, NC 27263 Phone (800) 434-7750 Fax (336) 434-7752 Website www.adenviro.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: Yes Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:		
Company	Listing Submitted	1/18/2024	Area of state conducts work
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Phone (336) 282-3586 Fax (336) 282-3587 Website AdadvancedEnvironmental.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: Yes Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	12/12/2025		Area of state conducts work
American Environmental Engineering of Florida, Inc. 3122 Mahan Drive Suite 801-313 Tallahassee, FL 32308	Phone (850) 832-5361 Fax Website www.aeeus.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring				UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:			Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			
Company	Listing Submitted	6/26/2024		Area of state conducts work
BUCKEYE ELM CONTRACTING, LLC PO Box 1026 MOCKSVILLE, NC 27028	Phone (336) 337-6001 Fax Website www.buckeye-elm.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring				UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:			Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST System Removal: Yes Other:
Environmental Service Firms				
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:			

UST Service Provider List (Mountains)

Company	Listing Submitted	10/16/2025	Area of state conducts work
Bunnell-Lammons Engineering (BLE) 6004 Ponders Court Greenville, SC 29615	Phone (864) 288-1265 Fax Website https://www.blecorp.com/		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: Yes Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: Yes Line Tightness Testing: Yes	Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): Yes UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: Yes	UST Compliance Consultants: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: Yes Other:		
Company	Listing Submitted	10/13/2025	Area of state conducts work
Bunnell-Lammons Engineering (BLE) 6004 Ponders Court Greenville, SC 29615	Phone (864) 288-1265 Fax Website https://www.blecorp.com/		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: Yes Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: Yes Line Tightness Testing: Yes	Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): Yes UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: Yes	UST Compliance Consultants: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: Yes Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	11/1/2023	Area of state conducts work
Catholic Protection Services, Inc. 916 Egypt Rd. Bluff City, NC 37618	Phone (423) 895-1500 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: Yes Corrosion Protection System Repairs: Yes Corrosion Protection System Testing: Yes Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	4/5/2023	Area of state conducts work
CDG, Inc. 4301 Taggart Creek Road Charlotte, NC 28208	Phone (704) 394-6913 Fax Website www.cdge.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: Yes Soil and Water Testing Lab: Yes	UST Compliance Consultants: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: Yes Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	6/27/2024	Area of state conducts work
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802 Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenv.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: Yes UST Equipment Installation - Other: Yes UST Equipment Repair: No UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	11/21/2023	Area of state conducts work
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678 Phone (704) 560-9154 Fax Website benconklincc@gmail.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: Yes Corrosion Protection System Repairs: Yes Corrosion Protection System Testing: Yes Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	10/13/2025	Area of state conducts work
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407	Phone (336) 214-9012 Fax Website www.dhgriffin.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: Yes Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:		
Company	Listing Submitted	1/6/2025	Area of state conducts work
ECS Southeast, LLC 5260 Greens Dairy Road Raleigh, NC 27616	Phone (919) 861-9910 Fax Website ecslimited.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted		Area of state conducts work
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616	Phone (984) 284-5571		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
	Fax		
	Website www.eisholdings.com		
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	Yes
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	Yes
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	Yes
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	Yes
Leak Detection Monitoring Services:	Yes	Other:	
Line Tightness Testing:	Yes		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	Yes
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes
Oil and Solvent Recycling:	Yes	Other:	
Soil and Water Testing Lab:	Yes		
Company	Listing Submitted		Area of state conducts work
Environmental Hydrogeological Consultants, Inc. DB PO Box 902 Red Springs, NC 28377	Phone (910) 843-4456		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
	Fax (910) 843-5376		
	Website www.environmentalinc.com		
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes
Oil and Solvent Recycling:	Yes	Other: OSRO Certified US Coast Guard Contractor	
Soil and Water Testing Lab:	Yes		
			Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other: Liquid/Hydro Excavate Vac Truck Services

UST Service Provider List (Mountains)

Company	Listing Submitted		Area of state conducts work
Environmental Laboratories, INC 15 Sulphur Springs Rd Greenville, SC 29617 Phone (864) 370-0637 Fax Website https://www.elabsinc.net/	10/27/2025		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: Yes Corrosion Protection System Repairs: Yes Corrosion Protection System Testing: Yes Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: Yes Line Tightness Testing: Yes	Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: Yes Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): Yes UST Internal Lining Inspections: Yes Other:		Dispenser Meter Repair/Calibration: Yes Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: Yes UST Equipment Installation - Other: No UST Equipment Repair: Yes UST System Installation - Complete Systems: No UST Piping/Sump Installation: Yes UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: Yes	UST Compliance Consultants: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: Yes Other:		
Company	Listing Submitted		Area of state conducts work
Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901 Phone (877) 297-6763 Fax Website www.keepmecompliant.net	5/14/2024		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: Yes Corrosion Protection System Repairs: Yes Corrosion Protection System Testing: Yes Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: No Line Tightness Testing: Yes	Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: Yes Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: Yes UST Equipment Installation - Other: Yes UST Equipment Repair: Yes UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	7/16/2024	Area of state conducts work
EnviroSouth, Inc. 3440 Augusta Road Greenville, SC 29605	Phone (864) 236-9010 Fax Website www.envirosouth.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	2/27/2026	Area of state conducts work
EnviroSouth, Inc. 3440 Augusta Rd Greenville, SC 29605	Phone (864) 236-9010 Fax Website www.envirosouth.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: Yes	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	5/6/2025	Area of state conducts work
ESNC Environmental Consulting, P.C. 1408 Christian Avenue Suite 11 Durham, NC 27705	Phone (919) 910-7767 Fax Website www.earthsys.net		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	10/13/2025	Area of state conducts work
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107	Phone (336) 725-5844 Fax Website www.evocorp.net		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: Yes Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	7/12/2023	Area of state conducts work
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054	Phone (704) 853-0800 Fax (704) 853-3949 Website www.excelengr.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	10/14/2025	Area of state conducts work
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28110	Phone (704) 845-4010 Fax (704) 845-4012 Website www.grienv.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: Yes	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	7/3/2024	Area of state conducts work
Groundwater Manage. Associates 4300 Sapphire Court Suite 100 Greenville, NC 27834	Phone (252) 758-3310 Fax Website www.gma-nc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	11/16/2023	Area of state conducts work
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834	Phone (252) 758-3310 Fax Website www.gma-nc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	11/14/2025	Area of state conducts work
HARCO Services LLC 2 Kelli Clark Ct SE Cartersville, GA 30121	Phone (770) 917-8846 Fax (770) 917-0921 Website harcoservices.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	3/31/2025	Area of state conducts work
Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203	Phone (704) 586-0007 Fax Website https://harthickman.com/		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	4/11/2023	Area of state conducts work
INENCO, Inc. 132 W. Statesville Avenue Mooresville, NC 27115 Phone (704) 662-8192 Fax (704) 662-8194 Website			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	12/12/2025	Area of state conducts work
JBL Solutions Inc. 806 Appii Rd Moncks Corner, SC 29461 Phone (603) 690-9071 Fax Website jblsolutionsinc.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: Yes Line Tightness Testing: Yes	Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: Yes Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:	Filtration and Polishing	

UST Service Provider List (Mountains)

Company	Listing Submitted		Area of state conducts work
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560	Phone	(919) 744-4391	Coastal (East of I-95): Yes
	Fax		Central (West of I-95 and East of I-77): Yes
	Website	jfpetrogroup.com/services/environmentalcompliance	Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	Yes	Other:	
Line Tightness Testing:	Yes		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Lamar Contractors, LLC 481 Judge Edward Dufresne Pkwy. Luling , LA 70070	Phone	(985) 785-7121	Coastal (East of I-95): Yes
	Fax	(985) 785-7124	Central (West of I-95 and East of I-77): Yes
	Website	www.lamarcontractors.com	Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Service Provider List (Mountains)

Company	Listing Submitted	5/30/2024	Area of state conducts work
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205	Phone (336) 382-7132 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	5/30/2024	Area of state conducts work
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897	Phone (228) 516-0498 Fax Website https://www.mcs-petroleum-div.com/		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: Yes Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: Yes UST Equipment Installation - Other: Yes UST Equipment Repair: Yes UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	4/20/2023	Area of state conducts work
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732	Phone (904) 814-3680 Fax Website mgfenvironmental.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:		
Company	Listing Submitted	10/14/2025	Area of state conducts work
Mid-Atlantic Associates, Inc. 409 Rogers View Court Raleigh, NC 27610	Phone (919) 250-9918 Fax Website www.maaonline.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	10/14/2025	Area of state conducts work
NCPCM 7300 Glenwood Avenue Raleigh, NC 27612	Phone (919) 782-4411 Fax Website www.ncpcm.org		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	1/27/2026	Area of state conducts work
NV5 Engineers and Consultants, Inc. 3300 Regency Parkway, Suite 100 Cary, NC 27518	Phone (919) 618-7792 Fax Website https://www.nv5.com/		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	10/14/2025	Area of state conducts work
OWL Services USA 1815 Gallagher Road Plymouth Meeting, PA 19462 Phone (610) 633-9732 Fax (610) 278-7621 Website www.owlservices.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: No Corrosion Protection System Repairs: Yes Corrosion Protection System Testing: Yes Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: Yes Line Tightness Testing: Yes	Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: Yes Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): Yes UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: Yes Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: Yes UST Equipment Installation - Other: Yes UST Equipment Repair: Yes UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST System Removal: Yes Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	10/21/2025	Area of state conducts work
Parliament Petroleum Services LLC 3277 Neely Ferry Road Laurens, SC 29360 Phone (864) 871-8058 Fax Website parliamentpetroleumservices.com			Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: Yes Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: Yes UST Equipment Installation - Other: Yes UST Equipment Repair: Yes UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST System Removal: Yes Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	11/1/2023	Area of state conducts work
Peak Hydrogeologic, PLLC 470 Hogback Mtn Rd Tryon, NC 28782	Phone (828) 817-5209 Fax Website https://peakhydrogeologic.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: Yes	UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:		
Company	Listing Submitted	10/13/2025	Area of state conducts work
Petroleum Equipment and Service, Inc PO Box 1949 Denver, NC 28037	Phone (704) 335-8801 Fax Website www.petroleumequipment.net		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: Yes Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: Yes UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	8/19/2024	Area of state conducts work
Piedmont Geologic, P.C. 6003-145 Chapel Hill Road Raleigh, NC 27607	Phone (919) 954-9700 Fax Website www.piedmontgeologic.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	11/1/2023	Area of state conducts work
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285	Phone (336) 870-3095 Fax (336) 310-4527 Website www.pilotenviro.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	10/14/2025	Area of state conducts work
Pyramid Environmental & Engineering, PC 503 Industrial Avenue P.O. Box 16265 Greensboro, NC 27406	Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:		
Company	Listing Submitted	10/14/2025	Area of state conducts work
Rick Rogers Consulting, LLC. 2764 Pleasent Road #405 Fort Mill, SC 29708	Phone (803) 280-0741 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: Yes Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	10/14/2025		Area of state conducts work	
Singleton Environmental, Inc. PO Box 604 Fletcher, NC 28732 Phone (828) 508-4510 Fax Website www.singletonenvironmental.com				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

Company	Listing Submitted	10/14/2025		Area of state conducts work	
Singleton Environmental, Inc. PO Box 604 Fletcher, NC 28732 Phone (828) 508-4510 Fax Website www.singletonenvironmental.com				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company	Listing Submitted		Area of state conducts work
SPATCO Energy Solutions 301 McCullough Dr Suite 500 Charlotte, NC 28262	Phone (800) 477-8286 Fax Website spatco.com	12/12/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	Yes
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	Yes
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	Yes
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	Yes
Leak Detection Monitoring Services:	Yes	Other:	
Line Tightness Testing:	Yes		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	Yes
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes
Oil and Solvent Recycling:	Yes	Other:	
Soil and Water Testing Lab:	Yes		
SR&R Environmental, Inc. 4920 Highway 421 N. Wilmington, NC 28401	Phone (910) 763-6274 Fax (910) 763-6132 Website www.srrenviro.com	7/30/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes
Oil and Solvent Recycling:	Yes	Other:	Fuel Polishing
Soil and Water Testing Lab:	No		

UST Service Provider List (Mountains)

Company	Listing Submitted	3/9/2026	Area of state conducts work
SynTerra Corporation 148 River Street Suite 220 Greenville, SC 29601	Phone (864) 421-9999 Fax Website www.synterracorp.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: Yes Soil and Water Testing Lab: Yes	UST Compliance Consultants: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: Yes Other:		
Company	Listing Submitted	8/15/2024	Area of state conducts work
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410	Phone (336) 854-8135 Fax Website https://www.terracon.com/		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted	10/14/2025	Area of state conducts work
Terraquest Environmental Consultants, P.C. 100 E. Ruffin St. Mebane, NC 27302	Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:		
Company	Listing Submitted	3/6/2024	Area of state conducts work
Titan Environmental Group 2005 Citation Drive Garner, NC 27529	Phone (984) 200-6825 Fax Website www.titanenvirogroup.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: Yes Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other:		

UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134	Phone (704) 504-1717 Fax (704) 504-1125 Website www.teamues.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			
Company	Listing Submitted			Area of state conducts work
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591	Phone (919) 469-3340 Fax Website www.withersravenel.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: No Other:			