		UST Service Provider List (Mo	untains)		
Company		Listing Submitted		Area of state conducts work	
Advanced Environmental Services, Inc.		Phone (336) 282-3586		Coastal (East of I-95): Yes	
PO Box 38218		Fax (336) 282-3587		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27438	V	Vebsite AdavancedEnvironmental.com		Mountains (West of I-77): Yes	
Comr	nliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	Yes
	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	Yes	Other:	<u></u>		
Soil and Water Testing Lab:	No				
-					
Company		Listing Submitted	7/19/2022	Area of state conducts work	
R & M WEST CONSTRUCTION CO OF TEXAS I	)BA D	Phone (863) 519-4441	7/19/2022	Area of state conducts work  Coastal (Fast of I-95): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS I	DBA D.	Phone (863) 519-4441	7/19/2022	Coastal (East of I-95): Yes	
	DBA D.		7/19/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD		Phone (863) 519-4441	7/19/2022	Coastal (East of I-95): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860	V	Phone (863) 519-4441  Fax (863) 519-4407	7/19/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860	V	Phone (863) 519-4441  Fax (863) 519-4407  Vebsite DWSHOUPPE.COM	7/19/2022 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860	V oliance Test	Phone (863) 519-4441 Fax (863) 519-4407  Vebsite DWSHOUPPE.COM  ting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860  Comp Automatic Line Leak Detector Testing:	V pliance Test	Phone (863) 519-4441 Fax (863) 519-4407  Vebsite DWSHOUPPE.COM  ting and Monitoring  Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860  Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	V Dliance Test No No	Phone (863) 519-4441 Fax (863) 519-4407  Vebsite DWSHOUPPE.COM  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	V Diance Test No No No	Phone (863) 519-4441  Fax (863) 519-4407  Vebsite DWSHOUPPE.COM  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No <u>Yes</u>
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Violiance Test No No No No No No	Phone (863) 519-4441  Fax (863) 519-4407  Vebsite DWSHOUPPE.COM  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No <u>Yes</u> No
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No No	Phone (863) 519-4441  Fax (863) 519-4407  Vebsite DWSHOUPPE.COM  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No <u>Yes</u> No No
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No No	Phone (863) 519-4441  Fax (863) 519-4407  Vebsite DWSHOUPPE.COM  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (863) 519-4441  Fax (863) 519-4407  Vebsite DWSHOUPPE.COM  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (863) 519-4441  Fax (863) 519-4407  Vebsite DWSHOUPPE.COM  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (863) 519-4441 Fax (863) 519-4407  Vebsite DWSHOUPPE.COM  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	No N	Phone (863) 519-4441 Fax (863) 519-4407  Vebsite DWSHOUPPE.COM  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  al Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (863) 519-4441  Fax (863) 519-4407  Vebsite DWSHOUPPE.COM  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  al Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes

		UST Service Provider List (Mou	ıntains)		
Company		Listing Submitted	6/26/2024	Area of state conducts work	
BUCKEYE ELM CONTRACTING, LLC		Phone (336) 337-6001		Coastal (East of I-95): Yes	
PO Box 1026		Fax		Central (West of I-95 and East of I-77): Yes	
MOCKSVILLE, NC 27028		Makaita www.huakaya.alm.aam		Mountains (West of I-77): Yes	
		Website www.buckeye-elm.com			
Comp	liance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	vironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/1/2023	Area of state conducts work	
Cathodic Protection Services, Inc.		DI (400) 005 4500		Coastal (East of I-95): Yes	
		Phone (423) 895-1500		Coastal (East of 1-33). 165	
916 Egypt Rd.		Fax			
The state of the s		Fax		Central (West of I-95 and East of I-77): Yes	
916 Egypt Rd.	V	,			
916 Egypt Rd. Bluff City, NC 37618		Fax		Central (West of I-95 and East of I-77): Yes	
916 Egypt Rd. Bluff City, NC 37618		Fax Website	No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	No
916 Egypt Rd. Bluff City, NC 37618	liance Tes	Fax  Website  ting and Monitoring	No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors	No No
916 Egypt Rd. Bluff City, NC 37618  Comp  Automatic Line Leak Detector Testing:	oliance Tes No	Fax  Website  Iting and Monitoring  Overfill Prevention Equipment Operability Check:		Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	
916 Egypt Rd. Bluff City, NC 37618  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Fax  Website  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	No
916 Egypt Rd. Bluff City, NC 37618  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No <u>Yes</u>	Fax  Nebsite  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
916 Egypt Rd. Bluff City, NC 37618  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No <u>Yes</u> <u>Yes</u>	Fax  Nebsite  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
916 Egypt Rd. Bluff City, NC 37618  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No Yes Yes Yes No	Fax  Nebsite  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
916 Egypt Rd. Bluff City, NC 37618  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No Yes Yes Yes No	Fax  Nebsite  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
916 Egypt Rd. Bluff City, NC 37618  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes Yes No No No No No No No No	Fax  Nebsite  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
916 Egypt Rd. Bluff City, NC 37618  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes Yes No No No No No No No No	Fax  Nebsite  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
916 Egypt Rd. Bluff City, NC 37618  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes Yes No	Fax  Website  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
916 Egypt Rd. Bluff City, NC 37618  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	No No Yes Yes Yes No	Fax  Website  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Ital Service Firms UST Compliance Consultants:	No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
916 Egypt Rd. Bluff City, NC 37618  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No Yes Yes Yes No	Fax  Website  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Ital Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
916 Egypt Rd. Bluff City, NC 37618  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No No Yes Yes Yes No	Fax  Website  Iting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Ital Service Firms  UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Mou	intains)		
Company		Listing Submitted	4/5/2023	Area of state conducts work	
CDG, Inc.		Phone (704) 394-6913		Coastal (East of I-95): Yes	
4301 Taggart Creek Road		Fax		Central (West of I-95 and East of I-77): Yes	
Charlotte, NC 28208		M. L. Mariana and an area		Mountains (West of I-77): Yes	
	V	Vebsite <u>www.cdge.com</u>		. ,	
Comp	liance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	6/27/2024	Area of state conducts work	
Cobb Environmental & Technical Services, Inc		Phone (662) 841-0995		Coastal (East of I-95): Yes	
P. O. Box 1602		Fax (662) 841-0810		Central (West of I-95 and East of I-77): Yes	
Tupelo, MS 38802		(662) 611 6616		Mountains (West of I-77): Yes	
	V	Vebsite cobbenv.com		Mountains (West of 1-77). Tes	
Comp	liance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
		UST Equipment Verification:	No		
Environmental Engineer/Geologist - Site Checks:	No	031 Equipment verification.	140		
		Waste Disposal and Treatment:	No		
Environmental Engineer/Geologist - Site Checks:					
Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:			

	l	JST Service Provider List (Mou	ıntains)		
Company		Listing Submitted		Area of state conducts work	
Conklin Corrosion Control LLC		Phone (704) 560-9154		Coastal (East of I-95): Yes	
118 Oak Point Lane		Fax		Central (West of I-95 and East of I-77): Yes	
Stony Point, NC 28678	14	Valorita hancanklinga@gmail.com		Mountains (West of I-77): Yes	
		Vebsite benconklincc@gmail.com			
Comp	liance Test	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	vironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	9/28/2022	Area of state conducts work	
D. H. Griffin Wrecking Company		Phone (336) 214-9012		Coastal (East of I-95): Yes	
4716 Hilltop Road		Fax		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27407				Mountains (West of I-77): Yes	
	V	Vebsite www.dhgriffin.com		modificants (west of 1-77). Tes	
Comp	liance Test	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	vironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
The state of the s					
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu Oil and Solvent Recycling:	No <u>Yes</u>	Waste Disposal and Treatment: Other:  Vacuum Truck S			

		UST Service Provider List (Mou	intains)		
Company		Listing Submitted	1/6/2025	Area of state conducts work	
ECS Southeast, LLC		Phone (919) 861-9910		Coastal (East of I-95): Yes	
5260 Greens Dairy Road		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27616	,	Website ecslimited.com		Mountains (West of I-77): Yes	
Comr		sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	6/30/2025	Area of state conducts work	
		Phone (984) 284-5571	6/30/2025	Area of state conducts work  Coastal (East of I-95): Yes	
Company EIS Holding, LLC. 5621 Departure Drive		Phone (984) 284-5571	6/30/2025	Coastal (East of I-95): Yes	
EIS Holding, LLC. 5621 Departure Drive Suite 101			6/30/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
EIS Holding, LLC. 5621 Departure Drive	,	Phone (984) 284-5571	6/30/2025	Coastal (East of I-95): Yes	
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616		Phone (984) 284-5571  Fax	6/30/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616		Phone (984) 284-5571  Fax  Website www.eisholdings.com	6/30/2025 Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	Yes
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616  Comp	oliance Tes	Phone (984) 284-5571 Fax  Website www.eisholdings.com  sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	Yes Yes
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	oliance Tes Yes	Phone (984) 284-5571  Fax  Website www.eisholdings.com  sting and Monitoring  Overfill Prevention Equipment Operability Check:	Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	oliance Tes Yes Yes	Phone (984) 284-5571  Fax  Website www.eisholdings.com  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u>
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Oliance Tes Yes Yes Yes	Phone (984) 284-5571  Fax  Website www.eisholdings.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	<u>Yes</u> <u>Yes</u>
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes Yes Yes Yes	Phone (984) 284-5571  Fax  Website www.eisholdings.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	Yes	Phone (984) 284-5571  Fax  Website www.eisholdings.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes Yes
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes	Phone (984) 284-5571  Fax  Website www.eisholdings.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes	Phone (984) 284-5571  Fax  Website www.eisholdings.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes Yes
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	Yes	Phone (984) 284-5571  Fax  Website www.eisholdings.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants:	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes	Phone (984) 284-5571  Fax  Website www.eisholdings.com  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants: UST Equipment Verification:	Yes Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Phone (984) 284-5571  Fax  Website www.eisholdings.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants:	Yes Yes Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes
EIS Holding, LLC. 5621 Departure Drive Suite 101 Raleigh, NC 27616  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes	Phone (984) 284-5571  Fax  Website www.eisholdings.com  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants: UST Equipment Verification:	Yes Yes Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes

UST Service Provider List (Mountains)	
Company Listing Submitted 7/2/2024 Area of state cond	ducts work
Environmental Hydrogeological Consultants, Inc. DB Phone (910) 843-4456 Coastal (E	ast of I-95): Yes
PO Box 902 Fax (910) 843-5376 Central (West of I-95 and E	ast of I-77): Yes
Red Springs, NC 28377  Website www.environmentalnc.com  Mountains (W	est of I-77): Yes
Compliance Testing and Monitoring UST Equipmment Serv	ice Contractors
Automatic Line Leak Detector Testing:  No Overfill Prevention Equipment Operability Check:  No Dispenser Meter Repair/Calibration	
Containment Sump Testing:  No Statistical Iventory Reconciliation Services:  No Leak Detection Equipment Installation	
Corrosion Protection Design Experts:  No Spill Prevention Equipment Testing:  No Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:  No Tank Tightness Testing:  No UST Equipment Installation - Other	
Corrosion Protection System Testing:  No UST Internal Inspections (Integrity Assessments):  No UST Equipment Repair:	No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complet	
Leak Detection Monitoring Services:  No Other:  UST Piping/Sump Installation:	No
Line Tightness Testing: No UST System Removal:	Yes
	xcavate Vac Truck Services
Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: No	
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No	
Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: Yes	
Oil and Solvent Recycling:  Yes  Other:  OSRO Certified US Coast Guard Contractor	
Soil and Water Testing Lab: Yes	
Company Listing Submitted 5/14/2024 Area of state cond	ducts work
Environmental Petroleum Services Phone (877) 297-6763 Coastal (E	
Environmental i eu dieum dei vides i mone (di i / 231-0100	ast of I-95): No
1001 O. I. D. I.D.I.	ast of I-95): No
1234 Gordon Park Rd Augusta. GA 30901  Central (West of I-95 and E	East of I-77): Yes
1234 Gordon Park Rd Augusta, GA 30901  Central (West of I-95 and E	•
1234 Gordon Park Rd Augusta, GA 30901  Fax  Mountains (West of I-95 and E	East of I-77): Yes lest of I-77): Yes
1234 Gordon Park Rd Augusta, GA 30901  Website www.keepmecompliant.net  Central (West of I-95 and E Mountains (W	East of I-77): Yes lest of I-77): Yes rice Contractors
1234 Gordon Park Rd Augusta, GA 30901  Website www.keepmecompliant.net  Compliance Testing and Monitoring  Central (West of I-95 and E Mountains (W	East of I-77): Yes  Vest of I-77): Yes  Vice Contractors  Yes
1234 Gordon Park Rd Augusta, GA 30901  Website www.keepmecompliant.net  Compliance Testing and Monitoring  Automatic Line Leak Detector Testing:  Yes Overfill Prevention Equipment Operability Check:  Yes Central (West of I-95 and E Mountains (W	East of I-77): Yes  Vest of I-77): Yes  Vice Contractors  Yes
1234 Gordon Park Rd Augusta, GA 30901  Website www.keepmecompliant.net  Compliance Testing and Monitoring  Automatic Line Leak Detector Testing:  Yes Overfill Prevention Equipment Operability Check:  Yes Overfill Prevention Services:  No Leak Detection Equipment Installar	lest of I-77): Yes lest of I-77): Yes lice Contractors  iii Yes tion Servicing: Yes Yes
1234 Gordon Park Rd Augusta, GA 30901  Website www.keepmecompliant.net  Compliance Testing and Monitoring  Automatic Line Leak Detector Testing: Containment Sump Testing: Yes Overfill Prevention Equipment Operability Check: Yes Overfill Prevention Services: No Leak Detection Equipment Installar Corrosion Protection Design Experts: Yes Spill Prevention Equipment Testing: Yes Spill Prevention Repair:	lest of I-77): Yes lest of I-77): Yes lest of I-77): Yes lice Contractors  The Yes lice Yes Yes Yes
Tax Augusta, GA 30901  Website www.keepmecompliant.net  Compliance Testing and Monitoring  Automatic Line Leak Detector Testing:  Containment Sump Testing:  Corrosion Protection Design Experts:  Corrosion Protection System Repairs:  Corrosion Protection System Repairs:  Corrosion Protection System Testing:  Corrosion Protection System Testing:  Corrosion Protection System Testing:  Corrosion Protection Equipment Installation - Other Corrosion Protection System Testing:  Corrosion Protection System Testing:  Yes UST Internal Inspections (Integrity Assessments):  No UST System Installation - Complet Installation - Complet	East of I-77): Yes  Vest of I-77): Yes  Vice Contractors  The contractors
1234 Gordon Park Rd Augusta, GA 30901  Website www.keepmecompliant.net  Compliance Testing and Monitoring  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Repairs: Corrosion Protection System Testing: Yes UST Internal Inspections (Integrity Assessments):  Central (West of I-95 and E Mountains (W	East of I-77): Yes  Vest of I-77): Yes  Vice Contractors  The contractors
Tax Augusta, GA 30901  Website www.keepmecompliant.net  Compliance Testing and Monitoring  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Repairs: Corrosion Protection System Testing: Corrosion Protection Equipment Installation - Other Corrosion Equipment Operability Check: Corrosion Equipment Corrosion System Testing: Corrosion Protection System Repairs: Corrosion Prote	East of I-77): Yes  Vest of I-77): Yes  Vice Contractors  The contractors
Tax Augusta, GA 30901  Website www.keepmecompliant.net  Compliance Testing and Monitoring  Automatic Line Leak Detector Testing:  Containment Sump Testing:  Corrosion Protection Design Experts:  Corrosion Protection System Repairs:  Corrosion Protection System Repairs:  Corrosion Protection System Testing:  Corrosion Protection Equipment Installation Services:  Corrosion Protection System Testing:  Corrosion Protection Equipment Installation Services:  Corrosion Protection System Testing:  Corrosion Protection System Testing:  Leak Detection Equipment Installation Installation Services:  Leak Detection Equipment Operability Check:  Yes UST Internal Inspections:  No UST System Installation - Complet UST Piping/Sump Installation:  Leak Detection Monitoring Services:  No Other:	East of I-77): Yes  Vest of I-77): Yes  Vice Contractors  The contractors
Tax Augusta, GA 30901  Website www.keepmecompliant.net  Compliance Testing and Monitoring  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Corrosion Protection System Testing: Corrosion Protection Equipment Operability Check: Corrosion Protection System Testing: Corrosion Protection System Repairs: Corrosion Protection System	East of I-77): Yes  Vest of I-77): Yes  Vice Contractors  The contractors
1234 Gordon Park Rd Augusta, GA 30901   Website   www.keepmecompliant.net   Website   www.keepmecompliant.net   Website   www.keepmecompliant.net   Wountains (Website   www.keepmecompliant.net   Wountains (Website   www.keepmecompliant.net   Website   www.keepmecompliant.net   Website   Websit	East of I-77): Yes  Vest of I-77): Yes  Vice Contractors  The contractors
1234 Gordon Park Rd Augusta, GA 30901  Website www.keepmecompliant.net  Compliance Testing and Monitoring  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Installation Services: Leak Detection Equipment Installation Repair: Leak Detection Equipment Installation Repair: Leak Detection System Testing: Leak Detection Equipment Installation Repair: Leak Detection Equipment Installation Repair: Leak Detection Equipment Installation - Other: Line Tightness Testing: Leak Detection Monitoring Services: No Other:  Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Other:  Corrosion Protection System Repairs: Leak Detection Equipment Operability Check: Leak Detection Equipment Installation - Completed UST Piping/Sump Installation: UST System Removal: Other:  Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No	East of I-77): Yes  Vest of I-77): Yes  Vice Contractors  The contractors
1234 Gordon Park Rd Augusta, GA 30901   Website   www.keepmecompliant.net   Website   www.keepmecompliant.net   Website   www.keepmecompliant.net   Wountains (Website   www.keepmecompliant.net   Wountains (Website   www.keepmecompliant.net   Website   www.keepmecompliant.net   Website   Websit	East of I-77): Yes  Vest of I-77): Yes  Vice Contractors  The contractors

		UST Service Provider List (Mou	ıntains)		
Company		Listing Submitted	7/16/2024	Area of state conducts work	
EnviroSouth, Inc.		Phone (864) 236-9010		Coastal (East of I-95): No	
3440 Augusta Road		Fax		Central (West of I-95 and East of I-77): Yes	
Greenville, SC 29605	,	At a later and a surface of the company		Mountains (West of I-77): Yes	
		Website www.envirosouth.com			
-	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/6/2025	Area of state conducts work	
ESNC Environmental Consulting, P.C.		Phone (919) 910-7767		Coastal (East of I-95): Yes	
1408 Christian Avenue		Fax		Central (West of I-95 and East of I-77): Yes	
Suite 11					
Durham, NC 27705	١	Website www.earthsys.net		Mountains (West of I-77): Yes	
Comp	oliance Tes	ting and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Line rightness resulty.		tal Camina Firma		Other:	
	nvironment	ai Service Firms			
	nvironment No	UST Compliance Consultants:	No		
Er	No		No No		
Emergency Cleanup - Spill/Release:	No <u>Yes</u>	UST Compliance Consultants:			
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No <u>Yes</u>	UST Compliance Consultants: UST Equipment Verification:	No		
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No <u>Yes</u> <u>Yes</u>	UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No		

	Į	JST Service Provider List (Mo	untains)		
Company		Listing Submitted		Area of state conducts work	
Excel Environmental Associates, PLLC		Phone (704) 853-0800		Coastal (East of I-95): Yes	
625 Huntsman Court		Fax (704) 853-3949		Central (West of I-95 and East of I-77): Yes	
Gastonia, NC 28054	M	Johnita www.avaalangr.com		Mountains (West of I-77): Yes	
		Vebsite www.excelengr.com			
_	liance Test	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal: Other:	No
	vironmenta	al Service Firms		Other.	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	7/3/2024	Area of state conducts work	
Groundwater Manage. Associates		Phone (252) 758-3310		Coastal (East of I-95): Yes	
4300 Sapphire Court		Fax		Central (West of I-95 and East of I-77): Yes	
Suite 100					
				Mountains (West of I-77): Yes	
Greenville, NC 27834	W	/ebsite www.gma-nc.com		Mountains (West of I-77): Yes	
·		Vebsite www.gma-nc.com		Mountains (West of I-77): Yes  UST Equipmment Service Contractors	
·		<u> </u>	No		No
Сотр	oliance Test	ting and Monitoring	No No	UST Equipmment Service Contractors	
Comp  Automatic Line Leak Detector Testing:	oliance Test No	ting and Monitoring Overfill Prevention Equipment Operability Check:		UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	No
Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  al Service Firms UST Compliance Consultants:	No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  UST Compliance Consultants: UST Equipment Verification:	No No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

		UST Service Provider List (Mou	untains)		
Company		Listing Submitted		Area of state conducts work	
Groundwater Management Associates, Inc.		Phone (252) 758-3310		Coastal (East of I-95): Yes	
4300 Sapphire Court		Fax		Central (West of I-95 and East of I-77): Yes	
Suite 100 Greenville, NC 27834				Mountains (West of I-77): Yes	
Greenville, NO 27004	\	Website www.gma-nc.com			
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Eı	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
_					
Company		Listing Submitted	3/31/2025	Area of state conducts work	
		Listing Submitted Phone (704) 586-0007	3/31/2025	Area of state conducts work  Coastal (East of I-95): Yes	
Company Hart & Hickman, PC 2923 S. Tryon Street		Phone (704) 586-0007	3/31/2025	Coastal (East of I-95): Yes	
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100			3/31/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company Hart & Hickman, PC 2923 S. Tryon Street		Phone (704) 586-0007	3/31/2025	Coastal (East of I-95): Yes	
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203	,	Phone (704) 586-0007 Fax	3/31/2025	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203	,	Phone (704) 586-0007  Fax  Website https://harthickman.com/	3/31/2025 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Comp	oliance Tes	Phone (704) 586-0007  Fax  Website https://harthickman.com/		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Company  Automatic Line Leak Detector Testing:	oliance Tes	Phone (704) 586-0007  Fax  Website https://harthickman.com/  sting and Monitoring  Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Company  Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Tes No No	Phone (704) 586-0007  Fax  Website https://harthickman.com/  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Company  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Dliance Tes No No No	Phone (704) 586-0007  Fax  Website https://harthickman.com/  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Company  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Diiance Tes No No No No No	Phone (704) 586-0007  Fax  Website https://harthickman.com/  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Company  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No No No No	Phone (704) 586-0007  Fax  Website https://harthickman.com/  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No No	Phone (704) 586-0007  Fax  Website https://harthickman.com/  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Company  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (704) 586-0007  Fax  Website https://harthickman.com/  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Company  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (704) 586-0007  Fax  Website https://harthickman.com/  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (704) 586-0007  Fax  Website https://harthickman.com/  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Company  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En  Emergency Cleanup - Spill/Release:	No N	Phone (704) 586-0007  Fax  Website https://harthickman.com/  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company  Hart & Hickman, PC 2923 S. Tryon Street Suite 100 Charlotte, NC 28203  Company  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (704) 586-0007  Fax  Website https://harthickman.com/  sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Mou	untains)		
Company		Listing Submitted		Area of state conducts work	
INENCO, Inc.		Phone (704) 662-8192		Coastal (East of I-95): Yes	
132 W. Statesville Avenue		Fax (704) 662-8194		Central (West of I-95 and East of I-77): Yes	
Mooresville, NC 27115		Website		Mountains (West of I-77): Yes	
Comp				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	sting and Monitoring  Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:	140	UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	Yes
		ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No.	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/15/2023	Area of state conducts work	
JF Petroleum Group		Phone (919) 744-4391	0,10,2020	Coastal (East of I-95): Yes	
100 Perimeter Park Drive		,		Central (West of I-95 and East of I-77): Yes	
Suite H		Fax			
Suite H Morrisville, NC 27560		Website jfpetrogroup.com/services/environmental	<u>compliance</u>	Mountains (West of I-77): Yes	
Morrisville, NC 27560			compliance		
Morrisville, NC 27560		Website jfpetrogroup.com/services/environmental	compliance Yes	Mountains (West of I-77): Yes	<u>Yes</u>
Morrisville, NC 27560  Comp	oliance Te	Website ifpetrogroup.com/services/environmental	-	Mountains (West of I-77): Yes  UST Equipmment Service Contractors	Yes Yes
Morrisville, NC 27560  Comp  Automatic Line Leak Detector Testing:	oliance Te	Website ifpetrogroup.com/services/environmental sting and Monitoring Overfill Prevention Equipment Operability Check:	Yes	Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	
Morrisville, NC 27560  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing:	oliance Te Yes Yes	Website jfpetrogroup.com/services/environmental sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	<u>Yes</u> No	Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Morrisville, NC 27560  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Yes Yes No	Website jfpetrogroup.com/services/environmental sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Yes No Yes	Mountains (West of I-77): Yes  UST Equipment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:	<u>Yes</u> <u>Yes</u>
Morrisville, NC 27560  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes Yes No	Website ifpetrogroup.com/services/environmental sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes No Yes Yes	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes
Morrisville, NC 27560  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Yes No No	Website ifpetrogroup.com/services/environmental sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes Yes No	Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes
Morrisville, NC 27560  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No No No No Yes	Website ifpetrogroup.com/services/environmental sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes No	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes
Morrisville, NC 27560  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No No Yes Yes Yes Yes Yes Yes	Website ifpetrogroup.com/services/environmental sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes No	Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes Yes
Morrisville, NC 27560  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No No Yes Yes Yes Yes Yes Yes	Website ifpetrogroup.com/services/environmental sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes No	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes
Morrisville, NC 27560  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er	Yes Yes No No No Yes Yes Yes Yes Yes Yes Yes Yes	Website ifpetrogroup.com/services/environmental sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes No No	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes
Morrisville, NC 27560  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er  Emergency Cleanup - Spill/Release:	Yes Yes No No No Yes Yes Yes Yes Yes Yes No No No	Website ifpetrogroup.com/services/environmental sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  other:	Yes No Yes Yes No No	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes
Morrisville, NC 27560  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes No No No Yes Yes Yes Yes Yes Yes No No No	Website ifpetrogroup.com/services/environmental sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Intal Service Firms  UST Compliance Consultants: UST Equipment Verification:	Yes No Yes Yes No No	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes
Morrisville, NC 27560  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	Yes Yes No No No Yes Yes Yes Yes Yes Yourner No	Website ifpetrogroup.com/services/environmental sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Intal Service Firms  UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	Yes No Yes Yes No No	Wountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes

		<b>UST Service Provider List (Mou</b>	ıntains)		
Company		Listing Submitted	12/20/2022	Area of state conducts work	
Jones Covey Group		Phone (888) 972-7581		Coastal (East of I-95): Yes	
9595 Lucas Ranch Rd STE 100		Fax (909) 484-0300		Central (West of I-95 and East of I-77): Yes	
Rancho Cucamonga, CA 91730				Mountains (West of I-77): Yes	
		Website		,	
Comp	oliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
E	nvironmer	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/30/2024	Area of state conducts work	
Company  Marley Trucking & Demolition Inc.		Phone (336) 382-7132	5/30/2024	Area of state conducts work  Coastal (East of I-95): Yes	
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road			5/30/2024		
Marley Trucking & Demolition Inc.		Phone (336) 382-7132  Fax	5/30/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road		Phone (336) 382-7132	5/30/2024	Coastal (East of I-95): Yes	
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205		Phone (336) 382-7132  Fax	5/30/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205		Phone (336) 382-7132  Fax  Website	5/30/2024 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205	oliance Te	Phone (336) 382-7132 Fax Website esting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205  Comparison of Comparison Containment Sump Testing: Corrosion Protection Design Experts:	oliance Te	Phone (336) 382-7132  Fax  Website  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No	Phone (336) 382-7132  Fax  Website  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone (336) 382-7132  Fax  Website  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No	Phone (336) 382-7132  Fax  Website  Peting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone (336) 382-7132  Fax  Website  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No	Phone (336) 382-7132  Fax  Website  Peting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Marley Trucking & Demolition Inc.  1768 Old Humble Mill Road Asheboro, NC 27205  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (336) 382-7132  Fax  Website  Peting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Marley Trucking & Demolition Inc.  1768 Old Humble Mill Road Asheboro, NC 27205  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (336) 382-7132  Fax  Website  Setting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Marley Trucking & Demolition Inc.  1768 Old Humble Mill Road Asheboro, NC 27205  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (336) 382-7132 Fax  Website  Seting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Marley Trucking & Demolition Inc.  1768 Old Humble Mill Road Asheboro, NC 27205  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanup	No N	Phone (336) 382-7132 Fax  Website  Peting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Intal Service Firms  UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Marley Trucking & Demolition Inc.  1768 Old Humble Mill Road Asheboro, NC 27205  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (336) 382-7132  Fax  Website  Esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Intal Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

		UST Service Provider List (Mou	ıntains)		
Company		Listing Submitted	5/30/2024	Area of state conducts work	
MERRITT COMMERCIAL SERVICES LLC		Phone (228) 516-0498		Coastal (East of I-95): Yes	
217 STRICKLAND RD		Fax		Central (West of I-95 and East of I-77): Yes	
WHIGHAM, GA 39897	v	Vebsite https://www.mcs-petroleum-div.com/		Mountains (West of I-77): Yes	
	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Living Inspections:	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No	UST Internal Lining Inspections: Other:	No	UST System Installation - Complete Systems: UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No No	Other.		UST System Removal:	<u>Yes</u> No
		10 1 5		Other:	INO
		al Service Firms		Othor.	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Lieting Culemitted	4/20/2022	Avec of state conducts would	
Outipatty		Listing Submitted	4/20/2023	Area of state conducts work	
MGF Environmental, PLLC		Phone (904) 814-3680	4/20/2023	Coastal (East of I-95): No	
MGF Environmental, PLLC 288 Gap Creek Rd			4/20/2023		
MGF Environmental, PLLC		Phone (904) 814-3680 Fax	4/20/2023	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
MGF Environmental, PLLC 288 Gap Creek Rd	V	Phone (904) 814-3680	4/20/2023	Coastal (East of I-95): No	
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732		Phone (904) 814-3680 Fax	4/20/2023	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	7 7
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732		Phone (904) 814-3680  Fax  Vebsite mgfenvironmental.com	4/20/2023 No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732  Comp	oliance Tes	Phone (904) 814-3680 Fax  Vebsite mgfenvironmental.com ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No	Phone (904) 814-3680  Fax  Vebsite mgfenvironmental.com  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No	Phone (904) 814-3680  Fax  Vebsite mgfenvironmental.com  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone (904) 814-3680  Fax  Vebsite mgfenvironmental.com  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732  Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (904) 814-3680  Fax  Vebsite mgfenvironmental.com  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone (904) 814-3680  Fax  Vebsite mgfenvironmental.com  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732  Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (904) 814-3680  Fax  Vebsite mgfenvironmental.com  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (904) 814-3680  Fax  Vebsite mgfenvironmental.com  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (904) 814-3680  Fax  Vebsite mgfenvironmental.com  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (904) 814-3680  Fax  Vebsite mgfenvironmental.com  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  al Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	Phone (904) 814-3680  Fax  Vebsite mgfenvironmental.com  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  al Service Firms  UST Compliance Consultants:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732  Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu Oil and Solvent Recycling:	No N	Phone (904) 814-3680  Fax  Vebsite mgfenvironmental.com  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  al Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	Phone (904) 814-3680  Fax  Vebsite mgfenvironmental.com  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company  Listing Submitted  9/8/2022  Area of state conducts work  Mid-Atlantic Associates, Inc.  409 Rogers View Ct Raleigh, NC 27610  Website www.maaonline.com  Compliance Testing and Monitoring  Automatic Line Leak Detector Testing: Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: Corrosion Protection Design Experts: No Tank Tightness Testing: No UST Internal Inspections: No UST Internal Inspections: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST System Installation - Complete Systems:  Leak Detection Equipment Results: No UST System Installation - Complete Systems:  Leak Detection Equipment Repair: No UST System Installation - Complete Systems:  Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST System Installation - Complete Systems:	rs No No No
409 Rogers View Ct Raleigh, NC 27610  Website www.maaonline.com  Compliance Testing and Monitoring  Automatic Line Leak Detector Testing:  No Overfill Prevention Equipment Operability Check:  No Statistical Iventory Reconciliation Services:  No Spill Prevention Equipment Testing:  No Spill Bucket Installation Repair:  Corrosion Protection System Repairs:  No Tank Tightness Testing:  No UST Internal Inspections (Integrity Assessments):  No UST Equipment Repair:  Leak Detection Equipment Operability Check:  No UST System Installation - Complete Systems:	rs No No No
Raleigh, NC 27610  Website www.maaonline.com  Compliance Testing and Monitoring  Automatic Line Leak Detector Testing:  No Overfill Prevention Equipment Operability Check:  No Dispenser Meter Repair/Calibration:  Containment Sump Testing:  No Statistical Iventory Reconciliation Services:  No Leak Detection Equipment Installation Servicing:  Corrosion Protection Design Experts:  No Spill Prevention Equipment Testing:  No Spill Bucket Installation Repair:  Corrosion Protection System Repairs:  No UST Equipment Installation - Other:  Corrosion Protection System Testing:  No UST Internal Inspections (Integrity Assessments):  No UST System Installation - Complete Systems:	rs No No No
Website www.maaonline.com  Compliance Testing and Monitoring  Automatic Line Leak Detector Testing:  No Overfill Prevention Equipment Operability Check:  No Dispenser Meter Repair/Calibration:  Containment Sump Testing:  No Statistical Iventory Reconciliation Services:  No Leak Detection Equipment Installation Servicing:  Corrosion Protection Design Experts:  No Spill Prevention Equipment Testing:  No Spill Bucket Installation Repair:  Corrosion Protection System Repairs:  No UST Equipment Installation - Other:  Corrosion Protection System Testing:  No UST Equipment Repair:  Leak Detection Equipment Operability Check:  No UST Internal Lining Inspections:  No UST System Installation - Complete Systems:	No No No
Automatic Line Leak Detector Testing:  No Overfill Prevention Equipment Operability Check:  No Dispenser Meter Repair/Calibration:  Containment Sump Testing:  No Statistical Iventory Reconciliation Services:  No Leak Detection Equipment Installation Servicing:  Corrosion Protection Design Experts:  No Spill Prevention Equipment Testing:  No Spill Bucket Installation Repair:  Corrosion Protection System Repairs:  No UST Equipment Installation - Other:  Corrosion Protection System Testing:  No UST Internal Inspections (Integrity Assessments):  No UST Equipment Repair:  Leak Detection Equipment Operability Check:  No UST System Installation - Complete Systems:	No No No
Automatic Line Leak Detector Testing:  No Overfill Prevention Equipment Operability Check:  No Dispenser Meter Repair/Calibration:  Containment Sump Testing:  No Statistical Iventory Reconciliation Services:  No Leak Detection Equipment Installation Servicing:  Corrosion Protection Design Experts:  No Spill Prevention Equipment Testing:  No Spill Bucket Installation Repair:  Corrosion Protection System Repairs:  No UST Equipment Installation - Other:  Corrosion Protection System Testing:  No UST Internal Inspections (Integrity Assessments):  No UST Equipment Repair:  Leak Detection Equipment Operability Check:  No UST System Installation - Complete Systems:	No No No
Containment Sump Testing:  No Statistical Iventory Reconciliation Services:  No Leak Detection Equipment Installation Servicing:  Corrosion Protection Design Experts:  No Spill Prevention Equipment Testing:  No Spill Bucket Installation Repair:  Corrosion Protection System Repairs:  No UST Equipment Installation - Other:  UST Equipment Repair:  Leak Detection Equipment Operability Check:  No UST Internal Lining Inspections:  No UST System Installation - Complete Systems:	No No
Corrosion Protection Design Experts:  No Spill Prevention Equipment Testing:  No Spill Bucket Installation Repair:  UST Equipment Installation - Other:  UST Equipment Repair:  UST Equipment Repair:  Leak Detection Equipment Operability Check:  No UST Internal Lining Inspections:  No UST System Installation - Complete Systems:	No
Corrosion Protection System Repairs:  No Tank Tightness Testing:  No UST Equipment Installation - Other:  UST Equipment Repair:  UST System Installation - Complete Systems:	
Corrosion Protection System Testing:  No UST Internal Inspections (Integrity Assessments):  No UST Equipment Repair:  UST Equipment Repair:  UST System Installation - Complete Systems:	
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems:	No
	No
LICT D'a la Othani	No
Leak Detection Monitoring Services: No Other: UST Piping/Sump Installation:	No
Line Tightness Testing: No UST System Removal:	No
Environmental Service Firms Other:	ļ
Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: No	
Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No	
Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Yes	ļ
Oil and Solvent Recycling: No Other:	ļ
Soil and Water Testing Lab: No	ļ
Company Listing Submitted 11/1/2023 Area of state conducts work	
Peak Hydrogeologic, PLLC Phone (828) 817-5209 Coastal (East of I-95): N	0
470 Hogback Mtn Rd Central (West of I-95 and East of I-77): Y	es
Tryon, NC 28782  Mountains (West of I-77): Yes	
Website https://peakhydrogeologic.com	62
Compliance Testing and Monitoring UST Equipmment Service Contractor	s
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration:	No
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other:	No
Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair:	No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services: No Other: UST Piping/Sump Installation:	No
Line Tightness Testing:  No  UST System Removal:	<u>Yes</u>
Environmental Service Firms Other:	
Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: Yes	
Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No	ļ
	ļ
Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Yes	ļ

		UST Service Provider List (Mou	intains)		
Company		Listing Submitted	8/19/2024	Area of state conducts work	
Piedmont Geologic, P.C.		Phone (919) 954-9700		Coastal (East of I-95): Yes	
6003-145 Chapel Hill Road		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27607	1	Website www.piedmontgeologic.com	Mountains (West of I-77): Yes		
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/1/2023	Area of state conducts work	
Company Pilot Geological , PLLC		Listing Submitted Phone (336) 870-3095	11/1/2023	Area of state conducts work  Coastal (East of I-95): Yes	
Pilot Geological , PLLC PO Box 128		Phone (336) 870-3095	11/1/2023	Coastal (East of I-95): Yes	
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court			11/1/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Pilot Geological , PLLC PO Box 128	,	Phone (336) 870-3095	11/1/2023	Coastal (East of I-95): Yes	
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285		Phone (336) 870-3095  Fax (336) 310-4527	11/1/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285		Phone (336) 870-3095  Fax (336) 310-4527  Website www.pilotenviro.com	11/1/2023 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comp	oliance Tes	Phone (336) 870-3095 Fax (336) 310-4527  Website www.pilotenviro.com  sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	oliance Tes No	Phone (336) 870-3095 Fax (336) 310-4527  Website www.pilotenviro.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No	Phone (336) 870-3095  Fax (336) 310-4527  Website www.pilotenviro.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone (336) 870-3095  Fax (336) 310-4527  Website www.pilotenviro.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Phone (336) 870-3095  Fax (336) 310-4527  Website www.pilotenviro.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone (336) 870-3095  Fax (336) 310-4527  Website www.pilotenviro.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (336) 870-3095  Fax (336) 310-4527  Website www.pilotenviro.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No	Phone (336) 870-3095 Fax (336) 310-4527  Website www.pilotenviro.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	No No No No No No No No No	Phone (336) 870-3095 Fax (336) 310-4527  Website www.pilotenviro.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Vo No Tvironmen Yes Yes	Phone (336) 870-3095  Fax (336) 310-4527  Website www.pilotenviro.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No Vo No Tvironmen Yes Yes	Phone (336) 870-3095  Fax (336) 310-4527  Website www.pilotenviro.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285  Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Vo No Tvironmen Yes Yes	Phone (336) 870-3095  Fax (336) 310-4527  Website www.pilotenviro.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

		UST Service Provider List (Mo	untains)		
Company		Listing Submitted		Area of state conducts work	
SR&R Environmental, Inc.		Phone (910) 763-6274		Coastal (East of I-95): Yes	
4920 Highway 421 N.		Fax (910) 763-6132		Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28401		Website www.srrenviro.com	Mountains (West of I-77): Yes		
Comm				UST Favingsment Comics Contractors	
-		esting and Monitoring	Nie	UST Equipment Service Contractors	NI-
Automatic Line Leak Detector Testing:	No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing: Corrosion Protection Design Experts:	No No	Spill Prevention Equipment Testing:	No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Corrosion Protection Design Experts.  Corrosion Protection System Repairs:	No No	Tank Tightness Testing:	No No	UST Equipment Installation - Other:	No No
Corrosion Protection System Repairs.  Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No No
Leak Detection Equipment Operability Check:	No No	UST Internal Inspections (integrity Assessments).	No	UST System Installation - Complete Systems:	No
Leak Detection Equipment Operability Check.  Leak Detection Monitoring Services:	No	Other:	INO	UST Piping/Sump Installation:	No
Line Tightness Testing:	No	Other.		UST System Removal:	Yes
		ntal Service Firms		Other:	163
			NI-		
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other: Fuel F	Polishing		
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/15/2024	Area of state conducts work	
Company Terracon		Phone (336) 854-8135	8/15/2024	Area of state conducts work  Coastal (East of I-95): Yes	
Terracon 7327- G West Friendly Avenue			8/15/2024		
Terracon		Phone (336) 854-8135  Fax	8/15/2024	Coastal (East of I-95): Yes	
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410		Phone (336) 854-8135 Fax Website https://www.terracon.com/	8/15/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410  Comp	oliance Te	Phone (336) 854-8135 Fax  Website https://www.terracon.com/		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410  Comp Automatic Line Leak Detector Testing:	oliance Te No	Phone (336) 854-8135  Fax  Website https://www.terracon.com/ esting and Monitoring  Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410  Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (336) 854-8135  Fax  Website https://www.terracon.com/ esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Phone (336) 854-8135  Fax  Website https://www.terracon.com/ esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No No	Phone (336) 854-8135  Fax  Website <a href="https://www.terracon.com/">https://www.terracon.com/</a> esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No No
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone (336) 854-8135  Fax  Website https://www.terracon.com/  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (336) 854-8135  Fax  Website https://www.terracon.com/  Pesting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone (336) 854-8135  Fax  Website https://www.terracon.com/  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (336) 854-8135  Fax  Website <a href="https://www.terracon.com/">https://www.terracon.com/</a> Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (336) 854-8135  Fax  Website https://www.terracon.com/  Pesting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er  Emergency Cleanup - Spill/Release:	No N	Phone (336) 854-8135  Fax  Website https://www.terracon.com/  esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Intal Service Firms  UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No The properties Yes Yes	Phone (336) 854-8135  Fax  Website https://www.terracon.com/ esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Intal Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No Yes Yes Yes	Phone (336) 854-8135  Fax  Website https://www.terracon.com/ esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Intal Service Firms  UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Terracon 7327- G West Friendly Avenue Greensboro, NC 27410  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (336) 854-8135  Fax  Website https://www.terracon.com/ esting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Intal Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

		UST Service Provider List (Mo	untains)		
Company		Listing Submitted		Area of state conducts work	
Titan Environmental Group		Phone (984) 200-6825		Coastal (East of I-95): Yes	
2005 Citation Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Garner, NC 27529	,	Website www.titanenvirogroup.com	Mountains (West of I-77): Yes		
		<u> </u>			
-		sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/27/2024	Area of state conducts work	
UES Professional Solutions 29, Inc.		Phone (704) 504-1717	8/27/2024	Area of state conducts work  Coastal (East of I-95): Yes	
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street			8/27/2024		
UES Professional Solutions 29, Inc.	,	Phone (704) 504-1717  Fax (704) 504-1125	8/27/2024	Coastal (East of I-95): Yes	
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134		Phone (704) 504-1717  Fax (704) 504-1125  Website www.teamues.com	8/27/2024	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134  Comp	oliance Tes	Phone (704) 504-1717 Fax (704) 504-1125  Website www.teamues.com  sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134  Compa	oliance Tes No	Phone (704) 504-1717  Fax (704) 504-1125  Website www.teamues.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134  Compa Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (704) 504-1717 Fax (704) 504-1125  Website www.teamues.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134  Comparing Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Phone (704) 504-1717  Fax (704) 504-1125  Website www.teamues.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Phone (704) 504-1717  Fax (704) 504-1125  Website www.teamues.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No No
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone (704) 504-1717  Fax (704) 504-1125  Website www.teamues.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (704) 504-1717  Fax (704) 504-1125  Website www.teamues.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134  Compa  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone (704) 504-1717  Fax (704) 504-1125  Website www.teamues.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (704) 504-1717  Fax (704) 504-1125  Website www.teamues.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134  Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (704) 504-1717  Fax (704) 504-1125  Website www.teamues.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  En Emergency Cleanup - Spill/Release:	No N	Phone (704) 504-1717  Fax (704) 504-1125  Website www.teamues.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (704) 504-1717  Fax (704) 504-1125  Website www.teamues.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No Ves Yes	Phone (704) 504-1717  Fax (704) 504-1125  Website www.teamues.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (704) 504-1717  Fax (704) 504-1125  Website www.teamues.com  Sting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

	l	JST Service Provider List (Mou	intains)		
Company		Listing Submitted	7/14/2022	Area of state conducts work	
VALLEY TANK TESTING		Phone (813) 671-9065		Coastal (East of I-95): Yes	
451 APOLLO BEACH BOULEVARD		Fax (866) 328-9796		Central (West of I-95 and East of I-77): Yes	
APOLLO BEACH, FL 33572	V	Vebsite WWW.VALLEYTANK.COM	Mountains (West of I-77): Yes		
Comr	liance Test	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/31/2023	Area of state conducts work	
• •		Elotting Gubillitted	170172020		
Valor Construction LLC		Phone (205) 577-1035	170172020	Coastal (East of I-95): Yes	
Valor Construction LLC PO Box 680654			170172020	Coastal (East of I-95): Yes	
Valor Construction LLC		Phone (205) 577-1035  Fax	1/01/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Valor Construction LLC PO Box 680654	V	Phone (205) 577-1035	11011/2020	Coastal (East of I-95): Yes	
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968		Phone (205) 577-1035  Fax	170172020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968		Phone (205) 577-1035  Fax  Vebsite  ting and Monitoring  Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968  Comparing Line Leak Detector Testing: Containment Sump Testing:	oliance Test	Phone (205) 577-1035  Fax  Vebsite  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968  Comparing Containment Sump Testing: Corrosion Protection Design Experts:	oliance Test	Phone (205) 577-1035  Fax  Vebsite  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968  Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No	Phone (205) 577-1035  Fax  Vebsite  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968  Comparing Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone (205) 577-1035  Fax  Vebsite  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (205) 577-1035  Fax  Vebsite  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No <u>Yes</u>
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968  Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone (205) 577-1035  Fax  Vebsite  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No Yes Yes
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968  Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (205) 577-1035  Fax  Vebsite  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u>
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (205) 577-1035  Fax  Vebsite  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No Yes Yes
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	No No No No No No No No No No	Phone (205) 577-1035  Fax  Vebsite  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  al Service Firms  UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No Yes Yes
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (205) 577-1035  Fax  Vebsite  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  al Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No Yes Yes
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	Phone (205) 577-1035  Fax  Vebsite  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No Yes Yes
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968  Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (205) 577-1035  Fax  Vebsite  ting and Monitoring  Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  al Service Firms  UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No Yes Yes

	U	ST Service Provid	der List (Mou	ntains)		
Company			Listing Submitted	11/1/2023	Area of state conducts work	
Withers Ravenel, Inc.	F	Phone (919) 469-3340			Coastal (East of I-95): Yes	S
115 MacKenan Drive	Fax				Central (West of I-95 and East of I-77): Yes	S
Cary, NC 27591	We	Website www.withersravenel.com			Mountains (West of I-77): Yes	
Comp	UST Equipmment Service Contractors					
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Op	perability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation	Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testi	ng:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrit	ty Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Environmental Service Firms					Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:		No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					